
Flood Situation Report

Area: 34.524°N 72.461°E (323.5 km²) Flood date: 2025-08-16 Generated: 2026-10-10 03:44 UTC

Flood / debris impact detected

Educational prototype generated automatically from satellite data. Not an official emergency map.

0.08 km²	5.07 km²	0	17.8 km	20	1
Flood water	Debris / mud	Buildings likely hit	Roads affected	Bridges hit	Settlements cut off



Settlements that lost or changed road access to a hospital

#	Settlement	Road access now	Buildings	Nearest hospital (before)	Before	Now
1		CUT OFF	0	Government Hospital Pacha Kala	8.7 km, 14 min	no route
2		Likely cut off	98	Government Hospital Pacha Kala	4.3 km, 7 min	no route
3		Likely cut off	47	Government Hospital Pacha Kala	0.7 km, 1 min	no route
4		Likely cut off	17	Government Hospital Pacha Kala	4.3 km, 6 min	no route
5		Likely cut off	7	Government Hospital Pacha Kala	17.4 km, 21 min	no route

+ 29 more (full list: dashboard / priority_list.csv)

Can we get there? Roads and bridges

Blocked or damaged roads (names from the pre-event map)

- Amnawar - Shalbandai Road: 1.63 km affected, 34.500°N 72.475°E
- Gokand Road: 1.03 km affected, 34.616°N 72.526°E
- Pirbaba Road: 0.56 km affected, 34.518°N 72.446°E
- + 29 more

Bridges likely hit

- Jowar - Pirbaba Road, 34.578°N 72.437°E
- Daggar Bridge, 34.502°N 72.459°E
- Pirbaba Road, 34.554°N 72.447°E
- + 17 more

Helicopter access for settlements cut off by road

mapped helipad: none within 5 km; flat open ground 0.1 km (34.548°N 72.399°E) :[CUT OFF] •
mapped helipad: none within 5 km; flat open ground 0.1 km (34.598°N 72.477°E) :[Likely cut off] •
mapped helipad: none within 5 km; flat open ground 0.5 km (34.587°N 72.444°E) :[Likely cut off] •
• + 17 more (full list: dashboard / priority_list.csv)

Flat open ground = slope at most 7°, at least 60 m clear, away from detected flood or debris and mapped buildings or power lines. Not checked: trees, unmapped wires or buildings, soft ground, debris the map missed. Confirm from the air. Distances are straight-line.

Data used

- Sentinel-1 radar: before 2025-08-04, after 2025-08-16 (track des-107, 12 days apart)
- Sentinel-1 radar: before 2025-08-08, after 2025-08-20 (track asc-173, 12 days apart)
- Sentinel-2 optical: second sensor (97% of area cloud-free); confirms radar and adds what only it sees (low confidence)
- OpenStreetMap as of 2025-08-14 (before the event)
- AI segmentation model: used, combined with rule-based detection
- Debris class only in mountain terrain (UNEP-WCMC definition); 100% of this area is mountain

Confidence and limits

- 0.29 km² of the flood/debris area is medium or high confidence.
- Sentinel satellites revisit an area only every few days: this system maps damage after the fact and cannot warn of a sudden glacier or lake outburst. Areas marked grey were hidden from the radar and are unknown, not safe. Road access uses mapped roads only. 'Likely cut off' rests on low-confidence detections (debris counts as confident only when a second radar pass or Sentinel-2 confirms it); 'Unknown' means the last route crosses roads the radar could not see. Travel times use nominal speeds per road class. Rows are ranked by priority: certainty, settlement size (mapped buildings), extra time.
- Before-images taken on or before 2025-08-14 (set by the operator: the area was still dry then). Change between that date and the after-image includes the whole build-up of the flood, and also any other change in that period (crops, construction).

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Model trained on Kuro Siwo: Bountos et al., 2024 (NeurIPS Datasets & Benchmarks). Run hkh_buner_aoi10_full.