
Flood Situation Report

Area: 46.505°N 14.835°E (293.1 km²) Flood date: 2023-08-04 Generated: 2026-10-10 03:51 UTC

Flood / debris impact detected

Educational prototype generated automatically from satellite data. Not an official emergency map.

0.01 km²	0.73 km²	3	7.6 km	15	0
Flood water	Debris / mud	Buildings likely hit	Roads affected	Bridges hit	Settlements cut off



Settlements that lost or changed road access to a hospital

#	Settlement	Road access now	Buildings	Nearest hospital (before)	Before	Now
1	Lokowitzen	Likely cut off	22	Splošna Bolnišnica Slovenj Gra	30.7 km, 36 min	no route
2	Poljana	Long detour	80	Splošna Bolnišnica Slovenj Gra	20.5 km, 22 min	29.9 km, 44 min
3	Sdoutz	Long detour	18	Splošna Bolnišnica Slovenj Gra	26.0 km, 30 min	33.5 km, 41 min
4	Kralj	Long detour	16	Splošna Bolnišnica Slovenj Gra	23.6 km, 25 min	31.3 km, 41 min
5	Koprivna	Long detour	15	Bolnišnica Topolšica	31.7 km, 49 min	39.8 km, 82 min
6	Holmec	Long detour	11	Splošna Bolnišnica Slovenj Gra	24.5 km, 26 min	32.1 km, 40 min
7	Topla	Long detour	9	Bolnišnica Topolšica	29.7 km, 48 min	46.0 km, 116 min

Can we get there? Roads and bridges

Blocked or damaged roads (names from the pre-event map)

- Poljana: 0.63 km affected, 46.547°N 14.895°E
- unnamed primary: 0.19 km affected, 46.547°N 14.899°E
- Trg svobode: 0.28 km affected, 46.544°N 14.966°E
- Mariborska cesta: 0.05 km affected, 46.524°N 14.854°E
- unnamed secondary: 0.39 km affected, 46.461°N 14.870°E
- + 29 more

Bridges likely hit

- Koroška cesta, 46.547°N 14.966°E
- bridge on unnamed secondary, 46.466°N 14.861°E
- bridge on unnamed secondary, 46.477°N 14.853°E
- bridge on unnamed tertiary, 46.471°N 14.848°E
- Topla, 46.478°N 14.773°E
- + 10 more

Helicopter access for settlements cut off by road

- Lokowitzen [Likely cut off]: mapped helipad: none within 5 km; flat open ground 0.3 km (46.549°N 14.822°E)

Flat open ground = slope at most 7°, at least 60 m clear, away from detected flood or debris and mapped buildings or power lines. Not checked: trees, unmapped wires or buildings, soft ground, debris the map missed. Confirm from the air. Distances are straight-line.

Data used

- Sentinel-1 radar: before 2023-07-24, after 2023-08-05 (track asc-146, 12 days apart)
- Sentinel-1 radar: before 2023-07-28, after 2023-08-09 (track des-022, 12 days apart)
- Sentinel-2 optical: second sensor (97% of area cloud-free); confirms radar and adds what only it sees (low confidence)
- OpenStreetMap as of 2023-08-03 (before the event)
- AI segmentation model: used, combined with rule-based detection
- Debris class only in mountain terrain (UNEP-WCMC definition); 100% of this area is mountain

Confidence and limits

- 0.05 km² of the flood/debris area is medium or high confidence.
- Sentinel satellites revisit an area only every few days: this system maps damage after the fact and cannot warn of a sudden glacier or lake outburst. Areas marked grey were hidden from the radar and are unknown, not safe. Road access uses mapped roads only. 'Likely cut off' rests on low-confidence detections (debris counts as confident only when a second radar pass or Sentinel-2 confirms it); 'Unknown' means the last route crosses roads the radar could not see. Travel times use nominal speeds per road class. Rows are ranked by priority: certainty, settlement size (mapped buildings), extra time.

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Model trained on Kuro Siwo: Bountos et al., 2024 (NeurIPS Datasets & Benchmarks). Run slo_meza.