
Flood Situation Report

Area: 46.580°N 16.200°E (406.1 km²) Flood date: 2023-08-04 Generated: 2026-10-10 03:56 UTC

Flood / debris impact detected

Educational prototype generated automatically from satellite data. Not an official emergency map.

2.44 km²	0.00 km²	0	4.6 km	1	0
Flood water	Debris / mud	Buildings likely hit	Roads affected	Bridges hit	Settlements cut off



Settlements that lost or changed road access to a hospital

No mapped settlement lost its road connection to a hospital.

Can we get there? Roads and bridges

Blocked or damaged roads (names from the pre-event map)

- Razkrižje: 0.02 km affected (uncertain), 46.530°N 16.269°E
- unnamed tertiary: 0.02 km affected (uncertain), 46.533°N 16.253°E
- unnamed unclassified: 0.26 km affected, 46.546°N 16.060°E
- Dolnja Bistrica: 0.06 km affected, 46.545°N 16.292°E
- Ulica ob kapelici: 0.02 km affected (uncertain), 46.655°N 16.137°E
- + 9 more

Bridges likely hit

- bridge on unnamed track, 46.560°N 16.224°E

Helicopter access for settlements cut off by road

- No settlement needs air access by this analysis. Mapped helipads in the area: 3.

Flat open ground = slope at most 7°, at least 60 m clear, away from detected flood or debris and mapped buildings or power lines. Not checked: trees, unmapped wires or buildings, soft ground, debris the map missed. Confirm from the air. Distances are straight-line.

Data used

- Sentinel-1 radar: before 2023-07-23, after 2023-08-04 (track des-124, 12 days apart)
- Sentinel-1 radar: before 2023-07-24, after 2023-08-05 (track asc-146, 12 days apart)
- Sentinel-2 optical: second sensor (100% of area cloud-free); confirms radar and adds what only it sees (low confidence)
- OpenStreetMap as of 2023-08-03 (before the event)
- AI segmentation model: used, combined with rule-based detection
- Debris class only in mountain terrain (UNEP-WCMC definition); 0% of this area is mountain

Confidence and limits

- 0.88 km² of the flood/debris area is medium or high confidence.
- Sentinel satellites revisit an area only every few days: this system maps damage after the fact and cannot warn of a sudden glacier or lake outburst. Areas marked grey were hidden from the radar and are unknown, not safe. Road access uses mapped roads only. 'Likely cut off' rests on low-confidence detections (debris counts as confident only when a second radar pass or Sentinel-2 confirms it); 'Unknown' means the last route crosses roads the radar could not see. Travel times use nominal speeds per road class. Rows are ranked by priority: certainty, settlement size (mapped buildings), extra time.
- Plains terrain (UNEP-WCMC mountain definition): flooding is mapped as water; the debris class applies only to mountain terrain.

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Model trained on Kuro Siwo: Bountos et al., 2024 (NeurIPS Datasets & Benchmarks). Run slo_mura.