
Flood Situation Report

Area: 28.070°N 85.240°E (1,529.2 km²) Flood date: 2026-08-26 Generated: 2026-10-10 03:43 UTC

Flood / debris impact detected

Educational prototype generated automatically from satellite data. Not an official emergency map.

1.09 km²	5.49 km²	474	44.7 km	40	28
Flood water	Debris / mud	Buildings likely hit	Roads affected	Bridges hit	Settlements cut off



Settlements that lost or changed road access to a hospital

#	Settlement	Road access now	Buildings	Nearest hospital (before)	Before	Now
1	बेत्रावती	CUT OFF	943	Bhagwati Memorial Hospital	10.6 km, 10 min	no route
2	देवीघाट	CUT OFF	782	Sanjivani Hospital	6.0 km, 7 min	no route
3	गोदाम	CUT OFF	588	Rasuwa District Hospital	30.7 km, 39 min	no route
4	गोठेन	CUT OFF	541	Rasuwa District Hospital	34.7 km, 45 min	no route
5	आमाछोदिङ्गो	CUT OFF	386	Rasuwa District Hospital	27.9 km, 35 min	no route
6	Chyamdole	CUT OFF	263	Rasuwa District Hospital	27.2 km, 34 min	no route

+ 38 more (full list: dashboard / priority_list.csv)

Can we get there? Roads and bridges

Blocked or damaged roads (names from the pre-event map)

- unnamed trunk: 0.30 km affected, 28.283°N 85.375°E
- Pasang Lhamu Highway: 3.45 km affected, 27.954°N 85.165°E
- Pasang Laahamu: 0.57 km affected, 28.253°N 85.366°E
- Devighat Path: 0.44 km affected, 27.864°N 85.115°E
- + 13 more

Bridges likely hit

- Pasang Lhamu Highway, 27.855°N 85.081°E
- devighat-Tadi bridge, 27.859°N 85.109°E
- Falaakhu River Bridge, 27.974°N 85.186°E
- Pasang Lhamu Highway, 27.970°N 85.185°E
- + 35 more

Helicopter access for settlements cut off by road

- बेत्रावती [CUT OFF]: mapped helipad unnamed helipad 1.7 km; flat open ground 0.7 km (27.975°N 85.192°E)
- देवीघाट [CUT OFF]: mapped helipad: none within 5 km; flat open ground 0.6 km (27.862°N 85.115°E)
- गोदाम [CUT OFF]: mapped helipad unnamed helipad 3.4 km; flat open ground 3.9 km (28.184°N 85.302°E)
- गोठेन [CUT OFF]: mapped helipad unnamed helipad 1.5 km; flat open ground 2.6 km (28.139°N 85.242°E)
- + 33 more (full list: dashboard / priority_list.csv)

Flat open ground = slope at most 7°, at least 60 m clear, away from detected flood or debris and mapped buildings or power lines. Not checked: trees, unmapped wires or buildings, soft ground, debris the map missed. Confirm from the air. Distances are straight-line.

Data used

- Sentinel-1 radar: before 2026-08-16, after 2026-08-28 (track asc-085, 12 days apart)
- Sentinel-1 radar: before 2026-08-24, after 2026-09-05 (track des-019, 12 days apart)
- Sentinel-2 optical: second sensor (40% of area cloud-free); confirms radar and adds what only it sees (low confidence)
- OpenStreetMap as of 2026-07-27 (before the event)
- AI segmentation model: used, combined with rule-based detection
- Debris class only in mountain terrain (UNEP-WCMC definition); 100% of this area is mountain

Confidence and limits

- 1.93 km² of the flood/debris area is medium or high confidence.
- Sentinel satellites revisit an area only every few days: this system maps damage after the fact and cannot warn of a sudden glacier or lake outburst. Areas marked grey were hidden from the radar and are unknown, not safe. Road access uses mapped roads only. 'Likely cut off' rests on low-confidence detections (debris counts as confident only when a second radar pass or Sentinel-2 confirms it); 'Unknown' means the last route crosses roads the radar could not see. Travel times use nominal speeds per road class. Rows are ranked by priority: certainty, settlement size (mapped buildings), extra time.

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Model trained on Kuro Siwo: Bountos et al., 2024 (NeurIPS Datasets & Benchmarks). Run trishuli_shub.