



TOOLING – BY CUSTOMER


ROTOR ASSEMBLY REMOVAL PLATE




DISASSEMBLY ROD



SPRING COMPRESSOR




SPRING RETAINING PIN




DISASSEMBLY


1. REMOVE HOUSING SNAP RING AND BEARING RETAINING PLATE




- ## 2. CAP HOUSING AND REMOVE ROTOR ASSEMBLY



3. REMOVE FLOATING SEAL, WAVE SPRING, O-RING, SEAL GUIDE, COIL SPRING, AND PIPE CAP.



4. CHECK SLEEVE I.D. FOR PITS. IF BADLY PITTED, PART WILL HAVE TO BE REPLACED.



A	WAS O-RING 755-604		04/02	R
LET.	REVISION	ECO	DATE	SIG

EQUIPMENT REF:

	ASSY/TEST FIXTURES REQUIRED:
--	---------------------------------

SCALE	FULL	
DRN	LG	09/18/97
ENGR		
APPD		

UNLESS OTHERWISE
SPECIFIED
TOLERANCES ± 0.10 .
DIMENSIONS IN ()
ARE IN MILLIMETERS.



DEUBLIN COMPANY
WAUKEGAN, ILLINOIS, U.S.A.

TITLE: 755 SERIES REPAIR INSTRUCTIONS

NO. DA-43 (SHT 1 OF 2) C.A.D. DRAWING

						EQUIPMENT REF:		<table><tr><td>SCALE</td><td colspan="2">FULL</td></tr><tr><td>DIN</td><td>LG</td><td>09/18/97</td></tr><tr><td>ENGR</td><td colspan="2"></td></tr><tr><td>APPRO</td><td colspan="2"></td></tr></table>		SCALE	FULL		DIN	LG	09/18/97	ENGR			APPRO			 DEUBLIN COMPANY WAUKEGAN, ILLINOIS, U.S.A.	
SCALE	FULL																						
DIN	LG	09/18/97																					
ENGR																							
APPRO																							
						ASSY/TEST FIXTURES REQUIRED:		UNLESS OTHERWISE SPECIFIED TOLERANCES ±.010. DIMENSIONS IN () ARE IN MILLIMETERS.		TITLE: 755 SERIES REPAIR INSTRUCTIONS													
A	O-RING WAS 755-604, ADDED SEAL AND O-RING TO ROTOR ASSEMBLY ADDED SEAL PLATE TO REPAIR KIT			04/02	RM					NO. DA-43 (SHT 2 OF 2) C.A.D. DRAWING													
LET.		REVISION		ECO	DATE	SIGN																	