

INDEPENDENT • EVIDENCE-LED • ACTIONABLE

# nextro.hu

## Full website audit

SEO · Web design · UX/UI · Accessibility  
Performance · Content · Conversion

Prepared for the website owner,  
development and marketing teams

Inspection date: 22 September 2026  
Public website · Desktop and mobile review

The core business story is credible and clearly structured.  
The immediate opportunity is to finish the commercial journey,  
repair readability and turn expertise into verifiable proof.

# Contents

|                                               |    |
|-----------------------------------------------|----|
| 1. Executive summary                          | 3  |
| Scope, methods and limitations                | 5  |
| 2. Technical SEO                              | 6  |
| 3. Performance audit                          | 8  |
| 4. On-page SEO                                | 10 |
| 5. Information architecture                   | 12 |
| 6. UX audit: first-time visitor journeys      | 13 |
| 7. UI audit                                   | 15 |
| 8. Professional web design evaluation         | 16 |
| 9. Accessibility audit                        | 17 |
| 10. Mobile audit                              | 19 |
| 11. Content quality audit                     | 21 |
| 12. Conversion effectiveness                  | 22 |
| 13. Page-by-page findings                     | 23 |
| 14. Screenshots and evidence                  | 30 |
| 15. Prioritized implementation roadmap        | 32 |
| 16. Final recommendations                     | 42 |
| Appendix A · Technical inventory              | 43 |
| Appendix B · Evidence and validation register | 45 |

## How to use this report

Read the executive summary and final priorities first. Use the finding IDs (F01-F24) to connect observations to the implementation roadmap. Screenshots are dated inspection evidence, not proposed designs. All website quotations are retained in Hungarian; analysis is in English.

Priority is a business/implementation judgment. CRITICAL denotes a launch/readiness blocker; HIGH denotes a substantial access, trust or conversion obstacle; MEDIUM denotes meaningful improvement; LOW denotes polish. Effort is relative scope, not a time or cost quotation.

## BUSINESS VIEW

# 1. Executive summary

NEXTRO presents a capable HVAC business with a coherent navy/green identity, a broad service offer, a nationwide operating message and prominently published contact details. The service and industry overviews contain useful technical explanations and FAQs. Basic crawlability, canonical URLs, HTTPS normalization and a real 404 response are in place.

**Overall condition: a sound brochure foundation, an unfinished commercial journey**

The site should not be treated as fully ready for conversion-focused promotion until its policy placeholders, product purchase/quotation states and obvious reading barriers are resolved. No traffic, ranking or conversion-rate data was available; this judgment is based on observed content and behavior.

## Strongest aspects

- Clear service breadth: installation, controls, commissioning, maintenance, renovation and in-house filter manufacture are explained rather than merely named.
- Trust foundations: company registration/tax details, distinct headquarters and warehouse addresses, working phone/email links, documented-work claims and a visible enquiry route.
- Technically accessible content: the main offer is present in raw HTML; all 29 content pages crawled returned 200, with titles and canonical tags. Sampled navigation did not lead to an HTTP error.

## Most important weaknesses

- The privacy, terms and shipping pages are placeholders, while forms ask visitors to accept them. Product shipping tabs expose an internal “[HIÁNYZIK: ...]” note (F01).
- The shop offers nine EV-charger variants, but only one has a visible price/add-to-cart action; seven advertised HVAC categories are empty (F02–F03).
- Dark text on dark hero panels, ambiguous homepage links and a 2.62 MB restaurant image create avoidable access, navigation and loading costs (F04–F06).
- Reference pages describe anonymous project types, not documented case studies. Commercial service detail pages are not yet developed (F07–F08).

## Biggest opportunity and expected impact

Make NEXTRO’s specialist delivery capability easier to verify and easier to buy or enquire about. Fixing the unfinished steps should reduce uncertainty; readable interfaces and contextual quote paths should improve access; deeper service pages should improve relevance to qualified searches. These are expected directional benefits—not forecasts of ranking, revenue or percentage uplift.

## THE TEN MOST IMPORTANT ACTIONS

# Executive priorities: act in this order

| Order / priority | Action                                                                                                 | Expected business effect                                                    |
|------------------|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|
| 1 · CRITICAL     | Replace privacy, terms and shipping placeholders; remove internal product-tab notes. F01               | Restore informed decision-making and reduce immediate trust/readiness risk. |
| 2 · HIGH         | Approve purchase vs quotation mode, price and availability for every product. F02                      | Remove ambiguity at the buying decision.                                    |
| 3 · HIGH         | Fix text contrast and unnamed/color-only links in shared templates. F04, F23                           | Make proof points, navigation and contact usable by more visitors.          |
| 4 · HIGH         | Repair homepage self-links, pseudo-links and context-losing cards. F05                                 | Help visitors reach the information the interface promises.                 |
| 5 · HIGH         | Replace empty shop routes with useful quote-led category pages or unpublish unfinished navigation. F03 | Avoid commercial dead ends.                                                 |
| 6 · HIGH         | Optimize restaurant/hero images and below-fold loading. F06                                            | Reduce transferred data and slower-network exposure.                        |
| 7 · HIGH         | Verify consent states, form delivery and transaction flows in an approved test environment. F15, F24   | Prove that enquiries, permissions and orders are handled reliably.          |
| 8 · HIGH         | Publish evidence-backed case studies and validate company claims. F08                                  | Support procurement confidence.                                             |
| 9 · HIGH         | Create substantive priority service detail pages and cross-links. F07                                  | Improve search-intent fit and contextual enquiries.                         |
| 10 · MEDIUM      | Finish snippets, category headings and sitemap hygiene; simplify the mobile enquiry. F09-F12, F14      | Polish discoverability and reduce effort.                                   |

Impact is qualitative. No analytics, Search Console, advertising, CRM, payment configuration, server logs or verified keyword-volume data was supplied. Establish a baseline before assigning financial targets.

## READ BEFORE INTERPRETING THE NUMBERS

# Scope, methods and limitations

| Workstream                  | What was actually inspected                                                                                                                                                                                                                        |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HTTP and SEO                | 29 public content pages: homepage, six primary navigation destinations, five policy/company-information pages, eight categories and nine products. Raw HTML, metadata, headings, images, links and JSON-LD were saved.                             |
| Discovery and routes        | robots.txt; sitemap.xml redirect; sitemap index and three child sitemaps; host/protocol variants; one slash variant; UTM and shop-sort parameters; a deliberately nonexistent URL. Cart/account and empty-session checkout were probed separately. |
| Browser / visual            | Desktop at 1280 × 720; mobile at 390 × 844; narrow reflow spot checks at 320 px. Homepage, service/sector/reference/about/contact/shop, category and product templates, policies, cart and 404 were inspected.                                     |
| Interaction / accessibility | Menu open/close, cookie rejection, product shipping tab, industry-card Enter/click behavior, skip-link activation, carousel focus and form labels/validity metadata. axe-core 4.10.3 on home, services, contact and the priced product.            |
| Performance                 | Browser Navigation/Resource Timing and buffered LCP/layout-shift entries; raw response headers and selected assets. One desktop sample is reported in detail, not a benchmark distribution.                                                        |
| PDF evidence                | Saved page extracts, screenshots, HTTP bodies, machine-readable crawl and accessibility output. Original screenshots are retained alongside the annotated copies used here.                                                                        |

## What was deliberately not done

No enquiry, newsletter subscription, login, account creation, payment or order was submitted. No production content or settings were changed. End-to-end mail delivery, checkout payment, CRM handoff and server-side validation remain unverified. Native form validity was inspected without a live submission. No penetration test, exhaustive external-link test or formal WCAG conformance certification was performed.

## Evidence labels and cautions

**Verified** means observed in saved HTTP/DOM/browser evidence. **Assessment** is an expert interpretation of that evidence. **Unverified** is a named test or fact still requiring access. The initial third-party text extractor returned an old maintenance page; subsequent live browser and five HTTP user-agent variants returned the live site. That discrepancy is not evidence of cloaking or a current maintenance outage.

The raw crawl's combined sitemap-location field contains page and image locations. This report uses the corrected XML count: **25 unique page URLs** (26 entries) and 26 unique image URLs. It does not misreport image locations as pages.

## CRAWLING, INDEXING AND URL BEHAVIOR

## 2. Technical SEO

| Check             | Verified result                                                                                                                 | Interpretation / next step                                                                                                 |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|
| Content responses | 29/29 crawled content pages returned 200; 29 unique ordinary internal navigation targets checked, none with HTTP errors.        | Healthy sample. This is not an exhaustive guarantee covering external links, query actions, assets and every possible URL. |
| robots.txt        | Accessible; disallows admin/log/upload utility paths and add-to-cart queries; permits admin-ajax. Advertises sitemap_index.xml. | No sitewide crawl block observed. Repeated User-agent groups are not by themselves an error.                               |
| Sitemaps          | Index plus page/product/product-category maps fetched. sitemap.xml → 301 → sitemap_index.xml. 25 unique page URLs.              | F12: cart/account noindex routes and empty-session redirecting checkout are included. Shop is duplicated across two maps.  |
| Indexability      | All 29 content pages show index/follow; cart/account separately show noindex/follow.                                            | Indexable placeholders and thin categories are not useful search destinations. Actual Google inclusion is unverified.      |
| Canonical URLs    | All 29 content pages have canonical tags. Tested UTM and shop-orderby pages canonicalize to the clean base URL.                 | Good duplicate-control foundation. Canonical is a hint, not a promise that engines accept it.                              |
| HTTPS / host      | HTTP non-www and HTTPS www each 301 to HTTPS non-www. HTTP www takes two 301 hops.                                              | Preferred host is consistent. Combine the two-hop route as a low-priority improvement (F21).                               |
| Trailing slash    | /szolgaltatasok → 301 → /szolgaltatasok/. Internal sampled URLs use trailing slashes.                                           | Consistent in the tested case; not an exhaustive route normalization test.                                                 |
| 404 handling      | The deliberately nonexistent path returns 404 and noindex/follow, with home/contact recovery links.                             | Correct status and useful recovery, not a soft 404.                                                                        |
| Utility routes    | Empty cart is a clear empty state. /penztar/ redirects 302 to /kosar/ without a cart.                                           | Expected empty-session behavior; a completed purchase was not tested.                                                      |

404 test URL: <https://nextro.hu/technical-audit-not-found-20260922-7e21/>

## WHAT THE HTML CONFIRMS

# Technical SEO: metadata and semantics

| Area                      | Finding                                                                                                                                      | Recommended treatment                                                                                                                                          |
|---------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Titles and descriptions   | No missing or exact-duplicate titles in the 29-page sample. Seventeen missing meta descriptions: all nine products and all eight categories. | Keep good main-page metadata. Finish commercial snippets and remove “Archives” (F10).                                                                          |
| Heading structure         | 23 pages have one H1; six empty categories have none. Homepage/contact skip H2 in places; sector peers use mixed H2/H3.                      | Repair semantic templates and peer levels (F11). Multiple levels are not an automatic ranking penalty.                                                         |
| Internal linking          | Navigation reaches the major hubs in one click. Four homepage learn-more links return home; apparent industry links are spans.               | F05: repair destinations and introduce contextual links to matching service/sector sections.                                                                   |
| Orphans / reachability    | No ordinary commercial orphan identified within the union of this crawl and the sitemap. Utility routes appear in the map.                   | A public crawl cannot prove absence of unlinked pages. Reconcile CMS export, logs and Search Console later.                                                    |
| Structured data           | Parseable JSON-LD present: WebPage/WebSite/Organization/breadcrumbs, with Product/Offer on only the priced product.                          | Enrich verified entity data; quote-only products must not receive invented offers (F16). Rich-result eligibility not tested.                                   |
| Image alternatives        | 288 img elements across the crawl; zero missing alt attributes; 11 empty alt values.                                                         | Do not treat intentional decorative/pixel empty alt as a defect. Review informative imagery and generic repeated reference-image descriptions contextually.    |
| Language / social / icons | HTML language is hu. OG and Twitter-card metadata are present; shop/contact/categories have no og:image. Favicon/apple icon links exist.     | Translate residual UI and complete purposeful previews (F20, F22). File names alone do not prove icon dimension errors.                                        |
| JavaScript SEO            | Core offer, links, FAQs and product text are in raw HTML, not only in a rendered app.                                                        | Keep meaningful links as anchors. Counters start at zero in source but reached 21/18/500+ after viewport-triggered animation; they are not reported as broken. |

## Duplication and parameter risk

The nine EV-charger pages legitimately differ by power and cable configuration but share substantial descriptive copy. Add meaningful selection guidance and specifications; consider variants only after search-demand and migration analysis. Do not blindly canonicalize real distinct products to the shop. The clean canonical on orderby=price and a UTM request is positive; broader filters/search/pagination were not exhaustively tested.

MEASUREMENTS, NOT ESTIMATED SCORES

### 3. Performance audit

**A fast-looking lab sample is not a Core Web Vitals pass**

The PageSpeed Insights API attempt returned HTTP 429 (quota exceeded). No Lighthouse score, CrUX field distribution or Search Console Core Web Vitals report was obtained. INP was not measured. The figures below are one unthrottled desktop browser observation, not real-user percentiles.

| Metric / observation       | Recorded value                                           | Meaning / limitation                                                                                                   |
|----------------------------|----------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|
| Desktop viewport           | 1280 × 720 CSS px                                        | No network/CPU throttling applied; not a controlled cold-cache multi-run benchmark.                                    |
| Navigation TTFB            | 315.5 ms from navigation start                           | Browser responseStart. Includes navigation setup; not a pure server-processing measurement.                            |
| LCP candidate              | 1,084 ms                                                 | Last buffered entry at collection, associated with background-pattern-2.svg. Later changes or field visits may differ. |
| Observed layout shifts     | 0.002466 sum excluding recent-input entries              | Short observation; not a lifetime/session-window CLS audit or a field CLS value.                                       |
| Load event end             | 2,779.7 ms from navigation start                         | Load event is not “fully interactive” or a complete performance verdict.                                               |
| Document size              | 286,100 decoded bytes; 52,597 compressed body bytes      | Navigation entry records gzip. HTML transfer including browser-reported overhead: 52,897 bytes.                        |
| Known resource transfer    | 5,559,340 bytes across 65 recorded resource entries      | Excludes injected axe and includes only observable transfer sizes. Cross-origin zeros may hide additional bytes.       |
| Known document + resources | 5,612,237 bytes (~5.61 MB, decimal)                      | A partial page-load payload at collection, before full-page scrolling, not an exhaustive fully scrolled page weight.   |
| Blocking / scripts         | 21 render-blocking entries; 20 script-initiated requests | About 330 kB decoded visible-size script bodies. Counts do not establish unused code or main-thread cost.              |

A later 390 px mobile sample was warm/reused-browser and therefore is not used as a comparable speed benchmark. No observed runtime exceptions were recorded by the injected error listener on the sampled later navigations; console messages, cross-origin errors and all interaction failures were not exhaustively captured.

## F06 · F19

# Performance: fix bytes before chasing scores

| Observed resource               | Encoded body bytes             | Why it deserves attention                                                                                       |
|---------------------------------|--------------------------------|-----------------------------------------------------------------------------------------------------------------|
| megoldas-etterem.png            | 2,624,647                      | Largest recorded homepage resource. A photographic restaurant image in PNG is a strong format/resize candidate. |
| hero-legkezekelo-gepterem.jpg   | 645,151                        | Large initial visual asset; optimize without lazy-loading the real hero.                                        |
| megoldas-ipar-2.jpg             | 545,178                        | Below-fold industry imagery is requested early as CSS background content.                                       |
| megoldas-nagykonyha-2.jpg       | 336,917                        | Use viewport-appropriate dimensions and defer until needed.                                                     |
| legtechnika-szellozo-kozeli.jpg | 306,614                        | Shared illustration/image can be served more economically.                                                      |
| Local font files                | 20,468 + 12,764 transfer bytes | Two WOFF2 Latin/Latin-ext requests observed; local delivery is a positive. Font-display was not validated.      |

## What is already working

Sampled CSS/JS responses are gzipped and have Cache-Control max-age=10368000. The browser uses HTTP/2. Minified stylesheet bundles are present. Product images generally carry intrinsic dimensions and several have srcset; homepage reference/product img elements use loading=lazy. These are meaningful foundations, so a “no compression/no caching/no lazy loading” diagnosis would be incorrect.

## What should change

- Convert and resize the large restaurant image first. Replace meaningful CSS backgrounds with responsive images where practical, and gate offscreen industry/background loading. Measure actual saved bytes; no savings percentage is assumed.
- Profile per-template CSS/JS coverage before removing assets. Homepage shop widgets, forms, consent and third-party integrations justify some code, but not necessarily every shared asset. Unused CSS, long tasks and total blocking time were not measured.
- Assess anonymous HTML caching carefully: the homepage returns no-cache/no-store while sampled static assets have long lifetimes; a conditional HTML request still returned 304. This does not reveal the entire origin/plugin cache architecture. Do not cache carts, accounts, checkout or personalized pages publicly.
- After changes run repeated cold mobile/desktop lab tests and collect real-user LCP/CLS/INP over time. Separate consent states and service/product templates so a homepage improvement does not conceal a checkout regression.

Complete resource URLs and headers are retained in evidence/performance-desktop.json and technical.json. Third-party MailerLite/Barion resource timing sizes were zero/opaque; those entries are not counted as genuinely zero-cost transfers.

## SEARCH INTENT AND PAGE-LEVEL CLARITY

## 4. On-page SEO

The core pages are written in Hungarian and have a clear HVAC theme. The largest SEO opportunity is not inserting more repeated keywords; it is matching a specific need to a substantive destination, then connecting that destination to credible evidence and a useful next step. No search volumes, rankings or competitor positions were measured.

| Page / likely intent           | Observed strength                                                                                    | Gap and recommended direction                                                                                                                |
|--------------------------------|------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Home / contractor discovery    | Title explicitly says Légtechnika egy kézből; introduction describes industrial/commercial services. | The H1 is the slogan FRISS LEVEGŐ. TISZTA MEGOLDÁS. Retain it as a brand line but give the main heading explicit service meaning (F17).      |
| Services / evaluate provider   | Ten service sections, a concrete maintenance FAQ and descriptions of commissioning/renovation.       | Short summaries do not fully satisfy individual high-intent queries. Build priority detail pages and link specific cards/FAQs to them (F07). |
| Solutions / sector fit         | Hotel, restaurant, kitchen, wellness, industry and residential needs are differentiated.             | The process comes before sector answers and section levels differ. Add a sector index, aligned H2s and relevant project proof.               |
| References / reduce risk       | Work types and delivery scope are explained, with experience/team/filter-production claims.          | No identifiable case evidence or quantified documented outcomes. Convert examples into substantiated case studies (F08).                     |
| About / company validation     | Foundation year, specialist team and named rating provider are stated.                               | Inconsistent tenure language and no verification link in main content. Add people, evidence and precise dates (F08, F20).                    |
| EV category / choose charger   | Power, phases, cable lengths, IP56, warranty and VAT/installation exclusions are mentioned.          | No meta description; title ends Archives; products are difficult to compare and mostly unpriced (F02, F10, F13).                             |
| Product / buy or request quote | Model/variant names and useful technical features are explicit.                                      | Dense shared copy, missing snippet descriptions and inconsistent commercial states reduce decision clarity.                                  |
| Contact / act now              | Phone, email, addresses and enquiry types are present.                                               | Use a specific next-step explanation and contextual form defaults rather than promising an unverified response time (F09).                   |

### Keyword use, depth and E-E-A-T

Technical language such as EC-motor, forgódob-csere and szűrő nyomásesése supports topic relevance. Add plain-language explanations, maintenance deliverables, downtime planning and suitability questions rather than repetitive keyword strings. Named responsible experts, original project media, documented claims and complete policies would provide stronger experience/trust signals than additional generic assurances.

## DRAFTS TO VALIDATE WITH THE BUSINESS

# On-page SEO: proposed Hungarian copy

These are editorial proposals, not measured keyword opportunities or guaranteed search snippets. Google may rewrite snippets. Use approved service and availability claims; do not promise price, stock or turnaround until confirmed.

| URL / field                               | Suggested replacement                                                                                                                                   |
|-------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| / · title                                 | Légtechnika: telepítés, felújítás, karbantartás   NEXTRO                                                                                                |
| / · H1                                    | Légtechnikai rendszerek telepítése és karbantartása egy kézből                                                                                          |
| / · description                           | Légkezelők telepítése, automatika, felújítás és karbantartás saját szakembergárdával. NEXTRO: 2005 óta, Budapesten és országosan. Kérjen ajánlatot.     |
| /szolgáltatások/ · H1                     | Légtechnikai szolgáltatások a tervezéstől a karbantartásig                                                                                              |
| /szolgáltatások/ · description            | Légkezelő telepítés, beüzemelés, karbantartás, forgódob-csere és egyedi szűrőgyártás. Ismerje meg a NEXTRO szolgáltatásait, és kérjen ajánlatot.        |
| /megoldások/ · title                      | Légtechnika hoteleknek, iparnak és otthonoknak   NEXTRO                                                                                                 |
| /bolt/ · title                            | Teltonika autótöltők és légtechnikai ajánlatkérés   NEXTRO                                                                                              |
| /termekategoria/autotoltok/ · title       | Teltonika EVC2 autótöltők: 7,4–22 kW   NEXTRO                                                                                                           |
| /termekategoria/autotoltok/ · description | Hasonlítsa össze a Teltonika EVC2 autótöltők teljesítményét és kábelváltozatait. 7,4, 11 és 22 kW, 36 hónap garancia. Kérjen segítséget a választáshoz. |
| 11 kW / 5 m product · title               | Teltonika EVC2 11 kW autótöltő, 5 m kábel   NEXTRO                                                                                                      |
| 11 kW / 5 m product · description         | Háromfázisú Teltonika EVC2 11 kW autótöltő 5 m beépített kábellel, app- és NFC-vezérléssel. Kérjen ajánlatot a készülékre és a telepítésre.             |
| /rolunk/ · H1                             | NEXTRO Kft. – légtechnika saját szakembergárdával, 2005 óta                                                                                             |

## A useful service-page outline

**H1:** Légkezelő karbantartás • **H2:** Mikor és kinek ajánlott? • **H2:** Mit tartalmaz a karbantartás? • **H2:** Felmérés, ütemezés és dokumentáció • **H2:** Kapcsolódó referenciák • **H2:** Gyakori kérdések • **H2:** Karbantartási ajánlat kérése. Link back to the hub, relevant filter supply and an actual reference. Do not create thin pages for every synonym.

Product example URL: <https://nextro.hu/termek/teltonika-evc2-okos-ac-autotolto-11-kw-5-m-beepitett-toltokabel/>

## MAKE THE NEXT CLICK SPECIFIC

## 5. Information architecture

### Current structure and reachability

The top-level menu is understandable: Szolgáltatások, Megoldások, Referenciák, Rólunk, Webshop, Kapcsolat. Each hub is one navigation click away from the homepage. Shop categories are exposed from navigation and the shop; a product can be reached directly from the homepage carousel/grid or via shop → product. Contact is consistently available. These are good foundations, not a case for a completely new navigation system.

The weakness is depth: ten service cards all lead to the same overview, while six industry cards expose non-link “Megoldások →” text. Four benefit CTAs return to the current homepage. Important commercial information can be close in clicks but still difficult to reach semantically because the destination does not preserve the visitor’s choice (F05, F07).

| Proposed grouping      | Contents / behavior                                                                                                                                                                               |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Services hub           | Installation; automation; commissioning; maintenance; renovation/rotor replacement; removal/replacement; filter manufacture. Start with detailed pages for the strongest, evidence-backed offers. |
| Sector solutions       | Hotels, hospitality/kitchens, wellness, industrial and residential. Add a sector index immediately; use anchors until each sector can justify a substantive page.                                 |
| References             | A filterable or clearly grouped case-study list linked to the relevant service and sector, with real project evidence.                                                                            |
| Products and enquiries | Clearly separate buy-online EV chargers from quote-led HVAC/filter ranges. A quotation range should collect specifications, not show a zero-product store state.                                  |
| About and contact      | Company/team/qualifications and verification links; a direct quote path, phone and address-role information. Keep policies consistently in the footer.                                            |

### Concrete linking changes

- Homepage “KARBANTARTÁS” → services maintenance anchor now; a dedicated maintenance page later. Carry that service selection into the contact form.
- Homepage Hotel card → /megoldasok/#hotel or a substantive hotel detail page. Use an actual anchor with “Szállodai légtechnikai megoldások” as the accessible purpose.
- Filter manufacture section → useful /termekategoria/szurok/ quote-led page with dimensions/type/quantity guidance, not an empty product list.
- Each approved case study → the service used and a “Hasonló feladatra kérek ajánlatot” enquiry carrying case context.

Do not change established URLs merely to improve their appearance. Existing Hungarian slugs are readable. If consolidating product variants or introducing new routes, keep a mapping and deliberate redirects/canonicals. Public discovery cannot exclude unknown orphan pages outside the sampled link/sitemap graph.

## WHERE PEOPLE MAY HESITATE

## 6. UX audit: first-time visitor journeys

| Journey step                  | What happens on Nextro                                                                                                                      | Likely hesitation / improvement                                                                                                             |
|-------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| 1 · Arrive from search        | The page is a real Hungarian HVAC business, with logo, core navigation and a quote CTA. Cookie controls may cover substantial mobile space. | A slogan alone is less explicit than a service promise. Explain offer/audience above the fold and keep consent concise and accessible.      |
| 2 · Choose a relevant service | Services hub has ten useful summaries; homepage cards all use the same destination.                                                         | The user must search again after clicking. Land at the matching section and develop true detail pages.                                      |
| 3 · Assess fit and trust      | Services/solutions FAQs explain work; references describe generic industrial/hotel/kitchen jobs.                                            | Procurement users cannot verify a comparable completed project. Add approved cases, dates, scope and evidence.                              |
| 4 · Contact the company       | Quote CTA reaches /kapcsolat/; phone/email and a labelled form are available.                                                               | Form burden and incomplete policies interrupt the last step. Simplify required fields and complete disclosures before promoting the funnel. |
| 5 · Buy a charger             | Shop lists nine variants; one has a price/add-to-cart control; eight show read-more.                                                        | Unclear stock/quote mode, uncertain delivery cost and internal shipping notes weaken purchase confidence. Fix readiness before advertising. |
| 6 · Urgent mobile repair      | Mobile navigation works, but the desktop phone strip disappears.                                                                            | A call-oriented visitor needs immediate contact, not a long scroll or an exploratory shop journey. Add a comfortable call action.           |

### Interaction patterns: positives and friction

Working skip navigation, labelled forms, large primary hero buttons and recognizable top-level naming support usability. Industry cards do respond to Enter by flipping, so they are not keyboard-inert; the problem is the link-like “Megoldások →” text that does not navigate. Carousel controls show visible focus. No universal “keyboard navigation is broken” claim is justified.


Hover/reveal cards, an animated service ticker, a reference carousel and shop hover controls add interaction variety. Reduce hidden information and motion where it does not support a task. Ensure touch users can see the same information, and verify reduced-motion behavior in a separate test; it was not formally measured here.

### Recommended journey test after fixes

Ask unfamiliar users to find maintenance scope, verify a relevant project, request a filter quotation and compare 11 kW versus 22 kW chargers. Observe wrong turns and unclear language before running an A/B test. No user-testing sessions or task-completion rates were collected in this audit.

F01 · F09 · F24

# UX: enquiry form and feedback




Contact form at 390 px. Labels are visible and associated; several required fields and a long message/terms sequence increase the effort before sending. Screenshot records the inspected layout, not a form submission.

| Observed detail                             | Meaning and concrete change                                                                                                                                                                          |
|---------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Correctly associated labels                 | Keep them. Do not replace them with placeholder-only inputs. First/last name, email, phone, company, subject, type and message are individually identified.                                          |
| Both email and phone marked required        | The plugin exposes aria-required=true; HTML native required is not used for most fields. This is not proof that server/plugin validation is absent. Make phone optional unless callback is selected. |
| Phone input is type=text                    | No inputmode/autocomplete was present. Use type=tel and autocomplete=tel; add name/email/organization autocomplete tokens for faster completion.                                                     |
| Blank native validity check                 | The unchecked policy checkbox made native checkValidity() false. Plugin error presentation and backend validation were not tested with a live submission.                                            |
| Policy acceptance and vague response timing | Visitors are asked to accept unfinished documents. Complete F01 first. Explain next steps and publish only a response expectation the team can meet.                                                 |
| Technical message prompt                    | Offer examples: town/site, service needed, equipment/model, urgency and preferred contact. Add optional attachments only if handling, storage and privacy are ready.                                 |

A safe authorized QA plan should cover empty/invalid values, focus moving to errors, aria-describedby/announcements, network failures, duplicate-send prevention, success confirmation and actual lead delivery. No customer request or test message was sent from the public site.

## READABILITY AND CONSISTENCY BEFORE COSMETIC REDESIGN

## 7. UI audit



E1 · <https://nextro.hu/szolgalatasok/> · Desktop 1280 × 720. The checklist inherits dark body text on a navy panel. Automated contrast measurement for these lines is 1.82:1. The outlined area identifies the affected component.

## Visual hierarchy and typography

The modern sans-serif family (Wix Madefor Display), generous whitespace, aligned card layouts and consistent navy/green identity generally support a professional impression. Main headings have strong scale. The service hero's most important proof points, however, are visually suppressed by contrast—not by a lack of content. Fixing semantic text colors will have more immediate value than replacing the typeface (F04).

Service-card paragraphs measured 14 px on the 390 px viewport while general text/form inputs were 16 px. Fourteen pixels is not automatically a WCAG failure, but dense technical copy is harder to scan at that size. Prefer a comfortable body scale, use short paragraphs/bullets and restrict long desktop text blocks to a readable measure.

## Components and spacing

- Buttons: preserve one clear quote/purchase primary action; distinguish secondary navigation. Some green/navy button text measured just below 4.5:1. Apply consistent tokens to all states, not isolated overrides.
- Cards and images: standardize product media frames and baseline alignment. Varied lifestyle crops can make nominally similar products feel inconsistent and hide variant differences (F13).
- Icons and links: decorative icons can remain decorative, but clickable containers must have names. Inline links need persistent non-color identification; repair the service overlay anchor (F23).
- Visual rhythm: reduce repetitive benefits and oversized repeated intro sections before changing the entire grid. The existing brand palette and layout system are worth retaining.

FROM TEMPLATE POLISH TO DEMONSTRABLE EXPERTISE

## 8. Professional web design evaluation



E2 · <https://nextro.hu/referenciak/> · Product filter imagery leads into generic project descriptions. The issue is relevance and proof, not image ownership: this audit does not establish whether any imagery is stock, commissioned or AI-generated.

### Brand coherence and perceived quality

The navy panels, green accents, line illustrations and generous spacing create a recognizably technical and current visual language. NEXTRO does not need a redesign solely to “look modern.” The perceived-quality gap comes from unfinished policy content, low-contrast proof text, generic project evidence and mixed-language ecommerce components. These are consistency and credibility problems, not a subjective need for a new style.

### A concrete homepage redesign direction

| Sequence                 | Design decision                                                                                                                                        |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1 · Explicit promise     | A descriptive HVAC H1, short audience/service statement, one quote CTA and a secondary phone/service link. Retain the slogan as supporting brand copy. |
| 2 · Choose a path        | Group service entry points by installation, maintenance/renovation and filters; preserve access to the complete offer.                                 |
| 3 · Proof                | Show three real projects with sector, scope and one documented result. Replace anonymous claims with permission-cleared evidence.                      |
| 4 · Fit and process      | A compact sector selection, four clear work stages and concise team/quality assurance. Avoid repeating the same benefit three times.                   |
| 5 · Commercial next step | Contextual enquiry or product selection; a short contact section with completed policy links. Keep the shop as a separate, coherent subjourney.        |

Treat decorative overlays/tickers as optional. They should not reduce contrast, inflate image cost or make the site’s actual offer harder to read. Establish a small component specification for buttons, cards, media crops, headings, form states and light/dark surfaces; verify it on one service and one product template before wider rollout.

## WCAG-RELATED FINDINGS; NOT A CONFORMANCE CERTIFICATION

## 9. Accessibility audit

Automated scans used axe-core 4.10.3 against WCAG 2 A/AA, 2.1 AA and 2.2 AA rule tags. Home/services were scanned on desktop; contact/priced product on a mobile viewport. Automated checks detect only part of accessibility. The counts below are node instances in specific snapshots, not a count of unique sitewide defects.

| Snapshot       | Automated violation types / instances                                            |
|----------------|----------------------------------------------------------------------------------|
| Homepage       | Color contrast: 4 nodes.                                                         |
| Services       | Color contrast: 12; inline link distinguished only by color: 1; unnamed link: 1. |
| Contact        | Color contrast: 5; inline link distinguished only by color: 2.                   |
| Priced product | Color contrast: 7. No other violation type returned in this snapshot.            |

| Severity / WCAG relevance                  | Concrete evidence                                                                                    | Fix / verification                                                                                                                                            |
|--------------------------------------------|------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HIGH · 1.4.3 Contrast                      | Service checklist #3a4a57 on #0f1f2f = 1.82:1 at 16 px. Active nav = 2.71:1; contact links = 3.49:1. | F04: correct theme tokens; verify 4.5:1 normal / 3:1 large text in all states.                                                                                |
| HIGH · 2.4.4 Link purpose / 4.1.2 Name     | A focusable .gspb-containerlink on services has no text, aria-label or other accessible name.        | F23: remove redundant overlay or label the real intended action; confirm screen-reader output.                                                                |
| HIGH · 1.4.1 Use of color                  | Service/contact inline links lack underlines and sufficient distinction from surrounding text.       | F23: persistent underline or another non-color cue; do not rely on hover alone.                                                                               |
| MEDIUM · 1.3.1 Relationships               | Missing category H1s, mixed peer sector levels and H1→H3 jumps make the outline inconsistent.        | F11: logical heading hierarchy. Missing H1 alone is not a blanket conformance verdict.                                                                        |
| MEDIUM · input purpose / mobile ergonomics | Phone field uses generic text input; personal-data inputs lack autocomplete. Menu box is 18 × 18 px. | F09/F14: appropriate autocomplete/type and larger target area. Target-spacing exceptions mean the small menu box is not here declared a proven 2.5.8 failure. |

## KEEP WHAT ALREADY WORKS

# Accessibility: strengths and remaining tests

## Verified positives

- The visible-on-focus “Ugrás a tartalomra” skip link received focus, showed a 2 px outline and moved focus to MAIN#main when activated.
- Form controls have associated text labels; newsletter email has an accessible label. Main HTML documents declare Hungarian language.
- All 288 crawled img elements have an alt attribute. Empty values occur on 11 instances and may be appropriate for decoration/tracking; do not replace them with redundant text indiscriminately.
- Carousel previous/next/dot controls have accessible names and visible focus in the tested sequence. Industry cards can be focused and toggled with Enter, although their displayed pseudo-links still need repair.
- Tested major mobile layouts did not show horizontal document overflow at 390 px; homepage and priced product also fit 320 px. The viewport configuration permits zoom rather than explicitly disabling it.

## Manual checks still needed

| Area                | Required follow-up                                                                                                                                                                    |
|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Screen readers      | NVDA/Firefox and VoiceOver/Safari journeys: heading outline, menu state, product tabs, card links, form errors and success announcements. No screen-reader session was conducted.     |
| Keyboard / overlays | Full tab order, focus trap/return, Escape close behavior, dropdown submenus, cookie settings and product gallery. The partial keyboard test does not prove every modal is accessible. |
| Reflow / scaling    | 200% text zoom and 400% browser zoom; landscape and additional phone/tablet widths. The 320 px spot check is not a complete reflow test.                                              |
| Motion              | Reduced-motion preference for counters, ticker, flip cards and carousel; user controls for persistent moving content where required.                                                  |
| Form feedback       | Authorized staging tests for validation association, required instructions, error summaries, aria-live messages and network failure recovery.                                         |
| Images / graphics   | Contextual review of decorative vs informative backgrounds and generic alt text; contrast over images must be checked in all responsive crops, not only by automated rules.           |


Use WCAG 2.2 AA as the implementation target, with human testing after automated fixes. The absence of a rule violation in one snapshot is not proof of compliance. Legal applicability and formal certification are outside this audit.

390 × 844 VIEWPORT; 320 PX SPOT CHECKS

# 10. Mobile audit



E3 · First-visit cookie panel occupies a substantial part of the 390 px viewport. Accept/reject/settings buttons are present and measured 350 × 45 px.



E4 · Opened mobile menu is legible and exposes the six principal destinations. The trigger itself has an 18 × 18 px measured box.

## What works

The menu opened and closed, the major page layouts stacked, form inputs remained readable at 16 px and no horizontal overflow was found on homepage, services, contact, shop and sampled product at 390 px. Homepage and the priced product also fit 320 px. The primary hero CTA is a comfortable size; the shop category list wraps within the viewport.

## Mobile-specific friction

- **Consent:** the long banner delays reading the offer, even though rejecting is available. Shorten the first-layer explanation and move detail into accessible settings/policy content without weakening choice (F15).
- **Urgent contact:** the desktop phone strip is hidden. On the measured mobile homepage, visible phone links appeared far down the document. Add immediate call/quote access rather than assuming desktop contact prominence carries over (F14).
- **Navigation:** enlarge the menu and close hit areas. Add aria-expanded state if the theme does not expose it, and verify state announcement and return focus rather than inferring behavior from appearance.
- **Length and scanning:** the homepage snapshot is 17,155 px tall, services 9,019, contact 5,568 and shop 5,752. These are viewport-specific layout observations, not performance scores. Consolidate repetition and add in-page indexes (F17).

## DESIGN FOR TOUCH, NOT JUST A NARROW COLUMN

# Mobile: detailed recommendations

| Component        | Observed behavior / risk                                                                                                 | Mobile improvement                                                                                                                                  |
|------------------|--------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| Hero             | Brand slogan and CTA fit; subtle preheading/proof text is difficult to see against dark imagery.                         | Use an explicit readable service promise; maintain contrast in the mobile crop. Do not spend the full first screen on decorative spacing.           |
| Industry cards   | Copy says to move the cursor over the card; Enter flips on desktop, but the displayed solution arrow is not a real link. | Use visible summaries or tap-expanding content with explicit state and a separate navigable CTA. Replace cursor-specific instructions.              |
| Services         | Stacked summaries use 14 px paragraph text and many similar blocks.                                                      | Increase comfortable reading scale where possible, add jump navigation and link to detail rather than repeating full summaries.                     |
| Products         | Lifestyle image plus long title pushes buying context down; power/cable differences require reading dense names.         | Show key selection attributes early; place approved price/availability or quote action with the product summary.                                    |
| Forms            | Multiple stacked fields, telephone mandatory via ARIA and generic text keyboard metadata.                                | Use appropriate input types/autofill, fewer necessary fields and contextual defaults. Keep a persistent label and clear error feedback.             |
| Sticky controls  | No useful persistent mobile call action was visible in the sampled homepage view.                                        | If adding a bottom bar, reserve safe-area space and verify it does not cover cookie controls, validation errors, product tabs or the submit button. |
| Cookies / popups | Consent is the main observed overlay; newsletter component exists. A complete popup timing audit was not performed.      | Check clean/returning sessions, settings reopening and any delayed promotions across devices; keep decline and close controls usable.               |

## Release acceptance

At 320, 390 and 430 px, verify a first-time visitor can dismiss or configure consent, open/close navigation, reach a selected service, identify a credible reference and contact the company. Then compare charger variants and reach an honest purchase or quote state. Test with touch and keyboard, in portrait/landscape and with text zoom. Do not substitute a desktop screenshot squeezed to phone width for this journey test.

## MAKE EXPERTISE SPECIFIC, CONSISTENT AND EVIDENCED

# 11. Content quality audit

The better passages are concrete: service FAQs describe filter replacement, heat-exchanger cleaning, controls checks and documentation; sector copy recognizes hospitality disruption and kitchen make-up air. The recurring weakness is unsupported breadth or repeated reassurance rather than poor grammar overall. Editing should preserve engineering specificity while making customer decisions easier.

| Observed example                           | Why it falls short                                                                         | Suggested improvement                                                                                                              |
|--------------------------------------------|--------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|
| "Contact us now"; "Price:"; "Archives"     | Template English appears in Hungarian commercial journeys.                                 | Use "Telepítési ajánlatot kérek", "Ár" and customer-facing category titles. F20.                                                   |
| "Közel 20 év" vs "20 éve" vs "21 év"       | Tenure statements are inconsistent; the About text says foundation was at the end of 2005. | Use stable "2005 óta" unless a precise anniversary claim is intentionally dated.                                                   |
| "Tudjon meg többet" → homepage             | Generic wording is coupled to a non-progressing destination.                               | Use "Légkezelő karbantartás részletei" or "Ismerje meg szakembergárdánkat", with the matching link.                                |
| "vigye a kurzort a kártyára"               | Desktop interaction instructions are not appropriate to a touch-first visitor.             | Prefer visible information and a real "Szállodai megoldások" link; explain tap/expand only if necessary.                           |
| Anonymous Ipari üzem / Szálloda references | Descriptions summarize work types but do not verify experience.                            | Add approved project/date/site context, challenge, delivered scope, photos and measured results only where documented.             |
| "rövid időn belül" / general guarantees    | The prospect cannot infer response timing or warranty conditions.                          | Publish an achievable response window only after internal approval; link to specific warranty/scope conditions.                    |
| Shared dense charger paragraph             | IP ratings, voltages and control functions are hard to compare.                            | Split into "Kinek ajánlott?", power/network/cable table, included items, installation requirements and warranty/shipping sections. |

## Example of more customer-oriented wording

**For maintenance:** "Üzemelő légkezelő karbantartására van szüksége? Felmérjük a rendszer állapotát, egyeztetjük a leállási lehetőségeket, és dokumentált karbantartási tervet készítünk. Írja meg a helyszínt, a berendezés típusát és a tapasztalt hibát." Validate the promised scope with the technical team before publication.

Do not manufacture testimonials, logos, qualifications, warranty terms or efficiency savings to fill the gaps. CompanyWall ranking, partner counts and annual filter-production statements were observed as site claims, not independently verified facts.

## TWO FUNNELS NEED TWO CLEAR PROMISES

# 12. Conversion effectiveness

## Likely primary goals

**Service funnel:** qualified quote requests, urgent service calls and filter enquiries. **Commerce funnel:** direct EV-charger orders where products are configured for purchase, with installation quotations as a related service. Newsletter subscription is secondary. These goals are inferred from the UI; business targets and channel economics were not supplied.

| Conversion lever       | Current observation                                                                                   | Specific recommendation                                                                                                              |
|------------------------|-------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| CTA clarity            | Repeated Ajánlatot kérek works well on service pages; product cards mostly say Tovább olvasom.        | Keep explicit service actions; use purchase or model-specific quote wording consistently (F02).                                      |
| Context preservation   | Service cards funnel to the general hub; the product contact panel leads to the generic contact page. | Prefill or visibly summarize selected service/model in the enquiry. Let the user edit it.                                            |
| Trust at decision time | Claims of team size, experience, guarantees and AA+ rating; few verifiable project specifics.         | Place approved case evidence, warranty scope and accountable company information beside the decision (F08, F18).                     |
| Form effort            | Eight data fields plus policy acceptance, with phone and email both marked required.                  | Offer minimal initial contact and progressive qualification. Complete policies before requiring acceptance (F01, F09).               |
| Purchase certainty     | One listed price; unclear delivery costs/timing and an internal shipping note.                        | Business sign-off of prices, stock/lead times, VAT, installation, shipping, returns and payment rules (F01-F02).                     |
| Competing actions      | Shop controls expose wishlist, comparison and quick view; homepage also promotes newsletter/products. | Keep secondary tools visually secondary. Test whether a simple variant table serves a nine-item range better than multiple overlays. |
| Outcome measurement    | No analytics/CRM/payment access; live submissions intentionally not made.                             | Consent-aware events plus authorized end-to-end QA; judge qualified leads and completed orders, not only button clicks (F24).        |

## What to measure after implementation

Track service/product entry page → quote start → valid successful submission → qualified lead; separate phone/email clicks from confirmed enquiries. For ecommerce track product views, variant choices, add-to-cart, checkout start, payment outcome and fulfilment issues. Review mobile versus desktop and traffic source under approved privacy rules. Establish baseline and sample sufficiency before an experiment; no conversion-rate estimate is justified from this inspection.

## HOME AND CORE SERVICE OFFER

# 13. Page-by-page findings

## Homepage

<https://nextro.hu/>

**Purpose:** Introduce NEXTRO, route service enquiries and expose the shop.

**Strengths:** Broad offer, explicit phone/email on desktop, distinct primary navigation and repeated quote access. Raw HTML and metadata describe HVAC clearly.

**SEO:** Slogan-only H1 is less topical than the title; no distinct destinations from service cards, and four learn-more links return home. Large background images are the main payload issue.

**UX:** Repeated experience/quality/speed sections and flip cards increase scanning effort. The apparent sector links do not navigate.

**UI / design:** Coherent palette and large CTA; some CTA text fails 4.5:1. Mobile consent dominates the first viewport and the phone strip disappears.

**Content:** Useful process explanation, but claims and anonymous project summaries need proof. Counters animate correctly when brought into view; the initial zeros are not a confirmed defect.

**Recommended change:** F04–F08, F14, F17: explicit offer heading, fewer repeated benefits, real context-preserving service/sector links, approved cases and optimized imagery.

## Services

<https://nextro.hu/szolgalatasok/>

**Purpose:** Explain the service portfolio and generate qualified enquiries.

**Strengths:** Ten service areas and useful practical FAQs; title and description are present. One responsible-partner story is easy to understand.

**SEO:** One hub carries many different intents; there are no deep service landing pages in the discovered commercial set. H1 “Szolgáltatásaink” is generic.

**UX:** The overview helps orientation but makes maintenance/filter prospects scan all services. Main links are predominantly generic contact actions.

**UI / design:** Dark hero checklist text measured 1.82:1; an unnamed overlay link is focusable. Mobile card copy is 14 px.

**Content:** Service descriptions are credible summaries, but need deliverables, suitability, scheduling, exclusions and linked case proof on detail pages.

**Recommended change:** F04, F07, F11, F23: fix hero/link semantics; add jump links, expand three priority service intents and attach a contextual enquiry to each.

## FIT AND PROOF

# Page findings: solutions and references

## Industry and residential solutions

<https://nextro.hu/megoldasok/>

**Purpose:** Help visitors identify a solution relevant to their building/sector.

**Strengths:** Differentiates hotel comfort, kitchen extraction, wellness humidity, industrial operations and residential needs. FAQs explain practical constraints.

**SEO:** Hotel/Wellness use H2 while peer sectors use H3; no dedicated sector detail URLs found. Title is descriptive and metadata is present.

**UX:** General four-stage process appears before sector detail; no immediate sector index was observed. Generic links do not preserve industry context.

**UI / design:** Consistent hero styling, but the dark checklist inherits the same visually weak treatment seen on related templates.

**Content:** Sector copy is more customer-oriented than generic slogans, but short summaries do not establish delivery evidence or sector-specific scopes.

**Recommended change:** F04, F07, F11, F17: add a sector jump index, equal H2 levels, service/case links and a “this sector” quote path. Expand separate pages only with substantive content.

## References

<https://nextro.hu/referenciak/>

**Purpose:** Provide evidence that NEXTRO has delivered comparable work.

**Strengths:** Lists industrial, hotel, kitchen and expansion work and explains the technical scope rather than showing logos alone.

**SEO:** Unique title/description; the missing opportunity is substantive project content, not a missing meta tag. No case-study URLs were discovered.

**UX:** A buyer cannot evaluate an identifiable comparable project, date, constraints or documented outcome. The only main CTA is generic contact.

**UI / design:** Filter-product imagery leads the page even though the headline promise is completed project experience. This weakens visual relevance.

**Content:** Anonymous project-type labels and partner/volume claims are not independent evidence. They may be true, but the page does not demonstrate them.

**Recommended change:** F08: create three permission-cleared cases with original project images, date/context/scope and documented results; link each to relevant services. Explicitly label confidential cases.

## CREDIBILITY AND ENQUIRY

# Page findings: about and contact

## About NEXTRO

<https://nextro.hu/rolunk/>

**Purpose:** Establish company expertise, stability and working methods.

**Strengths:** Foundation year, in-house trades, team size, manufacturer role and a named financial-rating provider give a useful company story.

**SEO:** Title and description exist; tenure wording can age badly. Add verified entity/contact details to the shared schema rather than more generic keywords.

**UX:** Claims are repeated more than demonstrated; there is no obvious named expert/team introduction in the inspected main content.

**UI / design:** Current navy/green style, with the related low-contrast checklist. The page would gain credibility from actual team/facility imagery and verified badges.

**Content:** 20 years / nearly 20 / more than 20 is inconsistent with references' 21-year language. AA+ and top 1.1% claims need current evidence and dates.

**Recommended change:** F08, F18, F20: use "2005 óta," show accountable people and qualification evidence, and link current rating verification. Do not infer the rating is false simply because proof is missing.

## Contact

<https://nextro.hu/kapcsolat/>

**Purpose:** Accept quotations, faults, service and filter enquiries.

**Strengths:** Phone/email links work as tel/mailto destinations; registered and warehouse/correspondence addresses are clearly distinguished. Labels and enquiry types are useful.

**SEO:** Title/description are specific; H1→H3 section jump is inconsistent and OG image is absent. Local listing accuracy outside the site was not verified.

**UX:** Phone and email are both required by the plugin's ARIA state; separate subject/type fields add burden. Response time remains vague. Terms/privacy links lead to placeholders.

**UI / design:** Inputs are 16 px on mobile and fit the viewport. Contact links have 3.49:1 contrast and are color-only within prose.

**Content:** No approved visiting/collection hours or appointment expectations are provided; technical message guidance can be more concrete.

**Recommended change:** F01, F04, F09, F18, F23-F24: complete notices, simplify the initial form, add autofill/telephone semantics and test real delivery in an authorized environment.

## CATALOGUE PROMISE VERSUS REAL AVAILABILITY

# Page findings: shop and category routes

## Webshop

<https://nextro.hu/bolt/>

**Purpose:** Browse and compare the catalogue, then purchase or enquire.

**Strengths:** Nine charger variants are discoverable, category navigation is visible and a sort control exists. Main shop description names the actual charger range.

**SEO:** Generic title; duplicate shop entry across sitemaps. Eight zero-product category destinations remain indexable and linked.

**UX:** Only one product has a price/add-to-cart; eight show read-more. Price filtering is of limited value for this price configuration.

**UI / design:** Consistent grid but inconsistent lifestyle crops and long near-identical titles complicate comparisons. “Price:” is left in English.

**Content:** The broad HVAC-store implication exceeds the purchasable catalogue seen. Empty-category fallback copy exists, so these are not literal blank pages.

**Recommended change:** F02–F03, F10, F13: explicitly separate online purchases from quote ranges, approve commercial states, add comparison attributes and simplify secondary shop actions.

## Air handlers: representative empty category

<https://nextro.hu/termekkategoria/legkezelok/>

**Purpose:** Offer air handlers or capture equipment-specific quotations.

**Strengths:** Intro explains new equipment/installation and provides a phone/contact fallback rather than only a no-results message.

**SEO:** No H1 or meta description; title ends “Archives”; indexable despite an empty catalogue. The same no-H1 issue affects five other categories.

**UX:** “Still being uploaded” and “no displayable product” are an unfinished-store message. EV chargers under popular products distract from air-handler intent.

**UI / design:** Category navigation occupies space without advancing this task; the empty-state hierarchy should instead emphasize a specification request.

**Content:** “A kategória termékei még nem tölthetők fel” sounds like an implementation limitation, not customer guidance.

**Recommended change:** F03, F10–F11: make this a purposeful quote-led page with device/application data, scope and a targeted CTA—or temporarily remove unfinished commerce navigation.

**Peer coverage:** /automatika/, /alkatreszek/, /futoegysegek/, /legfuggonyok/ and /szurok/ also lack H1s. /parasitok/ is empty but does have an H1. All eight category pages lack meta descriptions. These distinctions come from the complete category crawl, not extrapolation from one page.

## SELECTION AND ENQUIRY-ONLY STATE

# Page findings: charger category and product

## EV charger category

<https://nextro.hu/termekategoria/autotoltok/>

**Purpose:** Compare power and cable options across the nine Teltonika EVC2 variants.

**Strengths:** Introduction specifies 7.4/11/22 kW, phases, IP56, app/NFC, warranty and VAT versus installation scope.

**SEO:** H1 is present but description metadata is absent and title is an English archive default. Product-to-category internal links exist.

**UX:** No concise variant matrix; most items do not show a price or availability explanation. One priced item makes the others look incomplete.

**UI / design:** Grid fits mobile; long names and varying image compositions make scanning harder. The category strip also exposes seven zero-product ranges.

**Content:** Technical feature density is useful but needs plain-language selection advice: supply phases, cable need, site capacity and installation assessment.

**Recommended change:** F02, F10, F13: add a visible comparison table, intentional quote/purchase states and a tailored Hungarian search snippet.

## 11 kW / 5 m: sampled unpriced product

<https://nextro.hu/termek/teltonika-evc2-okos-ac-autotolto-11-kw-5-m-beepitett-toltokabellel/>

**Purpose:** Explain one charger configuration and convert product interest.

**Strengths:** Specific product heading and short summary; cable, phases and 36-month warranty are mentioned; image alt text is descriptive.

**SEO:** No meta description and no Product JSON-LD in the parsed page. Shared technical text limits differentiation, although the variant is real.

**UX:** No price or buy control; the separate “Contact us now” panel offers a generic installation enquiry, not an obvious model-specific request.

**UI / design:** Image and summary establish a product layout, but the commercial next step is visually subordinate to wishlist/compare and long text.

**Content:** Shipping tab contains the same internal missing-information note found in all nine product HTML pages. General network wording should be reviewed for model-specific clarity.

**Recommended change:** F01–F02, F13, F16, F20: label quotation mode, place a Hungarian contextual quote CTA beside the summary, publish approved delivery terms and accurate product facts.

## PURCHASE-READINESS BLOCKERS

# Page findings: priced product and policies

## 22 kW / 7.5 m: priced product

<https://nextro.hu/termek/teltonika-evc2-okos-ac-autotolto-22-kw-75-m-beepitett-toltokabellel/>

**Purpose:** Support a direct product purchase with optional installation.

**Strengths:** Visible 99 999 Ft price, quantity/add-to-cart and Product/Offer JSON-LD. Offer markup matches the displayed price and says InStock.

**SEO:** No meta description; structured data presence is not a Rich Results Test pass. Price/stock correctness is a business validation task, not independently proven by matching markup.

**UX:** The shipping tab exposes “[HIÁNYZIK: a konkrét szállítási díjak, határidők ...]” and links to an unfinished policy. No order was placed.

**UI / design:** Wide landscape product image and dense summary compete with the selection task; green breadcrumbs/tabs trigger contrast findings.

**Content:** Shared features do not clearly separate included product, installation, delivery and optional equipment at the point of purchase.

**Recommended change:** F01-F02, F04, F13, F16, F24: approve transaction terms/stock/price, show total-cost scope, improve product media/specifications and run an authorized checkout test.

## Privacy, terms and shipping information

<https://nextro.hu/adatkezelesi-tajekoztato/> • <https://nextro.hu/aszf/> • <https://nextro.hu/fizetesi-es-szallitasi-tajekoztato/>

**Purpose:** Explain data handling and contractual/delivery conditions. **Strength:** These destinations exist and are consistently linked. **SEO:** Each returns 200 and is indexable; descriptions repeat “feltöltés alatt” placeholder wording. **UX:** The user cannot inspect what the form asks them to accept. **UI:** A clean template cannot compensate for absent policy substance. **Content:** Main content consists of a short “currently being uploaded; return later” statement. **Action:** F01 is CRITICAL. Publish approved policies and remove internal notes before conversion-focused promotion; a qualified adviser must assess legal obligations.

## POSITIVE FOUNDATIONS TO PRESERVE

# Page findings: company details and recovery

## Impresszum

<https://nextro.hu/impresszum/>

**Purpose:** Identify the operator and hosting provider.

**Strengths:** NEXTRO name, Budapest address, email, tax number, company registration and registering court are present; hosting provider details are supplied.

**SEO:** Specific title/description and H1 are present. The shared Organization JSON-LD could reuse confirmed visible details.

**UX:** Company identity is reachable from the footer, supporting trust. It does not replace the incomplete privacy/contract/delivery policies.

**UI / design:** Plain text company details are readable; template phrasing such as company/sole-trader alternatives can be tailored.

**Content:** Values were observed but not independently reconciled with a registry. Registered address is distinct from the contact page's Szentendre warehouse.

**Recommended change:** F16, F18, F20: retain transparency, confirm accuracy, streamline template labels and align verified business data consistently across site/listings.

## Empty cart and 404 recovery

<https://nextro.hu/kosar/> ; <https://nextro.hu/technical-audit-not-found-20260922-7e21/>

**Purpose:** Recover empty-shopping and nonexistent-page journeys.

**Strengths:** Cart explains that it is empty and offers continue shopping. The 404 offers home/contact links and a clear Hungarian explanation.

**SEO:** Cart is noindex/follow but included in the sitemap; 404 returns an actual 404/noindex response. Empty-session checkout redirects to cart.

**UX:** Recovery is clear. This test does not prove add-to-cart persistence, populated checkout, payments or confirmation delivery.


**UI / design:** Both use the shared clean template; no severe layout defect was observed in these states.

**Content:** Error copy is understandable and avoids blaming the user. No additional promotional text is needed here.


**Recommended change:** F12: clean sitemap utility entries. F24: validate the full authorized transaction journey later; preserve real 404 status and the existing recovery links.

## DIRECT PROOF OF THE HIGHEST-PRIORITY CONTENT GAP

## 14. Screenshots and evidence



E5 · <https://nextro.hu/adatkezelesi-tajekoztato/> · The live policy page says the privacy notice is still being uploaded. The terms and shipping policy pages showed equivalent placeholders.




E6 · Priced 22 kW / 7.5 m product, “Szállítás és átvétel” tab. The public [HIÁNYZIK: ...] note says specific delivery fees, deadlines and carrier decisions are missing. The link above leads to the unfinished shipping policy. F01.

These screenshots are original live-browser captures with red outline annotations added for location only. They are not mockups. The product screenshot also shows the untranslated “Contact us now” link (F20).

F02 · F03 · F05

# Evidence: commercial dead ends



E7 · <https://nextro.hu/termekategoria/legkezelok/> · An empty HVAC category remains prominent in the shop taxonomy. Contact fallback exists, but the page still communicates catalogue incompleteness and promotes unrelated chargers.



E8 · 11 kW / 5 m product. Product name and features are present, but no price or direct purchase control is shown. The installation contact panel is not a prominent model-specific quote path.

## Evidence that is better expressed as DOM/HTTP data

The four homepage “Tudjon meg többet” anchors have href=<https://nextro.hu/>. Industry “Megoldások →” text is a span inside a focusable flip card, not an anchor. All ten homepage service cards link to /szolgaltatasok/ without a section fragment. These observations are retained in home-browser.json and the raw homepage response. A screenshot alone would not prove link destinations.

Contrast values are from saved axe node reports, payload from Resource Timing, and response/canonical/sitemap statements from saved HTTP bodies/headers. The evidence inventory at the end explains exactly which files support each class of claim.

## BUSINESS OWNER + DEVELOPMENT + MARKETING

# 15. Prioritized implementation roadmap

The roadmap contains 24 distinct recommendations: 1 CRITICAL, 10 HIGH, 11 MEDIUM, 2 LOW. IDs remain stable throughout the report. Expected impact is qualitative; effort describes relative implementation scope and dependencies, not a quoted duration.

| Phase                  | Actions and dependencies                                                                                                                     | Release evidence                                                                                                                     |
|------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| 1 · Restore readiness  | F01 policies/shipping; F02 product-state/price approval; F04/F23 access fixes; F05 link repair; F15 consent review.                          | Approved content; usable CTAs; no editorial placeholders; contrast/name tests pass; privacy behavior documented.                     |
| 2 · Remove friction    | F03 category strategy; F06 images; F09/F14 forms/mobile; F10–F12 snippets/headings/sitemap; F20 language.                                    | No advertised dead ends; measured payload reduction; mobile/form QA; clean indexing signals.                                         |
| 3 · Build authority    | F07 detailed commercial services; F08 case studies; F13 product selection; F16/F18 business/schema/local facts; F17 homepage simplification. | Approved expert content and evidence; contextual internal links and quotation handoff; consistent business data.                     |
| 4 · Optimize and prove | F19 measured asset work; F21–F22 polish; F24 end-to-end testing, baseline and experiments.                                                   | Repeatable lab/functional results and consent-aware outcome measurement. F24 testing must also gate initial transactional promotion. |

## Quick Wins

- **Repair navigation:** replace four homepage self-links, convert pseudo-links into real destinations and add stable service/sector anchors (F05).
- **Correct shared tokens:** fix dark checklist text, button/link contrast and anonymous overlay links rather than patching every page separately (F04, F23).
- **Finish obvious template text:** replace Contact us now / Archives / Price: and normalize tenure to 2005 óta (F10, F20).
- **Clean SEO signals:** populate metadata from approved product facts, restore category H1s and remove noindex utility routes from the sitemap (F10–F12).
- **Improve mobile inputs:** enlarge menu targets and add correct input types/autocomplete without rebuilding the whole form (F09, F14).

Immediate containment of F01 is essential, but the full policy/fulfilment solution is Moderate effort because it needs business and legal approval. Deleting a placeholder is not equivalent to publishing an adequate policy.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F01 / F02 / F03

## F01 · Published legal and shipping placeholders undermine informed enquiries and purchases

**CRITICAL** | Effort: Moderate | Expected impact: High | Content / trust / conversion

**Affected URLs:** <https://nextro.hu/adatkezelesi-tajekoztato/> • <https://nextro.hu/aszf/> • <https://nextro.hu/fizetesi-es-szallitasi-tajekoztato/> • All nine /termek/ pages; homepage and /kapcsolat/ forms

**Why it matters:** Visitors cannot review the information they are asked to accept or determine delivery costs and timing. This is an immediate trust and operational-readiness risk; legal compliance requires qualified review.

**Recommended solution:** Publish company-approved privacy, terms, delivery/payment and returns information; remove internal editorial notes from all product tabs. Review the enquiry checkbox's legal basis and wording with counsel. Gate transactional promotion until purchase policies and fulfilment are approved.

**Owner:** Business owner + legal/privacy + ecommerce

**Done when:** All linked policies contain approved, dated text; no public HIÁNYZIK or feltöltés alatt placeholders; enquiry consent wording matches the actual processing.

## F02 · Eight of nine products lack a clear commercial next step

**HIGH** | Effort: Moderate | Expected impact: High | CRO / ecommerce

**Affected URLs:** <https://nextro.hu/bolt/> • <https://nextro.hu/termekategoria/autotoltok/> • All /termek/ pages

**Why it matters:** Buyers cannot tell whether a product is available, quotation-only, temporarily unavailable or unfinished. The price is observed, not independently validated as correct.

**Recommended solution:** Choose purchase or quote mode per product. Show approved price, stock/lead-time and VAT/installation scope for purchasable products. For quote mode use Ár és telepítési ajánlat kérése beside the product title and preserve model/variant in the enquiry.

**Owner:** Ecommerce + development

**Done when:** Every product has one unambiguous primary action and availability state; business owner signs off prices; quote requests carry product context.

## F03 · Navigation prominently exposes seven empty product categories

**HIGH** | Effort: Moderate | Expected impact: High | IA / SEO / CRO

**Affected URLs:** <https://nextro.hu/bolt/> • <https://nextro.hu/termekategoria/legkezelok/> • <https://nextro.hu/termekategoria/automatika/> • <https://nextro.hu/termekategoria/szuok/> • <https://nextro.hu/termekategoria/alkatreszek/> • <https://nextro.hu/termekategoria/legfuggonyok/> • <https://nextro.hu/termekategoria/futoegysegek/> • <https://nextro.hu/termekategoria/parasitok/>

**Why it matters:** The site promises a broad HVAC store but exposes an EV-charger-only catalogue. Empty, indexable pages offer little search or purchase value.

**Recommended solution:** Turn quote-led categories into useful specification/enquiry landing pages, clearly distinguish them from buy-online ranges, and remove irrelevant popular-product widgets. If a category is genuinely unfinished, hide it from purchase navigation and temporarily noindex it rather than presenting a dead end.

**Owner:** Marketing + ecommerce + SEO

**Done when:** Each promoted category offers useful products or a focused specification/quote path; no unexplained zero-result routes remain.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F04 / F05 / F06

## F04 · Shared color tokens make important text difficult to read

**HIGH** | **Effort:** Quick | **Expected impact:** High | Accessibility / UI

**Affected URLs:** <https://nextro.hu/szolgalatasok/> • <https://nextro.hu/kapcsolat/> • <https://nextro.hu/> • Sampled product page; related dark hero templates

**Why it matters:** Users with low vision and people viewing a phone in glare may miss the very proof points and actions intended to persuade them. Normal text requires 4.5:1 for WCAG AA.

**Recommended solution:** Introduce semantic light-on-dark and dark-on-light text tokens; do not inherit body color inside dark heroes. Adjust green text/button combinations, add non-color active/link cues and retest default, hover, focus and disabled states across templates.

**Owner:** Design + frontend

**Done when:** All normal text in audited templates reaches 4.5:1, large text 3:1; regressions checked by automated and visual tests.

## F05 · Homepage discovery controls imply destinations they do not reach

**HIGH** | **Effort:** Quick | **Expected impact:** High | UX / internal linking

**Affected URLs:** <https://nextro.hu/>

**Why it matters:** Users repeat work, lose context and may interpret the interface as broken. Search engines receive no distinct destination from pseudo-links.

**Recommended solution:** Link the four benefit CTAs to relevant service/about/proof sections. Replace industry pseudo-links with actual anchors to matching industry sections/pages. Add stable service anchors immediately; use dedicated detail URLs when substantive pages are ready.

**Owner:** Content + frontend

**Done when:** Every apparent link reaches a relevant destination using mouse, touch and keyboard; each service/industry card preserves context.

## F06 · Large, eagerly requested background images dominate homepage payload

**HIGH** | **Effort:** Moderate | **Expected impact:** High | Performance

**Affected URLs:** <https://nextro.hu/> • </wp-content/uploads/2026/08/megoldas-etterem.png> • </wp-content/uploads/2026/08/hero-legkezelo-gepterem.jpg>

**Why it matters:** Fast desktop rendering does not remove mobile data and slower-network costs. Offscreen industry imagery competes for bandwidth with the initial experience.

**Recommended solution:** Create appropriately sized WebP/AVIF variants, preserve visual quality, use responsive picture/img markup for meaningful imagery and load below-fold backgrounds on demand. Keep the actual LCP image eager; avoid indiscriminately lazy-loading the hero.

**Owner:** Frontend + media/content

**Done when:** Restaurant image is right-sized and modern-format; offscreen cards no longer download unnecessarily at initial load; cold mobile lab tests show a smaller measured payload without image or layout regressions.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F07 / F08 / F15

## F07 · Ten services and six sectors lack deep, intent-specific landing paths

**HIGH** | **Effort:** Significant | **Expected impact:** High | SEO / information architecture

**Affected URLs:** <https://nextro.hu/szolgalatasok/> • <https://nextro.hu/megoldasok/> • <https://nextro.hu/>

**Why it matters:** A high-intent visitor cannot land directly on a complete explanation of one need. The existing breadth is diluted rather than organized into useful search destinations.

**Recommended solution:** Retain the two hubs. Build original detail pages first for légkezelő karbantartás, légkezelő felújítás/forgódob-csere and egyedi légtechnikai szűrőgyártás; connect them to sector examples, relevant products and a contextual enquiry. Add further pages only when genuine unique detail is available.

**Owner:** SEO + subject-matter experts + content

**Done when:** Each new page answers scope, fit, process, proof and next-step questions and is linked from its hub; no near-duplicate doorway pages.

## F08 · Reference content describes project types rather than evidenced case studies

**HIGH** | **Effort:** Significant | **Expected impact:** High | Content / E-E-A-T / CRO

**Affected URLs:** <https://nextro.hu/referenciak/> • <https://nextro.hu/> • <https://nextro.hu/rolunk/>

**Why it matters:** A procurement buyer needs evidence of comparable delivery, not only an assertion of capability. Generic imagery weakens the connection between claim and proof.

**Recommended solution:** Publish permission-cleared case studies with site/sector, date, problem, scope, real project photographs and documented results. Where clients are confidential, say so and include verifiable technical specifics. Link to current certification/rating evidence and identify responsible experts.

**Owner:** Sales + project engineers + marketing

**Done when:** Three representative case studies have approved evidence; numerical claims and ratings have a source/date; no fabricated testimonials or savings.

## F15 · Consent and third-party integration need a documented verification pass

**HIGH** | **Effort:** Moderate | **Expected impact:** High | Privacy assurance / performance

**Affected URLs:** <https://nextro.hu/> • <https://nextro.hu/cookie-nyilatkozat/> • Shared newsletter and cookie components

**Why it matters:** The incomplete privacy notice and third-party integrations make it important to verify what loads, stores or transmits data under each consent choice rather than assume the banner controls everything.

**Recommended solution:** In a clean-browser matrix, compare no choice/reject/granular/accept/revoke states. Classify each integration and its legal basis, gate non-essential behavior as appropriate and publish matching disclosures. Translate residual English preference/help text and verify newsletter confirmation handling.

**Owner:** Privacy lead + analytics/development

**Done when:** A retained request/storage audit maps each integration to purpose and consent behavior; policy and banner agree. This is a verification task, not a finding of a legal violation.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F23 / F24 / F09

## F23 · Anonymous overlay links and color-only inline links need semantic repairs

**HIGH** | **Effort:** Quick | **Expected impact:** High | Accessibility / frontend

**Affected URLs:** <https://nextro.hu/szolgalatasok/> • <https://nextro.hu/kapcsolat/> • Related hero/container link templates

**Why it matters:** A screen-reader user can land on a link with no purpose; color-dependent links are harder to identify. These are more specific than a blanket claim that keyboard access is broken.

**Recommended solution:** Remove redundant overlay anchors or give the intended link a meaningful accessible name; use real text links and underlines where links occur within prose. Test tab order and avoid nested interactive elements when making cards clickable.

**Owner:** Frontend + accessibility QA

**Done when:** No unnamed links in affected templates; links are identifiable without color alone; screen-reader and keyboard spot checks agree with automated results.

## F24 · Conversion measurement and end-to-end reliability are not yet evidenced

**HIGH** | **Effort:** Moderate | **Expected impact:** High | CRO / analytics / QA

**Affected URLs:** <https://nextro.hu/kapcsolat/> • <https://nextro.hu/bolt/> • Product-to-cart/checkout journey • Shared newsletter

**Why it matters:** A visually improved funnel may still lose leads after submission. Without a baseline, no uplift or conversion-rate claim is defensible.

**Recommended solution:** With owner approval use staging/test mode to verify form validation, delivery, spam handling, success feedback, product/cart totals, shipping, payment failure and confirmation. Implement consent-aware quote/call/email/add-to-cart/checkout events and review lead quality as well as volume.

**Owner:** QA + sales operations + analytics

**Done when:** Authorized test evidence proves end-to-end delivery and transaction states; events are documented, privacy-reviewed and deduplicated; a baseline is established before optimization experiments.

## F09 · The enquiry form asks for more effort than necessary

**MEDIUM** | **Effort:** Moderate | **Expected impact:** High | UX / forms / accessibility

**Affected URLs:** <https://nextro.hu/kapcsolat/> • <https://nextro.hu/>

**Why it matters:** Required telephone plus email, a separate subject and unassisted technical description add friction, especially on phones. This is a design concern, not a measured abandonment rate.

**Recommended solution:** Keep clear labels; make phone optional unless callback is chosen; consider a single full-name field and remove redundant subject. Use type=tel, autocomplete tokens and concise prompts for building/location/equipment. Preserve incoming service/product context. Explain what happens next using an approved response expectation.

**Owner:** Sales + UX + development

**Done when:** Mobile autofill and keyboard types work; only necessary inputs are mandatory; empty/invalid/error/success states and email delivery pass an authorized staging test.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F10 / F11 / F12

## F10 · Product and category search snippets are unfinished

**MEDIUM** | **Effort:** Quick | **Expected impact:** Medium | On-page SEO

**Affected URLs:** All nine /termek/ pages • All eight /termekategoria/ pages • <https://nextro.hu/bolt/>

**Why it matters:** Search snippets and shared links communicate less clearly than the underlying product data allows. Meta descriptions influence presentation, not guaranteed ranking or click-through gains.

**Recommended solution:** Write differentiated Hungarian descriptions for commercial pages and replace archive defaults with customer-facing category titles. Include model/power/cable variants on products and use a specific shop title. Resolve real catalogue availability before promising online purchase.

**Owner:** SEO + content

**Done when:** All intended commercial landing pages have relevant distinct titles and descriptions; previews are reviewed by pixel width, not only character count.

## F11 · Category headings and section hierarchy are inconsistent

**MEDIUM** | **Effort:** Quick | **Expected impact:** Medium | Semantic SEO / accessibility

**Affected URLs:** Six category URLs listed in the technical inventory • <https://nextro.hu/megoldasok/> • <https://nextro.hu/kapcsolat/> • <https://nextro.hu/>

**Why it matters:** Visual peers do not form predictable document sections for scanning and assistive navigation. Missing H1s reduce topic clarity; they are not proof of a ranking penalty.

**Recommended solution:** Render one descriptive H1 on category templates, make peer sectors the same heading level and use H2 section labels with H3 subtopics. Do not select heading tags to achieve a font size.

**Owner:** Frontend + SEO

**Done when:** Category pages have a meaningful H1 and all audited templates have a logical outline independent of visual styling.

## F12 · The sitemap includes noindex and redirecting utility routes

**MEDIUM** | **Effort:** Quick | **Expected impact:** Medium | Technical SEO

**Affected URLs:** <https://nextro.hu/page-sitemap.xml> • <https://nextro.hu/kosar/> • <https://nextro.hu/penztar/> • <https://nextro.hu/fiokom/>

**Why it matters:** The sitemap sends mixed discovery/indexing signals and contains routes that are not organic landing pages. The duplicate shop entry is redundant, not a duplicate-content penalty.

**Recommended solution:** Exclude utility/noindex routes from the sitemap and deduplicate shop inclusion. Keep cart/account noindex and allow crawlers to see that directive. Submit the cleaned sitemap in Search Console once access is available.

**Owner:** SEO + WordPress developer

**Done when:** Every sitemap page entry resolves directly to an intended indexable canonical 200 URL; cart, checkout and account are absent.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F13 / F14 / F16

## F13 · Product presentation makes model comparison unnecessarily difficult

**MEDIUM** | **Effort:** Moderate | **Expected impact:** Medium | UI / content / ecommerce

**Affected URLs:** <https://nextro.hu/bolt/> • <https://nextro.hu/termekategoria/autotoltok/> • All /termek/ pages

**Why it matters:** Users must read repetitive names to compare power, phases and cable options and cannot easily assess included hardware versus installation imagery.

**Recommended solution:** Use consistent product packshots and aspect ratios, a power/phase/cable comparison table and a labelled installation/gallery section. Keep imagery accurate to the offered SKU. Consider a single variant selector only after assessing URL demand and migration implications.

**Owner:** Ecommerce + design + product expert

**Done when:** Variant differences and included items are visible without opening every product; any URL consolidation has an explicit redirect/canonical plan.

## F14 · Mobile contact access and menu ergonomics can be improved

**MEDIUM** | **Effort:** Quick | **Expected impact:** Medium | Mobile UX / accessibility

**Affected URLs:** <https://nextro.hu/> • Shared mobile header • <https://nextro.hu/kapcsolat/>

**Why it matters:** A small target is harder to hit; an urgent maintenance visitor has no immediate call action in the mobile header. This is an ergonomic finding, not a proven WCAG target-size violation because spacing exceptions may apply.

**Recommended solution:** Give menu/close controls a 44 × 44 px design target with visible focus; add a labelled call action and/or compact quote/call bar after consent. Respect safe areas and avoid obscuring the form or cookie controls. Test opened-menu keyboard focus, Escape and return focus across devices.

**Owner:** UX + frontend

**Done when:** Menu and close controls have comfortable touch areas; phone/quote access is immediate on mobile; no overlay collision at 320–430 px.

## F16 · Structured data is basic and uneven across the catalogue

**MEDIUM** | **Effort:** Moderate | **Expected impact:** Medium | Structured data / local SEO

**Affected URLs:** <https://nextro.hu/> • All /termek/ pages • <https://nextro.hu/kapcsolat/> • <https://nextro.hu/impresszum/>

**Why it matters:** The entity graph omits useful verified business details; quote-only items are not represented consistently. Rich-result eligibility cannot be inferred from valid JSON alone.

**Recommended solution:** Enrich one consistent business entity with confirmed contact, address, social profiles and appropriate business type. Add accurate Product data where applicable; include Offer only when real price/availability supports it. Validate with Google's rich-result tooling and align shipping/returns markup only after policies are complete.

**Owner:** SEO + development

**Done when:** Schema matches visible, approved facts; no fabricated prices/reviews/offers; validators pass relevant checks without guaranteeing rich-result display.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F17 / F18 / F19

## F17 · The homepage repeats assurances and delays specific visitor decisions

**MEDIUM** | **Effort:** Moderate | **Expected impact:** High | UX / content / design

**Affected URLs:** <https://nextro.hu/> • <https://nextro.hu/megoldasok/>

**Why it matters:** Length alone is not a defect, but repeated assurances compete with service choice and proof. Mobile visitors must scan a long sequence to find the information relevant to them.

**Recommended solution:** Lead with explicit HVAC service scope and a quote/call action; follow with service pathways, proof, relevant sectors, concise process and contact. Consolidate repeated benefits. On solutions, add an immediate sector index before the general process. Retain useful depth in contextual detail pages.

**Owner:** UX + content + design

**Done when:** A first-time user can explain the offer, choose a relevant path and locate proof/contact without reading repeated sections; verify through observed usability sessions.

## F18 · Local contact and credibility information is present but incomplete for decision-making

**MEDIUM** | **Effort:** Moderate | **Expected impact:** Medium | Local SEO / trust / content

**Affected URLs:** <https://nextro.hu/kapcsolat/> • <https://nextro.hu/impresszum/> • <https://nextro.hu/rolunk/>

**Why it matters:** Prospects need to distinguish legal headquarters from a service/collection location. Search listings should not imply a staffed walk-in venue without business confirmation.

**Recommended solution:** Confirm and publish hours, appointment/collection rules, service area and appropriate directions. Keep name/address/phone consistent across the website and verified listings; review Google Business Profile separately with owner access. Add named technical contacts or accountable expert profiles where appropriate.

**Owner:** Business owner + local SEO + content

**Done when:** Each address has a clear role and approved visitor information; external listings are reconciled using authorized access.

## F19 · Shared assets and render-blocking requests warrant optimization after imagery

**MEDIUM** | **Effort:** Moderate | **Expected impact:** Medium | Performance / engineering

**Affected URLs:** <https://nextro.hu/> • Shared templates

**Why it matters:** Plugin/template assets can add work on pages where features are not used. Presence does not prove unused code or justify indiscriminate removal.

**Recommended solution:** Profile CSS/JS coverage and long tasks by template; conditionally enqueue shop/form assets, defer only compatible scripts and remove redundant styles after dependency tests. Assess anonymous HTML caching separately from cart/account/checkout. Keep local WOFF2 fonts and review font-display/weight use in a controlled trace.

**Owner:** WordPress performance developer

**Done when:** Coverage and repeatable lab traces justify removals; cart, forms, consent and navigation still work; personalized pages are not cached publicly.

## IMPLEMENTATION CARDS · PRIORITY ORDER

# Roadmap: F20 / F21 / F22

## F20 · Inconsistent and partly untranslated wording weakens polish

**MEDIUM** | **Effort:** Quick | **Expected impact:** Medium | Content / UI

**Affected URLs:** <https://nextro.hu/rolunk/> • <https://nextro.hu/referenciak/> • <https://nextro.hu/bolt/> • All /termek/ pages

**Why it matters:** Inconsistent dates and template language make a recently updated site look unfinished. Strong promises should match an operationally deliverable commitment.

**Recommended solution:** Prefer stable 2005 óta wording, translate customer-facing defaults and simplify technical jargon without losing accuracy. Publish approved warranty scope and response expectations, not invented guarantees. Have a Hungarian HVAC specialist review nomenclature and customer-facing explanations.

**Owner:** Hungarian editor + business owner

**Done when:** No unexplained English UI remains in primary journeys; tenure and guarantees are consistent and fact-checked.

## F21 · The HTTP www variant has an avoidable redirect hop

**LOW** | **Effort:** Quick | **Expected impact:** Low | Technical SEO / performance

**Affected URLs:** <http://www.nextro.hu/>

**Why it matters:** This adds a small delay for visitors and crawlers using the old host/protocol; it is not an indexation emergency.

**Recommended solution:** Where hosting rules permit, combine host and scheme normalization into one permanent redirect directly to the preferred HTTPS non-www URL, preserving path/query and avoiding loops.

**Owner:** Hosting/development

**Done when:** Every supported legacy host/scheme test reaches the preferred canonical host in one hop; paths and queries remain correct.

## F22 · Social preview and secondary metadata need finishing

**LOW** | **Effort:** Quick | **Expected impact:** Low | Social sharing / technical polish

**Affected URLs:** <https://nextro.hu/bolt/> • <https://nextro.hu/kapcsolat/> • All /termekategoria/ pages • Shared favicon markup

**Why it matters:** Commercial links can be less recognizable in messaging/social previews. This is presentation polish, not a demonstrated search-ranking issue.

**Recommended solution:** Add a purposeful branded fallback preview image and category-specific images where useful; validate rendered previews. Verify icon dimensions and browser appearance rather than inferring a failure from filenames.

**Owner:** Design + SEO/development

**Done when:** Key pages generate intentional previews; favicon metadata agrees with actual assets or is corrected where necessary.

## BUILD USEFUL DEPTH, NOT MORE TEMPLATE PAGES

# Strategic Improvements

| Initiative                        | Scope and dependencies                                                                                                                                                            | How to judge success                                                                                                                                                |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Service-intent architecture       | Expand maintenance, renovation/rotor replacement and filter manufacture first. Interview engineers, assemble scope/fit/process content and connect real cases. F07.               | Prospects can answer suitability and scope questions on one page; contextual enquiries preserve service intent. Assess organic/lead outcomes only after a baseline. |
| Evidence-led reference library    | Create at least three approved project stories across representative sectors. Use dates, actual photos, named or transparently confidential clients and documented outcomes. F08. | Sales can send a relevant case to a real prospect; every numerical result has evidence and permission.                                                              |
| Coherent product/quotation system | Choose the commercial model of each range, align stock/price/fulfilment data, complete policy content and make product selection easier. F01-F03, F13, F16.                       | Every advertised range has a purchase or quote route and known commercial terms; authorized checkout/enquiry tests succeed.                                         |
| Reusable accessible components    | Set a light/dark token system, headings, card link semantics, product media, form states, focus and motion rules. F04, F09, F11, F14, F23.                                        | Shared-template fixes pass automated and human tests at multiple widths without regressions.                                                                        |
| Measured optimization program     | Image/loading work followed by coverage-driven CSS/JS changes, documented consent and reliable outcome events. F06, F15, F19, F24.                                                | Repeated cold lab traces and real-user monitoring improve; privacy and functional tests remain valid.                                                               |

## Suggested governance

Assign a business approver to prices, warranties, fulfilment, company claims and response expectations; a technical owner to templates, performance and schema; and a content owner to service/case pages. Maintain one finding backlog with evidence, owner, acceptance test and release status. A single person should verify that the policy, product and form journeys tell the same story.

Do not start with a cosmetic sitewide rebuild. Resolve readiness/access blockers first, then prototype one commercial service and one product journey. Reuse proven components and preserve existing useful URLs and content.

RECOMMENDED ORDER OF IMPLEMENTATION

# 16. Final recommendations

NEXTRO’s service story and visual identity provide a workable foundation. The site’s largest weaknesses are concentrated in unfinished commercial details, inaccessible contrast, ambiguous navigation and insufficient proof—not a total absence of content or technical SEO. Address those weaknesses before spending on more traffic.

| Top 10 | Action                                                                                              |
|--------|-----------------------------------------------------------------------------------------------------|
| 1      | Publish approved privacy, terms and shipping information; eliminate public internal notes.          |
| 2      | Give every product a validated purchase or contextual quotation state.                              |
| 3      | Fix text contrast, unnamed links and color-only inline links in shared templates.                   |
| 4      | Repair homepage self-links/pseudo-links and preserve selected service/sector context.               |
| 5      | Replace empty store categories with useful quote-led ranges or remove unfinished promotion.         |
| 6      | Reduce the large restaurant/hero/background image payload and verify mobile loading.                |
| 7      | Complete consent and authorized end-to-end enquiry/checkout testing before transactional promotion. |
| 8      | Publish verifiable case studies, expert/company evidence and current claim sources.                 |
| 9      | Build original priority service detail pages and link them to proof and enquiry.                    |
| 10     | Finish commercial metadata, category headings, sitemap hygiene and mobile form ergonomics.          |

## Priorities by discipline

- SEO:** useful commercial depth and evidence first; then product/category snippets, headings, sitemap and accurate entity data.
- UX/UI:** readable dark surfaces, real destination links, shorter repeated homepage narrative, comfortable mobile call/menu access.
- Technical:** image bytes and conditional loading, carefully tested template assets, explicit indexing signals and reliable form/checkout behavior.
- Content:** complete policies, approve claims, replace anonymous references with evidence and remove template English.
- Conversion:** honest product availability/pricing, contextual quote paths, minimal necessary form effort and operationally verified handoff.

### Success criteria

A new visitor should understand the relevant offer, verify credible evidence, know the applicable terms and complete a clear enquiry or purchase journey. Verify that outcome with real tests and approved analytics; do not equate a better-looking homepage or a higher lab score with proven business success.

## 29 CRAWLED CONTENT PAGES

# Appendix A · Technical inventory

All rows below returned HTTP 200 and had a title, canonical tag and index/follow robots metadata in the raw crawl. “Meta” indicates presence of a description, not quality. Empty utility routes and the 404 probe are listed separately in the technical section. URLs below are relative to <https://nextro.hu/>.

| Path                                 | H1s | Meta    |
|--------------------------------------|-----|---------|
| /                                    | 1   | Yes     |
| /szolgaltatasok/                     | 1   | Yes     |
| /megoldasok/                         | 1   | Yes     |
| /referenciak/                        | 1   | Yes     |
| /rolunk/                             | 1   | Yes     |
| /bolt/                               | 1   | Yes     |
| /kapcsolat/                          | 1   | Yes     |
| /adatkezelesi-tajekoztato/           | 1   | Yes     |
| /aszf/                               | 1   | Yes     |
| /cookie-nyilatkozat/                 | 1   | Yes     |
| /impresszum/                         | 1   | Yes     |
| /fizetesi-es-szallitasi-tajekoztato/ | 1   | Yes     |
| /termekategoria/alkatreszek/         | 0   | Missing |
| /termekategoria/automatika/          | 0   | Missing |
| /termekategoria/autotoltok/          | 1   | Missing |
| /termekategoria/futoegysegek/        | 0   | Missing |
| /termekategoria/legfuggonyok/        | 0   | Missing |
| /termekategoria/legkezelok/          | 0   | Missing |
| /termekategoria/parasitok/           | 1   | Missing |
| /termekategoria/szurok/              | 0   | Missing |

## CONTINUATION OF THE 29-PAGE CONTENT CRAWL

# Technical inventory: products and utilities

All nine products below returned 200 with one H1, a title and a self-referencing canonical. All nine lack a meta description. The eight unpriced variants do not contain Product JSON-LD; the priced 22 kW / 7.5 m variant does. Paths are relative to <https://nextro.hu/>.

| Product path                                                                   | Visible price |
|--------------------------------------------------------------------------------|---------------|
| /termek/teltonika-evc2-okos-ac-autotolto-11-kw-5-m-beepitett-toltokabellel/    | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-11-kw-75-m-beepitett-toltokabellel/   | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-11-kw-kompakt-beepitett-kabel-nelkul/ | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-22-kw-5-m-beepitett-toltokabellel/    | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-22-kw-75-m-beepitett-toltokabellel/   | 99 999 Ft     |
| /termek/teltonika-evc2-okos-ac-autotolto-22-kw-kompakt-beepitett-kabel-nelkul/ | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-74-kw-5-m-beepitett-toltokabellel/    | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-74-kw-75-m-beepitett-toltokabellel/   | Not shown     |
| /termek/teltonika-evc2-okos-ac-autotolto-74-kw-kompakt-beepitett-kabel-nelkul/ | Not shown     |

## Separately tested utility routes

| Route     | Response / index directive                  |
|-----------|---------------------------------------------|
| /kosar/   | 200; noindex, follow                        |
| /fiokom/  | 200; noindex, follow; no login attempted    |
| /penztar/ | 302 to /kosar/ in the empty-session request |

These utility probes are not included in the 29 content-page crawl total. No customer data, authentication or live order was submitted.

## TRACEABILITY AND UNKNOWNNS

# Appendix B · Evidence and validation register

| Evidence file / source                                                           | What it supports                                                                                                                                                                                     |
|----------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| technical.json + http-evidence/                                                  | Raw crawl, metadata, HTTP status/redirects, canonical/robots tags, headings, image attributes, structured data, robots and sitemap responses, user-agent variations, caching samples.                |
| aggregates.json                                                                  | Corrected namespace-aware sitemap counts: 25 unique page URLs, 26 page entries and 26 unique image locations. Resource aggregates exclude injected axe.                                              |
| supplement.json                                                                  | Utility/noindex/checkout behavior, sitemap.xml redirect, orderby canonical, price states, Product/Offer data, basic Organization graph and favicon/OG checks.                                        |
| home-browser.json; services.json; megoldasok.json; referenciak.json; rolunk.json | Rendered text, heading outlines and main-page link destinations. Homepage pseudo-link behavior was also manually exercised.                                                                          |
| kapcsolat.json; product-priced.json; product-unpriced.json; category/shop JSON   | Forms/labels and rendered product/category commercial content; tab content confirmed with a browser click.                                                                                           |
| axe-home/services/contact/product.json                                           | Saved axe-core 4.10.3 node-level results. Home/services are desktop; contact/product mobile. A transient blank-tab test was discarded and the product file was replaced with a valid live-page scan. |
| performance-desktop.json; performance-mobile.json                                | Navigation/Resource Timing and buffered LCP/layout shifts. Desktop is the reported one-off observation; mobile was warm/reused and not a comparable benchmark.                                       |
| pagespeed-api.json                                                               | The HTTP 429/quota response. No PSI score or CrUX field result was available from this attempt.                                                                                                      |
| mobile-layouts.json; desktop-interactions.json; screenshots                      | Viewport sizes/overflow, fonts, visible errors, resolved counters and tested focus behavior; original and annotated screenshot evidence.                                                             |

## Unverified items requiring follow-up

Actual Google indexing, rankings, search demand, backlinks, analytics/conversion rates, field Core Web Vitals, INP, full-page lifetime CLS, unused CSS/JS coverage, long tasks, backend cache architecture, authenticated areas, payment completion, live email delivery, newsletter confirmation, registry/rating accuracy, full third-party consent payload/storage behavior and formal WCAG conformance. No metric in these areas is invented.

Audit files: /workspace/nextro-audit/ · Final PDF: /workspace/nextro.hu\_full\_website\_audit.pdf. The report reflects the public site observed on 22 September 2026; later changes may supersede a finding. Raw server Date headers are retained as received; the inspection date is the local audit record.