



Bus shelter — the four final reconstructions against the lidar reference

COLMAP




Acc 56.8 · Comp 39.0 · F1 46.3
set aside 10.9%

hloc + COLMAP




Acc 48.3 · Comp 40.5 · F1 44.1
set aside 11.5%

MASt3R-GA



Acc 44.6 · Comp 79.2 · F1 57.1
set aside 13.2%

VGGT



Acc 28.6 · Comp 96.4 · F1 44.1
set aside 34.5%

- reconstruction within 3 cm of the reference
- reconstruction farther than 3 cm, counted as error
- reconstruction set aside as a reference gap (\$4.5)