
Ate_Macoke | Vegetation Trajectories

2019–2023 NDVI and NDMI assessment over 2023 Landsat true-color imagery



VEGETATION TRAJECTORY

Recovery
Recovery to 2019 or partial recovery

Continued decline
Decline across both periods

Stable / mixed / disagreement
Combined residual category

Ate_Macoke parcel boundary

MAP INFORMATION

Satellite background	Landsat 8/9, 2023
Trajectory years	2019, 2022, 2023
Vegetation indices	NDVI and NDMI
Pixel resolution	30 meters
Coordinate system	UTM Zone 13N
EPSG code	32613
Change threshold	±0.05 index units

INTERPRETATION

Classes describe spectral vegetation trajectories, not independently verified grazing impacts. The gray class includes stable, mixed, and disagreement pixels.