
Top 1% history-increment overlap with FEM damaged process zone
Overlap fraction
1.0
0.8
0.6
0.4
0.2
0.0
FEM increment reference
0.829
0.091
0.129
0.149
0.084
PIDL increment
Process zone: FEM damage > 0.95
initial to c1
c1 to c20
c20 to c40
c40 to c60
c60 to c69