

ORAL PRESENTATIONS | CONCURRENT SESSION PRESENTATIONS

Sciences behind gemstone treatments

Characteristics of Commercial Grade Blue Sapphire Enhanced by Heat & Pressure

Thanong Leelawatanasuk¹, Thanapong Lhuaamporn¹, Nicharee Atsawatanapirom¹, Papawarin Ounorn¹, Visut Pisutha-Arnond¹, Wilawan Atichat¹


The Gem and Jewelry Institute of Thailand (Public Organization), Bangkok, Thailand

In this study, 18 commercial grade blue sapphire samples (1.33-4.99 ct.) treated with heat and pressure were purchased directly from a known producer. The trader also informed us that starting materials being used for his treatment in Korea were selected from an unsuccessful batch of normally heated sapphire samples from Sri Lanka. Their characteristics are reported and compared with data from previous studies¹⁻⁵.

The basic gem properties of those stones fall in the range of a normal corundum (S.G. 3.951-3.978, RI 1.760-1.770). Their internal features are altered or melted solid inclusions ("snow ball"), altered healed-fissures with secondary fingerprints, tension disc, a dotted pattern due to the dissolution of rutile silk. These features are mostly overlapping with those found in the traditionally heated stones. Nonetheless, their reaction to standard UV light can give us the first hint. As most study stones are inert to both LWUV and SWUV (except one showing very weak chalky blue under SWUV) in contrast to a chalky blue fluorescence along growth zones under SWUV commonly seen in a normally heated blue sapphire from Sri Lanka. Furthermore, a noticeably slightly healed border of the clear and flattened tension cracks as well as the presence of black graphite residue in surface-reaching cavities or fractures (as confirmed by Laser Raman Spectroscopy) are also the good evidences to indicate the treatment with heat-plus-pressure.

The chemical data analyzed by EDXRF gave relatively low iron content (0.04-0.21 %wt. Fe₂O₃) which are consistent with our database of the stones originated from Sri Lanka. The UV-Vis-NIR spectra revealed that the cause-of-color is mainly due to the Fe-Ti Inter-Valence-Charge-Transfer mechanism like those of the blue sapphires originated from metamorphic origin. As also previously reported, the Mid-InfraRed spectra obtained by FTIR spectrometer do show quite a unique strong OH-related absorption bands and small shoulders or peaks that have never been reported before in traditionally heated blue sapphires. However, four main IR spectral patterns were observed from those stones (Figure 1). The patterns (b), (c) and (d) have never been reported in the previous studies¹⁻⁵ before and can be used as the key identification criteria for a heat-plus-pressure-treated stone as well. Furthermore, by simply re-heating three selected stones from those 18 samples at 1500°C for 4 hrs. in an oxidation condition, the strong OH-related absorption bands and small shoulders or peaks indicative of heat-plus-pressure treatment disappear completely, and the stone blue colors turn paler or colorless.

In conclusion, the identification of a heat-plus-pressure-treated stone may pose some uncertainty by using standard gemological methods alone. However, with additional advanced analyses, especially the FTIR spectrometer, it can positively help identifying the treatment.



References

[1] Choi, H.M., Kim, S.K. and Kim, Y.C., 2014a. New treated blue sapphire by HPHT apparatus, Proceedings of the 4th International Gem and Jewelry Conference (GIT2014), pp.104-105.

[2] Choi H.M., Kim S.K. and Kim Y.C., 2014b. Appearance of new treatment method on sapphire using HPHT apparatus. ICGL Newsletter, Vol.4, pp.1-2, http://icglabs.org/wp-content/uploads/2014/12/ICGLNewsletter-2014FA.pdf

[3] Kim, H.K., Choi, H.M., Kim, Y.C., Wathanakul, P., Leelawatanasuk, T., Atsawatanapirom, N., Ounorn, P., and Lhuaamporn, T., 2016, HPHT-Treatmented blue sapphire: An update, The Journal of Gemmology, Vol.35, No.3, pp.208-210.

[4] Leelawatanasuk, T., Atsawatanapirom, N., Lhuaamporn, T., and Ounorn, P., 2016, GIT Gemstone Update "blue sapphire undergone high pressure high temperature enhancement" Gem and Jewelry Institute of Thailand, Bangkok, accessed July 26, 2016, Bangkok, http://www.git.or.th/2014/eng/testing_center_en/lab_notes_en/glab_en/2016/07/BlueSapphire_26072016.pdf

[5] Song, J. Noh, Y., and Song, O., 2015. Color enhancement of natural sapphires by high pressure high-temperature process, Journal of the Korean Ceramic Society, Vol.52, No. 2, pp.165-170.