[DFC-2023-201] Write-Up

작성자	박혜미	
분석 일자 2024.06.01~2024.06.06		
작성 일자	2024.06.07	
분석 대상	draft_server.001	
문서 버전	1.0	
작성자 E-mail	parkm0708@naver.com	





0. 목차

1.	문제	3
	분석 도구	
	환경	
	Write-Up	
	Flag	
	· 별도 첨부	
	Reference	



1. 문제

URL	-		
	Kate is a server administrator at a fashion design company and recentl underwent an internal audit within the company due to an incident where desig		
	files stored on the server were leaked. The company has requested a digital		
문제	forensics analysis of the server's volume to resolve this issue. Please provide the		
내용	analysis results for each question.		
	1) List the original and changed file names of the renamed files. (50 points)		
	2) List the file names of the deleted files. (50 points)		
	3) Provide the deleted time for each file. (100 points)		
문제 파일	(용량이 너무 커 첨부하지 않는다.)		
문제 유형	system forensics		
난이도	3 / 3		

2. 분석 도구

도구명	다운로드 링크	Version
HxD	https://mh-nexus.de/en/hxd/	2.5
ARIN	https://github.com/horensic/ARIN.git	-
DCode	https://www.digital-detective.net/dcode/	5.5

3. 환경


OS	
Windows 11 Home	



4. Write-Up


파일명	draft_server.001	
용량	2.99GB	
SHA256	05846f618c1406372693ee4e9da442740a505f5cac57958d43e07ccdd850c2c5	
Timestamp	2023-05-31 22:08:58	

1. 이름이 변경된 파일의 원래 파일명과 변경된 파일명을 나열합니다.



[그림 1] HxD draft_server


draft_server 문제 파일을 HxD 를 사용하여 열어보았더니 ReFS 파일 시스템이라는 것을 확인할수 있다. [7. Reference]에 첨부한 링크를 통해 renaming 의 opcode 패턴을 확인했다. (0x02 -> 0x02 -> 0x01 -> 0x01 -> 0x04)



[그림 2] ARIN을 사용한 ReFS 분석




[WHS-2] .iso




[그림 3] .csv로 저장

검색의 편리성을 위해 .csv 파일 형식으로 저장한다.



[그림 4] 검색

총 4개의 검색 결과가 나온다.



[그림 5] renaming에 관한 흔적

살펴보니 Redo Delete Row (0x2) -> Redo Reparent Table (0x5) -> Redo Insert Row (0x1)의 순서를 거쳐 0x600 에서 데이터를 업데이트하고 1008023_B.jpg 에 대한 데이터를 업데이트하는 걸 볼 수 있다.





```
1803D000 4D 4C 6F 67 07 75 DB AE 01 00 00 00 10 00 00 MLog.uÛs......
                                                                                  섹터 786,920
          D4 7C BC D5 69 D2 7D 40 9F E8 58 0B 84 41 AA 0D 0140iò}@ŸèX.,,A2.
1803D010
1803D020
          02 00 00 00 00 00 00 00 3D 00 00 00 01 00 00 00
                                                            . . . . . . . . = . . . . . . .
1803D030
          1803D040
                                                            . . . . . . . . . . . . . . . . .
1803D050
          00 00 00 00 78 00 00 00 00 00 00 00 00 00 00
1803D060
          1803D070
          00 00 00 00 00 00 00 00 3D 00 00 00 01 00 00 00
                                                              .....=....
1803D080
          8A 3F 59 A5 00 00 00 00 00 00 00 00 00 00 00 00
                                                            <.....P.....
8...^.....
18030090
          3C 00 00 00 01 00 00 00 50 0F 00 00 00 00 00
         38 00 00 00 88 0F 00 00 02 00 00 00 00 00 00 00
1803D0A0
1803D0B0
          28 02 00 00 08 00 00 00 80 00 00 00 00 02 00 00 00
1803D0C0
          01 00 00 00 38 00 00 00 01 00 00 00 40 00 00 00
                                                             ....8..........................
          1803D0D0
                                                            . . . . . . . . . . . . . . . . . . .
                                                             .....@;°n.Ýÿÿ
1803D0E0
          00 00 00 00 01 10 00 00 40 A1 B0 6E 8D DD FF FF
                                                            H.....h....
0à..0....
1803D0F0
          48 00 00 00 1C 00 00 00 68 00 00 00 18 00 00 00
1803D100
          30 E0 00 00 30 01 00 00 00 00 00 00 00 00 00
1803D110
          \mathbf{00} \ \ \mathbf{00} \ \ \mathbf{00} \ \ \mathbf{00} \ \ \mathbf{06} \ \ \mathbf{00} \ \ \mathbf{00}
1803D120
          20 00 00 80 00 00 00 00 1B 00 00 00 00 00 00 00
                                                             ..€.........
1803D130
          00 00 00 00 00 00 00 00 F8 00 00 00 05 00 00 00
                                                            ....ø....
1803D140
          02 \ 00 \ 00 \ 00 \ 38 \ 00 \ 00 \ 00 \ 02 \ 00 \ 00 \ 00 \ 48 \ 00 \ 00 \ 00
                                                            ....8......H...
          1803D150
                                                            ......8¢°n.Ýÿÿ
          00 00 00 00 00 00 00 00 38 A2 B0 6E 8D DD FF FF
1803D170
          58 00 00 00 1C 00 00 00 78 00 00 00 2A 00 00 00
                                                            X.....*...
1803D180
          A8 00 00 00 30 00 00 00 D8 00 00 00 1E 00 00 00
                                                             ...o...ø.....
          30 E0 00 00 30 01 00 00 00 00 00 00 00 00 00 00
                                                            0à..0.....
1803D1A0
          \mathbf{00} \ \ \mathbf{00} \ \ \mathbf{00} \ \ \mathbf{00} \ \ \mathbf{06} \ \ \mathbf{00} \ \ \mathbf{00}
1803D1B0
          30 01 00 00 80 01 00 00 00 00 00 30 00 01 00 0...€...........
                                                            1.0.0.8.0.2.2._.
1803D1C0
          31 00 30 00 30 00 38 00 30 00 32 00 32 00 5F 00
1803D1D0
          42 00 2E 00 6A 00 70 00 67 00 00 00 00 00 00 00
                                                             B...j.p.g.....
1803D1E0
          01 00 00 00 08 00 00 00 10 00 00 00 1C 00 00 00
                                                             . . . . . . . . . . . . . . . .
                                                            0à..0....
1803D1F0
          30 E0 00 00 30 01 00 00 00 00 00 00
1803D200
          0...1.0.0.8.0.2.
                                                                                  섹터 786.921
1803D210
          30 00 01 00 31 00 30 00 30 00 38 00 30 00 32 00
1803D220
          33 00 5F 00 42 00 2E 00 6A 00 70 00 67 00 00 00 3. .B...j.p.g...
```


[그림 6] 0x02 -> 0x05

이러한 흔적을 확인하고 HxD 에서 살펴보면 다음과 같이 적혀 있다.

```
석터 786.921
1803D210
      30 00 01 00 31 00 30 00 30 00 38 00 30 00 32 00 0...1.0.0.8.0.2.
1803D220 33 00 5F 00 42 00 2E <u>00</u> 6A 00 70 00 67 00 00 00 3._.B...j.p.g...
1803D230 B0 00 00 00 <mark>01 00 00 00</mark> 01 00 00 00 38 00 00 00
                                     °....8....
1803D240 02 00 00 00 40 00 00 00 15 00 00 00 00 00 00 ...@....
1803D260 00 00 00 00 00 00 00 50 00 00 1C 00 00 00
                                     .....P......
1803D280 30 E0 00 00 30 01 00 00 00 00 00 00 00 00 00 0 0à......
. . . . . . . . . . . . . . . . .
                                     ..€......
1803D2A0 20 00 00 80 00 00 00 1B 00 00 00 00 00 00
1803D2C0 OC 00 1A 00 31 00 30 00 30 00 38 00 30 00 32 00
                                     ....1.0.0.8.0.2.
     33 00 5F 00 42 00 2E 00 6A 00 70 00 67 00 FF FF 3. .B...j.p.g.ÿÿ
1803D2D0
```

[그림 7] 0x01

[WHS-2] .iso



[그림 8] 0x04 -> 0x04

0x04에서 데이터가 업데이트 되었고, 바뀐 파일명은 1008023_B.jpg이다.

이러한 구조를 따르며 다른 파일을 모두 검색한 결과 1번의 답은 다음과 같다.

- 1008022_B.jpg -> 1008023_B.jpg
 1012200_B.jpg -> 1012201_B.jpg
 1012377_B.jpg -> 1012378_B.jpg
- 1014394_B.jpg -> 1014398_B.jpg
- 2. 삭제된 파일의 파일명을 나열합니다.

삭제된 파일은 0x0F -> 0x02 -> 0x0F -> 0x02 -> 0x04의 순서를 가지고 있다.






```
섹터 798,456
185DF000
        4D 4C 6F 67 07 75 DB AE 01 00 00 00 00 10 00 00
                                                MLog.uÛ®.....
185DF010
       D4 7C BC D5 69 D2 7D 40 9F E8 58 0B 84 41 AA 0D
                                                Ô|4ÕiÒ}@ŸèX."Aª.
185DF020
        02 00 00 00 00 00 00 00 DF 05 00 00 01 00 00 00
                                                185DF030
        Þ.....
185DF040
        ....x.......
M.^€.....
185DF050
        00 00 00 00 78 00 00 00 00 00 00 00 00 00 00
185DF060
        n. e.
1,õö.,ÿÿß....
¤ã:Ó...^}o.Ýÿÿ
Þ....P....
185DF070
        6C B8 F5 F6 06 82 FF FF DF 05 00 00 01 00 00 00
185DF080
        A4 E3 3A D3 00 00 00 00 88 20 7D 6F 8D DD FF FF
       DE 05 00 00 01 00 00 00 50 0F 00 00 00 00 00
185DF090
185DF0A0
        38 00 00 00 88 0F 00 00 02 00 00 00 00 00 00 00
       185DF0B0
185DF0C0
185DF0D0
        57 00 00 00 00 00 00 00 53 00 00 00 00 00 00
                                                W.....s....
                                                .....!}o.Ýÿÿ
`....€..*..
°....È....
       00 00 00 00 01 10 00 00 A0 21 7D 6F 8D DD FF FF 60 00 00 00 1C 00 00 00 80 00 00 00 2A 00 00 00
185DF0E0
185DF0F0
185DF100
        B0 00 00 00 12 00 00 00 C8 00 00 00 10 00 00 00
185DF110
        D8 00 00 00 04 00 00 00 30 E0 00 00 30 01 00 00
                                                Ø.....0à..0...
185DF120
        . . . . . . . . . . . . . . . . .
185DF130
        00 00 00 00 00 00 00 00 30 01 00 00 80 01 00 00
185DF140
        00 \ 00 \ 00 \ 00 \ 30 \ 00 \ 01 \ 00 \ 31 \ 00 \ 30 \ 00 \ 31 \ 00 \ 33 \ 00
                                                ....0...1.0.1.3.
                                                1.9.1._.B...j.p.
g.p.g.u.€... ...
185DF150
       31 00 39 00 31 00 5F 00 42 00 2E 00 6A 00 70 00
185DF160
        67 00 70 00 67 00 75 00 80 01 00 00 A0 01 00 00
185DF170
        185DF180
       00 00 00 00 00 00 00 00 45 00 00 00 00 00 00
                                                .....E....
185DF190
        00 00 00 00 00 00 00 00 70 00 00 00 04 00 00 00
                                                ....p....p
185DF1A0
        W......
185DF1B0
        57 00 00 00 00 00 00 00 53 00 00 00 00 00 00
185DF1C0
        185DF1D0
        48 00 00 00 20 00 00 00 68 00 00 00 04 00 00 00
185DF1E0
```

[그림 9] 0x07 -> 0x04

삭제의 경우 Redo Free가 발생함으로 0x07 -> 0x04를 찾을 수 있다. ([7. Reference] 참조)



[그림 10] 0x0F -> 0x02



```
98 00 00 00
00 00 00 00
                               00 00 00 38 00 00 00
00 00 00 00 00 00 00
                                                  ....H...W.....
                                                                  섹터 798.465
185E0200
                  48 00 00 00
        185E0210
185E0230
        68 00 00 00 2A 00 00 00 30 E0 00 00 30 01 00 00 h...*...0à...0...
        185E0260
        00 00 00 00 30 00 01
                         00 31 00 30 00 31 00 33 00
185E0270
185E0280
          00 39 00 31
00 00 00 38
                    00 5F 00 42 00 2E 00 6A 00 70 00 00 00 00 88 00 00 00 02 00 00 00
185E0290
        185E02B0
        185E02C0
                    00 00 00 68 00 00 00 1E 00 00 00
185E02E0
        00 00 00 00 00 06 00 00 00 00 00 00 30 00 01 00
        30 00 01
31 00 5F
               00 31 00 30
00 42 00 2E
                         00 31 00 33 00 31 00 39 00 00 6A 00 70 00 67 00 00 00
185E02F0
185E0300
                                                1._.B...j.p.g...
185E0310
        00 01 00 00 08 00 00 00 00 01 00 00 04 00 00 00
                         00 01 00 00 00 48 00 00 00 ...8....H...
00 53 00 00 00 00 00 00 00 W.....S....
185E0320
185E0330
          00 00 00 00 00 00
185E0340
        00 00 00 00 07 10 00 00 00 00 00 00 00 00 00
        185E0360
        185E0370
185E0380
185E0390
        00 00 00 00 10 00 00 00
                            41 F2 49 D6 2E 4F D9 01
                                                  E7 E9 67 EC
E7 E9 67 EC
                    67 D9 01 E7 E9 67 EC AE 67 D9 01 67 D9 01 00 00 00 00 00 00 00 00
185E03A0
                                                 çégì®gÙ.....
¬tÅÁ....
185E03B0
185E03C0
       AC 74 C5 C1 01 00 00 00 00 00 00 00 00 00 00 00
                                                 ......
185E03E0
       . . . . . . . . . . . . . . . . . .
```

[그림 11] 0x0F -> 0x02

```
185E30A0 38 00 00 00 88 0F 00 00 02 00 00 00 00 00 00 00 8...^.....
185E30B0
       00 01 00 00 08 00 00 00 00 01 00 00 04 00 00
185E30C0
       02 00 00 00 38 00 00 00 01 00 00 00 48 00
185E30D0
       185E30E0
       00 00 00 00 03 10 00 00 00 00 00 00 00 00 00
185E30F0
       50 00 00 00 1C 00 00 00 70 00 00 10 00 00 00 P.....p.....
185E3100
       80 00 00 00 74 00 00 00 30 E0 00 00 30 01 00 00
                                           €...t...0à..0...
185E3110
       00 00 00 00 00 00 00 00 30 01 00 00 90 01 00 00
185E3120
185E3130
       00 00 00 00 10 00 00 00 41 F2 49 D6 2E 4F D9 01
185E3140 26 E3 39 FC AE 67 D9 01 26 E3 39 FC AE 67 D9 01
       26 E3 39 FC AE 67 D9 01 00 00 00 00 00 00 00 00
185E3160
       AC 74 C5 C1 01 00 00 00 00 00 00 00 00 00 00 00
                                           ¬tÅÁ.....
185E3170
```

[그림 12] 0x04

위와 같은 방식으로 다른 파일들도 식별한 결과 다음과 같이 정리할 수 있다.

- 1013191_B.jpg
 1012353_B.jpg
 1008103_B.jpg
 1013029_B.jpg
 1014381_B.jpg
- 3. 파일별로 삭제된 시간을 제공합니다.


파일이 삭제된 시간은 삭제된 파일의 부모 디렉터리의 수정 시간으로 알 수 있다. 또한, File deletion에 대한 이벤트 시간은 5번째 레코드의 Change Time을 확인하면 된다. ([7. Reference] 참조)



```
185E0210
185E0220
185E0230
185E0240
185E02B0
185E02C0
185E02D0
185E02E0
185E02F0
                                   185E0300
185E0310
185E0310
185E0320
185E0330
185E0340
185E0350
185E0360
185E0370
            00
                      00
                          00 00 00
185E0380
            00
                 00
                     00
                          30 01 00
185E0390
            00
                 10
                     00
                          41 F2
                               49 D6 2E 4F D9 01
       çégì®gữ.çégì®gử.
çégì®gử.
¬tÅÁ.
185E03A0
185E03B0
```

[그림 13] 0x04

위의 정보로 0x04의 레코드에서 Change Time을 확인할 수 있다. (0x01D967AEEC67E9E7) 또한, 4 번째에 기록되어 있는 것을 알 수 있다.



[그림 14] DCode를 사용하여 시간 확인

DCode를 사용하여 삭제된 파일들에 대한 삭제 시간을 알 수 있다.

위와 같은 방법을 사용하여 삭제된 파일의 시간을 알아본 결과는 다음과 같다.

1013191_B.jpg : 2023-04-05 20:08:17.2343783 (UTC +09:00) 1012353_B.jpg : 2023-04-05 20:08:43.7762854 (UTC +09:00) 1008103_B.jpg : 2023-04-05 20:09:13.4040759 (UTC +09:00) 1013029_B.jpg : 2023-04-05 20:09:38.4102339 (UTC +09:00) 1014381 B.jpg : 2023-04-05 20:10:06.9314698 (UTC +09:00)

[WHS-2] .iso



5. Flag

- 1. 이름이 변경된 파일의 원래 파일명과 변경된 파일명을 나열합니다.
 - A. 1008022_B.jpg -> 1008023_B.jpg
 - B. 1012200_B.jpg -> 1012201_B.jpg
 - C. 1012377_B.jpg -> 1012378_B.jpg
 - D. 1014394_B.jpg -> 1014398_B.jpg
- 2. 삭제된 파일의 파일명을 나열합니다.
 - A. 1013191_B.jpg
 - B. 1012353_B.jpg
 - C. 1008103_B.jpg
 - D. 1013029_B.jpg
 - E. 1014381_B.jpg
- 3. 파일별로 삭제된 시간을 제공합니다.
 - A. 1013191_B.jpg: 2023-04-05 20:08:17.2343783 (UTC +09:00)
 - B. 1012353_B.jpg: 2023-04-05 20:08:43.7762854 (UTC +09:00)
 - C. 1008103_B.jpg: 2023-04-05 20:09:13.4040759 (UTC +09:00)
 - D. 1013029_B.jpg: 2023-04-05 20:09:38.4102339 (UTC +09:00)
 - E. 1014381_B.jpg: 2023-04-05 20:10:06.9314698 (UTC +09:00)





4. 별도 첨부

- 문제 번역본

케이트는 패션 디자인 회사의 서버 관리자로 최근 서버에 저장된 디자인 파일이 유출되는 사건이 발생하여 회사 내에서 내부 감사를 받았습니다. 회사는 이 문제를 해결하기 위해 서버 볼륨에 대한 디지털 포렌식 분석을 요청했습니다. 각 질문에 대한 분석 결과를 제공해 주시기 바랍니다.

- 1) 이름이 변경된 파일의 원래 파일명과 변경된 파일명을 나열합니다. (50점)
- 2) 삭제된 파일의 파일명을 나열합니다. (50점)
- 3) 파일별로 삭제된 시간을 제공합니다. (100점)

OJE해 스쿨

WhiteHat School

5. Reference

- https://www.dfrws.org/wp-content/uploads/2021/01/2021_APAC_paper-forensic_analysis_of_refs_journaling.pdf