

Performance Report for:
https://nina-carducci.github.io/

Report generated: Wed, Feb 19, 2025 6:00 AM -0800
Test Server Location: Vancouver, Canada
Using: Chrome 117.0.0.0, Lighthouse 11.0.0

D	Performance 54%	Structure 79%	L. Contentful Paint 897ms	T. Blocking Time 384ms	C. Layout Shift 0.43
---	--------------------	------------------	------------------------------	---------------------------	-------------------------

Top Issues


High	Avoid enormous network payloads LCP	Total size was 29.7MB
Med	Properly size images	Potential savings of 22.1MB
Med	Use explicit width and height on image elements CLS	4 images found
Med	Serve static assets with an efficient cache policy	Potential savings of 27.1MB
Med	Avoid large layout shifts CLS	5 elements found

Focus on these audits first

These audits likely have the largest impact on your page performance.

Structure audits do not directly affect your Performance Score, but improving the audits seen here can help as a starting point for overall performance gains.

Page Details



How does this affect me?

Modern web users have a short attention span and expect a fast and seamless website experience. Delivering that fast experience can result in more traffic, more conversions, and more happiness.

As if you didn't need more incentive, **Google use Page Speed and Page Experience (including Web Vitals) signals in their ranking algorithm.**

About GTmetrix


GTmetrix

GTmetrix was developed as a tool for customers to easily test the performance of their webpages.

[Learn more about us.](#)

The waterfall chart displays the loading behaviour of your site in your selected browser. It can be used to discover simple issues such as 404's or more complex issues such as external resources blocking page rendering.





Performance Metrics

First Contentful Paint How quickly content like text or images are painted onto your page. A good user experience is 0.9s or less.	Good - Nothing to do here 289ms	Time to Interactive How long it takes for your page to become fully interactive. A good user experience is 2.5s or less.	Good - Nothing to do here 865ms
Speed Index How quickly the contents of your page are visibly populated. A good user experience is 1.3s or less.	Much longer than recommended 3.9s	Total Blocking Time How much time is blocked by scripts during your page loading process. A good user experience is 150ms or less.	Much longer than recommended 384ms
Largest Contentful Paint How long it takes for the largest element of content (i.e., a hero image) to be painted on your page. A good user experience is 1.2s or less.	Good - Nothing to do here 897ms	Cumulative Layout Shift How much your page's layout shifts as it loads. A good user experience is a score of 0.1 or less.	Much more than recommended 0.43

Browser Timings

Redirect	0ms	Connect	41ms	Backend	9ms
TTFB	50ms	DOM Int.	204ms	DOM Loaded	207ms
First Paint	289ms	Onload	1.5s	Fully Loaded	1.7s

IMPACT	AUDIT	
High	Avoid enormous network payloads LCP	Total size was 29.7MB
Med	Properly size images	Potential savings of 22.1MB
Med	Use explicit width and height on image elements CLS	4 images found
Med	Serve static assets with an efficient cache policy	Potential savings of 27.1MB
Med	Avoid large layout shifts CLS	5 elements found
Low	Efficiently encode images	Potential savings of 1.91MB
Low	Eliminate render-blocking resources FCP LCP	Potential savings of 80ms
Low	Serve images in next-gen formats	Potential savings of 8.83MB
Low	Avoid long main-thread tasks TBT	2 long tasks found
Low	Reduce unused JavaScript LCP	Potential savings of 29.0KB
Low	Reduce unused CSS FCP LCP	Potential savings of 25.5KB
Low	Avoid chaining critical requests FCP LCP	10 chains found
Low	Defer offscreen images	Potential savings of 8.57MB
Low	Minify CSS FCP LCP	Potential savings of 5.19KB
Low	Minify JavaScript FCP LCP	Potential savings of 16.3KB
N/A	Reduce JavaScript execution time TBT	32ms spent executing JavaScript
N/A	Largest Contentful Paint element LCP	900 ms
N/A	Reduce initial server response time FCP LCP	Root document took 8ms
N/A	Avoid an excessive DOM size TBT	131 elements
N/A	Reduce the impact of third-party code TBT	Third-party code blocked the main thread for 381ms
N/A	Minimize main-thread work TBT	Main-thread busy for 833ms
N/A	Avoid serving legacy JavaScript to modern browsers TBT	
N/A	User Timing marks and measures	