

Waymo FRONT camera ($k_1=0.0407$, $k_2=-0.3374$, $p_1=0.0016$, $p_2=-0.0008$)

(a) Distorted (raw Waymo)



(b) Undistorted (OpenCV, our fix)




(d) Corner crop, distorted



(e) Corner crop, undistorted



(c) Pixel displacement
max = 29.4 px, RMS = 3.87 px



(f) Displacement vectors (corner)

