


SECURED RIM & -CLEANOUT WITH ADJUSTABLE COLLAR SCORIATED COVER-**FINISHED** -ADJUSTABLE COLLAR FLOOR— INSIDE CAULK CONNECTION SHOWN WITH JOINT GASKET-CLEANOUT PLUG -BALANCE OF PIPING SAME AS CLEANOUT TO GRADE

5 FLOOR CLEANOUT NOT TO SCALE






7 WALL CLEANOUT NOT TO SCALE




NOTE: INSTALL HANGER ON OUTSIDE OF INSULATION. DO NOT INSULATE OVER

8 TYPICAL PIPE HANGER DETAIL NOT TO SCALE




ADA TUB AND SHOWER 1 REQUIREMENTS


NOT TO SCALE




2 SHOWER DRAIN NOT TO SCALE





3 CLEANOUT DETAIL NOT TO SCALE



4 EXTERIOR GRADE CLEANOUT · NOT TO SCALE







genesis engineering

group, llc. 134 fourth avenue north franklin, tn 37064 project #: 23-168

genesis

E S L