





DETAIL A — OWNER ENSUITE (latest FCStd; no changes)
WC front = -120.8 mm
D-CLK overlap = 45,504.3 mm²
minimum translation is report-only
WC footprint
door/opening
Task01 Y (mm)
Task01 X (mm)
6500
6000
5500
5000
4500
9000
9500
10000
10500
11000
11500



DETAIL B — MOTHER BEDROOM + MOTHER BATH
bed side = 173.6 mm
WC front = -71.1 mm
minimum translations report-only
Task01 Y (mm)
Task01 X (mm)
0
1000
2000
3000
4000
5000
6000
12000
13000
14000
15000
16000


DETAIL C — GUEST BATH
3kg WASHER = MISSING HUMAN GUIDE
No position invented
11000
10500
10000
9500
9000
8500
8000
Task01 Y (mm)
8000
8500
9000
9500
Task01 X (mm)


DETAIL D — MIDDLE GUEST ROOM
11000
10500
10000
9500
9000
8500
8000
Task01 Y (mm)
10000
10500
11000
11500
12000
12500
13000
Task01 X (mm)
foot 1437.8 mm
left 1034.6 mm
right 215.4 mm
1.2


DETAIL E — BALCONY DOOR / WARDROBE CONFLICT
G-GB-BALC opening
wardrobe overlap = 22,014.6 mm²
minimum movement report-only
Task01 Y (mm)
11200
11000
10800
10600
10400
10200
10000
10000
10500
11000
11500
12000
12500
Task01 X (mm)


DETAIL F — STUDY
Printer/NAS = MISSING GUIDE
No location invented
11000
10000
9000
8000
7000
Task01 Y (mm)
13000
13500
14000
14500
15000
15500
16000
Task01 X (mm)


DETAIL G — NORTH BALCONY / LAUNDRY
HUMAN_LOCKED stacked washer/dryer + freezer
Generic envelope overlay only
service / power / drainage = TO_VERIFY
13500
13000
12500
12000
11500
11000
10500
Task01 Y (mm)
8000
9000
10000
11000
12000
13000
Task01 X (mm)