

Silverline Power infrastructre pvt. ltd.

Regd. Office:100, GIDC Estate, Por Ramangamdi - 391243, Dist.

Vadodara, Gujarat.

Tel: +91 - 265 - 2830065, 2830754 E-mail: info@silverlinepower.com Website: www.silverlinepower.com

Corporate Indentity No.: U45207GJ2009PTC056480 Dt. 31-03-2009

GSTIN: 24AAMCS9275L1ZK

COMPLIANCE REPORT

Reference: PO No: 04/006390/20200335, Dated: 31/07/2020

Amendment Date: 17.03.2021

Inspection Date: 29.04.2021 & 13.05.2021

IVR NO: 010112014920/37 (8116167470)

Dear Sir,

With reference to Inspection dated 13-05-2021, we here with submit our compliance & Photos are as under.

Sr. No.	COMMENTS	OUR COMPLIANCE
3r. No.	a) Visual inspection carried out for ladder and perforated type cable tray lot wise (one sample each from a lot of 100 Nos) found burr in slot corner, bend portion in covers, ladder tray & perforated trays galvanizing lumps etc. observed which needs to be	1) Burrs in Slot Corner are Removed 2) Bends cover are repaired and checked with Fitment with the Cable tray and Clamp. 3) Galvanizing Lumps are removed after fitment no bends is observed from Cable
	rectified before dispatch of material	Tray and Covers.

FOR SILVERLINE POWER INFRASTRUCTURE PVT. LTD.

(Authorized Signatory)





1) Burrs in Slot Corner are Removed:





2) Bends cover are repaired and checked with Fitment with the Cable tray and Clamp.





3) Galvanizing Lumps are removed:

