INSPECTION VISIT REPORT



IVR - 8118167190 - 001 - Rev. 00

Gener	al:												
TUV India Control Or SAP Number:		8118167 ⁻	8118167190			Branch:			Mumbai				
Notification Name / Number:		email Dtd. 19/08/2021		Date(s)	Date(s) of Inspection:			20 & 21.08.2021					
Project Name & Location:		make was E308157) E308157	R&R of the existing Chinese make waste gas ESP(OC no E308157) E308157 -TATA LONG_SINTER ESP			Inspection Location:			AUTODATA, D240, TTC Ind. Area, sion - Panvel Exp., MIDC Industrial Area, Shiravane, Nerul, Navi Mumbai, Maharashtra, India				
TUV In	ndia Client Na	me:	ENVIRO I	THERMAX LIMITED - ENVIRO DIVISION IC NO 179878			End User Name:			TATA Steel Long Products Limited			
DEC /	PMC / EPC Na ble)	ame:	Not Appli	Not Applicable		Asgmt. I	DEC / PMC / EPC Asgmt. Number: (If applicable)			Not Applicable			
Vendo	r Name & Loc	cation:	Area, sion MIDC Inde Shiravane	AUTODATA D240TTC Ind. Area, sion - Panvel Exp., MIDC Industrial Area, Shiravane, Nerul, Navi Mumbai, Maharashtra, India			P.O. Number: (Client PO on Vendor)		PO. 124780 dated 24.05.2021				
(If applica	·		Not Applic	Nat Applicable			P.O. Number: If applicable – Vendor PO on Sub /endor)		Not Applicable				
Stages	of Inspection	n:											
	Kick Off / Pre I	nspection N	/leeting	eeting			eation \square		Interim Stages				
I	Document Rev	iew			☑ Final Insper	ection				Re-In	spection	n	
Item D	escription:	T							1		ı		,
P.O. Item Item Code Item Description		cription	iption				UOM	P.O. Qua	O. Offer Quan			Acceptable Quantity	
1 ELAK0016 THREE PH 26 (IC No 179		79878)	,				Nos.	02	2 02				
2 ELAK0016 Manual HT 25		T.Earth Switch for 83KV/1205mA HFTR			HFTR		Nos	02	02 02				
Refere	nce Documer	nts:											
Sr. No.	Document N	lame CI	ient Docume	nt I	Number	Vend	or	Docume	nt Nun	nber		Appr	oval Status
1)	PR / MR / AF	RM No	t Applicable			Not A	pp	olicable				Not A	pplicable
2) QAP / ITP / QCP TL/ENV/			NV/QAP-FAB/E308157 Rev. No.			Not Applicable				Approved by Thermax Ltd Dtd. 22/06/2021			
3) Drawing(s)			08157507 Rev 01 08157506 REV 01			Not Applicable					Approved in Code-A by Thermax Ltd Dtd 18/06/2021 Approved By Thermax Dtd 21.07.2021		
4)	Procedure(s,) No	ot Applicable			Not Applicable				Not Applicable			
5)	Datasheet(s)) No	ot Applicable				ot Applicable				Not Applicable		
6)	Others (Specify) No	ot Applicable			Not A	Not Applicable			Not Applicable			
Inspec	tion Activities	s Carried C	Out :										
Stages	s Witnessed:												

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way, legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT





Inspection carried out as per approved QAP, Design datasheet & result found acceptable. For details refer attached witness report Dtd. 20 & 21/08/2021 (100% Inspection done as per approved QAP).

THREE PHASE TR SET & TRCC 95KV, 1300MA Witnessed Serial no. - 3Φ21706, 3Φ21707.

Manual HT.Earth Switch for 83KV/1205mA HFTR - Part CAT No ELAK001625 OC NO E308157 (02 Nos) FABRICATED ITEMS

As per QAP Clause no. 3) HV Duct With TR set base frame

- a) Raw Material: Mech. & Chem. Properties. Test report review.
- b) Visual Found satisfactory w.r.t approved datasheet.
- c) Dimensional Found satisfactory w.r.t approved datasheet Drawing.
- d) Surface Preparation & Painting Found satisfactory w.r.t approved datasheet Drawing

BOUGHTOUT ITEMS

As per QAP Clause no. 3) TR Set & TRCC

- a) Raw Material: Mech. & Chem. Properties. Test report review.
- b) Visual Found satisfactory w.r.t approved datasheet.
- c) Dimensional Found satisfactory w.r.t approved datasheet Drawing
- d) H.V. & Megger Test Found satisfactory w.r.t approved datasheet Drawing
- 1) e) Simulation Test Found satisfactory w.r.t approved datasheet & drawing
 - f) Spark Test Found satisfactory w.r.t approved datasheet Drawing
 - g) Open Circuit Test Found satisfactory w.r.t approved datasheet & drawing
 - h) Short Circuit Test at Rated Output current Found satisfactory w.r.t approved datasheet & drawing
 - i) Load Regulation Test at 100% Rating Found satisfactory w.r.t approved datasheet & drawing
 - j) Functional Test (Checking Parameter Settings, All Alarms & Faults) Found satisfactory w.r.t approved datasheet & drawing
 - k) Measurement of Feedback Resistor. Found satisfactory w.r.t approved datasheet & drawing
 - I) Oil level check for Tank Found satisfactory w.r.t approved datasheet & drawing
 - m) Oil dielectric strength found more than 60 KV/2.5 mm Found satisfactory w.r.t approved datasheet & drawing
 - n) Pressure test applied at 0.5 bar for holding time 20 minutes No Leakage / No pressure drop observed during holding time
 - o) Paint shade verified with paint shade card & found RAL 7032 and Thickness found greater than 50 & 60 microns for Panel & TR set respectively.

As per QAP Clause no. 5) Electrical Access., Instruments & Mechanical Miscellaneous items & Instruments - Review of manufacturers TC (Calibration & Type test report As Applicable)

Visual Verification of Earthing unit, Operation Panels & TR Set found acceptable as per GAD.

Documents Reviewed:

Following documents were reviewed as per approved QAP & found in order;

As per QAP Clause no.1b) Test certificate of Bought out item as provided by the supplier Found to meet material specification requirements.

All measuring instruments/ equipment were verified for continued suitability for intended use, proper identification, calibration status, traceability to national standards & found satisfactory.

Details of Equipment(s) / Instrument(s) used for measuring / testing during Inspection: (Refer Notes)

Sr. No.	Detail of Equipment(s) /	Range	ID	Validity till Date	Calibration Certificate	NABL / OTHER CERT. BODIES / NABL Traceability	NON-NABL
	Instrument(s)				Number	Please tick whichev See Note 1 & 2	er is applicable See Note 3
1	Calibration status Attached					✓	

Notes:

1)

- 1) Other Certifying bodies are: NPL-India, CIPM (International Committee for Weights & Measures), ILAC & APLAC MRA Signatories
- Visiting inspector to ensure continued suitability for intended use, periodic maintenance, proper identification and valid calibration records and traceability to known National / International standards of the measuring Instrument(s) / testing equipment(s).
 Non NABL: If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only
- to technical content in the calibration certificate.

4) In lieu of table above inspectors may collect master list from manufacturer / vendor/ sub vendor with all above details clearly highlighting the details of instrument(s) / equipment(s) used during inspection.

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / English (Supplier / Manufacturer / Stockiest from their responsibility towards the Client / English (Supplier / Manufacturer / Stockiest from their responsibility towards the Client / English (Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / Supplier / Manufacturer / Stockiest from their suppl

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT



IVR - 8118167190 - 001 - Rev. 00

Conclusion	(Accentable)	Not Accentable	Accentance s	ubject to)

M/s. Autodata to obtain acceptance from the client for the observations as mentioned in Area of concern.

Pending Activities from this Visit:

Identification of Inspected Item(s):

Soft Stamped as " (Test sample selected double) on Witnessed HFTR Panel.

Areas of Concern:

- 1) Final touch up paint to be done wherever required before despatch.
- 3) As per approved QAP Raw Material: Mech. & Chem. Properties. Test report to be submitted (For CRCA sheets & Bus Bar)
- 4) Castel Key Interlock is in client scope.
- 5) Charge Ratio internally check by Manufactured.
- 13) BOM to be AS BUILT for
- a) Uninyvin 00
- b) 6" FAN & Filter
- c) terminal block QTY 84 instead of 67 Nos
- d) CT Ratio observed 200/5A 5VA Class 0.5 instead of 250/5A 10 VA.Class 1
- e) CT Make observed NEWTEK instead of RECO.
- f) Ammeter observed 200/5A instead of 250/5A.
- g) Thyristor Assembly THY-0721-1300-02
- h) Verified BOM attached.

HV Duct With TR set base frame

- 1) Stand as per approved drg 160mm required, Observed 170mm.
- 2) IP -55 for marshalling Box declared by vendor.

Non Conformities raised / Discrepancies observed during Inspection (If Any, Mention TUV India NCR Number):

None

Atta	chments:						
Ø	Inspection records – Total Page Nos.	1set	Ø	Master List of calibrated Instruments / equipment 1set			
V	Inspection Photos – Refer Page Nos.	3 to 12	☑	Others (Specify): None.			
Autl	horised Signatures:						
TINAL P. L. C. C. C.			Wester (O. I. Wester December 1997)				

TUV India Inspector(s):		Vendor / Sub Vendor Representative: (If Applicable)		
Name: Milind Surve	Date: 21-08-2021	Name: Mr. Satish Chavan		

Distribution List: ☑ TUV India Client / End User ☑ TUV India Executing / Originating Branch ☑ Vendor / Sub Vendor

Revision Number (If Applicable): 00 - Type Reason for revision here This Document Supersedes IVR No.: Mention Previous IVR Number.

Inspection Pictures:

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

Disclaimer: Inis IVR shall not be considered as final acceptance of inspected item(s). The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any wayle legally responsible for genuineness of the material / item(s) and document(s), if the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT

IVR - 8118167190 - 001 - Rev. 00






TRCC Panel

TR Verification






HV 3Φ T/R SALES ORDER # 15-5688-02 SERIAL # DC OUTPUT 95 kVP/1300 mA AC INPUT 415VAC,50Hz,3Ø AC INPUT CURRENT 183 A AC INPUT POWER 132 kVA MFG. DATE 2021/08 ACTIVE WEIGHT 780 kg 50 °C COOLING TYPE OIL VOLUME IS: 335 TOTAL WEIGHT 1838 kg

TAG Plate verification

TAG Plate verification





Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / Item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / Item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way legally responsible for genuineness of the material / Item(s) and document(s). If we calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate. Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT









HV TEST



HV TEST



Paint thickness verification



Paint Shade check

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way! legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT









Feedback check

Dimension check





Dimension check

Dimension check





Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way! legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT









Function check Short CKT test





Feed back check







Spark Test

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

Discalamer: Inis IVK shall not be considered as final acceptance of inspected item(s). The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / Item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / Item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any wayle (geally responsible for genuineness of the material / Item(s) and document(s), if the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.


Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT


IVR - 8118167190 - 001 - Rev. 00








Cable gland as per BOM Rapper check





Alarm Check Alarm Check





Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

Discalamer: Inis IVK shall not be considered as final acceptance of inspected item(s). The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / Item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / Item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any wayle (geally responsible for genuineness of the material / Item(s) and document(s), if the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT

IVR - 8118167190 - 001 - Rev. 00






INPUT SUPPLY
PHASE SEQUENCE
REVERSE TRCC TRIP

Induced Over voltage.

Reverse polarity check





Door thickness check

Cable gland plate dimension check





Dimension check

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the document, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT

IVR - 8118167190 - 001 - Rev. 00








C.R Check

Duct.





Pressure test

Earth switch check







Earth Switch check Earth Switch check

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way! legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT


IVR - 8118167190 - 001 - Rev. 00





Dimension check

Dimension check





Dimension check

Dimension check





Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / Item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / Item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way legally responsible for genuineness of the material / Item(s) and document(s). If we calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.


Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.

INSPECTION VISIT REPORT

IVR - 8118167190 - 001 - Rev. 00







End of Report

Disclaimer: This IVR shall not be considered as final acceptance of inspected item(s). The final acceptance will be given through Inspection Release Note.

The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way! legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Pvt. Ltd. and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.