



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Audit Report

Audit Details

Audit #	10425	Audit Type Iteration	1st Audit
Auditor	Channy Sok	Auditor User Group	MF - BV
Quality Plan Name			
AUDIT REPORT - PRINCIPLE 01 : COMPLIANCE WITH LAWS AND WORKPLACE REGULATIONS		AUDIT REPORT - PRINCIPLE 02 : PROHIBITION OF FORCED LABOR	
AUDIT REPORT - PRINCIPLE 03 : PROHIBITION OF CHILD LABOR		AUDIT REPORT - PRINCIPLE 04 : PROHIBITION OF HARASSMENT AND ABUSE	
AUDIT REPORT - PRINCIPLE 05 : COMPENSATION AND BENEFITS		AUDIT REPORT - PRINCIPLE 06 : HOURS OF WORK	
AUDIT REPORT - PRINCIPLE 07 : PROHIBITION OF DISCRIMINATION		AUDIT REPORT - PRINCIPLE 08: HEALTH AND SAFETY	
AUDIT REPORT - PRINCIPLE 09: FREEDOM OF ASSOCIATION & COLLECTIVE BARGAINING		AUDIT REPORT - PRINCIPLE 10: ENVIRONMENT	
AUDIT REPORT - PRINCIPLE 11: CUSTOMS COMPLIANCE		AUDIT REPORT - PRINCIPLE 12: SECURITY	
AUDIT REPORT SUMMARY		DETAILED REPORT	
Report	WRAP - Audit Report		
Factory			
Company Name	Yorkmars (Cambodia) Garment Mfg Co. Ltd	Description	Knitted Garments
Address Line 1	Preytea Village, Sangkat Choam Chao, Khan Porsenchey,	City	Phnom Penh
Country	Cambodia	ZIP Code	120911
Phone 1	+855 92 51 11 72	Email	nicole.mer@yorkmars.com
Website URL	https://yorkwellasia.com.hk/	Contact Name	Vann Socheata
Contact Number	+855 92 51 11 72	WRAP ID	14374

Conclusion

Audit Grade

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

N/A

✓ The auditor confirmed that the answers contained in this report have been answered to the best of their knowledge and all sections have been completed.

Photos 

Images

Part A: General view of the facility (25 Photos)

Facility name



Building view & gate



Security guards, gate house & entrance



Inside compound



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Production process



Cutting

Production process



Sewing

Production process



Ironing

Production process



Inspecting

Raw materials warehouse



Medical room (If present)



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Dining area



Kitchen/Food preparation area



Childcare room (If present)



Grievance/Suggestion box



Stairs



Stairs



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed


Dormitory/apartment building



Dormitory room/apartment room (if present)




CCTV screenshot of production floor weekly rest day photo 1 (List rest day date)



Weekly rest working on Aug 11, 2024

CCTV screenshot of production floor weekly rest day photo 2 (List rest day date)



Weekly rest working on Sept 15, 2024

Other



Accessory warehouse

Other



Washing section

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Other



Overview at site 2

Other



Factory name at site 2

Workers' Punching In/Out



PART B: Health & safety (42 Photos)

PPE (Personal protective equipment)



PPE (Personal protective equipment)



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Electrical box/cabinet with cover & warning signs



Electrical box/cabinet with wiring



Electrical box/cabinet with inner cover




Fire safety training noting training date



First aid responders/emergency safety personnel



Material safety data sheet (MSDS)



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

First aid box



Evacuation plan



Evacuation drill noting drill date (Photo 1)



Evacuation drill noting drill date (Photo 2)



Evacuation route



Evacuation route



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Emergency exit door



Emergency exit door



Emergency exit sign & emergency lights



Emergency exit sign & emergency lights



Assembly point



Fire extinguishers



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Fire extinguishers



Fire hydrant



Fire hose



Sprinkler (if applicable)



NA. Factory did not have sprinkler which was not required by local law.

Smoke detector



Fire alarm box



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Chemical storage/labeling



Chemical storage/labeling



Boiler



Compressor



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Machine safety warning label/Device



Sewing machine safety guard



Dorm/Apt. evacuation route (if present)



Dorm/Apt. emergency exit door



N/A. No exit door because out of the room is evacuation root lead to exit stair case or open area.

Dorm/Apt. emergency exit sign & emergency lights



Dorm/Apt. fire extinguisher (if present)



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Dorm/Apt. fire alarm



Dorm/Apt. stairs



Other



Toilet room

Other



Drinking water

Other



Waste house

Other



Generator room

PART C: Principle 12 Security (14 Photos)

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Perimeter fencing



Container storage (if applicable)



NA. Factory did not have Container storage area.

Employee parking



Visitor parking



Outside lighting



IT security room/communication equipment



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

CCTV & monitors



Packing area



Finishing goods warehouse



Loading area



Visitor log

ប្រតិបត្តិការចូលចេញពីសមាគមក្រុមហ៊ុន


VIP Visitor Log

04-2

No	Date	Visitor Name	ID Card No. (Photo)	Company Name	Purpose of visiting	Signature of Visitor	Signature of Host	Time In	Time Out	Remarks
1	16/12/2024	Chany	04432	RV	Audit	[Signature]	[Signature]	09:15	10:30	
2	16/12/2024	Leah	112	ITS	IT	[Signature]	[Signature]	10:44	11:55	
3	16/12/2024	Leah		ITS	IT	[Signature]	[Signature]	12:00	12:30	
4										
5										
6										
7										
8										
9										
10										

16/12/2024 10:13

Other



Password log in was required.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Other



Seal cabinet

Other



Camera at packing section

PART D: Non-compliances (9 Photos)

NC raised & respective audit question #



8.62-Observed workers did not use eye-shield while working with overlock machines at sewing section.

NC raised & respective audit question #



8.62-Observed workers did not use needle guard when working.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

NC raised & respective audit question #



8.20&8.40-Observed exit aisles were partially blocked by tables, machines, chairs and material at sewing section and packing section

NC raised & respective audit question #



8.20&8.40-Workers at sewing line 18 were blocked from all sides at their working station by sewing machines and garments.

NC raised & respective audit question #



8.31-Observed electric panel at material warehouse and generator room were not equipped with inner covers.

NC raised & respective audit question #



8.52-Liquid chemical containers at repairing room, generator area, waste house was not stored in secondary container to prevent leakage and spill.


Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Other



8.54-Chemical containers were not labelled at waste house and generator area.

Other



12.5.6-The CCTV records good warehouse, packing section, loading area were maintained for 15 days instead of at least 30 consecutive days. The record was maintained from Dec 2, 2024, to Dec 16, 2024.

Other



OB-8.40e-The factory installed a locking mechanism to ensure sliding doors always open during working time.

PART E: Proof of non-compliances closure (9 Photos)

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Proof of non-compliances closure

Proof of NC# 6.8a: One day off after six consecutive days work was provided to employee in December 2024.

Proof of non-compliances closure



Proof of NC# 8.20&8.40c: The emergency exit aisles at sewing section freely accessible during working time.

Proof of non-compliances closure

Proof of NC# 6.8a: One day off after six consecutive days work was provided to employee in January 2025.

Proof of non-compliances closure



Proof of NC# 8.20&8.40c: The workplace at sewing section freely accessible during working time.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Proof of non-compliances closure




Proof of NC# 8.20&8.40c: The emergency exit aisles at packing section freely accessible during working time.

Proof of non-compliances closure



Proof of NC# 8.20&8.40c: The emergency exit aisles at packing section freely accessible during working time.

Other



Proof of NC# 8.20&8.40c: The fire safety awareness training was provided to employees on January 18, 2025.

Other



Proof of NC# 8.28: Employee wearing personal protective equipment during working.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Other



Proof of NC# 8.28: Employee wearing facemask during working.

Others (23 Photos)

Photos photos 1



Proof of NC# 8.31: The inner isolator has been installed to electrical box at raw material warehouse and generator room.

Photos photos 2



Proof of NC# 8.52: All liquid chemical at repairing room were stored in the secondary containment.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Photos photos 3




Proof of NC# 8.52: All liquid chemical at generator room were stored in the secondary containment.

Photos photos 4



Proof of NC# 8.52: All liquid chemical at waste house were stored in the secondary containment.

Photos photos 5



Proof of NC# 8.52: The chemical spilled awareness training was provided to employees on January 30, 2025.

Photos photos 6



Proof of NC# 8.54: Proper label in local language was setup for all liquid storage in the generator room.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Photos photos 7



Proof of NC# 8.54: Proper label in local language was setup for all liquid storage in the waste house.

Photos photos 8



Proof of NC# 8.62: Employees who working with over-lock machine using eye-shield during working.

Photos photos 9



Proof of NC# 8.62: Employees who working with single needle machine using needle guard during working.


Photos photos 10



Proof of NC#8.62: The health & safety awareness training was provided to employees on December 21, 2024.


Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Photos photos 11



Proof of NC# 12.4.7: The data back-up was setup once a week, the latest of back-up was found on February 15, 2025.


Photos photos 12



Proof of NC# 12.4.7: The data back-up policy was updated on January 02, 2025.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Photos photos 13



Proof of NC# 12.4.7: The data back-up policy was updated on January 02, 2025.

Photos photos 14



Proof of NC# 12.5.6b: The CCTV record was recorded more than 30 consecutive days, it was 53 days start from December 31, 2024 until the assessment date (February 21, 2025).

Photos photos 15



Proof of NC# 12.5.6b: CCTV record at packing section in January 03, 2025.

Photos photos 16



Proof of NC# 12.5.6b: CCTV record at packing section in January 12, 2025.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Photos photos 17



Proof of NC# 12.5.6b: CCTV record at packing section in February 02, 2025.

Photos photos 18



Proof of NC# 12.5.6b: CCTV record at finished goods warehouse in February 2, 2025.

Photos photos 19



Proof of NC# 12.5.6b: CCTV record at finished goods warehouse in February 9, 2025.


Photos photos 20



Proof of NC# 12.5.6b: CCTV record at finished goods warehouse in February 16, 2025.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Photos photos 21



Proof of NC# 12.5.6b: CCTV record at loading area in January 05, 2025.

Photos photos 22



Proof of NC# 12.5.6b: CCTV record at loading area in January 19, 2025.

Photos photos 23



Proof of NC# 12.5.6b: CCTV record at loading area in January 31, 2025.

Quality Plan ([AUDIT REPORT SUMMARY](#)) 

Audit Summary

A. Facility name: (in English & local language, if needed)	Describe
Name (English): YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. Name (Local Language): យ៉កម៉ាស (ខេមបូឌា) ហ្គារ៉ាម៉េន អ៊ិមអេហ្វធី	
B. Facility address covered by the audit: (in English & local language, if needed)	Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Address (English): PHUM TRAPAING CHHREY, SANGKAT KAKAB, KHAN PORSENCHEHY, PHNOM PENH, CAMBODIA.

Address (Local Language): #០២៨៧ ផ្ទះលំ ភូមិត្រពាំងជ្រៃ សង្កាត់កាកាប ខណ្ឌពោធិ៍សែនជ័យ រាជធានីភ្នំពេញ កម្ពុជា។

C. Facility WRAP ID #:

Describe

14374

D. Facility type:

Renew Certification

N/A

E: Audit Date(s):

Initial Audit

Additional Follow-up Dates

December 16-18, 2024

Follow-Up Audit on February 21-22, 2025

F. Was the audit conducted on consecutive dates? If No, explain

Yes

N/A

G. Denied access (during this certification cycle)?

No

N/A

H. Audit result/report type:

Recommendation

N/A

I. Monitoring firm name & address:

Describe

Bureau Veritas (Cambodia) Limited.

#1186, St.371 (Sola), Sangkat Steung Meanchey, Khan Meanchey, Phnom Penh, Cambodia.

J. Monitoring firm APSCA#:

Describe

11600002

K. Lead auditor's name, APSCA designation & #:

Describe

Han Le (CSCA 21703042)

Follow-Up Audit on February 21-22, 2025: Channy SOK (CSCA217-2189)

L. The above audit conducted at this facility found that:

The facility was compliant with WRAP Principles

Refer to the Corrective Action Plan for details.

M. Did auditor(s) explain to facility WRAP's working hour & transparency/integrity policies?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

N/A

N. Did auditor(s) explain to facility WRAP's Working Hour Action Plan?

Yes

N/A

O. Was there a Working Hour Action Plan (WHAP) from last certification cycle?

No

N/A

P. Did auditor(s) explain to facility WRAP's Zero Tolerance Policy for facilities & monitors?

Yes

N/A

Q. Name & title of facility representative:

Describe

Mr. Sunny Chui-General Manager

Follow-Up Audit on February 21-22, 2025: Mr. Sunny Chui-General Manager

R. Names & titles of other attendees at the Closing Meeting:

Describe

Bureau Veritas (Cambodia) Limited:

1.Han LE – Lead Auditor

2.Theary LEANG – (Translator)

YORKMARS (CAMBODIA) GARMENT MFG CO., LTD.:

1.Mr. Gamini-Compliance Manager

2.Mr. Sok Moyukeo-HR Supervisor

3.Ms. Vann Socheata-Compliance Supervisor

4.Mr. Pich Daly-Compliance Assistant

Follow-Up Audit on February 21-22, 2025:

Bureau Veritas (Cambodia) Limited:

1. Channy SOK – Lead Auditor

YORKMARS (CAMBODIA) GARMENT MFG CO., LTD.:

1.Mr. Gamini-Compliance Manager

2.Mr. Sok Moyukeo-HR Supervisor

3.Ms. Vann Socheata-Compliance Supervisor

1.Mr. Pich Daly-Compliance Assistant

Quality Plan ([DETAILED REPORT](#)) 



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Part A: Facility Details

1. Does the facility have a business license?	Yes (List license no.)
License no.: 00005041 and original business registration number MOC-10308684 issued by Ministry of Commerce on June 21, 2012, with unspecified expiry date.	
2. Is the registered business name and site address the same as the audited facility? (If no, explain and provide registered name and address)	Yes
3. Does the business license include other businesses/facilities/sites? (If yes, provide explanation)	No
4. Does the facility have a parent company or belong to a corporate group? If Yes, provide name and address	No
5. Does the facility have any sister facilities in the same location or nearby? If Yes, describe	No
6. Facility phone #(s):	Describe
+855 23866417	
7. Facility email address:	Describe
Nil	
8a. Contact name & title #1:	Describe
Mr. Sunny Chui-General Manager	
8b. Contact #1 email address:	Describe
sunnychui@yorkmars.com	
8c. Contact #1 phone:	Describe
+855 885509773	
9a. Contact name & title #2:	Describe
Mr. Gamini K-CSR Manager	
9b. Contact #2 email address:	Describe
gamini@yorkmars.com	
9c. Contact #2 phone:	Describe
+855 92973194	

Part B: Audit Details



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

10. Monitoring firm name:	Describe
Bureau Veritas (Cambodia) Limited.	
11. Monitor's report #:	Describe
10243301485	
Follow-Up Audit on February 21-22, 2025: 10243652169	
12. Acknowledgement by official from monitoring firm: By signing this report, I confirm that our independent assessment was made in accordance with WRAP's requirements as outlined in the WRAP Monitors' Handbook and in keeping with the WRAP Policies for Recognition of Monitoring Partners.	Describe
By signing this report, I confirm that our independent assessment was made in accordance with WRAP's requirements as outlined in the WRAP Monitors' Handbook and in keeping with the WRAP Policies for Recognition of Monitoring Partners.	
13. Name & title of authorizing official:	Describe
Marinela Perucho, Regional Manager	
14. Was the audit unannounced within a 4-week window? If No, explain:	Yes
15. Was WRAP registration payment confirmed prior to the audit? If No, provide explanation:	Yes
16a. Lead auditor name, APSCA designation & #:	Describe
Han LE; CSCA21703042	
Follow-Up Audit on February 21-22, 2025: Channy SOK (CSCA21702189)	
16b. Audit team member 1 name, APSCA designation & #:	Describe
Channy SOK; CSCA21702189	
16c. Audit team member 2 name, APSCA designation & #:	Describe
Nil	
16d. Audit team member 3 name, APSCA designation & #:	Describe
Nil	
16e. Name(s) of technical expert(s):	Describe
Nil	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

16f. Name(s) of trainee auditor(s) (Trainee auditors may only observe WRAP audits; they cannot take an active part in the audit. Only WRAP accredited auditors' time is counted toward man-day requirements.):	Describe
Nil	
16g. Name(s) of translator(s) (Must NOT be from facility):	Describe
Theary LEANG	
16h. Names of others (incl. titles):	Describe
Nil	
17a. Day 1 time in/out facility for initial audit:	Describe
7:50-16:00	
17b. Day 2 time in/out facility for initial audit:	Describe
8:30 - 16:45	
17c. Day 3 time in/out facility for initial audit:	Describe
8:00 - 13:15	
17d. Day 4 time in/out facility for initial audit:	Describe
Nil	
17e. Day 5 time in/out facility for initial audit:	Describe
NA	
18a. Day 1 time in/out facility for 1st follow-up audit:	Describe
08:15-17:00	
18b. Day 2 time in/out facility for 1st follow-up audit:	Describe
08:00-16:15	
18c. Day 3 time in/out facility for 1st follow-up audit:	Describe
NA	
19a. Day 1 time in/out facility for 2nd follow-up audit:	Describe
NA	
19b. Day 2 time in/out facility for 2nd follow-up audit:	Describe
NA	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

20a. Total man-days spent at facility (1 man-day = 8 hours) during initial audit:	Describe
4.5	
20b. Total man-days spent at facility (1 man-day = 8 hours) during 1st follow-up audit:	Describe
2	
20c. Total man-days spent at facility (1 man-day = 8 hours) during 2nd follow-up audit:	N/A
N/A	
21. Who signed and agreed to CAP? (name & title):	Describe
Mr. Gamini-Compliance Manager	
Follow-Up Audit on February 21-22, 2025: Mr. Gamini-Compliance Manager	
22. Report written by:	Describe
Han Le	
Follow-Up Audit on February 21-22, 2025: Channy SOK	
23. Report reviewer and review date:	Describe
Jessie Dong / Dec 25, 2024	
24. If an on-site follow-up audit, was a facility tour conducted? If No, explain:	Yes
N/A	
25. If an on-site follow-up audit, was a tour in dormitory/apartment conducted? If No, explain:	Yes
N/A	
26. Were consultants present during any part of the audit? If Yes, what's the name of the consulting company and how did it participate in the audit? (Auditors must inform consultants of WRAP's requirements/rules on what a consultant can and cannot do.)	No
N/A	

Part C: Site Information

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

27. Provide applicable legally required licenses and permits, such as environmental, H&S, building safety licenses and permits, etc. Please list any relevant certificate (fire, safety, building, etc.) license numbers and expiration dates. If a certificate or permit has expired or is about to expire, mention whether the facility has applied for a renewal:

Describe

Business License # 00005041 (Original number: Inv. 1587 E/2012) and original business registration number MOC-10308684 issued by Ministry of Commerce on June 21, 2012 with unspecified expiry date.

Beside the business license, the facility has also obtained the other legally required licenses and permits such as:

- The facility maintained the Council for the Development of Cambodia (CDC) with certificate No. 1610/12 Cambodia Investment Board for opening the enterprise, was issued on July 19, 2012 with unspecified expiry date.
- The facility obtained the STATUTE of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. Business registration for their recording. MR. TAM KWOK CHEUNG (Chinese) is the owner, business type as Single Member Private Limited Company, was issued by the Ministry of Commerce on June 21, 2012 with reference No. 1959/2012 with unspecified expiry date.
- The Certificate for Factory Operation No. 2852, was issued by the Ministry of Industry, Science, Technology & Innovation on May 09, 2024. The validity is on May 09, 2027.
- The facility's operation permit was issued by the Ministry of Labour and Vocational Training with registered No. DE20210341, was issued on January 28, 2021 with unspecified expiry date.
- The facility's Tax Identification Number (TIN): L001-100187269 which was issued on October 08, 2015, and renewed by the Ministry of Economy and Finance once per year, the latest renewal was on January 05, 2024 for Patent Tax year 2024.
- The facility maintained the Environment management plan was issued by the Ministry of Environment in January 01, 2021.
- The facility's environmental permit No. 434, which was issued by the Ministry of Environment on September 27, 2012 with unspecified expiry date.
- The Environmental Protection Agreement has been made and approved by the Ministry of Environment on September 21, 2012 with reference No. 813 with unspecified expiry date.
- The facility obtains indoor air quality and noise control permit No. 1959, was issued on September 11 2024 for the raw warehouse building, and No. 778 for main facility, was issues by the Ministry of Environment on March 13, 2024 for main facility. The validity is for 1 year.
- The facility obtains air emission for steam boiler No. 776, were issues by the Ministry of Environment on March 13, 2024. The validity is for 1 year.
- The facility obtains air emission for generator No. 777, were issues by the Ministry of Environment on March 13, 2024. The validity is for 1 year.
- The facility obtains solid waste permit No. 1961 and 1963 for raw material warehouse building the main facility, was issues by the Ministry of Environment on September 11, 2024. The validity is for 1 year.
- The facility obtains liquid waste permit No. 1960 and 1962 for raw material warehouse building the main facility, on September 11, 2024. The validity is for 1 year.
- The facility's Social Insurance's Certificate of National Social Security Fund (NSSF) No. 09/12 and Enterprise Identification No. 1004124, dated on August 31, 2012 with unspecified expiry date.
- The factory internal work rule and regulation was established and approved with reference No. E1IR20220267, was issues by the Ministry of Labour and Vocational Training on April 21, 2022 with unspecified expiry date.

All permits and licenses was updated and valid as legal requirement.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Follow-Up Audit on February 21-22, 2025:

•The facility's Tax Identification Number (TIN): L001-100187269 which was issued on October 08, 2015, and renewed by the Ministry of Economy and Finance once per year, the latest renewal was on January 24, 2025 for Patent Tax year 2025.

28. Main products manufactured at site (e.g., knitted tops, women's pants):	Describe
---	----------

Garments (Knitted and woven tops and bottoms)

29. Production processes in audit scope (to be listed on WRAP certificate):	Describe
---	----------

Raw material warehouse, cutting, sewing, washing, inspection, ironing, packing and finishing goods warehouse.

30. Main buyers and their production percentages, and facility's export markets (Only if facility agrees to disclose buyers):	Describe
---	----------

Main client: COSTCO: 45%, REITMAN: 8%, NEW TIMES: 7%, ARITZIA: 30% and OTHER: 10%.

Main Market: USA: 20%, Canada: 70%, EU: 5%, and others: 5%.

31. Worker turnover rate:	Describe
---------------------------	----------

6.53%

32. Number of years facility has been in operation at this address/building(s) (If a facility is in the same address but moved to a different building, note so here):	Describe
--	----------

YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. has started the operations since June, 2012.

The facility has never been moved to other buildings in the same address and/or moved from other location in difference address. All the buildings are under operation of the audited facility.

33. Full description of the facility's surroundings, incl. compound if applicable:	Describe
--	----------

The facility's surroundings by fence with approx. 2.5 meters high with one main gate and controlled by security guards and monitored by CCTV at 2 sites (main site and new material warehouse). No compound facility available in the site.

34. Full description of building(s) (incl. # of buildings, # of floors in each building, production processes on each floor/building, size, and age of building(s)) (If building(s) is(are) shared, list all tenants in the building and specify which floors/sections are covered by this audit):	Describe
--	----------

Factory had 2 sites:

Site 1:

The total land area occupied by the main facility is about 21,798 square meters and 17,003.75 square meters for production area, located at Phum Trapeang Chhrey, Sangkat Kakab, Khan Porsenchey, Phnom Penh, Cambodia. They have started their operation at the existing location since June 2012.

The factory's building comprises of 6 main buildings and 3 dormitories buildings with sub-building with details as follows:

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

- Building A with ground floor and partial mezzanine floor.
Size: 4,200 square meters and Age of building is 25 years.
 - Ground floor: Main office, cutting section, heat transfer section, and fusing section.
 - Mezzanine floor: Marker room, and sample sewing section.
- Building B with only ground floor.
Size: 3,150 square meters and Age of building is 25 years.
 - Ground floor: Sewing section.
- Building C with ground floor and partial mezzanine floor.
Size: 3,885,05 square meters and Age of building is 25 years.
 - Ground floor: Sewing section.
 - Mezzanine floor: IE office.
- Building D with only ground floor.
Size: 2,437,79 square meters and Age of building is 25 years.
 - Ground floor: Infirmary room, ironing section, packing section, humidity room, and finished good warehouse.
- Building E with only ground floor.
Size: 2,438.15 square meters and Age of building is 25 years.
 - Ground floor: Finished goods warehouse.
- Building F with only ground floor.
Size: 202 square meters and Age of building is 25 years.
 - Ground floor: Washing section.
- Building G with only ground floor.
Size: 517 square meters and Age of building is 25 years.
 - Ground floor: kitchen and eating area for expatriate management staffs.
- Building H with 2 floors.
Size: 125.4 square meters and Age of building is 10 years.
 - Ground floor: Dormitory for expatriate management staffs.
 - First floor: Dormitory for expatriate management staffs.
- Building I with only ground floor.
Size: 48.36 square meters and Age of building is 10 years.
 - Ground floor: Dormitory for expatriate management staffs, breastfeeding room and day-care center.
- Other small sub-buildings for security guard house, generator room, air compressor, waste storage, eating area for workers, toilets for production employees, and parking area etc.

Site 2:

The total land area occupied by the new warehouse is about 19,118 m2 square meters and 15,000 square meters for warehouse building that located at Preytea Village, Sangkat Choam Chao, Khan Porsenchay, Phnom Penh, Cambodia, which was far away from the main site around 300 meters.

- Warehouse building with only ground floor.
Size: 15,000 square meters and Age of building is 21 years.
 - Ground floor: Warehouse office, laboratory room, accessories warehouse, fabric warehouse and fabric relaxation area.
- Other small sub-buildings for security guard house, generator room, waste storage, toilets for production employees, and parking area etc.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

All buildings and sites belong to the audited facility and all buildings were covered by this audit.

35. Does the facility share a building with other facilities/businesses? (If Yes, describe in detail)	No
36. If Yes to 35, does the facility conduct a joint evacuation drill with other facilities/businesses? (If No, describe in detail)	N/A
37. Does the facility share any workers or production processes with other facilities? (If Yes, describe in detail)	No
38a. Does the facility have a change in number of workers in the past 12 months? (If Yes, list % change and explain)	No
38b. Does the facility have a change in square footage in the past 12 months? (If Yes, explain)	No
38c. Does the facility have any significant structural changes in the past 12 months? (If Yes, describe)	No
38d. Does the facility have a change in management/ownership in the past 12 months? (If Yes, describe)	No
38e. Does the facility have a name change in the past 12 months? (If Yes, describe)	No
39. Regular workdays (e.g., Mon-Sat):	Describe
From Monday to Saturday	
40. Weekly rest day(s):	Describe
Full Sunday.	
41. List daily shifts, incl. night production:	Describe
The facility operates in 1 working shift with details as below:	
The business was start from 07:00 - 16:00 for production employees, and 08:00-17:00 for office staffs.	
42. Factory's peak season(s):	Describe
The peak season is from July to November in the past 12 months	
43: List the number and duration of daily legally required breaks:	Describe
1/ 11:00 – 12:00	
44. What is the lowest wage level paid for a regular work week/month?	At minimum
45. Are all relevant records, incl. wage and attendance records, kept in the audited facility for review? (If No, explain)	Yes
46. Are there dorms/apartments provided for workers/management?	Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Domitory was provided for management.

47a. If Yes to 46, who's providing the dorms?	Facility
47b. Full description of dormitories/apartments if applicable:	Describe
01 buildings with two floors and 01 building with one floor which was located in the same facility premise has been provided as dormitory, kitchen, and dining area for expatriate management staffs (41 Chinese, 6 Sri Lankan, 6 Filipino, 1 Indonesian, and 2 Vietnamese).	
48. % of workforce residing in dorms/apartments:	Describe
2.96	
49. What form of worker representation exists in the facility? (Note: Some form of worker representation must exist to address workplace grievances.)	Multiple forms of representation (specify)
There were two trade unions formed in the facility name: - Khmer Youth Trade Union of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. which was approved by the Ministry of Labor and Vocational Training on January 30, 2023, with registered No. 112180335, and reference No. 080. Mr. Im Sarith is the Union President - Khmer Union of Workers Spirit of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. which was approved by the Ministry of Labor and Vocational Training on November 21, 2024, with registered No. 112180479, and reference No. 814. Mr. So Sophal is the Union President The Seven (7th) mandate shop steward/worker representative of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. election was arranged on August 25, 2023 with 1,998 employees joined the election. The result of election was approved by the Ministry of Labor and Vocational Training on December 18, 2023. The shop steward/worker representative permit valid until August 26, 2025 with reference No. E1SS202301610. Mr. So Sophal is the highest vote.	
50. Number of production lines and main equipment used?	Describe
The facility operated with 448 of auto single needle machines, 321 of 4 thread overlock machines, 12 of 5 thread overlock machines, 88 of 4 needle flat lock machines, 132 of flat lock flatbed machines, 150 of flat lock cylinder bed machines, 71 of auto flat lock cylinder bed machines, 54 of basic double needle machines, 14 of waist trousers machines, 17 of button hole sewing machines, 26 of auto bar-tack machines, 12 of thread cutting machines, 10 of button sewing machines, 95 of zigzag sewing machines, 3 of crashed machines, 10 of needle inspection machines, 1 of color light box, 1 of hand pressure cutter, 9 of air compressors, 3 of auto cutting tables, 3 of machine cutting elastic, 5 of elastic machines, 2 of dehydrator, 7 of spreading machines, 5 of fabric inspection machines, 4 of fabric cutting machines, 10 of needle inspection machines, 22 of heating machines, 1 of laser machine, 2 of washing machines, 7 of dryer machines, 2 of packing machines, 4 of strapping machines, 4 of inkjet cutting plotter.	
51. Monthly production capacity:	Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

936,000 pieces.

52. List social compliance, environmental or CTPAT audits conducted in the past 6 months at this facility: (Only if facility agrees to disclose such info.)

Describe

-ILO audit was conducted on June 13-14, 2024

-BSCI Social audit was conducted on July 22-26, 2024.

53. List any workers unrest/strike in the past 12 months: Provide reasons for such occurrence.

Describe

No any workers unrest/strike in the past 12 months.

Part D: Personnel Information Overview

54a. Total # of workers (Do NOT include management or admin. staff) during initial audit:

Describe

1,689

54b. Total # of workers (Do NOT include management or admin. staff) during first follow-up audit:

Describe

1910

54c. Total # of workers (Do NOT include management or admin. staff) during second follow-up audit:

Describe

NA

54d. # of onsite sub-contracted workers during initial audit:

Describe

0

54e. # of onsite sub-contracted workers during first follow-up audit:

Describe

N/A

54f. # of onsite sub-contracted workers during second follow-up audit:

Describe

NA

54g. # of workers present during initial audit:

Describe

1,645

54h. # of workers present during first follow-up audit:

Describe

1814

54i. # of workers present during second follow-up audit:

Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

NA

55a. # of management & admin staff during initial audit:	Describe
--	----------

132

55b. # of management & admin staff during first follow-up audit:	Describe
--	----------

147

55c. # of management & admin staff during second follow-up audit:	Describe
---	----------

NA

Part E: Personnel Information Details

56a. # of male production workers:	Describe
------------------------------------	----------

159

Follow-Up Audit on February 21-22, 2025: 193

56c. # of female production workers:	Describe
--------------------------------------	----------

1,530

Follow-Up Audit on February 21-22, 2025: 1717

57a. # of other male workers:	Describe
-------------------------------	----------

0

57b. # of other female workers:	Describe
---------------------------------	----------

0

58a. # of male permanent workers:	Describe
-----------------------------------	----------

159

Follow-Up Audit on February 21-22, 2025: 193

58b. # of female permanent workers:	Describe
-------------------------------------	----------

1,530

Follow-Up Audit on February 21-22, 2025: 1717

59a. # of male temporary workers:	Describe
-----------------------------------	----------



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

0

59b. # of female temporary workers:

Describe

0

60a. # of male hourly workers:

Describe

159

Follow-Up Audit on February 21-22, 2025: 193

60b. # of female hourly workers:

Describe

1,530

Follow-Up Audit on February 21-22, 2025: 1717

61a. # of male piece rate workers:

Describe

0

61b. # of female piece rate workers:

Describe

0

62a. # of male domestic migrant workers:

Describe

0

62b. # of female domestic migrant workers:

Describe

0

62c. List ALL provinces/ states where domestic migrant workers are from:

Describe

NA

63a. # of male foreign migrant workers:

Describe

0

63b. # of female foreign migrant workers:

Describe

0

64a. # of male home workers:

Describe

0

64b. # of female home workers:

Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

0

65a. # of male security personnel:

Describe

28

Follow-Up Audit on February 21-22, 2025: 20

65b. # of female security personnel:

Describe

24

Follow-Up Audit on February 21-22, 2025: 26

66a. # of male management:

Describe

28

Follow-Up Audit on February 21-22, 2025: 29

66b. # of female management:

Describe

28

Follow-Up Audit on February 21-22, 2025: 27

67a. # of male line supervisors:

Describe

16

Follow-Up Audit on February 21-22, 2025: 16

67b. # of female line supervisors:

Describe

54

Follow-Up Audit on February 21-22, 2025: 54

68. Language(s) spoken by management:

Describe

Chinese / English/ Khmer

69. Language(s) spoken by line supervisors:

Describe

Khmer & Chinese

70. Language(s) spoken by workers:

Describe

Khmer



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

71. Were interviews conducted in a private and confidential manner? (If No, explain in detail)	Yes
72. Do auditor(s) and/or translator(s) speak ALL languages spoken by workers? Note: translator(s) must NOT be from facility. (If No, explain in detail)	Yes
73. Length of workers' contract: (e.g., 3 months or 3 years)	Describe
The facility practices as the firstly signs within 2 months for probation period and re-new every 3 months for Fixed Duration Contract (FDC) for 8 times. The Unfixed Duration Contract (UDC) will be issued to employees who working in the facility for 2 years and 2 months.	
74. # of young workers (legal min. working age up to 18 years old):	Describe
0	
75. Age of youngest worker on the day of the audit:	Describe
18 years old	
Follow-Up Audit on February 21-22, 2025: 18 years old	
76. Date of birth of youngest worker:	Describe
December 07, 2006	
Follow-Up Audit on February 21-22, 2025: January 05, 2007	
77. Date youngest worker was hired:	Describe
December 10, 2024	
Follow-Up Audit on February 21-22, 2025: February 03, 2025	
78. Youngest worker ID#:	Describe
YM8154	

Part F: Workforce Composition

79. Nationality of owner/owner entity:	Describe
Chinese	
80. Nationality of Management:	Describe
Chinese, Sri Lankan, Filipino, Indonesian, and Vietnamese.	
81. Nationality of workers (List Top 5 countries and their approximate % of the total workforce):	Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Cambodia-100%

82. List ALL other nationalities in the facility (if applicable) and their approximate percentage of the total workforce (if applicable):

Describe

NA

Part G: Worker Interviews

NOTE

If there are migrant workers in the audited facility, they must be selected for workers' interviews.

83a. Number of individual interviews with permanent workers during initial audit:

Describe

17

83b. Number of individual interviews with permanent workers during 1st Follow-up audit:

Describe

17

83c. Number of individual interviews with permanent workers during 2nd Follow-up audit:

Describe

NA

83d. Number of individual interviews with temporary workers during initial audit:

Describe

NA

83e. Number of individual interviews with temporary workers during 1st follow-up audit:

Describe

NA

83f. Number of individual interviews with temporary workers during 2nd follow-up audit:

Describe

NA

83g. Number of individual interviews with migrant workers during initial audit:

Describe

NA

83h. Number of individual interviews with migrant workers during 1st follow-up audit:

Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

NA

83i. Number of individual interviews with migrant workers during 2nd follow-up audit:

Describe

NA

83j. Number of individual interviews with contract workers from agency(ies) during initial audit:

Describe

NA

83k. Number of individual interviews with contract workers from agency(ies) during 1st follow-up audit:

Describe

NA

83l. Number of individual interviews with contract workers from agency(ies) during 2nd follow-up audit:

Describe

NA

84a. Number of group interviews with permanent workers during initial audit:

Describe

18 (3 groups of 6)

84b. Number of group interviews with permanent workers during 1st follow-up audit:

Describe

18 (3 groups of 6)

84c. Number of group interviews with permanent workers during 2nd follow-up audit:

Describe

NA

84d. Number of group interviews with temporary workers during initial audit:

Describe

NA

84e. Number of group interviews with temporary workers during 1st follow-up audit:

Describe

NA

84f. Number of group interviews with temporary workers during 2nd follow-up audit:

Describe

NA



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

84g. Number of group interviews with migrant workers during initial audit:	Describe
NA	
84h. Number of group interviews with migrant workers during 1st follow-up audit:	Describe
NA	
84i. Number of group interviews with migrant workers during 2nd follow-up audit:	Describe
NA	
84j. Number of group interviews with contract workers from agency(ies) during initial audit:	Describe
NA	
84k. Number of group interviews with contract workers from agency(ies) during 1st follow-up audit:	Describe
NA	
84l. Number of group interviews with contract workers from agency(ies) during 2nd follow-up audit:	Describe
NA	

Part H: Additional Auditor Remarks

Write any additional remarks here:	Describe
This is a re-new certification audit conducted by Bureau Veritas CPS Cambodia. 2 certified auditors were assigned to assess and verify the facility's operations against the WRAP principles and local legislations on a sampling 4.5 auditor-days basis. Lead auditor was conducted by in 3 consecutive days, and 1 team member was conducted on the first and second days. The facility provided 12 months of time and payroll records from December 2023 to November 2024 for review. Auditors selected 35 samples of November 2024 (Current month), September 2024 (Peak month) and July 2024 (Random month) to review. Total of 35 employees were selected for interview, including 30 female and 5 male employees. Audit Process: Overview of opening meeting, facility management responses: At 7:50 am, the audit team arrived at the facility and registered with security guards. After the introduction of the visit purpose to security staffs, auditors were requested to register name, company, person contact into security monitoring book. Auditor was invited to the facility meeting room. An opening meeting according to the WRAP principles was held with presence of the factory management and key staffs. They confirmed that the facility would	

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

be co-operative with audit team during auditing.

Attitude of workers:

The employees were comfortable during the interview. The interviews were carried out in a private room, without the presence of other facility personnel. During interview process, they confirmed that they were treated respectfully and have an equal opportunity in working overtime. They were pleased to work in the facility. During the facility tour, the employees were cooperative in providing information related to the compliance status of the facility.

Attitude of managers:

The facility representative showed a normal attitude in the assessment date. At the end of the audit, all findings were accepted by the facility representatives and promise to take corrective action as soon as possible.

Follow-Up Audit on February 21-22, 2025:

This is a first follow-up audit conducted by Bureau Veritas CPS Cambodia. 1 certified auditor was assigned to assess and verify the facility's operations against the WRAP principles and local legislations on a sampling 2 auditor-days basis, in which was conducted by 2 consecutive days.

The facility provided 2 months of time and payroll records from December 2024 to January 2025 reviews. Auditors selected 35 samples of January 2025 (Current month), and December 2024 (Random month) to review. Total of 35 employees were selected for interview, including 30 female and 5 male employees.

Audit Process:

Overview of opening meeting, facility management responses:

At 8:15 am, the audit team arrived at the facility and registered with security guards. After the introduction of the visit purpose to security staffs, auditors were requested to register name, company, person contact into security monitoring book. Auditor was invited to the facility meeting room. An opening meeting according to the WRAP principles was held with presence of the factory management and key staffs. They confirmed that the facility would be co-operative with audit team during auditing.

Attitude of workers:

The employees were comfortable during the interview. The interviews were carried out in a private room, without the presence of other facility personnel. During interview process, they confirmed that they were treated respectfully and have an equal opportunity in working overtime. They were pleased to work in the facility. During the facility tour, the employees were cooperative in providing information related to the compliance status of the facility.

Attitude of managers:

The facility representative showed a normal attitude in the assessment date. At the end of the audit, the facility management promise that they will maintain all the points has been corrected.

Based on site observation and document reviews, it is noted that the previous finding which was raised during Re-new Certification audit are appropriate to close via onsite follow-up.

All the findings for Principle 1, 6, 8 and 12 which were against the local/ national law and WRAP requirement have been corrected and well maintained on the management system.

Part I: Best Practices Observed



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Write any best practices observed here:	Describe
1. The facility pays each employee the attendant bonus with the amount of USD 15.00 per month, this practice is better than legal requirement which was requires only USD 10 per month; 2. The facility pays each employee the transportation & housing allowance with the amount of USD 9 per month, his practice is better than legal requirement which was requires only USD 7 per month; 3. The facility provides lunch allowance USD 12.00 per month for all workers, while local law does not require; 4. The facility pays each employee at 300% (200%+100%) of regularly premium rate for overtime on Holidays while the legal requirement only 200% (100%+100%).	

Part J: Written Policy & Responsible Person(s) Table

Does the facility have written policies in regards to WRAP Principle 1: Compliance with Laws and Workplace Regulations? (If Yes, list responsible person(s)' name and title)	Yes
Mr. Tay Ratana – HR & Admin Manager, Mr. Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor	
Does the facility have written policies in regards to WRAP Principle 2: Prohibition of Forced Labor? (If Yes, list responsible person(s)' name and title)	Yes
Mr. Tay Ratana – HR & Admin Manager, Mr. Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor	
Does the facility have written policies in regards to WRAP Principle 3: Prohibition of Child Labor? (If Yes, list responsible person(s)' name and title)	Yes
Mr. Tay Ratana – HR & Admin Manager, Mr. Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor	
Does the facility have written policies in regards to WRAP Principle 4: Prohibition of Harassment or Abuse? (If Yes, list responsible person(s)' name and title)	Yes
Mr. Tay Ratana – HR & Admin Manager, Mr. Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor	
Does the facility have written policies in regards to WRAP Principle 5: Compensation and Benefits? (If Yes, list responsible person(s)' name and title)	Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor

Does the facility have written policies in regards to WRAP Principle 6: Hours of Work? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor

Does the facility have written policies in regards to WRAP Principle 7: Prohibition of Discrimination? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor

Does the facility have written policies in regards to WRAP Principle 8: Health and Safety? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor

Does the facility have written policies in regards to WRAP Principle 9: Freedom of Association and Collective Bargaining? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor

Does the facility have written policies in regards to WRAP Principle 10: Environment? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor

Does the facility have written policies in regards to WRAP Principle 11: Customs Compliance? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.

Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) - Compliance Supervisor,
Mr. Uy Sarin – Shipping Manager



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Does the facility have written policies in regards to WRAP Principle 12: Security? (If Yes, list responsible person(s)' name and title)

Yes

Mr. Tay Ratana – HR & Admin Manager, Mr.
Sok Moyukeo – HR Supervisor, Ms. Vann Socheata (Nicole) -
Compliance Supervisor

Part K: Non-Compliance Table

Did the facility have any non-compliances with Principle 1: Compliance with Laws and Workplace Regulations? If so, please comment how many non-compliances were observed.

WRAP Principles

No non-compliances

N/A

Did the facility have any non-compliances with Principle 2: Prohibition of Forced Labor? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 3: Prohibition of Child Labor? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 4: Prohibition of Harassment and Abuse? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 5: Compensation and Benefits? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 6: Hours of Work? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 7: Prohibition of Discrimination? If so, please comment how many non-compliances were observed.

No non-compliances



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

N/A

Did the facility have any non-compliances with Principle 8: Health and Safety? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 9: Freedom of Association and Collective Bargaining? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 10: Environment? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 11: Customs Compliance? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Did the facility have any non-compliances with Principle 12: Security? If so, please comment how many non-compliances were observed.

No non-compliances

N/A

Quality Plan ([AUDIT REPORT - PRINCIPLE 01 : COMPLIANCE WITH LAWS AND WORKPLACE REGULATIONS](#)) 

Audit Questions and Objective Evidence/Comments

Principle 1: Compliance with Laws and Workplace Regulations

Facilities will comply with laws and regulations in all locations where they conduct business.

All facilities will comply with the legal requirements and standards of their industry under the local and national laws of the jurisdictions in which the facilities are doing business, along with any applicable international laws. This will cover all labor and employment laws of those jurisdictions, as well as laws governing the conduct of business in general, including rules and standards of ethics dealing with corruption and transparency, and any relevant environmental laws.

1.1a. Does the facility comply with all relevant local and national laws?

Yes

During the document review, site tour, employees and management interview, it was noted that the facility did not comply completely with relevant local and national law requirements as non-compliance noted in other principles.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Follow-Up Audit on February 21-22, 2025: Closed

Based on provided evidence, it was noted that all NCs were improved and closed. Therefore, the factory is complying with all relevant local and national laws.

1.1b. Does the facility comply with all labor and enforcement laws?

Yes

The facility has maintained Cambodian Labor Law Book in the facility and registered internal work rule and regulations to the Ministry of Labour and Vocational Training on April 21, 2022 with reference No. E1IR20220267.

1.1c. Is the facility's hiring process in accordance with the law?

Yes

Based on management interview, employees interview and document review, the facility directly hired employees by itself based on its internal recruitment procedure, its internal rule and regulation. The job announcement is posted on the main gate or spreading to employees through PA system. All candidates with 18 years old and above are free to apply for the job with job application filling, interview, and vacancy testing process.

1.1d. Is any of the facility's hiring done under government sponsorship?

No

No. Based on management interview, employees interview and document review, the facility directly hired employees by itself based on its internal recruitment procedure, its internal rule and regulation. The job announcement is posted on the main gate or spreading to employees through PA system. All candidates with 18 years old and above are free to apply for the job with job application filling, interview, and vacancy testing process.

1.1e. Has the facility received incentives to hire/train workers from private or government sponsored programs?

No

Based on management interview, employees interview and document review, the facility directly hired employees by itself based on its internal recruitment procedure, its internal rule and regulation. The job announcement is posted on the main gate or spreading to employees through PA system. All candidates with 18 years old and above are free to apply for the job with job application filling, interview, and vacancy testing process

1.1f. Does the facility comply with all ethics, anti-bribery, and anti-corruption laws?

Yes

The facility has copied and maintained Ethics codes /policies and Anti-corruption and bribery law in place.

1.1g. Does the facility comply with all environmental laws?

Yes

The facility registered with the Ministry of Environment Protection Notification and obtained the environment law for operation the business.

1.2a. Does the facility obtain current information on all relevant laws and regulations concerning each of the Principles and incorporate this information in its business practices?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

All the updated law has been timely sent from TAFTAC Membership (Textile, Apparel, Footwear, Travel Goods Association in Cambodia) charge of Human Resource and cascade the updated labor law; as per social compliance policies and procedures reviewed are found consistent with current updated-local law.
The facility has written about Social compliance policies and procedures and they are regularly reviewed and updated by responsible person.

1.2b. Does the facility have written policies and procedures for current information on all relevant laws and regulations on all 12 WRAP Principles?

Yes

Facility's Internal rule recognized by the Ministry of Labour and vocational Training and Code of Conduct that consists of relevant local laws and WRAP's handbook that pertaining to WRAP's 12 principles.

1.2c. Does the facility have a qualified person responsible for informing the facility and its workforce of changes to laws and regulations, or access to current publications on all relevant labor laws? (List their name and job title)

Yes

Name and job title:

1.Mr. Gamini-Compliance Manager

2.Mr. Sok Moyukeo – HR Supervisor

3.Ms. Vann Socheata (Nicole) -Compliance Supervisor

1.2d. When was the last time a major update in laws and regulations occurred in the last 12 months? (List all major changes that are relevant, e.g., an increase in minimum wage effective in January 2021)

Describe

The major changed listed as listed:

•Legal minimum wage for year 2023 with reference Prakas No. 247/22 KB/Br.K.Kh.L issued by Ministry of Labour and Vocational Training on September 21, 2022. It is to determine the minimum wage effective from January 1, 2023 onward as below:

USD 198 per month for probationary employees and USD 200 per month for regular employees.

•Legal minimum wage for year 2024 with reference Prakas No. 283/23, was issued by Ministry of Labour and Vocational Training on September 29, 2023. It is to determine the minimum wage effective from January 1, 2024 onward as below:

USD 202 per month for probationary employees and USD 204 per month for regular employees.

- Certificate of registration Implementation of Sub-Decree 108. "Completed the Quota of Employment of Persons with Disabilities". Form the Ministry of Social Affair, Veterans and Youth Rehabilitation.

-Prakas 170/22: Contribution Payments for Social Security Compulsory and Voluntary Pension Schemes. Implementation from October 1, 2022 onward.

1.3a. Does the facility have a policy ensuring that a worker can raise workplace concerns without fear of retaliation?

Yes

The facility has the "Non-Retaliation" policy as core standard reviewed on January 03, 2024.

1.3b. What procedures does the facility have in place to implement the policy?

Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The internal audit is to cover the requirements of local/national law and 12 WRAP Principles, due to the facility uses the WRAP pre-audit self-assessment and the its internal rule and regulation as the audit criteria.

1.4a. Does the facility conduct internal monitoring of its management system at least twice (02) a year? When was the last internal monitoring the facility conducted?

Yes

The facility assigns Ms. Vann Socheata (Nicole) -Compliance Supervisor conduct internal audit to ensure the updated local laws and WRAP principles strictly followed by all relevant staff. The facility has conducted internal audit twice per year, the last one was on December 07, 2024.

1.4b. Does the scope of these internal monitoring activities cover whether their written procedures and processes are meeting the requirements of local/national law and WRAP 12 Principles?

Yes

The internal audit is to cover the requirements of local/national law and 12 WRAP Principles, due to the facility uses the WRAP pre-audit self-assessment and the its internal rule and regulation as the audit criteria.

1.4c. Were the results of the internal monitoring communicated with top management?

Yes

As per management interview and document review, the result of internal audit including finding is communicated with relevant management and health and safety committee, it was on December 07, 2024.

1.4d. What were the findings from the last internal monitoring? List all findings regardless of whether they were corrected or not.

Describe

The internal audit finding was listed below:

1. There was no emergency exit light setup at the emergency exit door No. 3;
2. The fork-lift operator did not wear personal protective equipment during working at cutting section;
3. There was no inner isolator setup to one electrical box at cutting section;

1.4e. Were all the findings corrected? Provide details in the comment section.

Yes

Based on document review and management all the non-compliance found on internal audit on December 07, 2024, and corrected on December 10, 2024 as follow:

1. The emergency exit light was setup at emergency exit door No. 3;
2. The fork-lift operator was trained the personal protective equipment awareness;
3. The electrical box was setup with inner isolator;

1.5. During the previous two years, has the facility had any notices of noncompliance levied against it (including any legal proceedings or outstanding allegations concerning the facility's operations)?

No

Based on document review, employee and management interview, it was that there is no notice of non-compliance imposed against the facility in the past.

Subcontracting



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Subcontracting

Note: A facility is subcontracting when it appoints another facility to undertake part of the production processes for the manufacturing of goods. It involves circumstances where goods leave the facility to be partially completed and then sent back so the goods can be completed. Other services may also be subcontracted.

1.6. Does the facility subcontract any of its production operations? If the facility used subcontracting in the past 12 months but does not do so now, note this under this question. List the subcontracted production process(es). List the name(s) and address(es) of subcontractor(s).

Yes

The facility has used two (2) subcontractor companies for their production process as below:

1. PRINTING

NAME: TUNG CHOI FASHION TECHNOLOGY.

ADDRESS: NATIONAL ROAD#4, BREYBUENG, BEKCHAN COMMUNE, ONGSNUL DISTRICK, KANDAL PROVINCE, CAMBODIA.

2. EMBROIDERY

NAME: DA FENG DF EMBROIDERY CO., LTD.

ADDRESS: ST371, MOAL VILLAGE, DANGKOR COMMUNE,DANGKOR DISTRICK, PHN

1.7. Does the facility subcontract any other operations (such as canteen staff, security personnel, shipping services, cleaning staff, logistics, labor suppliers, etc.)? List the subcontracted services and name(s) and address(es) of subcontractors. List the name(s) and address(es) of subcontractor(s).

Yes

The facility used four logistic company and one security service provider with details as below:

1. SECURITY

NAME: M STRONG PROFESSIONAL CO., LTD.

ADDRESS: #550, ROAD #04, PHUM MOL, SANGKAT DANGKOR, KHAN DANGKOR, PHNOM PENH, CAMBODIA.

2. LOGISTIC

NAME: KINTETSU WORLD EXPRESS (CAMBODIA)CO., LTD.

ADDRESS: The icon professional building No. 216, Room No. 18-E3, Preah Norodom Blvd, Sangkat Tonle Bassac, Khan Chamkamon, Phnom Penh, Cambodia.

NAME: COHESION GLOBAL LOGISTICS (CAMBODIA) CO., LTD.

ADDRESS: No. 274, 3 Floor, Street Sothearos, Sangkat Tonle Bassac, Khan Chamkamon, Phnom Penh, Cambodia.

NAME: TRANSPEED CARGO PRIVATE LIMITED (CAMBODIA)

ADDRESS: No. 6, Street 41, (Norodom Blvd), Sangkat Tonle Bassac, Khan Chamkamon, Phnom Penh, Cambodia.

NAME: MAPLE GLOBAL LOGISTICS(CAMBODIA) CO., LTD.

ADDRESS: #A16 E1, Group 4, Tumnorp Village, Sangkat Phnom Penh Thmey, Khan Sen Sok, Phnom Penh, Cambodia.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

1.8. Has the facility informed the subcontractor(s) in writing of their obligations under the local/national labor law and WRAP's requirements?

Yes

The facility informed the subcontractors in writing of their obligations under the local/national labor law and WRAP's requirements. The latest was on Jan 25, 2024.

1.9. Does the facility keep the receipt of subcontractor's acknowledgment of these requirements? List the last time the acknowledgment was received.

Yes

The facility kept the receipt of subcontractor's acknowledgment of these requirements. The latest was on Jan 25, 2024.

1.10. Does the facility regularly review its list of subcontractors to make sure it is up to date? List the last time the review was conducted.

Yes

The facility regularly reviewed its list of subcontractors to make sure it is up to date. The last time the review was conducted on Jan 3.

Facility's Suppliers

1.11. Has the facility informed its top three (3) raw material suppliers for finished goods, e.g., fabrics, yarn, or leather, (by the value of business transacted with them in the preceding 12 months), in writing, of the facility's expectation that the supplier runs its operations in accordance with local/national laws and WRAP's Principles? List the names and addresses in English and local language of the top three (3) finished goods raw materials suppliers.

Yes

The facility used top 3 suppliers as below:

FABRIC:

1). YORKWELL AISA CO., LTD.

យ៉កវែល អេសៀ ខូលអិលធីឌី

ADDRESS: ROOM D, FLOOR8, HONG KONG SPINNERS INDUSTRIAL BUILDING, PHASE 5 760-761, CHWUNG SHA WAN ROAD, KOWLOON, HONG KONG.

បន្ទប់ទី ៨ ជាន់ទី៨ អាគារហុងកុងស្ទីនន៍អ៊ីនឌីស្ត្រីយ៉ាឡ លេខ៥៧៦០-៧៦១ ផ្លូវជុងសាវ៉ាន់ កូឡុង ហុងកុង ប្រទេសចិន។

THREAD:

2). HE JING YUAN (CAMBODIA) CO., LTD.

ហើ ជីង យ៉េន (ខេមបូឌា) ខូអិលធីឌី

ADDRESS: Phum Prey Bring Tbong, Sangkat Chom Chao, Khan Dangkor, Phnom Penh, Cambodia.

ភូមិព្រៃប្រឹងត្បូង សង្កាត់ចោមចៅ ខណ្ឌដង្កោ ភ្នំពេញ ប្រទេសកម្ពុជា។

ACCESSORIES:

3). KING LIM GARMENT CO., LTD.

យីង លីម ហ្គារម៉េន ខូអិលធីឌី



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

ADDRESS: #588, Phum Prey Sandek, Sangkat Chom Chao, Khan Posen Chhay, Phnom Penh, Cambodia.

ផ្ទះលេខ៥៨៨ ភូមិព្រៃសណ្តែក សង្កាត់ចោមចៅ ខណ្ឌពោធិ៍សែនជ័យ ភ្នំពេញ ប្រទេសកម្ពុជា។

Non-Compliances Found

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan ([AUDIT REPORT - PRINCIPLE 02 : PROHIBITION OF FORCED LABOR](#))

Audit Questions and Objective Evidence/Comments

Principle 2: Prohibition of Forced Labor

Facilities will not use involuntary, forced or trafficked labor.

Facilities will maintain employment strictly on a voluntary basis. Facilities will not use any forced, prison, indentured, bonded or trafficked labor. This will include ensuring that any workers they hire will be under labor contracts that fully comply with all relevant legal requirements and do not impose any form of coercion (including imposing substantial fines or loss of residency papers by workers leaving employment or restricting a worker's ability to voluntarily end his/her employment). In addition, workers should not be employed subject to any financial or collateral guarantee or debt security; any recruitment fees involved should be borne by facilities, not workers. Further, facilities will ensure that the workers' travel documents are not withheld, and that all written contracts are in a language understood by the workers.

2.1. Does the facility maintain a written procedure to avoid employing involuntary, forced, prison, indentured, bonded, or trafficked labor?

Yes

The facility has written social compliance policy and procedure for section of "Forced Labour Policies" as it internal core standard.

This written policy was included prohibits involuntary, forced, prison, indentured, bonded, or trafficked labor.

2.2. Does the facility have a program and materials used to train relevant individuals, including all individuals responsible for the hiring process, on the facility's policies and procedures prohibiting forced, prison, indentured, bonded, or trafficked labor?

Yes

The facility has established an internal training program about facility's social compliance policies and procedures including, prohibiting forced, prison, indentured, bonded, or trafficked labor.

Mr. Van Socheata-Compliance Supervisor is assigned to conduct training for all related personnel. The latest training was conducted on November 05, 2024.

2.3a. Are all workers working at the facility voluntarily, including overtime

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

hours?

All selected employees confirmed that they had applied for the job and are working in this facility voluntarily without force or threat.

The facility also has no complaint against this principle as per documents review. As per record reviewed, it was noted that the employees being signed the declaration of consent that they are working overtime based on voluntary basis.

2.3b. Is there evidence indicating that the facility forces any person (all onsite workers, including contracted ones) to work under the threat of any penalty or sanction?

No

From facility tour and workers interviews informed that, the workers are working at the facility voluntarily, including overtime.

2.3c. If production quotas are applicable, are workers required to reach a production target before ending the work shift?

No

The facility setup production targets for each sections. From interviewed workers, informed that all workers are not required to reach a production target before ending the work shift. All workers are freely to leave at the end of work shift, even though they cannot reach a production target and no any forced from the facility.

2.4. Are there any indications that workers' movements are being restricted at any time, including, but not limited to, legal breaks, lunch break, and the use of toilet?

No

From site observation and employees interview, it was noted that there is no evidence of workers' movements are being restricted at any time, including, but not limited to, legal breaks, lunch break, and the use of toilet.

2.5a. Are there exaggerated security measures or logistics restricting freedom of movement in use at the facility?

No

From site observation and employees interview, there is no evidence of exaggerated security measures or logistics observed during the facility tour and from employees' interview.

2.5b. Are there exaggerated security measures or logistics restricting freedom of movement in the dorms/apartments?

No

There are no exaggerated security measures or logistics restricting freedom of movement in dorms.

2.6. Were there any overt signs of fear or exaggerated obedience displayed by workers during the facility inspection?

No

From site observation and employee interview, there is no overt signs of fear or exaggerated obedience displayed by employees during the facility inspection.

2.7. Do security personnel and management act in a non-threatening manner?

Yes

From site observation and employee interview, it was noted that security guard act in a non-threatening manner.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

2.8. Are security guards posted for routine security reasons, in a proportionately logical number?	Yes
The facility's security job description, security personnel are limited in ensuring the facility security in accordance with local law such as protecting facility properties, employees and housing only	
2.9. Are all security service agreements free of any language or terminology that may imply the existence of involuntary, forced, prison, indentured, bonded, or trafficked labor conditions?	Yes
The facility has directly hired security guards and their employment contracts, they are freely from forced, prison,	
2.10. Do job descriptions or individual contracts for security workers limit their tasks to routine security matters such as protection of facility property or facility personnel?	Yes
The job descriptions and duties of the security guards are limited to normal security concerns and protection of facility property, personnel, visitors and guests	
2.11. Are the doors and gates of the facility locked only after business hours and for housing security reasons and in compliance with applicable fire codes?	Yes
All exits/doors are opened during working hours. Doors/gates are only close to ensure security in sections where there is no presence of employee.	
2.12. Does the facility prohibit all relevant individuals, including any person under the facility's direction (such as security guards), from coercing workers in any way, or unnecessarily limiting workers' freedom of movements?	Yes
According to the facility's policy and procedures of force labor and internal regulation, limiting employees' freedom of movement is strictly prohibited.	
2.13. Are workers freedom of movement unimpeded upon their shift's conclusion?	Yes
It was noted that, statement affirming that applicants are seeking employment voluntarily and are not under threat of any penalty, coercion or debt security was established or including in employment contract.	
2.14. Is it mandatory for workers to use facility provided services, such as canteen, dorms, or transportation? (If Yes, provide details, assessing any fees associated with that, including how such fees are deducted)	No
From facility tour and workers/ employees interview informed that no any mandatory for workers/employees to use facility provided services such as canteen, dorm or transportation. In addition, workers/employees use their own transportation such as: bike, motor cycle, rental car etc. The facility has provided only eating area to workers/employees.	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

2.15a. Does the facility require all hiring documents (e.g., an employment application or contract) to include a statement affirming that applicants are seeking employment voluntarily and are not under threat of any penalty, coercion or debt security?

Yes

It was noted from record review and employee interview that employees signed statement affirming that applicants are seeking employment voluntarily and are not under threat of any penalty, coercion or debt security while they initially joined the employment in the facility.

2.15b. Does the facility require all hiring documents (e.g., an employment application or contract) to be signed by each applicant?

Yes

The security personnel signed and sampled selection employees, they are signed off affirming letter which is stated that she/he works voluntarily and are not under threat of any penalty, coercion or debt.

2.15c. Does the facility require all hiring documents (e.g., an employment application or contract) to be maintained in the worker's personnel file?

Yes

Based on sampled employee, all of 35 sampled selection employees are kept the signing of affirming letter in the personnel files.

2.16. Does the facility obtain proof that anyone seeking employment is legally entitled to work in the country of manufacture in accordance with national immigration laws?

Yes

Through facility management and employees interviewed, noted that there were no foreign migrant production employees in the factory.

Only expatriate management staff was directly hired by the facility and work in the supervisory level and management level.

2.17a. Does the facility conduct adequate due diligence on labor brokers/agents used by the facility? Describe the policies and procedures used for vetting labor brokers/agents:

N/A

No broker/ agent used by the facility.

The facility has HR team to recruit employee/worker directly.

2.17b. Does the facility obtain an executed statement from all labor brokers/ agents used by the facility stating that the brokers/agents are not supplying labor that is involuntary, forced, prison, indentured, bonded, or trafficked? Name(s) and contact info of any brokers/agents supplying labor to the facility and their business license:

N/A

The facility hires employees directly.

2.17c. Is facility's hiring process, in part or in whole, managed by a 3rd party? If yes, describe.

No

The facility hires employees directly.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

2.17d. Are any of the workers recruited from vocational training centers? If yes, describe the process and the name(s) of the center(s).	No
The facility hires employees directly.	
2.17e. Were the basic terms of employment communicated to the migrant workers before they left their home country? Provide details about how this was done.	N/A
The facility does not recruits migrant production employees. However, all migrant/foreign employees are the nationalities and they are working in management/supervisory level.	
2.17f. Are migrant workers' activities monitored by a person besides their facility supervisor? If yes, describe.	N/A
The facility hires employees directly.	
2.17g. Do migrant workers (whether domestic or foreign) pay fees or give collateral to brokers/agents/local government in the receiving country? If yes, state the relevant laws.	N/A
NA. Factory did not hired any migrant worker.	
2.17h. If yes to g, describe the kinds of fees or collateral involved and how they are processed.	N/A
NA. Factory did not hired any migrant worker.	
2.17i. Does the facility have a plan to reimburse the fees directly to the affected workers? The reimbursement schedule must be over a reasonable period of time, not exceeding 3 years.	N/A
The facility hires employees directly.	
2.17j. If yes to 2.17i, how is the reimbursement distributed over the period of the plan?	N/A
The facility hires employees directly.	
2.17k. Does the facility have detailed records demonstrating the fees have been reimbursed to the affected workers according to the plan?	N/A
The facility hires employees directly.	
2.18. Does the facility issue wages/ compensation directly to workers, or in an unambiguous system that clearly shows that the worker controls the destination of his/her wages and access to his/her wages?	Yes
The employees' wages and benefits are calculated on a monthly rate basis plus over time and other benefits required by local law requirement such as attendance bonus, transportation and housing allowance, seniority bonus, and are	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

regularly paid twice per month in which the first payment is regularly paid by 25th of the month, and the second payment is regularly paid by 10th of the next month.

2.19a. Does the facility provide pay advances or loans to workers?

No

The facility does not provide pay advance or loans to workers.

2.19b. If yes to 2.19a, is there a written policy about the terms and conditions in place?

N/A

The facility does not provide pay advance or loans to workers.

2.19c. Is the policy communicated clearly to workers?

N/A

The facility does not provide pay advance or loans to workers.

2.19d. The terms and conditions shall not be used to bind workers to employment. Is there evidence that the facility is doing so?

N/A

The facility does not provide pay advance or loans to workers.

2.20. Does the facility hold original identification papers, travel documents, passports or other valuable personal items of their workers? If yes, provide details of relevant policies and procedures, including whether they involve any monetary deposit on the part of workers.

No

All selected employees stated that they are not required to pay any deposits or cash in advance during the recruitment process as well as employment.

2.21. Does the facility require any worker deposits or have any payment withholding/ deduction practices, either directly or on behalf of labor brokers/agents? If yes, provide explanations on what these deposits or withholdings/deductions are for.

No

No evidence of using subcontract to prison is found during this audit.

2.22a. Is there any prison labor used in this facility?

No

No evidence of using subcontract to prison is found during this audit.

2.22b. Does the facility subcontract production out to prison?

No

No evidence of using subcontract to prison is found during this audit.

2.23a. Do workers understand the terms of their employment?

Yes

All labor contracts of selected employees are in both languages (Cambodian/local and English) and signed by both parties (employer and employees).

2.23b. Are all work contracts in the language(s) understood by workers and signed by both parties (employer and workers)? For countries with at-will employment and/or no formal contracts, include a statement to that effect.

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

As per sampled selection employees and facility management interview, shows the time being signed the employment contract is regularly explained by HR personnel.

2.23c. Do contract provisions meet legal requirements and include all necessary information in a transparent and accurate manner? This includes, but is not limited to, wages, hours of work, days off, annual leave, disciplinary procedures that can result in termination, and, if relevant, dormitory terms and conditions.

Yes

As per employment contract reviewed, shows that the provisions meet legal requirements where is included relevant information listed as below:

1. Terms and condition of Fixed Duration Contracts including starting and ending date of the contract;
2. Wages and Benefits;
3. Premium rate for normal working, rest day and public holiday;
4. Working hours and ending shift;
5. Entitle leaves such as annual leave, special leave, sick leave, etc.,

2.23d. Are copies of contracts provided to workers and kept in personnel files?

Yes

All selected employees stated that they signed 02 copies of labor contract. 01 copy is provided to employee and 01 copy is kept in personnel files.

2.23e. Is there evidence that the facility has a practice of replacing or changing original contract terms to terms less favorable for the worker without the worker's knowledge and/or consent (i.e., contract substitution and supplemental agreements)?

No

No any evident is found to prove that facility has a practice of replacing or changing original contract terms to terms less favorable for the worker without the worker's knowledge and/or consent during this audit; Management representative stated that, the facility had a practice for giving prior notice to both union representative and worker representative whenever the facility had willing to change or amendment any term condition.

Non-Compliances Raised Against This Principle

Were non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan ([AUDIT REPORT - PRINCIPLE 03 : PROHIBITION OF CHILD LABOR](#))

Audit Questions and Objective Evidence/Comments



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Principle 3: Prohibition of Child Labor

Facilities will not hire any employee under the age of 15 (14 in less-developed countries) or under the minimum age established by law for employment, whichever is greater, or any employee whose employment would interfere with compulsory schooling.

Facilities will ensure they do not engage in any form of child labor, including, but not limited to, the internationally recognized worst forms of child labor. Consistent with ILO Convention 138, facilities may not employ any person at an age younger than the law of the jurisdiction allows and in any case not below the age of 15 (14 in less-developed countries), even if permitted by local law. In addition, facilities will adhere to local legal requirements regarding mandatory schooling. Further, if, where permitted by local law, a facility employs young workers (defined as workers whose age is between the minimum age of employment and 18 years), the facility will also comply with any applicable legal restrictions on the nature and volume of work performed by such young workers, as well as any other requirements imposed by law, including limitations related to working hours and to ensuring that such young workers do not perform any hazardous work (e.g., chemical handling or operating heavy machinery).

3.1. Does the facility maintain a written procedure to avoid employing child labor?

Yes

The facility has established and maintained the relevant policies and procedure regarding to "Prohibition of Child Labour" for its internal core standard, and it respected to the WRAP requirement as well as local law.

3.2. Are policies and procedures regarding child labor effectively communicated to all workers?

Yes

The facility has established an internal training program regarding to WRAP Principals also including facility's policy on "Child Labor Policy", also communicated on to relevant employees training on Child Labor training on November 05, 2024 by Ms. Vann Socheata-Compliance Supervisor.

3.3a. Do the programs and materials used to train relevant individuals on the child labor policies and procedures, including all individuals responsible for the hiring process, cover the requirements to obtain appropriate age documentation?

Yes

The facility has a training program regarding child labor policy and procedure to recruitment staffs that require appropriate age documentation must be checked for all prospective employees

After checked the appropriate age documentation, these documents were kept in the employees' personnel file for reference.

Ms. Vann Socheata-Compliance Supervisor assigned to conduct training for all related personnel.

3.3b. Do the programs and materials used to train relevant individuals on the child labor policies and procedures, including all individuals responsible for the hiring process, cover the requirements to review age documentation for authenticity?

Yes

The training material is included age documentation for authenticity.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

3.3c. Do the programs and materials used to train relevant individuals on the child labor policies and procedures, including all individuals responsible for the hiring process, cover the requirements to interview ALL prospective workers?

Yes

The facility staffs review workers' job application forms and keep in each individual personal file.
Every prospective worker must show their original ID card to HR officer for comparing with family book and other documents, and to verify their age during recruiting process before making a copy to keep for reference.

3.4. Does the facility explicitly prohibit all forms of child labor?

Yes

The facility has established and maintained the relevant policies and procedure regarding to "Prohibition of Child Labour" for its internal core standard, and it respected to the WRAP requirement as well as local law.

3.5a. Does the facility obtain proof of age documentation from potential workers and review the documentation for authenticity prior to hiring through an interview process (interview checklist maintained)?

Yes

Interview checklist for prospective employees is established by the facility and required to use during interview process.
Interview records are maintained and available to review

3.5b. Does the facility obtain proof of age documentation from potential workers and review the documentation for authenticity prior to hiring by comparing photo on age document with physical appearance of person?

Yes

Through employee interview and document review, the recruitment staff has compared photo on age document with physical appearance of person.

3.5c. Does the facility obtain proof of age documentation from potential workers and review the documentation for authenticity prior to hiring through worker's completed and signed employment application?

Yes

The employment application includes the following:

- Name of applicant
- Gender
- Nationality
- Date of Birth
- National ID number
- Contact phone number
- Place of birth
- Present resident
- Covid-19 Vaccination card
- Education Background
- Working experiences and records of interviewer is being signed by the applicant.

3.5d. Does the facility obtain proof of age documentation from potential workers and review the documentation for authenticity prior to hiring

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

through other methods (Please list)? Apply extra diligence in locations where child labor is common.

HR team requests the original ID card, Birth Certificate and family book etc. to verify and compare photo on identity document with physical appearance of the document holder.
Every prospective worker/employee must show their original ID card to HR Manager for verifying with family book and other documents, especially to verify their age during recruiting process before copy to keep for reference.

3.6. Does the facility retain proof of age documentation for each worker and maintain the information in the worker's personnel file for the length of time as required by law?

Yes

Based on personnel files check, the age proofs such as national ID card, family book, national election card Covid-19 vaccination card, or birth certificate were maintained with the application form and employment contract. The employment contract and application form have the employment date which can track how long an employee has been working in the facility.

3.7. Is there any evidence that suggests child labor is being utilized at the facility? (If a reasonable suspicion exists that there are age-borderline workers, be extremely cautious and attentive to assessing this compliance. If you suspect the age of any individual(s) you observe in the facility, you MUST seek to include them in the review process for age authentication, including worker interview.)

No

Rough site observation and employee interview, there is no evidence that suggests child labor is being employed at the facility.
As per observation during facility tour, there was no any suspicion of young employees and/or child employees were working in the facility, According to sampled selection personnel files.

3.8a. If young workers (legal minimum working age up to 18 years old) are employed, does the facility ensure that it has written policies and procedures related to recruitment and employment practices of young workers?

N/A

The facility did not use young employees. However, young worker policy and procedure were established in the facility.

3.8b. If young workers (legal minimum working age up to 18 years old) are employed, does the facility ensure that it has policies to safeguard young workers, including, but not limited to, ensuring young workers having access to the facility's grievance mechanism?

N/A

The facility did not use young employees.

3.8c. If young workers (legal minimum working age up to 18 years old) are employed, does the facility ensure that worker's assigned tasks are appropriate for their age, including, but not limited to, operating of heavy machinery, hazardous work environment, etc.?

N/A



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility did not use young employees.

3.8d. If young workers (legal minimum working age up to 18 years old) are employed, does the facility ensure that overtime/night work complies with local/national law?

N/A

The facility did not use young employees.

3.8e. If young workers (legal minimum working age up to 18 years old) are employed, does the facility ensure that medical check/registration with local bureau (if applicable) are conducted?

N/A

The facility did not use young employees.

3.8f. If young workers (legal minimum working age up to 18 years old) are employed, does the facility ensure that it accurately maintains the list of young workers?

N/A

The facility did not use young employees.

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan ([AUDIT REPORT - PRINCIPLE 04 : PROHIBITION OF HARASSMENT AND ABUSE](#)) 

Audit Questions and Objective Evidence/Comments

Principle 4: Prohibition of Harassment and Abuse

Facilities will provide a work environment free of supervisory or co-worker harassment and abuse, and free of corporal punishment in any form.

Facilities will ensure a workplace that is respectful of a worker's rights and dignity. This includes ensuring that no corporal punishment or physical coercion be used. Facilities will not engage in or tolerate – either at the workplace or in residential quarters provided by facilities or labor brokers acting on their behalf – any sexual harassment or abuse, indecent or threatening gestures, abusive tone or language or any other kind of undesired physical or verbal contact, such as bullying. In particular, facilities will ensure proper training at all levels - including management, supervisors and workers - to secure a workplace free of harassment and abuse.

4.1a. Does the facility maintain a written procedure on the prohibition of harassment, abuse, and corporal punishment?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility has established and maintained the relevant policies and procedure regarding to "Harassment or Abuse" for its internal core standard, and they comply with the WRAP requirement as well as local requirement.

4.1b. Are the definition(s) of the non-compliant behavior(s) and management policy(ies) consistent with the intent to prohibit all forms of this behavior?

Yes

The following behaviors are considered as harassment, abuse, and corporal punishment. The details are described below:

- Pervert, maltreat the mind and the body.
- Abuse, threaten, or using verbal outrage that impacts another's honor.
- Any actions that may impact another's spirit
- Solicitation of sexual favors by promise or reward.
- Dismissing if refused sexual advance any impolite words and behaviors that make somebody uncomfortable.

4.2a. Does the facility have an effective and mandatory program to train relevant individuals, including all individuals responsible for the supervision of workers, on the facility's policies and procedures prohibiting all forms of harassment, abuse, and corporal punishment?

Yes

The facility has established an internal training program regarding to WRAP Principals also including facility's policy on "Harassment or Abuse" also communicated on to relevant employees and new comer.

4.2b. Does the facility provide the trainings to its workers on the facility's policies and procedures prohibiting all forms of harassment, abuse, and corporal punishment?

Yes

The facility has established an internal training program regarding to WRAP Principals also including facility's policy on "Harassment or Abuse" also communicated on to relevant employees.

Ms. Vann Socheata-Compliance Supervisor is assigned to conduct training for all related personnel by including in the WRAP Principle training. The latest training was conducted on November 05, 2024. In additional, above policy and procedure are posted on bulletin board in the production workshop for employees' reference.

4.2c. How often does the training to relevant individuals and workers occur?

Describe

The facility has plan to randomly select the existing employees to join the induction training with new hire employees, and the induction training is including the "Prohibition of Harassment or Abuse", and this induction training for new hired employees is conducted every month.

The management informed that the main refresher training will be conduct once per year.

4.2d. When was the last training conducted?

Describe

The last "Harassment and Abuse" training was included in WRAP 12 principle training on November 05, 2024.

4.3a. Does the policy include reasonable punitive repercussions for non-compliance and repeated non-compliance? Note: The policy must apply to the behavior of all workers with special emphasis placed upon supervisory personnel.

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

All employees must comply with this policy and take appropriate measures to ensure such conduct does not occur. All complaints will be investigated in timely and confidential manner. If the investigation reveals the complaint is valid, disciplinary action will be taken to stop the harassment immediately and remedial action to prevent its reoccurrence will be taken.

4.3b. Are the punitive repercussions effectively communicated to workers?

Yes

The facility's management board and supervisors has signed the statements to acknowledge their understanding.

4.3c. Does the facility keep the records of all disciplinary action?

Yes

Disciplinary records were maintained.

4.4. Has the facility's management signed statements affirming their understanding of the facility's anti-harassment and abuse policies? (Note: If the facility has not required signed statements in the past, evidence of statements signed on a prospective basis, i.e., from a certain date forward, is acceptable.)

Yes

The facility's management board and supervisors has signed the statements to acknowledge their understanding.

4.5a. Does the facility communicate the policy on the prohibition of harassment and abuse to workers and third-party services (e.g., security guards, kitchen services)?

Yes

The facility informed its subcontractors were informed about their obligation under WRAP's requirement with affirming letter on January 25, 2024.

4.5b. When was the last time of such communication internally and externally?

Describe

Affirming letter dated on January 25, 2024.

4.6a Does the facility encourage workers to report instances of harassment or abuse, without fear of retribution, through effective communication of facility policies?

Yes

Employees are encouraged to report instances of harassment or abuse via hot lines or suggestion boxes post around the workshops. According to the procedure of investigating labor dispute, all investigations would be carried out with complete confidentiality for related employees.

4.6b. If any incidents of harassment or abuse were reported, were they resolved in a timely manner?

N/A

No incidents of harassment or abuse were reported. According to the facility's anti-harassment and abuse procedures, the independent investigation shall be immediately carried out for any report of incident of harassment and abuse. Identity of reporter shall be kept confidentially during the investigating process. Appropriate discipline measure shall be applied to any violator.

4.6c. Describe the process.

Describe



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Harassment & abuse violation reported - investigation and collect evidences - Review - Reporting - Discipline (if any) - record maintained.

4.7a. While inspecting the plant, were any signs noted of physical abuse (including but not limited to shared physical characteristics evident in many workers), such as: Bruising?

No

During site observation, it was found that there was no sign noted of bruising found during the audit.

4.7b. While inspecting the plant, were any signs noted of physical abuse (including but not limited to shared physical characteristics evident in many workers), such as: Obvious physical injuries (casts, or other corrective wraps, an exaggerated repetition of the same medical condition)?

No

There was no sign of physical injuries found during the audit.

4.7c. While inspecting the plant, were any signs noted of physical abuse (including but not limited to shared physical characteristics evident in many workers), such as: Isolated workers?

No

During site observation, there was no sign of isolated workers found during the audit.

4.7d. While inspecting the plant, were any signs noted of physical abuse (including but not limited to shared physical characteristics evident in many workers), such as: Overt sights of corporal or psychological punishment?

No

There is no evidence of corporal or psychological punishment found in this audit. It is determined through employees' interview.

4.8a. Through interviews with workers, were there any complaints about: Verbal abuse?

No

It is determined through employees' interview there was no verbal abuse in the facility.

4.8b. Through interviews with workers, were there any complaints about: Sexual harassment?

No

There was no sexual harassment occurred in the facility.

4.8c. Through interviews with workers, were there any complaints about: Threatening gestures?

No

There was no threatening gesture occurred in the facility.

4.8d. Through interviews with workers, were there any complaints about: Monetary deduction discipline?

No

There was no monetary deduction discipline occurred in the facility.

4.8e. Through interviews with workers, were there any complaints about: Bullying?

No



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

There was no bullying occurred in the facility.

4.8f. Through interviews with workers, were there any complaints about: Intimidation?

No

There was no intimidation occurred in the facility.

4.8g. Through interviews with workers, were there any other complaints?

No

There were no any other complaints.

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan (AUDIT REPORT - PRINCIPLE 05 : COMPENSATION AND BENEFITS) 

Audit Questions and Objective Evidence/Comments

Principle 5: Compensation and Benefits

Facilities will pay at least the minimum total compensation required by local law, including all mandated wages, allowances and benefits.

Facilities will ensure proper compensation for their employees for all the work done, by providing in a timely manner all the wages and benefits that are in compliance with the local and national laws of the jurisdiction in which they are located. This will include any premiums for overtime work or work done during holidays, as well as any other allowances or benefits, including any mandatory social insurance, required by local law.

5.1a. Does the facility maintain a compensation and benefits policy that includes all of the following: A detailed description of the workers' compensation and benefits at the time of employment?

Yes

The facility has written WRAP handbook where included social compliance policy and procedure for section of "Working hours and Benefit Policy" "Salary Payment Policy" has reviewed by competent management staff for its internal implementation.

5.1b. Does the facility maintain a compensation and benefits policy that includes all of the following: Both written and verbal explanations of wage calculations provided at the time of employment?

Yes

Wage calculation explanation in written and verbal was provided to employees at induction training.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

5.1c. Does the facility maintain a compensation and benefits policy that includes all of the following: A requirement that changes relating to compensation rates or methods of wage calculations shall be communicated timely and effectively?

Yes

Compensation rates or methods of wage calculations are required to communicate to employees before implemented.

5.1d. Does the facility maintain a compensation and benefits policy that includes all of the following: All compensation and benefits at least meet the local requirements?

Yes

All compensation and benefits of the facility are met and exceeded legal requirement and will be reviewed regularly by Compliance team via internal audit.

Based on payroll record review and sampled employees for interview, it was noted that the payment of employees meet and exceeded the legal requirement as below:

1. The wage in 2024 of employees was USD 202 per month for probation period, and USD 204 per month for regular employees. This practice is complied with legal requirement.

2. The facility pays each employee the attendant bonus with the amount of USD 15.00 per month, this practice is better than legal requirement which requires only USD 10 per month.

3. The facility pays each employee the transportation & housing allowance with the amount of USD 9 per month, this practice is better than legal requirement which requires only USD 7 per month.

4. The facility provides lunch allowance USD 12 per month for all workers, while local law does not require.

5. The facility provides overtime meal allowance 2,000 Riel (approximately USD 0.50) per day for workers who work overtime 2 hour per day Monday to Saturday which is complied with legal requirement.

6. The facility pays overtime premium rate in accordance with legal requirement are listed below:

~ Pays at 150% of regularly premium rate for overtime work from Monday to Friday, and 200% of premium rate paid to employee who worked overtime 2 hours per day on Saturday, this practice is better than legal requirement which requires only 150%;

~ The facility pays each employee at 300% (200%+100%) of regularly premium rate for overtime on Holidays while the legal requirement only 200% (100%+100%).

~ Pays at 200% for premium rate for work on rest day (Sunday).

5.2a. Does the facility compensate workers consistently with their terms of employment and in accordance with local/national laws and regulations related to minimum wage?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Based on payroll record review and sampled employees for interview, it was noted the payment of employees meet the legal requirement as below:

In 2024, the minimum wage in 2024 of employees was USD 202 per month for probation period, and USD 204 per month for regular employees. This practice is complied with legal requirement.

5.2b. Does the facility compensate workers consistently with their terms of employment and in accordance with local/national laws and regulations related to on time wage payments?

Yes

The employees' wages and benefits are calculated on an hourly rate basis plus over time and other benefits required by local law requirement such as attendance bonus, transportation and housing allowance, and are regularly paid twice per month in which the first payment with 50% of basic wage and overtime wage, it is regularly paid no later than 25th of the month, and the second payment is regularly paid no later than 10th of the next month with the rest basic wage plus other benefits required by local law requirement such as attendance bonus, transportation and housing allowance, seniority bonus etc..

5.2c. Does the facility compensate workers consistently with their terms of employment and in accordance with local/national laws and regulations related to overtime premium?

Yes

According to document review, employees interview and management interview, the facility pays overtime premium rate as below:

- Weekday overtime is 150% of basic wage from Monday to Friday, and 200% on Saturday.
- Night work overtime is 200% of basic wage;
- Weekly rest day is 200% of basic wage.
- Public holiday is 300% of basic wage (200%+100%);
- Night work 130%;

5.2d. Does the facility compensate workers consistently with their terms of employment and in accordance with local/national laws and regulations related to on time payment for resignation/ termination/dismissal/severance?

Yes

According to management interview and document review, the payment of resigned worker was paid 48 hours after the last working day, and it was in compliance with the local labor law.

5.2e. Does the facility compensate workers consistently with their terms of employment and in accordance with local/national laws and regulations related to benefits, including but not limited to, entitled leave, maternity leave, etc.?

Yes

All benefits required by national laws including maternity leave, sick-leave, special leave, annual leave, day-care center, breast-feeding time are provided to all eligible employees.

Whenever employees applied for sick-leave, special leave and annual leave, the facility does not deduct any wages of employees.

All employees are provided annual 1.5 days per month and 18 day per year. The granted annual leave is added 1 day up every 3 years. The un-used annual leaves of employees are compensated to employees by cash.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

5.3. Do the facility's trainee and probation policies comply with the local/national laws?	Yes
The probation employees are guaranteed at least equal with legal minimum wage. However, the facility did not use trainee.	
5.4a. Does the facility meet its obligations on social insurance?	Yes
The facility pays the social insurance of worker accident and injury to the National Social Security Fund (NSSF) every month.	
5.4b. Does the facility cover all eligible workers under social insurance? If No, provide explanations.	Yes
All employees currently work for the facility, they receive the social insurance including work accident and health care which is 100% paid by facility.	
5.4c. Does the facility make the required payments to the government without delay?	Yes
The facility pays the social insurance of worker accident and injury to the National Social Security Fund (NSSF) every month. The last payment was checked-out on November 25, 2024, pay for the month of October 2024 for 2,052 workers.	
5.5a. Does the facility post legal minimum wage rates, overtime premium rates, benefits policies, social insurance, and additional payment information in the language(s) understood by the facility workers?	Yes
Legal minimum wage rates, overtime premium rates, benefits policies, social insurance, and additional payment information in local language (Khmer) are posted on bulletin board for all employees to reference.	
5.5b. Are workers provided with adequate communication of their legally mandated minimum compensation rights, including overtime premiums?	Yes
According to sampled employees interview, management interview and document review, the facility communicated the policy and procedures related to "Compensation and Benefits" to management level staff and workers through training and posting on the notice board. Ms. Vann Socheata-Compliance Supervisor is assigned to conduct training for all related personnel by including in the WRAP Principle training. The latest training was November 05, 2024.	
5.6a. Does the facility produce and retain payroll records to support compensation, including overtime and benefits?	Yes
The facility has well maintained payroll records to support compensation including overtime and benefits. The past 12-months of payroll and time records is available for review during the day of audit.	
5.6b. Does the facility keep such records for such time as required by local/national laws? Please state the record retention time required by local/national laws.	Yes
The facility management informed that will keep all the records of payroll more than 03-years.	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

5.6c. In the case the facility pays its workers through wire transfers, does the facility produce and retain proof of bank statements showing all the transactions in a verifiable way? (Note: The name of the worker, salary amount, and the date of the transaction must appear on the bank slip showing the transaction, as well as the recipient's bank name and account.)

Yes

The facility pays its employees by bank transfer.

The payment is paid by bank transfer (ACLEDA Bank) to workers and records of payment are verified for the months of November, September and July 2024.

5.7a. Does the facility provide all workers with a pay record or stub that lists the components of the wages paid, including all deductions?

Yes

According to sampled employee interviews, pay slip is provided individually to each employee every month prior pay day. It is in the local language of employees with details of hours worked, entitled wage, legal benefits and withholding/deduction including basic wage, overtime wage, food allowance for OT work, transportation and housing allowance, attendant bonus, and income tax deduction.

5.7b. Do all workers sign off on wage pay records/stub, including when done by direct transfer into the worker's bank account?

Yes

Employees signed on payroll records whenever they receive wages from the facility.

5.7c. List all deductions show on workers' paystub.

Describe

Salary tax and pension schemes as legal requirement

5.8a. Are there any piece rate workers in the facility? If so, review a sampling of the documentation for piece rate workers as compared to wage rate workers to ensure compliance with this Principle.

No

No piece rate workers worked in the facility

5.8b. Does the facility have a written and coherent policy on piece rate compensation, including overtime premium rates?

N/A

No piece rate workers worked in the facility

5.8c. Does the piece rate compensation at least satisfy the minimum compensation prescribed by law?

N/A

No piece rate workers worked in the facility

5.8d. Do workers sign off on material counts for piece rate systems?

N/A

No piece rate workers worked in the facility

5.9a. Does the facility have a daily/weekly/ monthly quota for its production workers to meet?

No



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility has the daily quota for production workers to meet the target. However, the worker could leave the workplace after working hour.

5.9b. What percentage of workers reach the quota within a regular work shift?

Describe

From interviewed workers, informed that around 80% of workers could reach a production target within a regular work shift.

5.9c. What happens when the quota is not met?

Describe

No any issue to workers, even though they cannot reach a production target and workers freely to leave and the end of work shift.

Does this facility have a Social Insurance Waiver? If Yes, upload a picture of the waiver and add an English translation if necessary.

No

The facility did not have a Social Insurance Waiver.

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan ([AUDIT REPORT - PRINCIPLE 06 : HOURS OF WORK](#)) 

Audit Questions and Objective Evidence/Comments

Principle 6: Hours of Work

Hours worked each day, and days worked each week and each month, should not exceed the limitations of the country's law. Facilities will provide at least one day off in every seven-day period, except as required to meet urgent business needs.

Facilities are required by local law to adhere to any limits set on regular working hours as well as any limits set on overtime work. Long term participation in the WRAP Certification Program is contingent upon meeting the limitations set by local law. WRAP recognizes that this can be a particularly challenging requirement, especially when taking into account local enforcement norms and customs. In light of this reality, WRAP will permit full compliance with local laws on working hours to be achieved incrementally, provided that a given facility meets the following conditions: is fully transparent about its working hours; ensures that those hours are all being worked voluntarily, in conditions that protect worker safety and health; compensates all employees in keeping with WRAP Principle 5; and shows improvement toward meeting the working hours requirements from one audit to the next.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

6.1. Does the facility have procedure to ensure compliance with national and local laws?

Yes

The facility has written WRAP handbook where included social compliance policy and procedure for section of "Hour of Work" for its internal implementation.

6.2. Does the facility have an effective program and relevant materials to train all individuals, including all individuals responsible for production coordination and scheduling, to ensure that workers work no more than the legal maximum hours, including overtime ceilings?

Yes

The facility has established an internal training program regarding to WRAP Principals also including facility's policy on "Working hours and Benefit Policy" "Salary Payment Policy" Ms. Vann Socheata-Compliance Supervisor was assigned to conduct training for all related personnel by including in the WRAP Principle training on November 05, 2024.

6.3a. Are all workers made aware, at the time of hiring, of facility policies and procedures that specify the legal limitations on the maximum hours of work per day, week and month, both regular and overtime?

Yes

Based on document review and employee interview, it was noted that working hour policy and procedure were trained to employees at induction training and the maximum working hours of the facility such as: All employees are not required to work more than 10 hours per day (08 regular hours and 02 overtime hours); 60 hours for weekly working hours (48 hours for regular working hours and 12 hours for weekly overtime).

6.3b. Are all workers made aware, at the time of hiring, of facility policies and procedures that specify the legal limitations on the maximum number of consecutive days they can legally be required to work?

Yes

All employees are required to work for 6 consecutive days per week. It is prohibited from using the same employee for more than six days per week.

6.4a. Does the facility retain complete and accurate time records onsite of at least the past 12 months that reflect the days and dates workers worked (if the local requirement is more than 12 months, follow the local one)?

Yes

The facility uses finger scanning system to record working hours of employees. Employees are required to record their time in/out 4 times per day. The day and dates employees worked are indicated on attendant record.

6.4b. Does the facility retain complete and accurate time records onsite of at least the past 12 months that reflect the number of hours worked each day (if the local requirement is more than 12 months, follow the local one)?

Yes

Attendance record review, the number of hours worked each day is reflected on the time record.

6.5a. Does a crosscheck of other facility records, such as production records and CCTV (if applicable), show any 7th day work?

Yes

It was noted that some workers worked on Sunday in August 18 and September 15, 2024.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

6.5b. Does a crosscheck of other facility records, such as production records and CCTV (if applicable), show inconsistencies with time records?

No

As per production record and cross checked are consistencies with time records.

6.6a. Are daily overtime hours worked in compliance with local/national laws? Check any that applies. If there are excessive overtime hours, state the total number of hours including overtime.

No

Based on document review, employee and management interviews, it was noted that some workers worked overtime more than 2 hours per day with detail is as below:

- 34 out of 35 sample selected workers worked overtime from 4 to 7 hours per day in November 2024 at all sections.
- All 35 sample selected workers worked overtime from 4 to 6 hours per day in September 2024 at all sections.
- 30 out of 35 sample selected workers worked overtime from 4 to 6 hours per day in July 2024 at all sections.

Follow-Up Audit on February 21-22, 2025:

Based on selected payroll and time record review, employee and management interviews, it was noted that:

- 27 out of 35 selected employees worked overtime more than 2 hours per day, the maximum was from 4 to 5 hours per day in January 2025.
- 25 out of 35 selected employees worked overtime more than 2 hours per day, the maximum was from 4 to 5.5 hours per day in December 2024.

6.6b. Are weekly overtime hours worked in compliance with local/national laws? Check any that applies. If there are excessive overtime hours, state the total number of hours including overtime.

N/A

Not Applicable; No legal requirement on weekly overtime hours.

6.6c. Are monthly overtime hours worked in compliance with local/national laws? Check any that applies. If there are excessive overtime hours, state the total number of hours including overtime.

N/A

Not Applicable;
No legal requirement on monthly overtime hours.

6.6d. Are quarterly overtime hours worked in compliance with local/national laws? Check any that applies. If there are excessive overtime hours, state the total number of hours including overtime.

N/A

Not Applicable;
No legal requirement on quarterly overtime hours.

6.6e. Are yearly overtime hours worked in compliance with local/national laws? Check any that applies. If there are excessive overtime hours, state the total number of hours including overtime.

N/A

Not Applicable;
No legal requirement on yearly overtime hours.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

6.7a. Does the facility have a written, rational, and well-communicated policy defining 'urgent business needs'? Note: The definition of 'urgent business needs' cannot be vague or open-ended. It must be limited to delays/interruptions in production caused by natural calamities, non-repetitive production deadlines or unforeseen circumstances beyond the facility's control. A coherent and consistent rationale must be evident in the definition and infrequent deployment of 'urgent business needs'.

Yes

The written "urgent business needs" policy was established and reviewed on January 02, 2024 in which definition of urgent business needs was described:

- Discovery that the remaining time-plan for production may not conform from its remaining actual time to meet the scheduled shipment.
- Discovery of materials and accessories are insufficient that lower the on-going production from its estimated output planned forecast. Overtime would be needed to meet its schedule shipment.
- Occurrence of calamity disturbances, power supply failure, machine troubles that affect the production from its planned period.
- Natural disasters from floods, storms and fire.
- Political uprising or worker strike/demonstration in the country.
- This policy was communicated to all workers when they start working here. In addition, this policy is periodically refreshed to all workers when the urgent production periods are coming.

6.7b. Were there occurrence(s) of urgent business needs in the past 12 months? If Yes, list the number of instances and the occasions occurred: E.g., November 4 - 12, 2020

No

The urgent business needs were not identified in the facility in the past 12 months.

6.7c. If yes to 6.7b, does the facility provide one day off after 13 consecutive working days, if applicable?

N/A

The urgent business needs were not identified in the facility in the past 12 months.

6.7d. If yes to 6.7b, list: department(s) & # of workers involved in each department and provide reasons for such occurrence(s):

Describe

The urgent business needs were not identified in the facility in the past 12 months.

6.8a. Other than cases of "urgent business needs", do workers get at least one day off after six consecutive working days?

Yes

Based on document review, employee and management interviews, it was noted that selected workers did not get at least one day off after six consecutive working days, as below observed:

- 2 out of 35 sample workers at the finishing section worked 14 days before taking a day off, it was from 1 to 14 November 2024.
- 25 out of 35 sample workers at all production sections worked from 16.5 to 27.5 days before taking a day off, it was from 01 to 28 September 2024.
- 3 out of 35 sample workers at finishing section worked from 17 to 31 days before taking a day off, it was from 1 to 31 July 2024.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Follow-Up Audit on February 21-22, 2025: Closed

Based on selected payroll and time record of December 2024 and January 2025 reviews, employee and management interviews, it was noted that one day off after six consecutive days work was provided to employees.

6.8b. If no to 6.8a, in the past 12 months, how many instances occurred where workers worked more than 6 consecutive days? List the number of instances and the occasions occurred: E.g., one time, November 4 - 12, 2020

Describe

The instances occurred where workers worked more than 6 consecutive days with detail at below:

- November 1-14, 2024
- September 1-28, 2024
- August 05-17, 2024
- July 1-31, 2024
- June 10 to 17, 2024
- May 13 to 25, 2024
- April 22 to 30, 2024
- March 11 to 23, 2024
- March 25 to 31, 2024

According to document review, there were some workers worked on Sunday, not whole the factory.

6.8c. If no to 6.8a, list department(s) & # of workers involved and reasons for such occurrence(s):

Describe

Department(s): All sections

of workers in each department:

- November 1-14, 2024: 248 workers.
- September 1-28, 2024: 436 workers.
- August 05-17, 2024: 125 workers.
- July 1-31, 2024: 125 workers.
- June 10 to 17, 2024: 268
- May 13 to 25, 2024: 115 workers
- April 22 to 30, 2024: 54 workers
- March 11 to 23, 2024: 25 workers
- March 25 to 31, 2024: 46 workers

Reasons for such occurrence(s): Did not provide the reason during the assessment date.

6.9 Are notifications of maximum regular and overtime hour policies visibly posted in the language(s) understood by the facility's workers and management personnel?

Yes

The working hour policy and procedure and overtime notification are posted on the bulletin board in the production workshop for employees' reference.

Non-Compliances Raised Against This Principle



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

Yes

1. NC# 1 : Observation

WRAP Principle Q 6.6a: Are daily overtime hours worked in compliance with local/national laws? Check any that applies. If there are excessive overtime hours, state the total number of hours including overtime.

National/Local Law: PRAKAS 80/99 and AC AWARD 10/04.

Finding: Based on document review, employee and management interviews, it was noted that some workers worked overtime more than 2 hours per day with detail is as below:

- 34 out of 35 sample selected workers worked overtime from 4 to 7 hours per day in November 2024 at all sections.
- All 35 sample selected workers worked overtime from 4 to 6 hours per day in September 2024 at all sections.
- 30 out of 35 sample selected workers worked overtime from 4 to 6 hours per day in July 2024 at all sections.

Facility's corrective action plan: The facility shall ensure to limit overtime working hours to comply with legal requirement.

Projected completion date: N/A

Responsible person's name and title: Ms. Van Socheata-Compliance Supervisor

Follow-Up Audit on February 21-22, 2025:

Based on selected payroll and time record review, employee and management interviews, it was noted that:

- 27 out of 35 selected employees worked overtime more than 2 hours per day, the maximum was from 4 to 5 hours per day in January 2025.
- 25 out of 35 selected employees worked overtime more than 2 hours per day, the maximum was from 4 to 5.5 hours per day in December 2024.

Quality Plan ([AUDIT REPORT - PRINCIPLE 07 : PROHIBITION OF DISCRIMINATION](#)) 

Audit Questions and Objective Evidence/Comments

Principle 7: Prohibition of Discrimination

Facilities will employ, pay, promote, and terminate workers on the basis of their ability to do the job, rather than on the basis of personal characteristics or beliefs.

Facilities will ensure that all terms and conditions of employment are based on an individual's ability to do the job, and not on the basis of any personal characteristics or beliefs. Facilities will ensure that any employment decision – involving hiring, firing, assigning work, paying or promoting – is made without discriminating against the employees on the basis of race, color, national origin, gender, age, sexual orientation, religion, disability, or other similar factors (pregnancy, political opinion or affiliation, social status, etc.).

7.1. Does the facility have procedures and practices to ensure compliance and remediation with the facility policy?

Yes

Non-Discrimination Policy" is established, reviewed and maintained for the internal core standard of the facility, and it is in compliance with the local law.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

7.2. Are the facility's written policy, practices and procedures on discriminatory behavior effectively communicated to and understood by all workers and management personnel?

Yes

Through the facility tour, the discrimination policy in local language (Khmer) is posted on the bulletin board.

7.3. Does the facility have an effective program and materials used to train relevant individuals, including all individuals responsible for the supervision of workers and the hiring process, on the facility's policy and procedures prohibiting discrimination?

Yes

Sampled employees interview, management interview and document review, the facility communicated the policy and procedures related to prohibition of discrimination to management level staff, employees and security guards through training and posting on the notice board.

Ms. Vann Socheata-Compliance Supervisor is assigned to conduct training for all related personnel by including in the WRAP Principle training. The latest training was conducted on November 05, 2024

7.4. Does the facility effectively communicate the requirements of this Principle to third parties (subcontractors, labor brokers/ agencies, industrial parks, export processing zones, free trade zones, etc.) that may recruit and screen applicants on its behalf in writing?

N/A

No third party is engaged or used for applicant recruitment or screening. Currently, all employees are directly hired by employees.

7.5. Has the facility had any discrimination charges filed against it by workers, regulatory agencies or any outside agency during the past two years? If so, please provide details.

No

According to document review and employee interview, there was no discriminatory charge filed against by employee.

7.6. Does the facility explicitly prohibit mandatory pregnancy testing as a condition of employment or continued employment?

Yes

According to document review and employee interview, the mandatory pregnancy testing as a condition of employment prohibited in the facility.

7.7. Are workers with the same job and seniority paid the same rate, irrespective of race, color, national origin, gender, age, sexual orientation, religion, disability, or other characteristics?

Yes

As per payroll record review, facility's policies and internal rules and employee interview, the employees receive same pay for the same job and seniority irrespective of other personal characteristics.

7.8. Do all workers have an equal opportunity to work overtime?

Yes

As per sampled employee interview and facility management interview, all employees daily informed to sign on the overtime work on their voluntary basis prior to overtime work and they may sign off the voluntary overtime



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

application form if they want to work overtime.

7.9. Do all workers sign statements (statements may be included in an employment application or contract), written in the language(s) understood by workers, affirming their receipt and understanding of the facility's anti-discrimination policies and procedures?

Yes

Based on document review and management interview, it was noted that, no evidence of signed statements affirming letter from all 35 sample employees to confirm they receipted and understood of the facility's anti-discrimination policies and procedures was provided for auditor review, due to no such statement or affirming form was established yet.

7.10. Are pregnant women engaged in work that creates a risk for their pregnancy or reproductive health?

No

According to observation during facility tour and employee interview, pregnant women work light jobs to reduce the risk for their pregnancy or reproductive health.

7.11a. Does the facility have written policies and procedures related to termination and layoff?

Yes

The facility established policy and procedure on resign and termination. The policy and procedure was issued with dual language.

7.11b. Do these policies and procedures comply with local/national laws?

Yes

Based on document review, the policy and procedure on resign and termination is in compliance with national labor law.

7.11c. Does the facility provide training to all workers on termination and layoff policies and procedures, particularly to newly hired workers?

Yes

According to document review and employee interview, the last training about termination and layoff policy and procedure is provided to employees.

7.12. Can workers terminate employment by giving proper notice (defined by local laws or by contract terms) at any time and without penalty?

Yes

According to policy and procedure review and employee interview, employees are aware of the policy and procedure. It was confirmed that if employees or employer notice about termination of employment within the proper time which required by law, there will be no any penalty.

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A



Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Quality Plan (AUDIT REPORT - PRINCIPLE 08: HEALTH AND SAFETY) ↓

Health and Safety Overview

Principle 8: Health and Safety

Facilities will provide a safe and healthy work environment. Where residential housing is provided for workers, either directly by facilities or through labor brokers, facilities will ensure it is safe and healthy housing.

Facilities will provide a safe, clean, healthy and productive workplace for their employees. Facilities shall prioritize worker health and safety above all else, and proactively address any safety issues that could arise. This will include a wide variety of requirements, such as, ensuring, among other things, the availability of clean drinking water (at no charge to workers), adequate medical resources, emergency exits and safety equipment, well-lit and comfortable workstations, and clean restrooms. Further, facilities shall adequately train all their workers on how to perform their jobs safely.

8.1. Does the facility comply with all relevant health and safety laws and regulations, including any directives related to public health issued by relevant local authorities?

Yes

The facility obtains certificates, recording of inspection and training of fire drills, first aid training, industrial operation licenses, and certain heavy machines/equipment operated in the facility.

8.2. Has facility management deployed an adequate plan to address public health issues in the facility

Yes

The facility management has set up a system to address public issues in the facility such as conducting regular health and safety risk assessment, internal monitoring. All identified issues/hazards regarding health and safety will be addressed as soon as possible.

8.3. Does the facility undertake internal monitoring of its health and safety systems, including fire safety, to ensure it is following written procedures/processes and meeting the requirements of all relevant laws? Please describe the nature of the internal monitoring procedures, including frequency and coverage

Yes

The internal monitoring of health and safety including fire safety is undertaken by Ms. Vann Socheata-Compliance Supervisor. The scope of internal monitoring covered entire of the facility. The last internal monitoring was conducted on December 07, 2024.

8.4a. Have risk assessments been carried out throughout the facility, including fire risk assessments?

Yes

The facility has regularly carried out/conducted general risk assessment including fire risk and health & hygiene risk.

8.4b. How often does the facility perform risk assessments?

Describe

Risk assessments are conducted on August 22, 2024



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

8.4c. Were the findings communicated with management and health & safety committee?

Yes

Findings of risk assessment were communicated with management and health & safety committee on the same date.

8.4d. Were actions taken to correct the findings? (Note: If a facility had findings from risk assessments but has since corrected them, no NC should be raised.) Please describe the actions taken and resulting improvement/correction.

Yes

The corrective action had been taken.

The facility had reviewed and reduced risky of risk assessment as the following:

- 1). Written policy and procedure to prevent the risk;
- 2). Providing training;
- 3). Conduct meeting with OSH committee

8.5. Does the responsible person(s) work with health & safety committee to address findings from the facility's internal monitoring and risk assessments?

Yes

Name(s) and title(s):

Mr. Gamini-Compliance Manager

Mr. Sok Moyukeo – HR Supervisor

Ms. Vann Socheata (Nicole) - Compliance Supervisor

The health & safety committee conducted meeting at least every 3-month.

The latest was conducted on December 14, 2024

8.6a. Is a regular occupational health check arranged for workers involved in hazardous job duties, if any?

Yes

The facility provided health check for all employees when first joining facility. Anyway, no hazardous job duty was found in the facility.

8.6b. Is the regular occupational health check free for the applicable workers?

Yes

The facility provided health check for all employees when first joining facility for free of charge.

8.7. Has the facility properly tracked health, safety, and fire incidents in the past 12 months?

Yes

The facility has kept the record health, safety, and fire incidents, was recorded by onsite infirmity staff and submitted to General department of Health of The Ministry of Labor Vocational and Training.

The recording health, safety, and fire incidents are regularly review by OSH committee.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

8.8. Does the facility have an effective program and materials to train relevant individuals, including all individuals responsible for the supervision of workers, on all of the relevant occupational health and safety issues?

Yes

Occupational health and safety training was provided to employees at induction training and annual refresher training for all employees. Training record and training material were available for review. The latest for induction training was conducted on December 03, 2024 and latest general health and safety training was conducted on October 09, 2024.

8.9. Does the facility have a written safety program, including written emergency procedures to handle natural disasters, fire safety, and emergencies and industrial accidents?

Yes

The facility has a written safety program, including written emergency procedures to handle natural disasters, fire safety, and emergencies and industrial accidents. The new emergency procedure was updated on January 02, 2024 to include new warehouse.

8.10a. Are health and safety reports maintained by the facility?

Yes

The last risk assessment was conducted on August 22, 2024. The latest general health and safety training was conducted on October 09, 2024.

8.10b. Are heavy machinery inspection (boilers, compressors, etc.) documents maintained by the facility?

Yes

Based on document review, heavy machinery is annually inspected by Ministry of Industry & Handicraft. In addition, the facility obtains certificates of generators, forklifts, boiler and air compressors.

8.10c. Are maintenance reports maintained by the facility?

Yes

The maintenance report is regularly maintained by mechanic team. All machines are equipment's are mechanic team.

8.10d. Are fire extinguisher records, noting the date of inspection and expiration, maintained by the facility?

Yes

The facility regularly inspects its fire extinguishers for monthly basis. During the facility tour, the sampled fire extinguishers were found valid and functioning.

8.10e. Are emergency evacuation drill records (at least semi-annual, roughly six months apart) for all shifts, including night shift, and childcare, noting the date and detailed results, maintained by the facility? List at least three (3) emergency evacuation drill dates, two (2) in the past and one (1) planned for every shift, if applicable. List the time it took for all personnel to evacuate.

Yes

The facility conducts external training for firefighting and evacuation drill training every 6 months. The last two times training were on May 25, 2024, and November 02, 2024, each evacuation drill took about 60 second to evacuate to the assembly point. No injury occurred during the training when the employees evacuated from their workplace to the identified assembly points.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility has planned to conduct upcoming fire drill training on May 05, 2025.

8.10f. Are work injury reports maintained by the facility?

Yes

The facility has maintained work injury reports including the nature and frequency of accidents and records were provided for review.

8.10g. Are clinic logs, noting date and reason for visit, maintained by the facility?

Yes

The facility has maintained proper visit logs noting the reason for visit of clinic room and hospital that provide medical service treatment for facility.

8.11. Have any government agencies inspected the facility for compliance with safety and health regulations during the past two years? If yes, please list the findings.

Yes

The facility has an annually inspection from Department of Health and result meet local law requirement.

No any finding was found.

8.12a. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for heat stress/extreme temperatures?

Yes

The water-cooling system and exhaust fans are installed in the buildings.

8.12b. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for paint spray/spot cleaning booths?

Yes

There were sufficient PPE in spot cleaning room.

8.12c. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for welding safety?

N/A

No welding activity in the facility

8.12d. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for respiratory safety?

Yes

Face masks were provided to employees with free of cost.

8.12e. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for a bloodborne pathogen program?

Yes

Bloodborne pathogen program was established in place.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

8.12f. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for hearing/noise control?

Yes

The facility has provided PPEs such as earplugs to the operators.

8.12g. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for indoor air quality?

Yes

The facility obtains indoor air quality and noise control permit No. 1959, was issued on September 11 2024 for the material warehouse building, and No. 778 for main facility, was issues by the Ministry of Environment on March 13, 2024 for main facility. The validity is for 1 year.

8.12h. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for cotton dust ventilation?

Yes

The working environments factors such as heat, temperature, ventilation, noise, and dust were measured to meet local standard.

8.12i. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for workplace illumination?

Yes

From facility tour, the overall of workplace illumination are acceptable.

8.12j. Does the facility address the following occupational health and safety needs required by the relevant laws and regulations for sanitary waste disposal?

Yes

Trash from eating area was disposed to dustbin and moved to outside the facility every day. The facility had a separate area for waste from the workshop. Waste collecting and disposal was done by licensed waste handling company.

General Building Requirements

8.13. Does a visual inspection of the facility's building(s) suggest any potential concerns about physical integrity?

No

There was no potential concern about physical integrity of facility's buildings found at factory.

8.14. Are there any cracks on any of the building structures observed during the audit? If so, please include photos in Photo SECTION.

No

There was no crack on the building structures.

8.15. What is the overall general appearance of this facility? Please explain your assessment designation.

Good



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

During facility tour, it was noted that the general appearance was good.

8.16. Is the overall general appearance of the maintenance shop acceptable and not in a condition that could cause serious injury or harm?

Yes

The overall general appearance on this facility was good. The health and safety policy were posted on notice board for reference. Caution or warning signage were posted at the workshop.

8.17. Is trash properly disposed of both inside and outside the facility?

Yes

Trash bins were placed both inside and outside the facility. Hazardous wastes were collected and treated separately by the facility

8.18a. Are the toilets and washrooms in the facility in sanitary and serviceable condition?

Yes

The factory provided sufficiently toilet for all employees. Toilets were separated by gender and were in sanitary and serviceable condition.

8.18b. Are the toilets and washrooms in the facility meeting minimum quantity required by law?

Yes

There were 106 toilets (22 male and 68 females at the main site; 6 male and 10 females at new material warehouse) including 20 western style toilets for pregnant employees.

8.18c. Are the toilets and washrooms in the facility stocked adequately with soap and toilet paper?

Yes

The hand washing basins are supplied with liquid soap for employees washing their hands.

8.19. Are emergency exits unlocked during times when the facility is occupied to allow free, unobstructed exit from the facility?

Yes

All emergency exits were unlocked and unblocked during working hours.

8.20. During the facility visit, were any aisles blocked or restricting easy access to emergency exits?

No

As per site observation, worker and management interview, it was noted that 7 out of 30 observed exit aisles were partially blocked by tables, machines, chairs and material at sewing section and packing section.

In addition, at least 6 workers at sewing line 18 were blocked from all sides at their working station by sewing machines and garments.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation, it was noted that the emergency exit aisles and workplace were not block and freely accessible during working. In addition, the facility has provided fire safety awareness training to employees on January 18, 2025.

8.21a. Has the facility appropriately identified areas that, for fire safety purposes, should be designated as "non-smoking"?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility appropriately identified areas for fire safety purpose and non-smoking sign was posted at production areas.

8.21b. Is the facility properly enforcing the "non-smoking" policy for areas so designated?

Yes

The factory provided a smoking area for employees.

The "non-smoking" areas are posted with "No smoking" signs in the warehouse and production area.

8.22a. Does the facility maintain first aid supplies as required by law or if no legal requirement exists, as recommended by a local medical provider or relevant authority?

Yes

The first aid supplies were provided with 16 first aid items as per legal requirement.

8.22b. Are these first aid supplies available and accessible to all areas of the facility?

Yes

The facility provided first aid kits throughout the production areas and easy for employee's access. Employees also confirmed that they could get the first aid supplies from the box easily.

8.23. Is there clean and free drinking water that is easily accessible to all workers at the facility? List potability test report numbers, if applicable. If not, describe how the facility determines the drinking water is suitable for consumption.

Yes

The potable drinking water is provided to employees near production areas. Employees could access to it easily. Drinking water is provided to all employees with free of charge and the water is inspected every 6 months and certified by Pasteur Du Cambodge. The last testing report was on August 19, 2024.

8.24a. Is the facility's crèche/childcare area operated and maintained in a safe and healthy manner?

Yes

The childcare center was provided for female employees who have child/children from 1.5 year to 3 years old. However, the facility has paid USD 9 per month to employees instead of providing childcare center.

8.24b. Does the location of the crèche/childcare meet the local law requirements?

Yes

The childcare center has been set up in the facility as per legal requirement.

8.25a. Is the facility's canteen/cafeteria operated and maintained in a safe and healthy manner?

Yes

During the facility tour, it was observed that the eating area was available to the facility and it was operated in a safe and healthy manner

8.25b. Does the canteen/cafeteria have the required licenses to operate?

N/A



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Only eating area was provided for employees.

8.25c. Does the staff have the required health certificates?

N/A

Only occupational health check prior employment were conducted for employees.

Personal Protection Equipment (PPE)

8.26. Is appropriate PPE provided to affected workers in a timely manner and at no cost?

Yes

According to employee interview, facility management interview and policy review, PPE is provided to employee with free of charge.

8.27 Is the PPE appropriate and adequate for the workers' job and in good condition?

Yes

As per sampled employees interview (electrician, boiler operators, mechanics, cutting employees, and sewing machine operators) confirmed that, their PPEs (mask, metal glove, helmet, and safety shoes) were provided by the facility free of charge. They added that, they are free to change all poor quality PPEs once they meet.

8.28 Are all workers required to use PPE found using it?

Yes

As per site observation, worker and management interview, it was noted that workers did not use appropriated provided personal protective equipment, as below observed:

-20 out of 100 observed workers did not wear provided facemask at all sections.

-01 observed worker did not use provided goggles, special respiration, and gloves when praying chemical (acetone) as instruction of MSDS at spot leaning room.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation, document review, employee and management interviews, it was noted that:

- Production employees wearing their provided facemask during working.

- The employee who working at chemical spraying section wearing their provided personal protective equipment properly during working.

Remark: The facility has provided chemical management and personal protective equipment awareness training to employees on January 30, 2025.

Electrical Safety

8.29. Is there a qualified electrician in the facility responsible for maintaining electrical safety? If not, what is the facility doing to ensure electrical safety?

Yes

There was 1 qualified electrician; Mr. Chhay Phanno and Mr. Pho Sok Pao; obtained electrical certificate issued by the Ministry of Labour and Vocational Training on November 15, 2023. The validity is on October 05, 2026.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

8.30a. Does a visual inspection of the wiring indicate good general condition of cabling?

Yes

The condition of cabling is good since the facility used electrical conduit to isolate the electrical power connection.

Electrical safety inspection is regularly conducted by internal electrician with record maintained.

8.30b. Does a visual inspection of the wiring indicate no exposed or loose wires?

Yes

Based on facility tour, wiring is found to be tidy.

8.30c. Does a visual inspection of the wiring indicate proper insulation/grounding/earthing?

Yes

No exposed wiring was found as observed during the facility tour.

8.31a. Does a visual inspection of the electrical boxes and cabinets verify complete enclosures with covers provided?

Yes

As per site observation, worker and management interview, it was noted that 3 out of 10 observe electric panel at material warehouse and generator room were not equipped with inner covers.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation, it was noted that the inner isolator was installed to the electrical panels at raw material warehouse and generator room. In addition, the electric safety awareness training was provided by the Ministry of Industry, Science, Technology & Innovation on December 25, 2024.

8.31b. Does a visual inspection of the electrical boxes and cabinets verify switches and outlets maintained in good working order?

Yes

Swathes and outlets were maintained in good condition.

8.31c. Does a visual inspection of the electrical boxes and cabinets verify all knockouts/trips in place?

Yes

Knockouts/trips were found in its place.

8.31d. Does a visual inspection of the electrical boxes and cabinets verify adequate labeling with safety warning?

Yes

All electrical control boxes were posted with safety warning sign.

8.32a. Does the facility maintain a safety committee comprised of workers and management, which holds regular meetings and keeps minutes of proceedings?

Yes

The facility has a health and safety committee which is included of management, production line leaders, employees' representatives, and health care staff and holds meetings at least every 3 months to find the resolution for any unsafe condition. The last meeting was on December 12, 2024.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

8.32b. Does the committee discuss the findings from internal monitoring/risk assessments and find solutions? When was the last time the discussion occurred?	Yes
The facility has conducted meeting every 3-month with health and safety committee for their awareness and their preventive action taken.	
The last meeting was on December 12, 2024.	
8.32c. Does the committee discuss the health, safety, and fire incidents, if any, that happened in the facility and make the necessary preventative changes as needed?	Yes
Health and Safety Committee meeting was conducted every month. The committee has discussed the health, safety, and fire incidents, if any that happened in the facility and make the necessary preventative changes as needed.	
8.33a. Does the facility conduct health & safety and fire safety orientation training for all new workers?	Yes
New employees are given orientation on health and safety and fire training before they start working. The latest orientation training was conducted on December 03, 2024.	
8.33b. Do ALL workers have the right to remove themselves from serious imminent danger without seeking permission?	Yes
All workers have the right to remove themselves from serious imminent danger without seeking permission.	
8.34a. Does the fire safety training cover informing workers of the locations of fire alarm pull/button stations?	Yes
Employees are informed about the locations of fire alarm buttons and fire alarms also are set up with signage which are visible and easily to indicate.	
8.34b. Does the fire safety training cover informing workers of the locations of fire extinguishers in and near their work area?	Yes
Employees are informed about the locations of fire extinguishers and the signage of fire extinguisher as wisely posted at production workshop.	
8.34c. Does the fire safety training cover specific training for workers concerning the dangers of smoke inhalation?	Yes
The dangers of smoke inhalation are included in the orientation on health and safety.	
8.34d. Does the fire safety training cover informing workers of the locations of nearest exits and assembly points?	Yes
Employees are informed the location of nearest exits and assembly points.	
8.35. Is worker training conducted for first aid and safety?	Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The first aid and safety training was provided to employees regularly. The latest was on December 17, 2024.

8.36. Are the first aid responders /emergency safety personnel properly trained and identified?

Yes

The picture and ID No. of the first aid responders in each section were posted on the first aid boxes in the workplace visibly to all employees.

The first aid team was posted next to the first aid kits.

8.37. Have selected workers been trained on the proper use of firefighting equipment?

Yes

All selected employees confirmed they were trained on fire safety, emergency procedures and the use of firefighting equipment during firefighting and emergency evacuation drill training.

8.38. Have all workers who have any contact with chemicals and hazardous materials been trained on how to safely handle and dispose of specific chemicals and hazardous materials and how to eliminate fire risk?

Yes

According to document review and employee interview, the employees who used chemical have been trained on safety handling.

Fire Safety

8.39a. Does the facility have an emergency evacuation plan, in the language(s) understood by workers, posted in view of the facility's workers?

Yes

During site tour, it was noted that evacuation map was posted in the Khmer language for all production areas.

8.39b. Does the plan correspond accurately with the facility's actual floor plan?

Yes

The evacuation map reflected exactly the actual floor.

8.40a. Does a facility tour verify that emergency exits are in adequate number which meets the law requirements?

Yes

Emergency exits were in adequate number.

8.40b. Does a facility tour verify that emergency exits are in adequate locations?

Yes

Emergency exits were provided in adequate location in place.

8.40c. Does a facility tour verify that emergency exits are unimpeded, including the path leading to emergency exits?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

As per site observation, worker and management interview, it was noted that 7 out of 30 observed exit aisles were partially blocked by tables, machines, chairs and material at sewing section and packing section. In addition, at least 6 workers at sewing line 18 were blocked from all sides at their working station by sewing machines and garments.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation, it was noted that the emergency exit aisles and workplace were not block and freely accessible during working. In addition, the facility has provided fire safety awareness training to employees on January 18, 2025.

8.40d. Evacuation routes/paths are clearly marked?

Yes

Evacuation routes were marked with marking lines and arrows.

8.40e. Does a facility tour verify that emergency exits are opening outwards or always secured open during working hours? (If inward opening/sliding/rolling emergency doors are found to be secured open during working hours, raise it as an observation in CAP.)

No (Observation)

As per site observation, worker and management interview, It was noted that 10 out of 15 observed exit doors at all sections were sliding door or open inward door. However, the factory installed a locking mechanism to ensure doors always open. Besides that, warning sign was posted to remind workers do not close the door.

8.40f. Does a facility tour verify that emergency exits are leading to a safe assembly point?

Yes

From facility tour, emergency exits were leading to the safe assembly point in front of warehouse and production buildings.

8.41. Can assembly point(s) accommodate ALL workers?

Yes

According to facility tour and employee interviews, the assembly point in front of factory building enough for all employees.

8.42a. Does a facility tour verify that safety equipment is visible?

Yes

The firefighting equipment was visible in the factory.

8.42b. Does a facility tour verify that safety equipment is appropriate in functionality and number?

Yes

The firefighting equipment was appropriate in functionality and numbers.

8.42c. Does a facility tour verify that safety equipment is properly distributed throughout the facility?

Yes

The firefighting equipment was adequately distributed throughout the facility.

8.42d. Does a facility tour verify that safety equipment is easily accessible?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Firefighting equipment was free of obstruction and easily accessible.

8.42e. Does a facility tour verify that safety equipment is properly mounted?

Yes

The firefighting equipment was properly mounted.

8.42f. Does a facility tour verify that safety equipment is unblocked and free of obstruction?

Yes

The fire equipment was unblocked and free of obstruction.

8.42g. Does a facility tour verify that fire extinguishers are appropriate for the class(es) of fires possible in the area?

Yes

All fire extinguishers were appropriate for the class of fires expected in the place.

8.43. Are the fire-fighting water hoses and connections in usable condition?

Yes

Fire-fighting water hoses were installed and connected in good and usable condition.

8.44. Does the facility have appropriate measures to ensure adequate water pressure for fire-fighting water hoses and sprinkler systems?

Yes

Adequate water pressure was provided for fire-fighting water hoses. In order to ensure water pressure, facility conducted checking water pump and testing at least once per week.

Sprinkler Valves

8.45. Do sprinkler valves appear in good working order? If local/national laws do not require facilities to have sprinklers, state so.

N/A

The sprinkler system is not required by law.

8.46. Are all sprinkler heads kept unobstructed from storage or other materials?

N/A

The sprinkler system is not required by law.

Fire Alarm Boxes

8.47a. Are fire alarms unobstructed and identified?

Yes

All fire alarm call points were free of obstruction.

8.47b. Does the facility have a test schedule for all fire alarm boxes? State how the facility maintains this schedule.

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility had a test schedule for all fire alarm boxes on monthly basis

8.47c. Do fire alarms have flashing lights?

Yes

Strobe light alarm was installed at the workshop

8.47d. Are fire notification mechanisms audible?

Yes

During testing process, the fire alarm was audible. As workers interview, they were well aware of the sound of fire alarm. Strobe light alarm was installed at the workshop

Emergency Evacuation

8.48. Are lighting and alarm systems adequate and fitted with back-up systems?

Yes

Battery for fire alarm system was available in the facility

Emergency Lighting

8.49a. Is appropriate lighting in place in the facility?

Yes

Per site observation noted that emergency lighting was installed at appropriate location in the facility.

8.49b. Is the emergency power system working and in good condition?

Yes

Per testing and site observation noted that the emergency power system was worked in good condition.

8.49c. Does the facility regularly conduct a test to ensure the emergency power system is functioning correctly?

Yes

Per testing and site observation noted that the emergency power system was in good condition.

Stairwells

8.50a. Are all stairwell handrails in good condition?

Yes

All stairwell handrails was in good condition.

8.50b. Are all stair treads in good condition and does its width meet local law?

N/A

No local law requirement on stair treads. However, all stair treads was in good condition.

8.50c. Are all stair widths in compliance with the requirements of all relevant laws?

N/A



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

No local law requirement on stair widths. However, all stair widths was appropriate and safe.

8.50d. Are the stairways provided with appropriate artificial and emergency lighting?

Yes

The stairways were provided with appropriate artificial and emergency lighting.

8.50e. Are stairwells completely clear of obstructions?

Yes

All stairwells were completely clear of obstructions.

8.50f. Does the facility ensure stairwells are not used for storage?

Yes

The facility ensured stairwells were not used for storage.

Chemical Safety

8.51. Does the facility have a chemical safety program?

Yes

The facility has a documented policy and procedure on chemicals. In addition, the facility also has a chemical safety program to train related employees regularly.

8.52. Where applicable, does the facility properly store hazardous/toxic materials?

Yes

As per site observation, worker and management interview, it was noted that 10 of out of 25 liquid chemical containers at repairing room, generator area, waste house was not stored in secondary container to prevent leakage and spill.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation and management review, it was noted that all liquid chemical at repairing room, generator room and waste house were storage in the secondary containment. In addition, the facility has provided the chemical spilled awareness training to employees on January 30, 2025.

8.53. Does the facility have the required government storage and usage permits for chemicals, if required?

N/A

The facility was not legally required to obtain permit to use chemicals

8.54. Does the facility maintain documentation for chemical labeling (including fire safety), chemical usage warnings, and proper handling instructions?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

As per site observation, worker and management interview, it was noted that 5 out of 25 chemical containers were not labelled at waste house and generator area.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation, and management review, it was noted that all the proper label in local language was setup to all chemical container storage in the waste house and generator room.

8.55a. Are MSDSs available (in appropriate language(s)) for all chemicals used by the facility?

Yes

MSDS were posted at chemical warehouse and handling area in local language.

8.55b. Does the facility have functional eye washing machines if applicable?

Yes

Eye wash station was well functional during testing by auditor.

8.56. Does the facility ensure that all solvent wastes and flammable liquids are properly stored (including being kept in closed containers when not in use) at all times and kept away from potential ignition sources?

Yes

Chemical storage areas are free of ignition sources.

8.57 Are the chemical storage areas free of ignition sources, including lamps and lights?

Yes

Chemical warehouse was away from combustible material, ignition sources.

Boiler/Compressor/Generator Rooms

8.58a. Is the location of the boiler/compressor/ generator room consistent with all relevant requirements? (If no local or national laws apply, please describe the location of the boiler and compressor room.)

Yes

Air compressors, boiler and generator were located separately from the production buildings with restriction notice posted.

8.58b. Are boilers/compressors/ generators separated from production floor/office space as required by the relevant laws?

Yes

Air compressors, boiler and generator were located separately from the production buildings with restriction notice posted.

8.59. Are there housekeeping and maintenance procedures in place for the boiler and compressor rooms? Please describe the nature and execution of these procedures

Yes

The facility had housekeeping and maintenance procedures for the separated rooms of air-compressors.

8.60. Are there any fuel leaks?

No



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

According to facility tour, no fuel leaks observed.

8.61. Is the boiler operator certificate valid and authentic?

N/A

There was no boiler using in the facility.

Machine Safety

8.62. Do machines have required safety measures?

Yes

As per site observation, worker and management interview, It was noted that machine guard was not used properly, as below observed:

-15 out of 50 observed workers did not use eye-shield while working with overlock machines at sewing section.

-20 out of 50 observed workers did not use needle guard when working.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation, it was noted that employees who working with single needle sewing machine and overlock machine were used needle guard and eye-shield properly during working. In addition, the health & safety awareness training was provided to employees on December 21, 2024.

8.63. Do machines have relevant safety warnings in the language(s) understood by workers/machine operators?

Yes

All the machines have relevant safety warnings in local language spoken by workers/machine operators.

8.64a. Do machine operators have the required licenses?

Yes

The certificates of 4 air compressor operators, 3 generator operators, 1 steam boiler operator, and 7 fork-lift operators were issued by the Ministry of Industry, Science, Technology & Innovation on November 15, 2023, the expire date is on October 05, 2026.

8.64b. Do machine operators have the trainings as required by law?

Yes

Machine operators have provided machine safety training at induction training and re-fresher training on a regular basis.

Shared Building

8.65. Does the facility conduct joint risk assessments with other operations in the building?

N/A

There was no shared building in the facility.

Dormitories/Apartments

8.66a. Are there dorms/apartments provided for workers?

No



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

No dormitory provided to employees, only transport and housing allowance is provided to each employee.

8.66b. Are there dorms/apartments provided for management?

Yes

56 expatriate management (41 Chinese, 6 Sri Lankan, 6 Filipino, 1 Indonesian, and 2 Vietnamese) were provided onsite dormitory for accommodation with free of charge.

8.66c. If Yes to 8.66a and/or 8.66b, are the dormitories/apartments physically separated from the production building(s) and warehouse(s)?

Yes

Dormitory building was separated with production building and warehouses.

8.67. Does the dormitory/apartment have a written safety program, including written emergency procedures to handle natural disasters, fire safety, and emergencies and industrial accidents?

Yes

The facility established a written safety program, including written emergency procedures to handle natural disasters, fire safety, and emergencies and industrial accidents

8.68. What is the overall general appearance of the dormitory/apartment? Please explain your assignment designation.

Good

The dormitory was provided for foreign managers only. It was in good condition.

8.69. Does a visual inspection of the dormitory/apartment building(s) suggest any potential concerns about physical integrity?

No

No potential concerns about physical integrity were visually observed.

8.70. Has the facility posted an emergency evacuation plan of the dormitories/ apartments in the language(s) understood by the residents?

Yes

The facility posted an emergency evacuation plan of the dormitory in the language understood by residents

8.71. Does the facility conduct regular emergency evacuation drills (at least semi-annual) for the dormitories/ apartments?

Yes

The facility conducts external training for firefighting and evacuation drill training every 6 months. The last two times training were on May 25, 2024, and November 02, 2024, each evacuation drill took about 60 second to evacuate to the assembly point. No injury occurred during the training when the employees evacuated from their workplace to the identified assembly points.

The facility has planned to conduct upcoming fire drill training on May 05, 2025.

8.72. Does a dormitory/apartment tour verify that safety equipment is in compliance with the law requirements?

Yes

All safety equipment was functional and adequate as legal requirements.

8.73. Are exits unlocked during times when the dormitories/apartments are occupied to allow free, unobstructed exit from the dormitories?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

All exits unlocked during times when the dormitory was occupied to allow free, unobstructed exit from the dormitory

8.74. During the dormitory visit, were any aisles blocked or restricting easy access to emergency exits and to a safe assembly point?

No

All observed aisles were free from obstruction.

8.75. Is there clean drinking water that is easily accessible? List potability test report numbers, if applicable.

Yes

Clean drinking water was easily accessible.

8.76. Are the toilets and washrooms in sanitary and serviceable condition?

Yes

Toilet and wash rooms were located inside each room.

8.77. Is trash properly disposed of both inside and outside the dormitory/apartments?

Yes

Trash was properly disposed of both inside and outside the dormitory.

Dormitories Fire Alarm

8.78a. Are fire alarms unobstructed and identified?

Yes

Site observation noted that fire alarm was unobstructed and identified.

8.78b. Does the facility have a test schedule for all fire alarm boxes? State how the facility maintains this schedule.

Yes

Site observation noted that fire alarm box was internally inspected once per year.

Dormitories Emergency Lighting

8.79. Is the emergency power system working and in good condition?

Yes

Site observation noted that lighting was appropriately arranged in the dormitory.

Dormitories Stairwell

8.80. Are all stairwell handrails in good condition?

Yes

It was noted that 2 out of 2 observed stairwell were in good condition.

8.81. Are all stair treads in good condition and does its width meets local/national law?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Stair treads was in good condition.

8.82. Are stairwells completely clear of obstructions?

Yes

The stairwells in dormitory were completely clear of obstructions.

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan ([AUDIT REPORT - PRINCIPLE 09: FREEDOM OF ASSOCIATION & COLLECTIVE BARGAINING](#))

General Questions

Principle 9: Freedom of Association & Collective Bargaining

Facilities will recognize and respect the right of employees to exercise their lawful rights of free association and collective bargaining.

Facilities will respect the freedom of each employee to choose for him- or her-self whether or not to join a workers' association. Facilities cannot discriminate against workers based on whether or not they choose to associate. Both the facility and the workers shall ensure they conduct themselves in accordance with all relevant laws in this regard. Facilities will ensure an effective mechanism is in place to address any workplace grievances.

9.1 Does the facility have procedures that recognize and respect the right of workers to exercise their lawful rights of free association and collective bargaining?

Yes

The facility has written WRAP handbook where included social compliance policy and procedure for section of "Freedom Of Association & Collective Bargaining" for its internal implementation.

9.2a. Which of the following does the facility have: (Note: Facility is required to indicate whether an informal or formal association of workers exists. If a lawful association of workers exists, include a representative of such association in the interview process. Some form of effective mechanism must exist to address workplace grievances.) (List the name of the lead workers' representative (in the union, association, workers' committee, or collective representation of workers.)

A union

Workers' committee

Collective representation of workers

There were two trade unions formed in the facility name:

- Khmer Youth Trade Union of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. which was approved by the Ministry of Labor and Vocational Training on January 30, 2023, with registered No. 112180335, and reference No. 080. Mr. So Sophal is the Union President



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

- Khmer Union of Workers Spirit of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. which was approved by the Ministry of Labor and Vocational Training on August 10, 2021, with registered No. 112180479, and reference No. 539. Mr. Im Sarith was the Union President

No association is formed by employees inside or outside of the facility yet.
The facility has union and shop steward (worker representative) only.

The Seven (7th) mandate shop steward/worker representative of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. election was arranged on August 25, 2023 with 1,998 employees joined the election. The result of election was approved by the Ministry of Labor and Vocational Training on December 18, 2023. The shop steward/worker representative permit valid until August 26, 2025 with reference No. E1SS202301610.
Mr. So Sophal was the highest vote.

Shop steward/ Worker Representative was freely elected by all employees of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. The election of the seven (7th) mandate was held on August 25, 2023 with reference election report E1SS202301610, and valid for 2 years till August 26, 2025.

9.2b. Does this workers' group operate free from coercion or illegal restrictions to its operations?

Yes

Based shop steward/ worker representative interview, the shop steward is free to perform its duty such as internal meeting, external meeting, and to discuss/settle concern raised by employees with employer without any discrimination or penalty.

9.2c. Does the facility consult with the worker representatives on any issues that are a requirement by law such as facility disclosures, mass lay-offs, restructuring of the business etc.?

Yes

The facility discussed with employee's representative if any changing of working condition such as wages and benefits, working hour, or discipline practice.

The facility has its internal rule which is consulted with and agreed by the shop stewards before submitting to Labor Department for approval.

The facility always talks to the employee representatives on any workplace issue to solve the labor problem in a respectable manner.

9.2d. Is there any bargaining agreement or labor-management negotiation on workplace issues? Specify what agreement exists.

Yes

Based document review, trade union representative interview and management interview, there was no collective bargaining agreement established at the facility.

9.2e. If yes to 9.2d, how is the CBA/bargaining agreement implemented?

N/A

No the CBA/bargaining agreement was implemented.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

9.2f. If there is an CBA/bargaining agreement, do the terms meet the legal minimum requirements?

N/A

No the CBA/bargaining agreement was implemented.

Grievance Mechanism

9.3a. Does the facility have a documented grievance mechanism? Describe the mechanism in full, such as Workers' committee/representative/union members, round-table discussion, open door, suggestion box, helpline/hotline, and/or electronic online form, including how grievances are collected by facility designated personnel.

Yes

The facility has grievance procedure as below:

1. Employees may report the incidents through suggestion/ grievance box which provided by the facility for anonymity.
2. For emergency incidents, employees may report the incident cases to line leaders, supervisors, shop steward or trade union representative to get problems solved in timely fashion.
3. If line leaders, supervisors, shop steward or trade union representative cannot find the solution for the incidents, they are required to submit a written letter about incident to administrative department of the facility to find the solution within 1 day.
4. If facility management cannot find the solution, the facility and employee may file the case to Ministry of Labor and Vocational Training and court.
5. Log the record.

9.3b. Does the facility's responsible person(s) regularly review whether there were submissions of any grievances?

Yes

Based on employee interview, the selected employees are aware of the grievance mechanism of the facility. Firstly, they can raise their concern to their line leader/supervisor, if not this, then they can go to their elected shop steward, if not this, then they can lodge their complaint to suggestion box, if not this then they can directly management representative or appointed liaison officer. Currently, the facility setup 6 suggestion boxes for employees to use.

9.3c. What is the frequency of such review? (Note that the frequency should not be less than once a week.)

Describe

HR team, worker representative and union opened suggestion boxes together every week and conduct a meeting if have any issues.

9.3d. How does the facility address the grievances in a timely manner?

Describe

HR team will invite worker representatives and unions to join a meeting in case of found any grievances from workers.

9.3e. Does the facility maintain the records of such review?

Yes

The facility maintained records properly.

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

9.3f. How many grievances were received in the past 6 months?	Describe
From HR team interview and records review, no grievance was received in the past 12 months. In addition, it was informed that mostly they got minor issues which solved immediately once received from workers and no any serious cases from workers' grievances.	
9.3g. Does the facility have the resolution policy in place regarding the reported grievances by workers?	Yes
Grievance/compliant handling procedure / Non-retaliation policy and suggestion box policy were established.	
9.3h. What is the resolution process undertaken by the facility and human resources management in response to the grievances?	Describe
From interviewed with worker representative, mostly workers go to discuss/consult with their supervisors, worker representative or office staffs directly, in case of have any issues. Minor issue will be solved immediately once received direct grievance from workers. In case of cannot solve immediately, HR team will call relevant person such as shop steward and trade union if worker prefer to attend a meeting to find the solution.	
9.3i. Describe any appeal process available to workers.	Describe
Workers have right to discuss/consult directly with their supervisors, worker representative or office staffs in case of have any issues. In addition, they also can report through grievance letter in suggestion boxes in case of have any issues.	
9.3j. Is the grievance mechanism known to ALL workers? (Please provide grievance reference numbers to any evidence of the grievance mechanism being used)	Yes
Based on sample employee's interview, the selected employees are aware of the grievance mechanism of the facility. Firstly, they can raise their concern to their line leader/supervisor, if not this, then they can go to their shop steward/trade union representative, if not this, then they can lodge their complaint to suggestion box, if not this then they can directly management representative or appointed liaison officer. Currently, the facility setup 6 suggestion boxes for employees to use and 1 suggestion box at new material warehouse.	
9.3k. Are there any penalties to workers associated with using the grievance mechanism?	No
Based on sample employees interview, no penalty is implemented to those employees have been used the grievance mechanism channel. By the way, employees are encouraged to use all provided grievance mechanism channel in order to improve the working condition of the facility.	
9.3l. Describe any confidential reporting channel available to workers.	Describe
Grievance/complaint handling procedure and Suggestion box policy were established. Workers have rights to discuss/consult directly with their supervisors, worker representative or office staffs, in case have any issues. In addition, they also can report through grievance letter in suggestion boxes, in case have any confidential issues for reporting.	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

9.3m. Does the facility provide effective grievance mechanism trainings to its managers and supervisors?	Yes
The facility provided Grievance/complaint handling and Suggestion box policy training to office staffs, supervisors and shop steward on July 13, 2024.	
9.4a. If there is a union, are workers aware of the existence of the union? (Name(s) of union(s))	Yes
As per employees interview, they are aware of the availability of the union in the facility, because they are informed by the facility during the orientation training. In addition, the representative of each union also come to invite them to join as their union members based on their voluntary basis. The detail of the available unions are: There were two trade unions formed in the facility name: - Khmer Youth Trade Union of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. which was approved by the Ministry of Labor and Vocational Training on January 30, 2023, with registered No. 112180335, and reference No. 080. Mr. So Sophal is the Union President - Khmer Union of Workers Spirit of YORKMARS (CAMBODIA) GARMENT MFG CO., LTD. which was approved by the Ministry of Labor and Vocational Training on August 10, 2021, with registered No. 112180479, and reference No. 539. Mr. Im Sarith is the Union President	
9.4b. Are organization meetings held in the factory premises?	Yes
Shop steward and unions were given with office stationary for their working process. In addition, they all are entitled 2 hours off per week with full payment to conduct their weekly meeting.	
9.5a. Are there formal communication procedures between union/worker representatives/committee members and management? (NOTE: If a facility does not have a union, an answer is still needed.)	Yes
Communication procedure between employees' representative and employer was established in the facility.	
9.5b. What are the procedures for union/workers' representatives/committee members meeting with management to discuss work-place issues?	Describe
Based on the procedure, the 3-parties dialogue is monthly conducted to discuss on working conditions, suggestion from employees, production plan, etc.	
9.5c. Are union/workers' representatives/committee members consulted in establishing safe working conditions?	Yes
Shop steward/employees representatives have consulted on safe working conditional procedure and requirement.	
9.5d. Does management respond to union/ workers' representatives/committee members within a defined time?	Yes
The facility regularly enter into discussions with the employees' representatives in an open manner and within the terms of local/national law in case of the terms of local/national law are updated.	



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

9.6. Does the facility enter into discussions with the workers' representatives in an open manner and within the terms of local/national law? (NOTE: If a facility does not have a union, an answer is still needed.)	Yes
The meeting minute is displayed on the bulletin board where employees could access and read.	
9.7. Are the minutes of facility/worker representative meetings documented and available to the workers? (NOTE: If a facility does not have a union, an answer is still needed.)	Yes
The meeting minute is displayed on the bulletin board where employees could access and read	
9.8. Are workers' representatives elected on a free and confidential basis by the workers without interference from management? If no, what is the election process?	Yes
From record review and employee interview, it was noted that workers' representatives elected on a free and confidential basis by the workers without interference from management.	
9.9a. Does the facility discriminate, harass, or abuse against workers who form or participate in lawful associations?	No
The facility recognizes and respects the right of employees to exercise their lawful rights of free association and collective bargaining, and to hold opinions without interference from the factory management.	
9.9b. Does the facility discriminate, harass, or abuse against workers who choose not to join any union?	No
All interviewees confirmed, they are free to join or not join trade union organization on their own willingness without any discrimination.	
9.10a. Does the facility communicate its policies and practices pertaining to this Principle to facility workers that may perform recruitment or screening of applicants?	Yes
The facility communicates its policies and practices pertaining to this Principle to all facility employees	
9.10b. Does the facility communicate its policies and practices pertaining to this Principle to Third Parties (e.g., free zone office services, labor brokers/agencies) that may perform recruitment or screening of applicants?	N/A
No third party is engaged or used for applicant recruitment or screening. Currently, all employees are directly hired by employees.	

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:	No
--	----



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

N/A

Quality Plan (AUDIT REPORT - PRINCIPLE 10: ENVIRONMENT) 

Audit Questions and Objective Evidence/Comments

Principle 10: Environment

Facilities will comply with environmental rules, regulations and standards applicable to their operations, and will observe environmentally conscious practices in all locations where they operate.

Facilities will ensure compliance with all applicable legally mandated environmental standards, and should demonstrate a commitment to protecting the environment by actively monitoring their environmental practices. In particular, facilities will ensure proper waste management, including monitoring the disposal of any waste material - whether solid, liquid or gaseous - to ensure such disposal is done safely and in a manner consistent with all relevant laws. Facilities are encouraged to minimize their impact on the environment by applying the principles of reduce, reuse and recycle throughout their operations.

10.1. Does the facility have an environmental management system relevant to its industry?

Yes

The facility has written "Environment Health and Safety Policy" registered with the Ministry of Environment with reference #434 dated September 27, 2022, "Waste Management Procedure/ Solid Waste and Liquid Waste Management Procedure" as its internal core standard.

10.2a. Does the facility's environmental management system address where and how solid, chemical, sanitary, and waste-water substances are disposed of?

Yes

The solid waste or pieces/scrap of garment are disposed through a legal third party.

10.2b. Does the facility recycle as required by the law?

Yes

All solid wastes are discharge to the authorized for Industrial Waste Disposal for Transportation to land fill, waste collector company for damage and recycling process as per requirement determined by law.

10.3. Does the facility have a program and materials to train relevant individuals on each practice of the environmental management system, including the prevention and control of harmful release of industrial waste into the environment?

Yes

The internal training/ Risk assessment and Internal audit program regarding of WRAP Principals are also including policy and procedure "ENVIRONMENT", and also communicated to security guard. Ms. Vann Socheata-Compliance Supervisor assigned to conduct training for all related personnel by including in the WRAP Principle training. The latest training was conducted on November 05, 2024.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

10.4a. Does the facility maintain records of emission events?	Yes
The facility keeps its maintenance records of generators in the management office for easy reference. The health and safety policy including environmental protection has also been set up and available	
10.4b. Do emissions meet the permissible standards as defined by the law?	Yes
The air emission parameter was accepted by local law.	
10.5. Does a review of the following records reveal any irregularities: local government environmental inspection reports, certificates/permits, notices of deficiencies, corrective action notices or plans held by the facility, any correspondence from government officials	No
Based on document review and management interview, it was noted that the facility obtain environment permits as below: The facility maintained the Environment management plan was issued by the Ministry of Environment in January 01, 2021. •The facility's environmental permit No. 434, which was issued by the Ministry of Environment on September 27, 2012 with unspecified expiry date. •The Environmental Protection Agreement has been made and approved by the Ministry of Environment on September 21, 2012 with reference No. 813 with unspecified expiry date. •The facility obtains indoor air quality and noise control permit No. 1959, was issued on September 11 2024 for the material warehouse building, and No. 778 for main facility, was issues by the Ministry of Environment on March 13, 2024 for main facility. The validity is for 1 year. •The facility obtains air emission for steam boiler No. 776, were issues by the Ministry of Environment on March 13, 2024. The validity is for 1 year. •The facility obtains air emission for generator No. 777, were issues by the Ministry of Environment on March 13, 2024. The validity is for 1 year. •The facility obtains solid waste permit No. 1961 and 1963 for raw material warehouse building the main facility, was issues by the Ministry of Environment on September 11, 2024. The validity is for 1 year. •The facility obtains liquid waste permit No. 1960 and 1962 for raw material warehouse building the main facility, on September 11, 2024. The validity is for 1 year.	
10.6. What is the facility's long-term sustainability management plan, including monitoring its water and electricity consumption and utilize renewable energy?	Describe
The facility monitored and control on water, and electrical consumption through installing the inlet and outlet water, the electrical power supply for electric equipment is posted the poster to save the energy and be able to use new technology of machinery and electronic which is saving the energy.	

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:	No
--	----



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

N/A

Quality Plan (AUDIT REPORT - PRINCIPLE 11: CUSTOMS COMPLIANCE) ↓

Audit Questions and Objective Evidence/Comments

Principle 11: Customs Compliance

Facilities will comply with applicable customs laws, and in particular, will establish and maintain programs to comply with customs laws regarding illegal transshipment of finished products.

Facilities will ensure that all merchandise is accurately marked or labeled in compliance with all applicable laws. In addition, facilities will keep records for all materials and orders, as well as maintain detailed production records.

11.1. Does the facility keep copies of all applicable customs/trade program laws and regulations?

Yes

From documents review, the copies of applicable customs laws were maintained with updated written policy on "Customs Compliance" is maintained a core standard of the facility assigned Mr. Uy Sarin – Shipping Manager to work with transportation company:

-Simex Asia Line Co. Ltd

-Shenda Logistic (Combodia) Ltd.

-Cohesion Global Logistic (Combodia) Co. Ltd

-Century Distribution Systems (Cambodia) Co. Ltd

to assure the shipping process and shipping document are compliance with the Customs Law.

11.2a. Does the facility comply with all applicable customs/trade program laws and maintain practices to comply with customs/trade program laws regarding illegal transshipment of products (in the event possible illegal transshipment activity, appropriate host government agency shall be notified)?

Yes

The facility monitors its production on per style basis by using the production plan. The plan indicates the PO number, item number, style number, color, and quantity of items under production to track the production.

11.2b. Does the facility monitor its productions on a per style basis?

Yes

From documents of compliance manual review, the policy and procedures include the commitment of the facility staying compliance with valid and applicable customs laws and maintain practices to comply with customs laws on illegal transshipment of products.

11.2c. Does the facility trace country of origin using records such as production, shipping, verification reports, quality control reports, and individual piecework sheets, for all inputs?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The country of origin is traced by production records, shipping documents, verification reports, quality control reports, and individual report, for all inputs

11.2d. Does the facility verify production on an on-going basis at subcontracting facilities, including keeping records of such verification?

Yes

The facility verified production on an on-going basis at subcontracting facilities, including keeping records of such verification such as transferring record, production record of subcon, etc.

11.2e. Does the facility maintain a machine inventory and update it annually?

Yes

The machine inventory was updated annually by the shipping officer after gathering all information from the production department.

11.2f. Does the facility ensure that the proper category designation is determined for all goods destined for the US market?

Yes

The facility policies and procedure include proper category designation for all goods destined for the US market.

11.3. Does the responsible person ensure that origin determining documents are maintained for at least the period of record retention required by law?

Yes

The logistic company ensure origin-determining Import & Export and signed on CO which is approval by local customs. Documents were maintained for at least 5 years and the selected document was provided to review.

11.4. Does the facility stay current with possible illegal transshipment activity in the host country through communication with appropriate bodies such as the host government, trade association, etc.?

Yes

Documented confirmation of the correct category and country of origin for goods through verification of correct country of origin such as binding rulings from the US Customs Service, confirmation with purchasing company, knowledgeable/trained staff, etc. was maintained

11.5a. Does the facility maintain an organized system of production documentation that contains records of the country of origin for all goods produced in the facility?

Yes

The facility maintained an organized system of production documentation from material receiving to dispatch. Records are available to review.

Shipping department is assigned one staff to proceed the Country of Origin (CO) form such as form A, B, C... the ensure that the Import & Export have CO which is approval by local customs.

11.5b. Does the facility maintain an organized system of production documentation that contains a production profile (indicating name, address, production process, production type, and machine inventory) of any subcontracting facility?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

A production profile (indicating name, address, production process, production type, and machine inventory) of any subcontracting facility was maintained.

11.5c. Does the facility maintain an organized system of production documentation that contains production/purchase orders (with information such as conditions of production, payment, and finished product specifications)?

Yes

The facility has maintained the information of purchase orders with information such as conditions of production, payment, and finished product specifications by merchandiser.

11.5d. Does the facility maintain an organized system of production documentation that contains raw material invoices (indicating country of origin of manufacturing facility)?

Yes

Import documents for raw materials & accessories were provided contains the following documents:

- Custom Declaration and Permit;
- Commercial Invoice and Packing List;
- Bill of Lading;
- Customs Bonded Warehouse Issuance Reports;
- Clearance Document.

11.5e. Does the facility maintain an organized system of production documentation that contains payment proof of raw material, local transportation?

Yes

The facility presented the documents for its shipment as follow:

- Delivery receipts;
- Material inspection reports and;
- Warehousing records for review.

11.5f. Does the facility maintain an organized system of production documentation that contains shipping/receiving documents (outgoing and incoming records of components/ inputs sent to or received from another facility)?

Yes

The production reports such as cutting reports, daily sewing report, quality control reports and finishing daily output were reviewed and are found consistent with each other.

11.5g. Does the facility maintain an organized system of production documentation that contains worker work records – accurate records of worker work hours that can be linked to the production of specific products?

Yes

The production reports such as cutting reports, daily sewing report, quality control reports and finishing daily output were reviewed and are found consistent with each other.

11.5h. Does the facility maintain an organized system of production documentation that contains quality control records (which may include

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

facility name and address, purchase order number, style number, date of the quality check, buyer, name, stamp or signature of an inspector, comments on production)?

The daily quality control report includes the buyer name, style number, color, quantity, date of inspection, inspectors name and workmanship comments

11.5i. Does the facility maintain an organized system of production documentation that contains export documents (including, packing list, manifest, bill of lading/airway bill from truck, ship, plane or train indicating the export date, exporting entity, destination, shipping lines, importing entity, and any charges incurred)?

Yes

Completed set of export documents were provided for review, non-negotiable bill of lading, container interchange receipt, country of origin declaration, pro-forma invoice and customs clearance which indicates uniform data of exporting company, shipment date, and container

11.5j. Does the facility maintain an organized system of production documentation that contains number of units produced marked with a traceable mark?

Yes

Each unit was found marked with specific ID number for produce tracking.

11.5k. Does the facility maintain an organized system of production documentation that contains documented confirmation of the correct category and country of origin for goods through verification of correct country of origin such as binding rulings from the US Customs Service, confirmation with purchasing company, knowledgeable/trained staff, etc.?

Yes

Documented confirmation of the correct category and country of origin for goods through verification of correct country of origin such as binding rulings from the US Customs Service, confirmation with purchasing company, knowledgeable/trained staff, etc. was maintained.

11.6a. Do the facility's production records include verification of subcontractor performance?

Yes

Verification record for subcontractor was included into factory's production records.

11.6b. What records are used? (Select all that apply)

Date and location of the verification

Product(s) verified

Style number

Phase of production

Ref. indicator for worker(s) performing operations

Name/stamp or signature of verifying staff

The record was included date and location of the verification, Product(s) verified, purchasing company, Style number, Phase of production, Reference indicator for worker(s) performing operation, Name/stamp or signature of verifying staff

Non-Compliances Raised Against This Principle



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:

No

N/A

Quality Plan (AUDIT REPORT - PRINCIPLE 12: SECURITY)

Security Vision & Responsibility

Principle 12: Security

Facilities will maintain appropriate procedures in order to ensure proper corporate security, transportation security, and people and physical security at the facility.

Facilities will ensure adequate controls are in place to safeguard against introduction of any non-manifested cargo. In this regard, WRAP recognizes the United States Customs and Border Protection (CBP)'s CTPAT Guidelines for Foreign Manufacturers as minimum requirements and has adopted those guidelines under this Principle.

12.1.1a. Does the facility have a security program to ensure the security of its premises, its goods in the facility?

Yes

The facility has established security policies and procedures. It was reviewed in January 02, 2024 to ensure the security of its premises, its goods in the facility

12.1.1b. Does the facility top management demonstrate their commitment to the program by signing the security statement?

Yes

All security policies and procedures of the facility were signed to commit to implement by management.

12.1.1c. Is such document posted onsite or shared during security trainings?

Yes

It was posted on bulletin boards and provided training to employees annually for entire employees and employees of sensitive sections and new employees were trained via induction training program.

12.1.1d. Does the facility communicate its security program within its facility and also with its business partners? Business partners refer to the entities the facility has business relationship with, in particular, transportation/logistics providers, customers, raw material suppliers, subcontractors, service providers (including IT service providers), etc.

Yes

During the document review, it was noted that the factory has communicate its security program within the facility and also with its business partners and signed acknowledgement.

12.1.2. Does the facility have a cross-functional team from the relevant departments responsible for the implementation and monitoring of its

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

security program? List at least two (2) people and their department from the team:

Security committee was established on Jan 3, 2024 for monitoring and ensuring adhere to security program of WRAP. Below of 05 main person in-charge as bellows:

- Ms. Vong Chantrea-Admin Assistant
- Mr. Nut Reaksmeay/ Security leader
- Mr. Keo Bunnara/ Key controller and loading supervisor
- Mr. Chheurn Chin/ Container Check 7 point
- Mr. Nun Naeth/ Container Check 7 point

12.1.3. Does the facility have an effective written review process for its security program that is updated promptly when pertinent changes are made in the facility's operation and level of risk?

Yes

Security review procedure were established in the facility. Security review was conducted on yearly basis or pertinent changes.

12.1.4a. Does the facility have Point(s) of Contact (POC) – responsible persons - for its security program?

Yes

The facility assigned Security committee with for monitoring security program.

12.1.4b. Are these individuals trained to have the necessary knowledge on CTPAT program requirements?

Yes

POC person has been trained on CTPAT by compliance department.

12.1.4c. Do POCs have a mean of obtaining and validating updates of security requirements?

Yes

POC updated new requirement on security via audit program and information from Client.

12.1.4d. Do the POCs provide regular updates to top management on issues related to the program, including the progress or outcomes of any audits, security related exercises, and CTPAT validations?

Yes

Security committee provided regular updates to top management on issues related to the program, including the progress or outcomes of any audits, security related exercises, and CTPAT validations.

Risk Assessment

12.2.1. Has the facility conducted security risk assessment (RA) to identify any security vulnerabilities in its facility and mitigate them by taking the necessary measures?

Yes

The risk assessment on security was carried out on Oct 19, 2024.



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

12.2.2. Does your risk assessment document and map the movement of your cargo?

Yes

Cargo movement map was established on June 26, 2023 and shared to their forwarder

12.2.3. Does the facility review its security risk assessment (RA) at least once a year? (More frequent reviews must be done if risk factors dictate so.)

Yes

The risk assessment on security was carried out on Oct 19, 2024

12.2.4. Does the facility ensure risks addressing towards crisis management, business continuity, security recovery plan and business resumption?

Yes

It was noted that emergency response plan with crisis management, business continuity, security recovery plan and business resumption was established and last reviewed on Oct 19, 2024.

Business Partners Security

12.3.1a. Does a written and up-to-date risk-based process exist for screening of new and monitoring of existing business partners?

Yes

The facility established policy and procedure to screen and monitor their new and exist business partners annually

12.3.1b. Does the facility address the weaknesses found in its business partners' security assessments?

Yes

Security assessment for service suppliers (security,, material suppliers was conducted at least once per year.

12.3.1c. Are the actions, taken to mitigate any identified deficiency, effective and in time?

Yes

Corrective action plan was required to all findings of business partners

12.3.2. If the facility has undergone any CTPAT/AEO (Authorized Economic Operator) audit within the past 24 months, provide the evidence.

Describe

It is not applicable, due no C-TPAT/AEO (Authorized Economic Operator) audit within the past 24 months.

12.3.3. If the facility subcontracts transportation services to a highway carrier, the carrier has to be CTPAT certified. Does the facility meet this requirement? ONLY applicable for land transportation to the US.

N/A

The factory was located in Cambodia so no land transportation to the US.

12.3.4. If a highway carrier works directly for the facility's buyer through a written contract, does the contract stipulate adherence to CTPAT's

N/A



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Minimum Security Criteria (MSC) requirements? ONLY applicable for land transportation to the US.

The factory was located in Cambodia so no land transportation to the US.

Cybersecurity

12.4.1. Does the facility have written cybersecurity policies and procedures to protect its information technology (IT) systems, including procedures for the recovery (or replacement) of IT systems and/or data if a data breach occurs?

Yes

The facility established written cybersecurity policies and procedures on to protect its information technology (IT) systems, including procedures for the recovery of IT systems

12.4.2. Does the facility have installed sufficient software/hardware protection from malware and internal/external intrusion (firewalls) in its computer system?

Yes

Anti-virus software was installed for all computers in the facility.

12.4.3. Does the facility regularly test the security of its IT infrastructure based on the defined frequency (but at the minimum once a year)?

Yes

The facility conducted yearly test the security of its IT infrastructure.

12.4.4. Does the facility have a system in place to identify unauthorized access of IT systems/data or abuse of policies and procedures?

Yes

The factory had installed firewall identify unauthorized access of IT systems/data or abuse of policies and procedures. In addition, server and other IT equipment was stored in locked room with restricted access.

12.4.5a. Does the facility restrict user access based on job description or assigned duties?

Yes

The facility has required all the employees register the account and get approve from management and IT.

12.4.5b. Does the facility require its system users to update their passwords regularly (but at the minimum once a year)?

Yes

Computer's password was required to change every 90 days.

12.4.5c. Does the facility employ secure technologies to safeguarded its IT systems used by remote users?

Yes

The factory prohibited all remote users accessing to company network.

12.4.5d. For facility staff using personal devices to conduct company work, does the facility require the staff to adhere to the company's cybersecurity policies and procedures?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Personal device was prohibited to use for company work.

12.4.5e. Does the facility remove employee's computer and network access upon ending of employment?

Yes

Policy and procedure on removing employee's computer and network access upon termination was established.

12.4.6. Does the facility follow any international cybersecurity framework, such as National Institute of Standards and Technology (NIST) for establishing cyber security protocols? (N/A for US facilities.)

Yes

The facility followed international cybersecurity framework for establishing cyber security protocols.

12.4.7. Does the facility back up its data stored in its network at least once a week?

Yes

During the observation, document review and management interview, the facility did not back up its data stored in its network at least once a week. As the security policy, the data pack-up was conducted every month.

Follow-Up Audit on February 21-22, 2025: Closed

Based on site observation and management review, it was noted that the facility has setup automatic storage for data back-up in its network once a week, normally back-up every Saturday, the latest back-up found on February 15, 2025. In addition, the facility has updated their data back-up policy from every month to once a week on January 02, 2025.

12.4.8. Does the facility have back-up power for its computer network so the facility can back up the necessary data before the power shuts down?

Yes

The facility has back-up power for its computer network, so the facility could back up the necessary data before the power shuts down.

Conveyance & Instruments of International Traffic Security

12.5.1a. If the containers/trucks stay in the facility, does the facility ensure that they are not tampered?

Yes

The facility established process to ensure containers/trucks were not tampered.

12.5.1b. The containers/trucks are parked in an access-controlled area?

Yes

Physical access control at sensitive area was established. CCTV, fence and security monitoring were provided to ensure without un-authorized access.

12.5.2a Does the facility have documented procedures in place to verify the physical integrity of the container structure prior to loading?

Yes

The facility has established the documented procedures in place to verify the physical integrity of the container structure prior to loading



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

12.5.2b. Does the procedure include the reliability of the locking mechanisms of the doors?

Yes

The procedure includes the reliability of the locking mechanisms of the doors

12.5.2c. Prior to loading/stuffing/packing, does the facility conduct 7-point inspection on its containers and unit load devices (ULD) (Select all that apply):

Front wall Left side Right side Floor Ceiling/Roof Inside/outside doors, incl. locking mechanisms Outside/Undercarriage

Prior to loading, the facility conducted 7-point (Front wall/Left side/Right side/Floor/ Ceiling Roof/ Inside and Outside door/ Outside/undercarriage) inspection on its containers and records were maintained to review

12.5.3a. Does the facility conduct inspections of conveyances at the point of loading/stuffing?

Yes

The facility inspected conveyances at point of loading area to ensure that adhere to security regulation.

12.5.3b. If conveyances are stored in the facility, does the facility inspect them when they enter and depart the storage yards?

Yes

It was noted that trailer inspection was applied accordingly. Factory provided refresh training for security on trailer inspection procedure and require to implement in practice for all trailers.

12.5.3c. Does the facility inspect trailers for the following (Select all that apply):

Fifth wheel area Exterior - front/sides Rear - bumper/doors Right side Floor Ceiling/roof Inside/outside doors and locking mechanisms Outside/Undercarriage

The facility ensured trailer would be inspected Fifth wheel area

- Check natural compartment/skid plate; - Exterior
- Front/sides; Rear
- Bumper/doors;
- Front wall;
- Left side;
- Right side;
- Floor;
- Ceiling/roof;
- Inside/outside doors and locking mechanisms;
- Outside/Undercarriage as the written procedure.

12.5.3d. Does the facility conduct inspections of its tractors on the following, if applicable (Select all that apply) (ONLY applicable for land transportation to the U.S.):

N/A

Not applicable since the factory located in Cambodia.

12.5.4a. Does the facility ensure that conveyances are equipped with external hardware that can reasonably withstand attempts to remove it?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility inspected conveyances to ensure that it can reasonably withstand attempts to remove it

12.5.4b. Prior to attaching any locking device, does the facility inspect a container/truck or any other means of transportation and its locking mechanism to detect tampering?

Yes

The facility inspected a container/truck and its locking mechanism to detect tampering prior to attaching any locking device.

12.5.5. Does the facility's security inspection of its conveyances & IIT include the following elements (select all that apply):

Container/Trailer/IIT number

Date of inspection

Time of inspection

Name of employee conducting inspection

Specific areas of IIT that were inspected

Container and truck inspection records were maintained and available to review, date/time/inspector name/inspection area were included into the inspection minutes

12.5.6a Does the facility perform its security inspections in an area of controlled access and monitored by CCTV if applicable? (Facilities supplying only to local markets or not exporting to the US are not required to have CCTV, but they must have security inspections in the areas with controlled access.)

Yes

The facility has total 227 camera heads was installed at the loading and unloading areas, finished good warehouse, packing section and main entrance/exit.

12.5.6b. Are CCTV records, minimum of 24/7 and 30 consecutive days, kept in sensitive areas (cargo handling and storage areas, yard and storage areas for containers, trucks and trailers, packing areas and entrance/exit)? Facilities supplying only to local markets or not exporting to the US are not required to have CCTV records.

Yes

It was noted that the facility installed camera heads at the loading and unloading areas, finished good warehouse, packing section, loading area, main entrance/exit and other areas. However, the CCTV records good warehouse, packing section, loading area were maintained for 15 days instead of at least 30 consecutive days. The record was maintained from Dec 2, 2024, to Dec 16, 2024.

Remark: other CCTV record at other section could be maintained since Aug 1, 2024.

Follow-Up Audit on February 21-22, 2025: Closed

Based on CCTV record review, it was noted that the record of CCTV of all sections, especially in the sensitive area such as packing section, finished goods warehouse and loading area were recorded more than 30 consecutive days, it was 53 days start from December 31, 2024 until the assessment date (February 21, 2025).

Seal Security



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

NOTE

For the facilities supplying only to local markets, the facilities not direct exporters, or the facilities using Less Than Container Load (LCL) or using local Inland Container Depots (ICDs), only questions 12.6.8, 12.6.9, and 12.6.10a & b are applicable under THIS section.

12.6.1a. Does the facility affix a high-security seal to all loaded trailers and containers bound for the U.S.?

N/A

All containers are taken responsibility by the forwarders and trucking companies nominated by US customers. The containers are secured by seals of the Government's Customs and forwarders. The facility uses customs seal for export.

12.6.1b. Do the seals meet or exceed the current ISO 17712 standards for high-security seals?

Yes

The seals met or exceed the current ISO 17712 standards for high-security seals.

12.6.1c. Does the facility have documented procedures stipulating how seals are to be controlled and affixed to loaded containers and trailers?

Yes

The facility had documented procedures stipulating how seals was to be controlled and affixed to loaded containers and trailers.

12.6.1d. Does the facility have documented procedures for recognizing and reporting compromised seals and/or containers/trailers to US Customs and Border Protection or the appropriate local authority?

Yes

The facility haddocumented procedures for recognizing and reporting compromised seals and containers to the appropriate local authority.

12.6.1e. Does the facility have designated workers for the distribution of seals for integrity purposes?

Yes

Im-export staff was assigned for the distribution of seals for integrity purposes.

12.6.1f. Controlling access to seals must have the following elements (Select all that apply):

Seals managed only by authorized personnel

Secure storage

Issuance of seals recorded in log

Track seals via the log

Controlling access to seals was secured. All seal was stored in locked cabinet and mornitored by designed staff. Seal log was maintained to record the the receipt of new seals and usage. Only authorized personnel was assigned to affix seals to containers.

12.6.2. Does the Seal security policy and procedure include "controlling seals in transit" and "seals broken in transit"?

Yes

Seal security policy and procedure include "Seal Control Policy"

12.6.3a. If seals are found broken in transit, the following must be done: If a load is examined, record replacement seal number.

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Currently, no broken in transit was noted in the facility up to audit date.

However, the facility a clear specific seal security policy which including the process to investigate and record the replacement seal number in case of seal broken incident happen. The facility uses customs seal for export.

12.6.3b. If seals are found broken in transit, the following must be done:
The driver must immediately notify dispatch when a seal is broken, indicate who broke it, and provide the new seal number.

Yes

Factory had procedure which was trained to relevant employees including drivers to immediately notify dispatch when a seal was broken, indicate who broke it, and provided the new seal number.

12.6.3c. If seals are found broken in transit, the following must be done:
The carrier must immediately notify the shipper, broker, and importer of the seal change and the replacement seal number.

Yes

Factory had procedure which was trained to relevant employees. The carrier immediately notified the shipper, broker, and importer of the seal change and the replacement seal number.

12.6.3d. If seals are found broken in transit, the following must be done:
The shipper must note the replacement seal number in the seal log.

Yes

Factory had procedure which was trained to relevant employees. The shipper must note the replacement seal number in the seal log.

12.6.4a. Seal discrepancies are found: Does the facility retain altered or tampered seals to aid in investigations?

Yes

Factory had procedure which was trained to relevant employees to ensure retaining altered or tampered seals to aid in investigations.

12.6.4b. Seal discrepancies are found: Does the facility investigate the discrepancy and follow-up with corrective measures (if warranted)?

Yes

Factory had procedure that the facility investigated the discrepancy and follow-up with corrective measures.

12.6.4c. Seal discrepancies are found: If applicable, does the facility report compromised seals to CBP and the appropriate foreign government to aid in the investigation?

Yes

Factory had procedure that the facility reported compromised seals to CBP and the appropriate foreign government to aid in the investigation

12.6.5. Are all shipments sealed right after loading/stuffing/packing?

Yes

Based on record review and employee interview, it was noted that all shipments sealed right after loading by local customs officer for (IIT).

12.6.6a. Does the facility maintain an inventory of seals?

Yes

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility maintain an inventory of seals for internal seal. The high security seal and customer seal was issued separately for each shipment upon loading time.

12.6.6b. If yes to 12.6.6a, does the facility management or a security supervisor conduct audits of seals that includes periodic inventory of stored and reconciliation against seal inventory logs and shipping documents?

Yes

The facility management and a security supervisor conducted audits of seals that includes periodic inventory of stored and reconciliation against seal inventory logs and shipping documents.

12.6.7a. Does the facility seal verification process followed the VTT process: V – View seal and container locking mechanisms; ensure they are OK

Yes

VTT was include the seal policy and provided for review on the audit day.

12.6.7b. Does the facility seal verification process followed the VTT process: V – Verify seal number against shipment documents for accuracy

Yes

VTT was include the seal policy and provided for review on the audit day.

12.6.7c. Does the facility seal verification process followed the VTT process: T – Tug on seal to make sure it is affixed properly

Yes

VTT was include the seal policy and provided for review on the audit day.

12.6.7d. Does the facility seal verification process followed the VTT process: T – Twist and turn the bolt seal to make sure its components do not unscrew, separate from one another, or any part of the seal becomes loose

Yes

VTT was include the seal policy and provided for review on the audit day.

NOTE

The following questions are applicable to the facilities supplying only to local markets, the facilities not direct exporters, or the facilities using Less Than Container Load (LCL) or using local Inland Container Depots (ICDs).

12.6.8. Does the facility apply a locking device to all its shipments right after loading/stuffing/packing?

Yes

The facility did apply internal metal seal to all its shipments right after loading/stuffing/packing.

12.6.9. Does the facility maintain records of the locking devices as required by the applicable custom rules or for at least 3 months?

Yes

The facility did maintain records of the internal metal seal as required by the applicable custom rules or for at least 3 months.

12.6.10a. Does the facility record any broken locking device incidents and take the necessary preventative measures?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

The facility did record any broken internal metal seal incidents and take the necessary preventative measures.

12.6.10b. Does the facility have the procedures to address any incidents occurred during transit?

Yes

The facility did have the procedures to address any incidents occurred during transit.

Procedural Security

12.7.1. Does the facility have security officer/manager or other designated personnel during the loading/stuffing of cargo into containers/trucks?

Yes

Mr. Uy Sarin – Shipping Manager department head was assigned to monitor loading process

12.7.2. Does the facility have procedures in place to ensure complete and necessary information in clearing of merchandise/cargo? (Not applicable to non-exporting facilities.)

Yes

The facility established procedure to ensure complete and necessary information in clearing of merchandise/cargo.

12.7.3. Does the facility verify the accuracy of the information in the bill of lading (BOs) and/or manifests with the shipper or its agent? (Not applicable to non-exporting facilities.)

Yes

Shipping documents were completed and controlled by logistic subcontractor and factory

12.7.4. Does the facility have written procedures for reporting an incident? (Note: The report must include a description of its internal escalation process.)

Yes

Written procedures for reporting an incident of security break was established in the facility

Incident was found --> inform to the person in charge via hotline--> collect information --> inform to top management/ authorized party/ government--> investigation--> result --> keep record

12.7.5. Does the facility have documented procedures in place to identify, challenge and address unauthorized/unidentified persons?

Yes

The facility has documented procedures in place to identify, challenge and address unauthorized/unidentified persons.

12.7.6. Does the facility investigate and resolve any shortages, overages and other significant discrepancies or anomalies?

Yes

The facility established procedure to resolve and investigate shortages, overages, and other significant discrepancies or anomalies.

12.7.7a. Is cargo that is being shipped reconciled against information on the cargo manifest?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Finished products were reconciled against information on the cargo manifest before shipped

12.7.7b. Is all cargo accurately described, and are the weights, labels, marks, and piece count indicated and verified?	Yes
---	-----

Shipping documents were completed and controlled by transportation service company.

12.7.7c. Does the facility verify departing cargo against purchase or delivery orders?	Yes
--	-----

Shipping documents were completed and controlled by transportation service company.

12.7.7d. Are drivers delivering or receiving cargo positively identified before cargo is received or released?	Yes
--	-----

List of drivers from service provider were maintained and verified by security team

12.7.7e. Are documented procedures in place to track the timely movement of incoming and outgoing goods?	Yes
--	-----

It was noted that the factory did not have procedure to track the timely movement of incoming and outgoing goods.

Agricultural Security

12.8.1. Does the facility have written procedures designated to prevent visible pest contamination to include compliance with Wood Packaging Materials (WPM) regulations?	Yes
---	-----

It was noted that the factory did not have written procedures designated to prevent visible pest contamination.

12.8.2. Does the facility inspect its cargo staging areas and its immediate surrounding areas to ensure these areas remain free of visible pest contamination?	Yes
--	-----

The cargo loading areas were constructed to remain free of visible pest contamination.

12.8.3a. Has pest contamination been found during the conveyance/instruments of international traffic inspection?	No
---	----

No pest contamination been found during the conveyance/ instruments of international traffic inspection.

12.8.3b. If yes to 12.8.3a, was washing/vacuuming carried out to remove such contamination?	N/A
---	-----

No pest contamination been found during the conveyance/ instruments of international traffic inspection.

12.8.4. Has the facility maintained the records of its pest contamination removal activities for at least one (1) year?	Yes
---	-----



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Pest control was conducted once a week and documents were maintained in at least 1 year for review

Physical Access Controls

12.9.1a. Does the facility have a physical access control procedure for cargo handling and storage facilities?

Yes

The facility has established physical access control procedure for sensitive areas such as warehouse, packing section.

12.9.1b. Do the facility's cargo handling and storage facilities have physical barriers and/or deterrents that prevent unauthorized access? If no, describe what measures are in place to prevent unauthorized access

Yes

Loading and unloading areas were provided with barrier that prevented unauthorized access. In addition, factory assigned person in charge at sensitive area to control access of unauthorized person.

12.9.2a. Is there perimeter fencing enclosing the areas around cargo handling and storage facilities?

Yes

The warehouses and packing section were separated with other areas by physical fence.

12.9.2b. Is interior fencing within a cargo handling area used to segregate domestic, international, high value, and hazardous cargo?

N/A

No domestic or high value, and hazardous cargo in the facility

12.9.2c. Is all fencing regularly inspected for integrity and damage?

Yes

It was inspected daily by security guards.

12.9.3. Are gates through which vehicles and/or personnel enter or exit manned and/or monitored? (The number of gates should be kept to the minimum necessary for proper access and safety.)

Yes

There were only 1 entrance gates in the facility (for each site) and it was monitored 24/7 by security guards and CCTV

12.9.4. Are private passenger vehicles prohibited from parking in or adjacent to cargo handling and storage areas?

Yes

Parking lots were separated with warehouses

12.9.5. Is there adequate lighting provided inside and outside the facility including the following areas: entrances and exits, cargo handling and storage areas, fence lines and parking areas?

Yes

The lighting system was installed at sensitive area such as entrance gates (inside and outside), loading/unloading area, perimeter fence, etc.

12.9.6. Does the facility ensure its security technology physical

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

infrastructure from unauthorized access?

The facility ensures its security technology physical infrastructure from unauthorized access.

Physical Security

12.10.1a. Does the facility have written procedures governing how identification badges and access devices are granted, changed and removed?

Yes

The facility has written procedures governing how identification badges and access devices are granted, changed and removed.

12.10.1b. Does the facility restrict access to sensitive areas based on job description or assigned duties? Sensitive areas include cargo handling and storage areas, yard and storage areas for containers, trucks and trailers, packing areas and entrance/exit, IT server rooms, shipping/receiving areas where import documents are kept, and seal storage areas.

Yes

List of authorized personnel was posted at entrance of sensitive areas and person in charge was assigned to monitor in/out at these areas

12.10.1c. Does the facility remove access of devices upon the employee's end of employment?

Yes

Access devices such as key and employee badge were removed by the facility upon the employee's end of employment

12.10.2. Are visitors required to register at the main entrance and provided proper visitor bages? (Select all elements that facility's visitor log includes)

Provided visitor badge

Date of visit

Visitor's name

Verification of photo identification

Time of arrival

Company point of contact

Time of departure

Visitor's signature

Visitors are required to register at the main entrance and provided with proper visitor badges. Information of visitors including date of visit, name, ID number, Company, Time of arrival and departure, Company point of contact, time of departure and visitor's signature were recorded in visitor logbook.

12.10.3. Does the facility require positive identification from driver before cargo is received or released?

Yes

Drivers were required to register with security guards at entrance gate before cargo is received or released

12.10.4a Does the facility keep a cargo pickup log?

Yes

Cargo pickup log was recorded and monitored by security guards.

12.10.4b. Does the facility personnel (not cargo drivers) log in and out of cargo drivers?

Yes



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Security guard was recorded log in/out of cargo drivers.

12.10.4c. Is the cargo log securely kept?

Yes

It was kept by security guard

12.10.4d. Does the cargo pickup log have the following items recorded (Select all that apply)?

Driver's name

Date and time of arrival

Employer

Truck number

Trailer number

Time of departure

Seal # affixed to shipment at time of departure

Cargo pickup log with detail information was recorded by security guard at entrance gate. Per document checking and interview with relevant persons noted that driver names/ Date and time of arrival/ Employer/ Truck Number/ Trailer Number/ Time of departure and The seal number affixed to the shipment at the time of departure were recorded into the cargo pickup logbook.

12.10.5. Does the facility require carrier to make deliveries and pickups by appointment only with driver's name and truck number?

Yes

Per provided evidence, it was noted that the factory had required forwarder to inform them driver name and truck number by deliver note before shipping date. This information was informed via email.

12.10.6. Does the facility have documented procedures in place to check mails and parcels upon arrival?

Yes

Mail & package inspection procedure was established in the facility.

12.10.7. If the facility use security guards, does it have written policies and procedures for security guards' work instructions?

Yes

Work instruction for security guards were established and trained to security guard at induction training and annual refresher training.

Personnel Security

12.11.1. Does the facility verify applicant's employment history and conduct reference checks prior to hiring, to the extent possible and allowed under the law?

Yes

The facility has verified application information, such as employment history and references, prior to employment.

12.11.2. Once employed, are periodic checks and reinvestigations performed based on cause, and/or the sensitivity of the worker's position?

Yes

All selected workers were checked background annually.

12.11.3. Does the facility have a code of conduct for security personnel?

Yes

The facility had a code of conduct for security personnel

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

Education, Training & Awareness

12.12.1a. Has the facility established and maintained a security training and awareness program, including code of conduct training for security personnel, for its personnel in sensitive areas and positions?	Yes
Security training program was established in the facility with general security training and special training for sensitive areas	
12.12.1b. Does the facility keep training records which include the date of the training, names of attendees and the topics of the training?	Yes
Training records with detail of date, name of trainees, topics and signature of employees were maintained and available to review	
12.12.2a. Does the facility train its relevant personnel who conduct security inspections of empty conveyances and Instruments of International Traffic (IIT)?	Yes
Training on truck inspection was provided for relevant employees such as security guards, shipping employees, etc.	
12.12.2b. Does the facility training contain the following contents (Select all that apply):	
☒ Signs of hidden compartments ☒ Concealed contraband in compartments ☒ Signs of pest contamination	
The training document was included signs of hidden compartments/ Concealed contraband/ pest contamination.	
12.12.3. Does the facility train its relevant personnel on its cybersecurity policies and procedures?	Yes
During the document review and management interview, it was noted that security training, including cybersecurity training was provided for employees.	
12.12.4. Does the facility train its relevant personnel operating and managing security technology systems?	Yes
Security technology systems was trained for relevant employees at least once per year.	
12.12.5. Does the facility train its relevant personnel on how to report security incidents and suspicious activities?	Yes
Training on how to report security incidents and suspicious activities was provided to all employees at induction and annual refresher training.	

Non-Compliances Raised Against This Principle

Were any non-compliances raised against this Principle? If Yes, note whether they are Major, Minor, or Observations:	No
--	----



WRAP - Audit Report

Rec

Audit #: 10425, Factory: Yorkmars (Cambodia) Garment Mfg Co. Ltd, Address Line 1: Preytea Village, Sangkat Choam Chao, Khan Porsenchey,, City: Phnom Penh, Country: Cambodia, Approval Status: Completed

N/A