



Comprehensive

Car Inspection Report



Thorough inspection with

140+ quality checks




Precise insights from

experienced technicians



Trusted by

over 600,000 customers



Hyundai Verna

SX1.5VTVT IVT | 2025 | AT | Petrol

Inspection location: Gurgaon

Report generated on: 24 Apr, 2025



10M +

200 +

1M+

Cars Inspected Cities present

Cars sold



Content of report

1 You

Your report at a glace

Overview of your overall car condition



02

Inspection summary

Category wise ratings and condition



03

Detailed Evaluation of each category

- 1. Exterior & Tyres
- 2. Engine & Transmission
- 3. Steering, Suspension & Brakes
- 4. Air Conditioning
- 5. Electricals & Interiors
- 6. Other Details



04

OEM installed features & specs

- 1. Safety
- 2. Fuel & Performance
- 3. Entertainment & Communication
- 4. Dimensions & Capacity
- 5. Engine, Transmission & Brakes
- 6. Comfort & Convenience






At a glance









Health report summary

Based on our evaluation, your car is free from accidents, flood damage, and meter tampering. Additionally, there's surface rust on the left A-pillar and right rear door. The engine has minor noise. There's leakage from the engine oil side cover and battery acid

- Based on our evaluation, your car is free from accidents, flood damage, and meter tampering.
 Additionally, there's surface rust on the left A-pillar and right rear door. The engine has minor noise.
- There's leakage from the engine oil side cover and battery acid leakage. The clutch is hard, and the leather seats are worn out.
- Based on our evaluation, your car is free from accidents, flood damage, and meter tampering.
 Additionally, there's surface rust on the left A-pillar and right rear door. The engine has minor noise



☆ Inspection summary

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview.

Exterior & Tyres

The exterior of the car has scratches and some parts have been repainted. The tyres have a tread depth of 3-5mm.

3.7/5

Neutral

🛱 Engine & Transmission

The engine is in good condition. There are no issues with blow-by, engine sound, or exhaust smoke. However, the engine oil is dirty.

4.5/5

Excellent

Steering, Suspension & Brakes

Your car's steering, suspension, and brakes are all in good condition. There are no issues that need immediate attention.

4.5/5

Excellent

Air Conditioning

The air conditioning in your car is working perfectly. The AC, heater, and climate control are all functional.

4.7/5

Excellent

Electricals & Interiors

Your car has all the electrical features working well, including power windows, airbags, music system, and a reverse camera. The interior is in good condition with leather seats and a sunroof.

4.4/5

Excellent



Vehicle images





















01. Exterior & Tyres

Perfect parts: 26 | Imperfect parts: 25



Parameters	Perfect	Imperfect
Boot Floor		
Pillar LHS A	0	
Pillar LHS B	0	
Pillar LHS C		
Pillar RHS A		
Pillar RHS B		
Pillar RHS C		
Apron LHS		
Apron RHS		
Apron RHS LEG		
Apron LHS LEG		
Firewall		
Cowl Top		
Upper Cross Member (Bonnet Patti)		
Front Show		
Lower Cross Member		
Radiator Support		





Parameters	Perfect	Imperfect
Head Light Support		
Windshield Rear		
Light LHS Taillight		
Light LHS Fog Light		
Light RHS Fog Light		
ORVM - Manual / Electrical LHS		
Tyre Spare Tyre		
Grill		
Is the Car Waterlogged?	•	
Roof		•
Bonnet/Hood		9
Dicky Door / Boot Door		•
Quarter Panel LHS		•
Quarter Panel RHS		•
Fender LHS		0
Fender RHS		•
Running Border LHS		•
Running Border RHS		•
Door LHS Front		•





Parameters	Perfect	Imperfect
Door LHS Rear		1
Door RHS Front		•
Door RHS Rear		•
Windshield Front		•
Light LHS Headlight		0
Light RHS Headlight		0
Light RHS Taillight		•
Bumper Front		•
Bumper Rear		•
ORVM - Manual / Electrical RHS		•
Alloy Wheel		•
LHS Front Tyre		•
LHS Rear Tyre		•
RHS Front Tyre		•
LHS Rear Tyre		•

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details



Roof: No Dents, Scratched



Bonnet/Hood: No Dents, Scratched



Dicky Door / Boot Door: No Dents, Scratched



Quarter Panel LHS: No Dents, Repainted



Quarter Panel RHS: No Dents, Repainted



Fender LHS: No Dents, Scratched, Repainted



Fender RHS: No Dents, Repainted



Running Border LHS: No Dents, Scratched, Repainted



Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details



Running Border RHS: No Dents, Repainted



Door LHS Front: No Dents, Scratched, Repainted



Door LHS Rear: No Dents, Repainted, Scratched



Door RHS Front: No Dents, Repainted



Door RHS Rear: No Dents, Repainted



Windshield Front: Scratched



Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details





LHS Rear Tyre: 0 30% life remaining



RHS Front Tyre:



70% life remaining





LHS Rear Tyre: 0 30% life remaining




02. Engine & Transmission

Perfect parts: 11 | Imperfect parts: 01



Parameters	Perfect	Imperfect
Engine		
Engine Sound		
Exhaust Smoke	Ø	
Engine Permissible Blow by (Back Compression)		
Clutch	②	





03. Electricals & Interiors

Perfect parts: 14 | Imperfect parts: 00



Parameters	Perfect	Imperfect
4 Power Windows		
Airbag Feature		
Music System		
Leather Seat		
Sunroof		
Steering Mounted Audio Control		
ABS		
Rear Defogger		



Parameters	Perfect	Importost
Parameters	Periect	Imperfect
Reverse Camera		
Electrical		
Interior		
Parking Sensor		
No. Of Airbags		
No. Of Power Windows		
Parameters	Number	
No. Of Airbags	2	

4

04. Steering, suspension & Brakes


Perfect parts: 02 | Imperfect parts: 01

No. Of Power Windows




Parameters	Perfect	Imperfect
Steering		
Suspension		•
Brake		





06. Other details

Available: 02 | Not available: 00







\$ OEM installed features & specs

Understanding the features and specifications of the Hyundai Verna is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.







Safety

Parameters	Metric
Front Fog Lights	Yes
ISOFIX-Child Seat Anchor Points	Yes
Anti-lock Braking System (ABS)	No
Central Locking	Keyless Entry
Rear Defogger	Yes
Airbags	04

Parameters	Metric
Max power (bhp)	81.80
Max torque (Nm)	114.7
Fuel tank capacity (lit)	24
Emission Standard	BSIV







a Entertainment & Communication

360 degree camera Instrument panel type Speaker brand

Analogue & digital JBL Yes




❖ Interior & Exterior





∠ [¬] Dimensions & Capacity



Engine, Transmission & Brakes

Parameteres	Metric
Gear Box- No. of Gears	04
Displacement (cc)	1800
Transmission type	Manual
Cylinders	02
Break type (rear)	Drum
Break type (front)	Drum
Number of disc brakes	02



Comfort & Convenience

Parameteres		Metric		
Seat upholstery (cc)		1800		
Auto climate control		Yes		
Wireless charging pad		Yes		
Steering wheel material		Alloy & Syntheti	ic Leather	
Smart Card/Smart Key		Yes		
Top model		Yes		
Parking sensors	Rear AC		Power windows	
No ((合))	Yes		Front & rear	
Steering adjustment		Driver seat adjustment		
Tilt & telescope		Manual		
Cruise control	Air conditoner Yes		Push button start Yes	E





Thank you for choosing us!

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition. Thank you once again for your trust and patronage.

Other services by

CHALLAN ↗

SERVICE HISTORY **↗**

PERSONAL LOAN 7





Buying, selling, and financing pre-owned cars is now easier than ever!

Experience CARS24 App on mobile





Keep in touch

