
SDET Technical Task - Siemens

Bug Report - Bugs, Design Issues, and Suggestions to improve usability and performance (S3 sample site)



Project: SDET / http://s3-design-sample-site.s3-website-us-west-2.amazonaws.com/

Author: Yasmin Afifi Date: 12-08-2025

Summary: Report all available bugs, design issues and suggestions to improve usability and performance, for http://s3-design-sample-site.s3-website-us-west-2.amazonaws.com/ site

Design Issues

ID	BU-001
Title	Untitled page titles
Severity	Minor
Priority	P2
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open page
Steps to Reproduce	Observe browser tab title
Expected	Descriptive <title> per page</th></tr><tr><th>Actual</th><th>Shows 'Untitled Document'</th></tr><tr><th>Evidence</th><th>Annual of hope sends dail and was and passage annual and annual a</th></tr><tr><th>Suggestions / Notes</th><th>Set meaningful titles per page</th></tr></tbody></table></title>

ID	BU-002
Title	No favicon
Severity	Trivial
Priority	P3
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html,
	products.html, contact.html
Preconditions	Open site
Steps to Reproduce	Look at browser tab icon
Expected	Custom favicon
Actual	Default/no favicon
Paddones	
Evidence	(a) (a) A between (c) design ranges described was over prescribed expectations (a) (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
	Acong Companies The principle is not smooth for enclasers the groups; (The principle is a final section) of our discovering ou
	Property of the Control of the Contr
	Produce conflowing The conflowing conflowin
	To an analysis of the second s
Suggestions / Notes	Add favicon.ico or link rel='icon'


ID	BU-003
Title	Search shows typed text, not placeholder
Severity	Minor
Priority	P2
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open any page
Steps to Reproduce	Inspect search field
Expected	Uses placeholder text
Actual	Literal 'Search' value prefilled
Evidence	
	Acme Chemicals **Company Products Contact** Acme Chemicals **Society Products Contact** Acme Chemicals **Society Products Contact** **A farme Chemicals **A farme Chemical
Suggestions / Notes	Use placeholder attribute, not value

ID	BU-004
Title	No friendly error page for missing routes (403 AccessDenied instead of 404.html)
Severity	Minor
Priority	P2
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	N/A
Steps to Reproduce	Open http://s3-design-sample-site.s3-website-us-west- 2.amazonaws.com/does-not-exist.html
Expected	Custom 404 page with site header/footer and 404 status
Actual	403 AccessDenied and custom error doc also AccessDenied
Evidence	
	⊕ 43 Forbidden Code: AccessDesiried © A Net worw \$3 design-sample-site.3 website us west 2-amazonaws.com/does-not-exist.html
	Message: Access Denied Requestle: 5371FAMENTHPIPS Hessit: AssrptishOnv-ZE-FAWUfplaBk-iqlunj@q3G7ReRlegCtrklsRW00ViR26insQun39nfF+HANdEDLD8- An Error Occurred While Attempting to Retrieve a Custom Error Document Code: AccessDenied Message: Access Denied
Suggestions / Notes	Configure 404.html in S3

ID	BU-005
Title	No site logo/brand graphic
Severity	Minor
Priority	P2
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open homepage
Steps to Reproduce	Look at header area
Expected	Branded logo or styled brand
Actual	Plain text 'Acme Chemicals' (no logo)
Evidence	A Not secure s3-design-sample-site.s3-website-us-west-2 amazonaws.com/index.ht Acme Chemicals SELECTOR To point is domain-relev diversities. It iterate a pre-
Suggestions / Notes	Provide an PNG logo and alt text

Usability & Accessibility

ID	BU-006
Title	Brand/logo not clickable
Severity	Minor
Priority	P2
Triority	
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open non-Home page
Steps to Reproduce	Click brand text
Expected	Navigates to Home (index.html)
Actual	Not clickable
Evidence	And Control of Management and Anderson and Control of Management and Anderson and A
Suggestions / Notes	Wrap brand in



ID	BU-008
Title	Search has no working submit
Severity	Major
Priority	P1
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open any page
Steps to Reproduce	Type query and press Enter / click button
Expected	Query submits and returns results/feedback
Actual	No action on Enter; no working button
Suggestions / Notes	## Unstitled Document ## 13-design-cample-sites/3-website-us-web 2-anazonaws.com/index.html ## 23-design-cample-sites/3-website-us-web 2-anazonaws.com/index.html ## 23-design-cample-sites/3-website-us-web 2-anazonaws.com/index.html ## 25-design-cample-sites/3-website-us-web 2-anazonaws.com/index.html ## 25-design-cample-sites/3-website-us-web 2-anazonaws.com/index.html ## 25-design-cample-sites/3-website-us-w
Suggestions / Notes	Add submit button and handle Enter

ID	BU-009
Title	Unbalanced page layout due to missing media
Severity	Minor
Priority	P3
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open homepage
Steps to Reproduce	Observe layout
Expected	Balanced layout with meaningful content
Actual	Large empty grey area in center
Evidence	Accord Colonials Accord Colon
Suggestions / Notes	Replace Flash area with real content/layout

ID	BU-010
Title	Non-responsive layout (fixed width)
Severity	Major
Priority	P1
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Resize window / open on phone
Steps to Reproduce	Observe responsiveness
Expected	Layout adapts to screen sizes
Actual	Fixed width; horizontal scrolling
Suggestions / Notes	Acme Chemicals S033777 The point is not merely to enhance the strength. The point is domain-relevant customer centricity. It's not about verifiable diversities. It's about a dadership-defined value realization. Pr literate a pre-plan, paving the way for a planning granularity. Product Application Chiegometer Chiegometer
Suggestions / Notes	Implement responsive grid/breakpoints

Performance

ID	BU-011
Title	No HTTPS (HTTP only)
Severity	Major
Priority	P1
Triority	
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html,
	products.html, contact.html
Preconditions	Open http URL
Steps to Reproduce	Check connection security
Expected	Redirect to https with TLS
Actual	Remains Not secure (HTTP)
Evidence	Address bar
Suggestions / Notes	Terminate TLS; 301 HTTP→HTTPS
35 ,	

Functional Bugs

ID	BU-012
Title	Home hero/media fails ('This plug-in isn't supported')
Severity	Major
Priority	P1
Environment	S3 Sample Site – Desktop (HTTP). Pages: index.html, company.html, products.html, contact.html
Preconditions	Open Home
Steps to Reproduce	Observe main panel
Expected	Hero/media renders
Actual	Plugin placeholder shown
Evidence	A Not more 13 dough sample which welcome on west 2 semantaneous control and the sample of the sample
Suggestions / Notes	Replace with HTML5 media/image