



Field-Induced Subsurface Plastic Activity

Large-area orientation mapping of a conditioned copper cathode


(a) Sloped-anode geometry



(b) Three-tier hierarchy



(c) Misorientation distributions broaden with field exposure



(d) Candidate mechanism — from field to dislocation evolution



First large-area observation of field-induced dislocation structure $\rightarrow$ candidate physical basis of the conditioning state E_s