

检测报告

编号 : GZIN2101004786MR_CN

日期 : 2021-07-28

页码 : 1 of 5



客户名称: 深圳市三曜科技有限公司

客户地址: 深圳市前海深港合作区前湾一路1号A栋201

样品名称 : 三曜纳微纳米涂料

以上信息及样品由客户提供及确认, SGS 不承担证实客户提供信息的准确性、适当性和(或)完整性的责任。

SGS 参考号 : CP21-003450

收样日期 : 2021-01-25

测试开始时间 : 2021-01-25

测试结束时间 : 2021-07-28

测试结果 : 请见下页 (除另有特别说明外, 此报告结果仅对测试样品负责)

通标标准技术服务有限公司广州分公司
检测中心
授权签名

彭卫玲

授权签字人

SGS-CSTC Standard Technical Services Co., Ltd.
Guangzhou Branch Testing Center Reliability Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

198 Kazhu Road, Sciencetech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgs.com
中国·广州·经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

检测报告

编号 : GZIN2101004786MR_CN

日期 : 2021-07-28


页码 : 2 of 5

结果总结:

序号	测试项目	测试方法	结果	结论
1	中性盐雾 (NSS) 试验	ASTM B117-19	详见结果	/

备注: 合格: 达到要求
不合格: 未达到要求
/: 不下判定

原样照片:



检测报告

编号 : GZIN2101004786MR_CN

日期 : 2021-07-28

页码 : 3 of 5

测试项目: 中性盐雾(NSS)试验

样品描述: 金属件

测试方法: ASTM B117-19

测试条件:

沉降盐液浓度: (5±1)% NaCl(m/m)

试验箱温度: (35±2)℃

盐雾沉降率: (1.0~2.0)ml/(80cm²·h)

沉降盐液 pH 值(23±3)℃: 6.5~7.2

暴露时间: 3000 小时

测试结果:

样品	暴露时间	外观
#1	500h	无可见腐蚀
#2		无可见腐蚀
#3		无可见腐蚀
#1	1000h	无可见腐蚀
#2		无可见腐蚀
#3		无可见腐蚀
#1	1500h	无可见腐蚀
#2		无可见腐蚀
#3		无可见腐蚀
#1	2000h	无可见腐蚀
#2		无可见腐蚀
#3		无可见腐蚀
#1	2500h	无可见腐蚀
#2		无可见腐蚀
#3		无可见腐蚀



SGS-CTC (Shanghai) Technical Services Co., Ltd.
Guangzhou Branch Testing Center Reliability Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

198 Kazhu Road, Sci-tech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t(86-20) 82155555 f(86-20) 82075188 www.sgs.com.cn
中国·广州·经济技术开发区科学城科珠路198号 邮编:510663 t(86-20) 82155555 f(86-20) 82075188 e sgs.china@sgs.com

检测报告

编号 : GZIN2101004786MR_CN

日期 : 2021-07-28




页码 : 4 of 5

样品	暴露时间	外观
#1	3000h	无可见腐蚀
#2		无可见腐蚀
#3		无可见腐蚀

备注:

- 1.背面叶片和铜管焊接部位不计入评价范围。
- 2.根据客户要求,中间查样的结果是取样后冲洗风干后评定的。

测试照片:


	
测试中	参照样品 测试样品-500h
	
参照样品 测试样品-1000h	参照样品 测试样品-1500h

检测报告

编号 : GZIN2101004786MR_CN

日期 : 2021-07-28

页码 : 5 of 5

			
参照样品 测试样品-2000h		参照样品 测试样品-2500h	
			
参照样品		测试样品-3000h	

设备信息:

设备	型号	设备编号	校准日期	下次校准日期
循环腐蚀试验仪	BCX3000	GZMR-AG-E054	2020-08-25	2021-08-24

附录信息: 此测试报告是报告编号 GZIN2101004786MR 的中文译本, 中英文版本如有歧义, 概以英文版为准。

***** 报告结束*****