


Rank 10 recurrent bad event | session_pre3 | zxy 2025_09_28_16_35_30



event_uid: vehicle_instability_allraw_zxy_2025_09_28_16_35_30_000185120
 sample_id: vehicle_instability_allraw_zxy_2025_09_28_16_35_30_000185120_pre3_label3_response_coverage
 road=straight old_phase=secondary level=extreme_active morphology=multi_correction
 best RMSE: RBF KRR=2.323; KNN template=2.334
 worst RMSE: formal ridge=3.190; dir-gated KNN=2.599