

PDF

GTKWave

N 1410 s0140

PDFread_eightsmatri_multiplactivate s chro ise

8826 sDUTPDF

RTL9ffbb67b8b344d9269766f9ee6f4750be714841

0 08 / 0 20 / 0 80 / 0 FF A i,j] i+2j+1 W21

2 118 NO_ACTIVATION31 24] 88

ReLU0 09 / 0 21 / 0 91 / 0 FF A i,j] 4(i-j W 64l C 256(i-j


ReLU8ma (0,i-j

196196196GTKWaveGHW56 AXI196

28VHDLVCD11212

PNGPS/PDF.gtkGHW/VCDJSONi de .html

/	s	s	
eight_i structio _e	4785	4785	1
eight_e 0	4825	4955	14
mmu_load_ eight	4855	4985	14
mmu_i structio _e	4795	4795	1
buffer_e 0	4835	4965	14
reg_ rite_e	5025	5155	14
activatio _i structio _e	4975	4975	1
buffer_ rite_e 1	5305	5435	14
IRQ	5445	5445	1
R	5505	8805	56



/ 0 80 1 /

MMU


eight_e 0 mmu_load_ eight

0 13

4825 4855 s

MMU

14



/ 0 80 2 /

SDS

MMU

buffer_e 0


la e

reg_rite_e

5025 5155 s

14

reg_accumulate 0



/ 0 80 3 /

5305 5435 s


0 13

7

ReLU

la e0 7 la e1 6 la e13 0


0



/ 0 80 4 / IRQ


5035 5435 s IRQ 5435 s 5445 s 5445 s e _flags_cs 0 1

i structio _e _cs



/ 0 80 5 /

8	AXI	AR	5455 s	R	5505 s	5	56	8805 s	RRESP 0	RDATA	RVALID/RREAD
---	-----	----	--------	---	--------	---	----	--------	---------	-------	--------------



/ 0 80 6 /

PDF


AXI

0 80000

0

WSTRB 0 3

la e12/13 AW W B



ReLU / 0 91 1 /

MMU


eight_e 0 mmu_load_ eight

0 13

4825 4855 s

MMU

14



ReLU / 0 91 2 /

SDS

MMU

buffer_e 0


la e

reg_rite_e

5025 5155 s

14

reg_accumulate 0



ReLU / 0 91 3 /

5305 5435 s


0 13

7

ReLU

la e0 7 la e1 6 la e13 0


0



ReLU / 0 91 4 / IRQ


5035 5435 s IRQ 5435 s 5445 s 5445 s e _flags_cs 0 1

i structio _e _cs



ReLU / 0 91 5 /

8 AXI AR 5455 s R 5505 s 5 56 8805 s RRESP 0 RDATA RVALID/RREAD



ReLU / 0 91 6 /

PDF

AXI

0 80000

0

WSTRB 0 3

la e12/13 AW W B

