





NOTES

- SE03 | Existing helicopter hangar**
Detached helicopter hangar at the wooded edge of the developed area. Existing landing strip extends towards the house. Hangar remains shown on the proposed site plan.
- SE11 | Existing solar array**
Existing ground-mounted solar PV array beyond the stable group, reached from the internal access road. Array remains shown on the proposed site plan.
- SP01 | Replacement house**
Replacement dwelling comprises the main house, linked kitchen building and coach house. Principal entrance faces the horseshoe drive; rear garden faces the proposed pool and existing lake.
- SP02 | Horseshoe carriage drive**
New horseshoe-shaped drive to the principal entrance. Noble Architecture to confirm alignment, width, turning geometry and surface finish on the coordinated site plan before a full application.
- SP03 | Studio access route**
New side access roadway through the coach house carriage arch to the studio buildings of SP04 and the field gate of SP16. Noble Architecture to coordinate clearances, vehicle movements and pedestrian access before a full application. Carriage arch as CE02.
- SP04 | Studio buildings**
Three single-storey timber-framed studio buildings by Bonni Outbuildings, replacing the hay barn of SE12. Each 9,000 x 5,000 mm external. Units 1 and 2: home office workspaces, one with a podcasting studio. Unit 3: private gym, at right angles to Units 1 and 2 and joined by SP15. Use to SP18. Cladding, roof covering and colour to be confirmed before a full application.
- SP05 | Landing strip retention**
Retain part of the existing paved landing strip serving the hangar. Reconfigure the connecting road to meet the new driveway. Noble Architecture to identify retained and removed surfacing before a full application.
- SP06 | Side road and parking**
New side road through the tree line between the hangar and the approach from Deans Lane, serving the proposed carport. Noble Architecture to coordinate alignment, turning and tree impacts before a full application.
- SP07 | Four-car timber carport**
Indicative single-storey, open-sided timber carport for four cars against the tree line. Substantial oak framing under consideration, with a solid roof covering to match the house. Applicant and Noble Architecture to confirm design, dimensions and materials before a full application.
- SP08 | Rear swimming pool**
New outdoor swimming pool between the rear of the house and the lake. Noble Architecture to confirm pool dimensions, terrace extent, finishes and plant location before a full application.
- SP09 | Pool terrace steps**
Steps descend from the house towards the pool, following the ground falling towards the lake. Noble Architecture to confirm levels, step arrangement, retaining edges and provision for step-free access before a full application.
- SP10 | Hangar privacy hedge**
New privacy hedge along the hangar line. Noble Architecture to confirm alignment, species, planting size, spacing and maintained height before a full application, coordinated with signifiers and the retained trees.
- SP11 | Front pond options**
Front pond treatment unresolved. Retention, removal or relocation towards the woodland to be discussed with the applicant. Noble Architecture to establish watercourse connections and ecological implications before defining works. Main lake retained.
- SP12 | Tree line adjustments**
Local adjustments to the tree lines around the revised access and carport. Noble Architecture to coordinate with an arboriculturist and identify individual removals, retained tree protection and replacement planting before a full application.
- SP13 | Internal fence removal**
Remove the internal fences identified within the revised garden layout, including the sports fence between house and lake. Noble Architecture to mark removal limits on DS1 before issue; no external boundary removal proposed by this note.
- SP14 | Studio pile foundations**
Studio buildings and link on drilled auger piles; no concrete slab or strip footings. Pile positions to the manufacturer's and a structural engineer's design, set out with the arboriculturist where they fall within the root protection areas of retained trees.
- SP15 | Glazed corner link**
Single-storey glazed link, 2,500 x 2,500 mm, joining Unit 2 to Unit 3 at the corner. Frame, glazing and roof to be confirmed before a full application.
- SP16 | Field gate access**
Existing field gate on the site boundary beyond the studio buildings retained, with the track to it. Straight vehicle route to the gate kept clear alongside the studio buildings; no parking in front of it. Reached by SP03; parking to SP17.
- SP17 | Studio parking**
Five marked parking spaces for the studio buildings: three in front of Unit 3 and two overspill spaces at the access end of the hardstanding. No space in front of the track to the field gate of SP16. Bay sizes and surface to be confirmed before a full application.
- SP18 | Studio use**
Studio buildings used as a home office and home gym by the occupiers of the dwelling, ancillary to its residential use. Not business premises; no separate business use.
- GN01 | Drawing Scope**
Drawings describe the proposed development for planning assessment. They are not construction drawings or a complete Building Regulations specification. Obtain coordinated construction details, structural calculations and Building Control approval before relevant work starts. Refer discrepancies to Noble Architecture before proceeding.
- GN02 | Survey And Dimensions**
Site information derived from a photogrammetric aerial survey of the holding, with purchased Ordnance Survey data to the site plans. No measured building survey of the existing dwelling has been carried out. Proposed buildings are derived from Noble Architecture's three-dimensional model. Do not scale from these drawings. Verify all dimensions on site.
- GN03 | Pre-Application Status**
Issued for pre-application advice. Materials, dimensions and levels are indicative at this stage and to be fixed before a planning application.

Mapping Data Credentials
OS License Number: 100053143
© Crown copyright 2026 Ordnance Survey

