


The sync taps were never lost — they were looked for in the wrong channel



The pilot report concluded only one of three sync taps was recorded. Three raps inside a few hundred milliseconds fall into one or two 200 ms windows of the 5 Hz derived channel. The 50 Hz raw accelerometer had them the whole time — a reporting artifact, not a data-quality failure.