









结果摘要

原始幅值	恢复幅值	原始相位	恢复相位	幅值不确定度	相位不确定度	SNR 提升
55.65 mV	56.14 mV	-1.66°	-1.39°	0.24 mV	0.18°	+21.95 dB