


Multi-day temp/r.h. plots, Q1 & Q2, H-123






Queue 2 (south, first unit done) fluctuates within acceptable tolerance. Queue 2 has less fluctuation, but drifts and is outside acceptable tolerance with respect to the 26C target temperature.

One day temp/r.h. plots, Q1 & Q2, H-123





The temperature profile for Queue 2 is consistent with the idea that heating from the lights causes some fluctuation.
There is no evidence of this for Queue 1.

Queue2 in H123 Queue1 in H123