

SA1BI-01



REPLACEMENT

Using SST and a press, remove the bushing. 09550-10012 (09553-10010), 09710-22021 (09710-01071)



Using SST and a press, install a new bushing. (b) SST 09550-10012 (09553-10010), 09710-22021 (09710-01071)