
Destin DIY | Tuk-Me-In


http://demodiy.qa.destindiy.com/

Aim: To find the faults in the designs (Aug-20,2021)

Login Page

- ----Login Page not aligned at center perfectly.
- -- left -> on tab
- -- right -> on mobile.
- -- must be at center inside the container--







Buttons positions and alignments

Side Nav bar position fixed --

Send and Proceed button not aligned properly.







Button's text Spilled out

Button's elements spilled out from box


Buttons are not aligned properly.







- -To Do list → better to have some padding
- -> Past Programs heading better to have centered

-> Destin Diy Image and USD boxes are displaying bigger in mobile screen.










Event page -> Better to have all options (All types) .search button centered with padding.

Copyright text-size better to have less than 16px.

Create Field options boxes are unequal in sizes.









cancel button -> center


Media box overflow from container






-back to the previous page button size big.


Participants and add new button padding not properly






User Img width

Save and Close button better to be at the left side





- -> For only mobile screen must have main container margin-left:
- -1rem; as the site container was tending to right-side.
- activity button spilled out from container.

