



The geometry imposes no floor

with perfect angles every class returns the source, 7.0 mm



so the whole loss is the angle

one perfect leg roughly doubles it, two make it exact



The substituted leg keeps its MEASURED impact point and gets only its direction replaced, so the test changes the angle and nothing else. ntof_athens_26/pair_vertex_imaging | 33 runs of the condor full pass, stage-3 tracks, leg pointing cut as marked