


Crater report 2201 of RG5

General information



ID: 2201

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 196m ± 9.0m

Mean depht: $11.4m \pm 1.2m$

d/D ratio: 0.058 ± 0.007

Circularity index: 0.94

Mean slope: 7.03

Geometric center coordinates: (3643871.44,

230666.6934)

Coordinates of the crater's lowest point : (3643877.4999999, 230642.49999999048)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.41	0.19
10°	6.45	0.18
20°	5.95	0.18
30°	5.65	0.18
40°	5.23	0.17
50°	4.59	0.18
60°	4.3	0.19
70°	4.43	0.22
80°	4.63	0.22
90°	5.0	0.24
100°	4.79	0.22
110°	4.79	0.23
120°	5.08	0.21






130°	5.51	0.2
140°	5.9	0.19
150°	6.05	0.19
160°	6.69	0.19
170°	7.26	0.19
180°	7.99	0.19
190°	7.85	0.18
200°	7.92	0.17
210°	8.09	0.17
220°	8.18	0.15
230°	8.91	0.16
240°	8.5	0.16
250°	8.82	0.16
260°	9.64	0.16
270°	10.06	0.17
280°	9.57	0.17
290°	9.16	0.17
300°	8.8	0.16
310°	8.67	0.15
320°	8.47	0.15
330°	7.94	0.16
340°	7.54	0.17
350°	7.39	0.18

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

