


Crater report 1642 of RG5

General information



ID: 1642

Study area: RG5 Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 168m ± 12.0m

Mean depht: $6.0m \pm 0.7m$ d/D ratio : 0.036 ± 0.005

Circularity index: 0.91

Mean slope: 4.81

Geometric center coordinates: (3635856.783,

235180.0456)

Coordinates of the crater's lowest point : (3635872.4999999, 235162.4999999904)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.07	0.24
10°	5.48	0.22
20°	5.13	0.23
30°	4.72	0.21
40°	4.36	0.19
50°	3.95	0.19
60°	3.47	0.21
70°	3.04	0.22
80°	3.17	0.24
90°	3.26	0.25
100°	3.22	0.26
110°	3.29	0.24
120°	3.39	0.23






130°	3.62	0.19
140°	3.78	0.18
150°	4.19	0.19
160°	4.68	0.19
170°	5.04	0.2
180°	5.29	0.2
190°	5.15	0.19
200°	5.08	0.19
210°	5.22	0.19
220°	5.28	0.17
230°	5.25	0.17
240°	5.01	0.17
250°	4.88	0.18
260°	5.26	0.19
270°	5.77	0.2
280°	5.72	0.2
290°	5.71	0.21
300°	5.72	0.2
310°	6.01	0.19
320°	6.16	0.19
330°	5.91	0.2
340°	5.94	0.22
350°	6.02	0.24

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

