



RS18 TabFM soft-GMD pipeline: one exploratory recovery, no confirmed recovery
11 V, 3 m, 2 coded bits/s; frozen 12-symbol list and margin-20 acceptance


A Actual 200 Hz dual-sensor samples — sequence 2, sync field, 50% duty



B Signal conditions



C Payload decoding (green = correct; red = failed/rejected)



Sequence 24 passed initial hard RS; the soft-GMD list added sequence 2 during development. All four prospective candidates were safely rejected. Hard-decoder cells report pre-RS symbol errors; RS(18,6) hard correction limit is 6 symbols.