


Actual accepted 5° polygon; view rotated into airfoil coordinates for comparison. Original vertices and far boundary unchanged.
Refinement affects 3,378 (level 1) and 3,391 (level 2) baseline cells, within 0.0892 chord of the trailing edge.
Actual repaired meshes. Native quality checks precede flow sensitivity. No new flow result is shown here.