

PUBLISHED: 07-JUN-2017
2015.0 RANGE ROVER (LG), 303-14

ELECTRONIC ENGINE CONTROLS - TDV8 4.4L DIESEL

EXHAUST MANIFOLD TEMPERATURE SENSOR (G1509576)

REMOVAL AND INSTALLATION

18.31.60	SENSOR - EXHAUST MANIFOLD TEMPERATURE - RENEW	4400 CC, TDV8	0.3	USED WITHINS	
----------	---	------------------	-----	-----------------	--

SPECIAL TOOL(S)



REMOVAL



NOTE:


Removal steps in this procedure may contain installation details.

1. Refer to: [Engine Cover - 4.4L V8 - TdV8](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

- 2.

Refer to: [Fuel Filter Element](#) (310-01D Fuel Tank and Lines - TDV8 4.4L Diesel, Removal and Installation).

3.




4.



NOTE:

If required move aside the exhaust heat shield.




Torque: 9 Nm

5.



CAUTION:

Before disconnecting any components, make sure the area is clean and free from foreign material. When disconnected all openings must be sealed.



- *Special Tool(s):* [JLR-303-1573](#)
Torque: **32 Nm**

INSTALLATION

1.



CAUTION:

If accidentally dropped or knocked install a new sensor.



NOTE:

If the original sensor is to be installed, apply lubricant meeting specification ESE-M12A4-A to the thread of the sensor.

To install, reverse the removal procedure.