
Kitchen floor IR · raw reflectance and candidate grout indications

Red: phone impacts · green: coincident IR dips · gray: turnaround



Only two candidate dips; no clean 304.8 mm repeating pattern. Sensor offsets and grout-grid phase are uncalibrated.