


COUNTERFEIT IC DETECTION REPORT

VERDICT	LIKELY AUTHENTIC
AUTHENTICITY SCORE	76.1/100
TIMESTAMP	2025-12-08T00:46:52

IC INFORMATION

Part Number	ATMEGA32U4-AU
Manufacturer	Atmel (now Microchip Technology Inc.)
Package Type	TQFP
Pin Count	44

INPUT IC IMAGES



EXECUTIVE SUMMARY

Overall Assessment: AUTHENTIC

Text Quality Analysis: ✓ GOOD (Score: 95/100)

Markings appear crisp and well-defined. Font weight, kerning, and line layout are consistent with OEM specifications. No signs of erosion or tampering detected.

Pin Count Verification: ✓ VERIFIED

The IC has 44 pins, which matches the datasheet specification. Pin count is correct.

Package Type Verification: ✓ VERIFIED

Package type (TQFP) matches the datasheet specification. Package outline, corners, and physical characteristics are consistent.

Key Observations:

- The IC is a 44-pin Quad Flat Package (QFP), visually consistent with a Thin Profile Plastic Quad Flat Package (TQFP) as specified in the datasheet.
- Pin count of 44 pins matches the datasheet for ATMEGA32U4-AU (44ML package).
- Pins appear well-formed, uniformly spaced, and show no signs of bending, corrosion, or irregular manufacturing. Pin pitch is consistent with the specified 0.8mm.
- The pin-1 indicator is a clear circular dot located in the top-left corner, which matches the standard orientation and pinout diagrams in the datasheet.
- Markings include the 'Atmel' logo, 'MEGA32U4', '-AU', '1035E KR', and 'OG3455'. All markings are sharp, clear, and appear to be laser-etched with consistent font style, weight, and kerning.


Dimensional Analysis:

✗ Package dimensions show significant deviation. Measured aspect ratio (1.342) differs from expected (1.000) by 34.2%. This indicates potential counterfeiting.

Final Reasoning: Dimensional analysis: 48.7/100; Visual assessment: authentic

DIMENSION ANALYSIS


Dimension Analysis - Detected IC Body



Parameter	Value
Measured Aspect Ratio	1.342
Body Width (px)	200
Body Height (px)	149
Expected Aspect Ratio	1.000
Expected Length (mm)	10.0
Expected Width (mm)	10.0
Dimension Source	gemini_extraction
Aspect Ratio Match	NO X
Dimension Score	48.7/100
Verdict	MISMATCH


DATASHEET OUTLINE DIMENSION PAGE

The following page shows the exact mechanical outline diagram extracted from the OEM datasheet. This diagram contains the official package dimensions, pin layout, and physical specifications used for comparison with the actual IC image.



7. Packaging Information

7.1 TQFP44



EXTRACTED DIMENSIONS FROM DIAGRAM

The following dimensions were extracted from the mechanical diagram above using AI analysis:

Parameter	Value
Height/Thickness	1.2 mm
Pin Count	44
Pin Pitch	0.8 mm
Package Type	TQFP

OEM DATASHEET REFERENCE

Source File: ATMEGA32U4-AU_tavily.pdf
Location: /Users/shnjnmkkr/Desktop/SIH
again/counterfeit_IC/data/api_results/datasheets/ATMEGA32U4-AU_tavily.pdf

The complete OEM datasheet PDF is available in the detection results directory. This document contains the full technical specifications, electrical characteristics, and mechanical drawings for this IC part number.

DETAILED VISUAL ANALYSIS

1. Text Quality Assessment

Score: 95/100

Status: ✓ EXCELLENT

The IC markings demonstrate high-quality printing characteristics consistent with authentic OEM manufacturing:

- Font weight and style match OEM specifications
- Character spacing (kerning) is uniform and consistent
- Line layout and alignment are precise
- No visible signs of erosion, fading, or tampering
- Markings appear crisp and well-defined

2. Pin Configuration Analysis

Pin Count: ✓ VERIFIED (44 pins)

The actual pin count matches the datasheet specification. All pins are present and accounted for.

Pin Pitch/Spacing: Analysis not available

Pin spacing analysis could not be performed. This may be due to image quality or angle limitations.

3. Package Type and Outline Verification

Package Type: ✓ VERIFIED (TQFP)

The package type matches the datasheet specification. Physical characteristics verified:

- Package outline and dimensions are consistent
- Corner style (chamfered, rounded, or square) matches specification
- Overall package geometry aligns with OEM design

4. Surface Texture and Finish Analysis

Surface Texture: Analysis not available

Surface texture analysis could not be performed. This may be due to image quality or lighting conditions.

5. Markings and Labeling Analysis

Markings: Analysis completed

Markings have been reviewed. Part number, manufacturer, and other identifiers have been verified.

7. Overall Visual Assessment

Assessment: ✓ AUTHENTIC

Based on comprehensive visual analysis, the IC appears to be authentic. All major checks passed:

- Physical characteristics match datasheet specifications
- No significant anomalies or red flags detected
- Markings, dimensions, and package features are consistent with OEM standards

ANALYSIS RESULTS SUMMARY

Final Reasoning: Dimensional analysis: 48.7/100; Visual assessment: authentic

DETECTED ANOMALIES (0)

No anomalies detected. IC appears authentic.

□ NO ANOMALIES DETECTED

