


20260510 IC3392 GAS pairwise Flux_Error cut test in same binning

Here we redo the pairwise `GAS` comparison after adding the `v3tk_v7.6.8_7000_samebinning` run, and so we change the reference run to match the same binning scheme as `v7.6.8` runs:

- x axis / reference: `7.6.8 7000/53 same-bin`
- y axis / comparison: `7.6.8 9100/40`
- gas lines: `OIII5006`, `HA6562`, `NII6583` and `SII6716`
- each pairwise figure: 4 rows by 2 columns, with pairwise scatter on the left and residuals on the right









First, we verify that they are now truly in the same binning scheme:



And clearly, with same binning scheme, all seem to follow the 1:1 relation, even velocity dispersion, though there are still a few outliers and `[O III]` still looks ugly.









IC3392 FLUX: Flux/Err cut overlay, 7.6.8 9100/40 vs 7.6.8 7000/53 same-bin

● F/E > 0 ● F/E > 3 ● F/E > 5 ● F/E > 10 ● F/E > 20 ● F/E > 50




IC3392 VEL: Flux/Err cut overlay, 7.6.8 9100/40 vs 7.6.8 7000/53 same-bin

● F/E > 0 ● F/E > 3 ● F/E > 5 ● F/E > 10 ● F/E > 20 ● F/E > 50



IC3392 SIGMA: Flux/Err cut overlay, 7.6.8 9100/40 vs 7.6.8 7000/53 same-bin



Below i also show the plot that focus on [O III]'s SIGMA:

OIII 5006 SIGMA focus: 7.6.8 9100/40 vs 7.6.8 7000/53 same-bin

