DoN 0.85 · matched seed 10: recorded SF stop and MF passage

Median SF failure time among the 17 MF-only successful seed pairs; tie broken by seed ID.

(a) First-corner geometry and actual footprints



(b) Actual clearance over the first 10 seconds



SF: previous solve reported success; plant integration crosses the boundary at 4.7 s. The next 20 guard steps apply zero input, then the trial fails.

Points are actual 0.1 s records; lines only connect samples. Negative clearance means map-boundary intrusion; zero means obstacle contact/overlap. No continuous-time guarantee.