



ONE-LINE DIAGRAM. NOT TO SCALE.

**GENERATOR PLANT ONE-LINE // SCALE: NONE**

## REVISIONS

| REV | DATE | DESCRIPTION | BY | APPR |
|---|---|---|---|---|
| C | 21 OCT 2019 | Generator 1 replaced. | DC | PG |
| B | 04 APR 2011 | Fuel polishing system. Provision for a third generator. | | |
| A | 16 MAY 2005 | Initial issue. Two generators, paralleling switchgear. | | |

## NOTES

1. Two 500 kW diesel generators paralleled on a common bus. Either one carries the critical load.
2. GEN-1 replaced 2019, same rating.
3. Automatic start on loss of utility; both units sync and close to the bus, then feed ATS-1 (PWR-001).
4. Bulk tank 8,000 gal with day tanks at each generator.
5. Fuel polishing filters the bulk tank continuously.
6. Bus, breaker space and foundation provided for a third generator (GEN-3, not installed).
7. Monthly run under load; annual load bank test at the load bank connection.

## LEGEND

- Generator
- Circuit breaker
- Transformer
- Bus
- Transfer switch / switchgear
- Future / provision only

**OER // ENGINEERING**

# GENERATOR PLANT AND PARALLELING SWITCHGEAR, SITE A

| DRAWING NO. | REV | SHEET |
|---|---|---|
| PWR-005 | C | 1 OF 1 |

| DRAWN | CHECKED | APPROVED |
|---|---|---|
| D. CHEN | M. REED | P. GREENE |

| DATE | SERIES |
|---|---|
| 21 OCT 2019 | POWER |

CONTROLLED DOCUMENT // CUSTODIAN: ENGINEERING / MAINTENANCE // DO NOT SCALE