

STM TripModifications

Detours whose cancelled range is shorter than the detour itself

In a detour at the end of a line, the cancelled range collapses to a single stop while the detour shape published in the same entity skips a longer run of stops. The stops in between stay in the trip although the vehicle never reaches them, and a stop the vehicle no longer serves is sometimes re-added as a replacement stop. Detours in the middle of a line are correct. Each page below shows one affected modification: the same detour shape in both panels, the stops as the feed claims them on the left, and as the shape implies them on the right.

Feed timestamp 1788621300 (2026-09-05 11:15 America/Montreal) · 132 entities examined · 8 repaired

A stop is taken to be unserved when it lies more than 100 m from the detour shape. Stops the vehicle does serve measure 0–26 m from it; the errors below measure 94–471 m, so the reading does not depend on where in that gap the line is drawn.

Entity	Route	Declared	Repaired	What changed
detour_10_N_2_69807	10	[1..1]	[1..3]	+2 stops cancelled
detour_11_E_20_61935	11	[24..29]	[23..29]	+1 stop cancelled
detour_166_S_17_60568	166	[37..37]	[32..37]	+5 stops cancelled
detour_50_E_16_63626-71448-71733	50	[19..19]	[19..20]	+1 stop cancelled
detour_50_W_14_63627-71730	50	[14..14]	[14..15]	+1 stop cancelled, dropped 54346 (241 m)
detour_50_W_14_63627-71730	50	[1..1]	[1..2]	+1 stop cancelled, dropped 53692 (358 m)
detour_97_W_17_53917-70112	97	[35..35]	[19..35]	+16 stops cancelled
<i>Replacement stop not on the detour</i>				
detour_165_N_15_60565	165	[1..1]	[1..1]	dropped 52201 (173 m)
detour_370_W_7_68984	370	[76..77]	[76..77]	dropped temp_stop_2551 (159 m)
detour_50_E_16_63626-71448-71733	50	[1..1]	[1..1]	dropped 54346 (123 m)
detour_50_E_16_63626-71448-71733	50	[21..21]	[21..21]	dropped 53692 (479 m)


Route 10: cancelled range [1..1] should be [1..3]

10 — De Lorimier → Nord


detour_10_N_2_69807 · modification 0 · trip 299890319

2 stops kept in the trip sit up to 262 m from the detour shape.

STM's feed as published



After repair




Route 11: cancelled range [24..29] should be [23..29]

11 — Parc-du-Mont-Royal → Est


detour_11_E_20_61935 · modification 0 · trip 299595623

1 stop kept in the trip sits up to 309 m from the detour shape.

STM's feed as published



After repair



 Scheduled route
  Detour shape from the feed
  Stop still served
  Stop cancelled
  Replacement stop
  Changed by the repair


Route 166: cancelled range [37..37] should be [32..37]

166 — Queen-Mary → Sud


detour_166_S_17_60568 · modification 0 · trip 300260968

5 stops kept in the trip sit up to 412 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 50: cancelled range [19..19] should be [19..20]

50 — Vieux-Montréal / Vieux-Port → Est


detour_50_E_16_63626-71448-71733 · modification 1 · trip 299891283

1 stop kept in the trip sits up to 208 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 50: cancelled range [14..14] should be [14..15]

50 — Vieux-Montréal / Vieux-Port → Ouest


detour_50_W_14_63627-71730 · modification 0 · trip 299891282

1 stop kept in the trip sits up to 241 m from the detour shape; replacement stop 54346 is 241 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 50: cancelled range [1..1] should be [1..2]

50 — Vieux-Montréal / Vieux-Port → Ouest


detour_50_W_14_63627-71730 · modification 1 · trip 299891282

1 stop kept in the trip sits up to 183 m from the detour shape; replacement stop 53692 is 358 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 97: cancelled range [35..35] should be [19..35]

97 — Avenue-du-Mont-Royal → Ouest


detour_97_W_17_53917-70112 · modification 1 · trip 299595485

16 stops kept in the trip sit up to 471 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 165: a replacement stop is not on the detour

165 — Côte-des-Neiges → Nord


detour_165_N_15_60565 · modification 0 · trip 300262016

replacement stop 52201 is 173 m from it.

STM's feed as published




After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair

replacement stop temp_stop_2551 is 159 m from it.

After repair



9 of 11


Route 50: a replacement stop is not on the detour

50 — Vieux-Montréal / Vieux-Port → Est


detour_50_E_16_63626-71448-71733 · modification 0 · trip 299891283

replacement stop 54346 is 123 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 50: a replacement stop is not on the detour

50 — Vieux-Montréal / Vieux-Port → Est

detour_50_E_16_63626-71448-71733 · modification 2 · trip 299891283

replacement stop 53692 is 479 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair