

STM TripModifications

Detours whose cancelled range is shorter than the detour itself

In a detour at the end of a line, the cancelled range collapses to a single stop while the detour shape published in the same entity skips a longer run of stops. The stops in between stay in the trip although the vehicle never reaches them, and a stop the vehicle no longer serves is sometimes re-added as a replacement stop. Detours in the middle of a line are correct. Each page below shows one affected modification: the same detour shape in both panels, the stops as the feed claims them on the left, and as the shape implies them on the right.

Feed timestamp 1789847242 (2026-09-19 15:47 America/Montreal) · 132 entities examined · 16 repaired

A stop is taken to be unserved when it lies more than 100 m from the detour shape. Stops the vehicle does serve measure 0–26 m from it; the errors below measure 94–471 m, so the reading does not depend on where in that gap the line is drawn.

Entity	Route	Declared	Repaired	What changed
detour_11_E_20_61935	11	[24..29]	[23..29]	+1 stop cancelled
detour_150_E_7_67911-69997	150	[23..23]	[13..24]	+11 stops cancelled, dropped 53034 (2128 m)
detour_150_W_8_67912	150	[1..1]	[1..13]	+12 stops cancelled, dropped 54117 (1839 m)
detour_166_S_17_60568-72280-72334	166	[37..37]	[32..37]	+5 stops cancelled
detour_166_S_17_60568-72280-72334	166	[1..1]	[1..4]	+3 stops cancelled
detour_29_W_1_67757	29	[26..26]	[22..26]	+4 stops cancelled, dropped 54140 (162 m)
detour_468_W_16_71606	468	[29..29]	[28..29]	+1 stop cancelled, dropped 58286 (120 m)
detour_470_W_23_71609	470	[24..24]	[23..24]	+1 stop cancelled, dropped 58286 (120 m)
detour_50_W_14_63627-67767	50	[14..14]	[14..15]	+1 stop cancelled, dropped 54346 (241 m)
detour_97_E_18_61937-64739	97	[1..1]	[1..9]	+8 stops cancelled, dropped temp_stop_56217 (282 m), dropped 54010
detour_97_W_17_53917-70112	97	[35..35]	[27..36]	+9 stops cancelled, dropped 54010 (313 m), dropped temp_stop_56217
Replacement stop not on the detour				
detour_131_N_6_70921	131	[1..1]	[1..1]	dropped 53083 (119 m)
detour_165_N_15_60565	165	[1..1]	[1..1]	dropped 52201 (173 m)
detour_370_W_7_68984	370	[76..77]	[76..77]	dropped temp_stop_2551 (159 m)
detour_37_E_12_72326	37	[22..24]	[22..24]	dropped temp_stop_2631 (148 m)
detour_50_E_16_63626-67766	50	[1..1]	[1..1]	dropped 54346 (123 m)
detour_57_N_9_71636	57	[2..2]	[2..2]	dropped 52829 (196 m)


Route 11: cancelled range [24..29] should be [23..29]

11 — Parc-du-Mont-Royal → Est


detour_11_E_20_61935 · modification 0 · trip 299595623

1 stop kept in the trip sits up to 309 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 150: cancelled range [23..23] should be [13..24]

150 — René-Lévesque → Est

detour_150_E_7_67911-69997 · modification 0 · trip 299890326

11 stops kept in the trip sit up to 1971 m from the detour shape; replacement stop 53034 is 2128 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair

Route 150: cancelled range [1..1] should be [1..13]

150 — René-Lévesque → Ouest

detour_150_W_8_67912 · modification 0 · trip 299890325

12 stops kept in the trip sit up to 2027 m from the detour shape; replacement stop 54117 is 1839 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair

166 — Queen-Mary → Sud

5 stops kept in the trip sit up to 412 m from the detour shape.

The map displays the proposed bus route in the Sherbrooke area. The route is shown as a green line with a grey segment. Key stops and locations are marked with blue stars and labels: Sherbrooke / Guy, Guy-Concordia (Guy / De Maisonneuve), and Guy / Sainte-Catherine. A red 'X' marks the intersection of Guy / Sainte-Catherine. The route also passes through several other streets, including Avenue des Pins, Avenue Docteur, Rue Redpath, Rue Simpson, Rue Goy, Rue Crescent, Rue Bishop, Rue Mackay, Avenue Lincoln, Rue St-Marc, Rue Towers, Rue Tupper, Rue Baile, and Rue Marie. A scale bar at the bottom left indicates a distance of 250 m.

The map shows the study area in Sherbrooke, Quebec. Key features include:

- Scale:** 250 m.
- Streets:** AVENUE DES PINS O, AVENUE DOCTEUR P, RUE REDPATH, RUE SIMPSON, RUE LINCOLN, RUE CRESCENT, RUE BISHOP, RUE MACKAY, RUE ST-MARC, RUE TOWERS, RUE TUPPER, RUE BAILE, RUE STE-CATHERINE O, RUE DE LA SALLE.
- Landmarks:** P&G Wallens, Sherbrooke / Guy, Guy-Concordia station (marked with a red 'X').
- Proposed Route:** A grey line indicating the proposed bus route, starting from the Guy-Concordia station and ending at the intersection of Rue de la Salle and Rue Ste-Catherine O.
- Other Labels:** temp_stop_1721, temp_stop_52202, 37. Guy / Sainte-Catherine, 29. dt Station Guy-Concordia (Guy / De Maisonneuve).

Basemap: Esri, HERE, Garmin, © OpenStreetMap contributors. Transit data: Société de transport de Montréal, CC-BY 4.0.


Route 166: cancelled range [1..1] should be [1..4]

166 — Queen-Mary → Sud


detour_166_S_17_60568-72280-72334 · modification 2 · trip 300260968

3 stops kept in the trip sit up to 188 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 29: cancelled range [26..26] should be [22..26]

29 — Rachel → Ouest


detour_29_W_1_67757 · modification 0 · trip 299890763

4 stops kept in the trip sit up to 288 m from the detour shape; replacement stop 54140 is 162 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 468: cancelled range [29..29] should be [28..29]

468 — Express Pierrefonds / Gouin → Ouest


detour_468_W_16_71606 · modification 0 · trip 299610762

1 stop kept in the trip sits up to 333 m from the detour shape; replacement stop 58286 is 120 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 470: cancelled range [24..24] should be [23..24]

470 — Express Pierrefonds → Ouest


detour_470_W_23_71609 · modification 0 · trip 300262400

1 stop kept in the trip sits up to 333 m from the detour shape; replacement stop 58286 is 120 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 50: cancelled range [14..14] should be [14..15]

50 — Vieux-Montréal / Vieux-Port → Ouest


detour_50_W_14_63627-67767 · modification 0 · trip 299891282

1 stop kept in the trip sits up to 241 m from the detour shape; replacement stop 54346 is 241 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 97: cancelled range [1..1] should be [1..9]

97 — Avenue-du-Mont-Royal → Est


detour_97_E_18_61937-64739 · modification 0 · trip 299595484

8 stops kept in the trip sit up to 466 m from the detour shape; replacement stop temp_stop_56217 is 282 m from it; replacement stop 54010 is 317 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair

9 stops kept in the trip sit up to 471 m from the detour shape; replacement stop 54010 is 313 m from it; replacement stop temp_stop_56217 is 256 m from it.




Route 131: a replacement stop is not on the detour

131 — De l'Assomption → Nord


detour_131_N_6_70921 · modification 0 · trip 299890353

replacement stop 53083 is 119 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 165: a replacement stop is not on the detour

165 — Côte-des-Neiges → Nord


detour_165_N_15_60565 · modification 0 · trip 300262016

replacement stop 52201 is 173 m from it.

STM's feed as published




After repair




Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair

replacement stop temp_stop_2551 is 159 m from it.

STM's feed as published



After repair



 Scheduled route
  Detour shape from the feed
  Stop still served
  Stop cancelled
  Replacement stop
  Changed by the repair

Route 37: a replacement stop is not on the detour

37 — Jolicoeur → Est


detour_37_E_12_72326 · modification 0 · trip 299613139

replacement stop temp_stop_2631 is 148 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 50: a replacement stop is not on the detour

50 — Vieux-Montréal / Vieux-Port → Est


detour_50_E_16_63626-67766 · modification 0 · trip 299891283

replacement stop 54346 is 123 m from it.

STM's feed as published



After repair




Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 57: a replacement stop is not on the detour

57 — Charlevoix → Nord
detour_57_N_9_71636 · modification 0 · trip 299613530
replacement stop 52829 is 196 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair