

STM TripModifications

Detours whose cancelled range is shorter than the detour itself

In a detour at the end of a line, the cancelled range collapses to a single stop while the detour shape published in the same entity skips a longer run of stops. The stops in between stay in the trip although the vehicle never reaches them, and a stop the vehicle no longer serves is sometimes re-added as a replacement stop. Detours in the middle of a line are correct. Each page below shows one affected modification: the same detour shape in both panels, the stops as the feed claims them on the left, and as the shape implies them on the right.

Feed timestamp 1791035496 (2026-10-03 09:51 America/Montreal) · 133 entities examined · 10 repaired

A stop is taken to be unserved when it lies more than 100 m from the detour shape. Stops the vehicle does serve measure 0–26 m from it; the errors below measure 94–471 m, so the reading does not depend on where in that gap the line is drawn.

Entity	Route	Declared	Repaired	What changed
detour_166_S_17_72334	166	[1..1]	[1..4]	+3 stops cancelled
detour_358_E_4_61565-73023	358	[28..28]	[26..28]	+2 stops cancelled
detour_468_W_16_71606	468	[29..29]	[28..29]	+1 stop cancelled, dropped 58286 (120 m)
detour_470_W_23_71609	470	[24..24]	[23..24]	+1 stop cancelled, dropped 58286 (120 m)
detour_50_W_14_63627-73269	50	[14..14]	[14..15]	+1 stop cancelled, dropped 54346 (241 m)
detour_97_E_18_64739-72785	97	[1..1]	[1..9]	+8 stops cancelled, dropped 54010 (502 m)
detour_97_W_17_53917-72787	97	[35..35]	[27..36]	+9 stops cancelled, dropped 54010 (487 m)
Replacement stop not on the detour				
detour_37_E_12_72326	37	[22..24]	[22..24]	dropped temp_stop_2631 (148 m)
detour_50_E_16_63626	50	[1..1]	[1..1]	dropped 54346 (123 m)
detour_57_N_9_71636	57	[2..2]	[2..2]	dropped 52829 (196 m)


Route 166: cancelled range [1..1] should be [1..4]

166 — Queen-Mary → Sud


detour_166_S_17_72334 · modification 0 · trip 300260968

3 stops kept in the trip sit up to 188 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 358: cancelled range [28..28] should be [26..28]

358 — René-Lévesque → Est


detour_358_E_4_61565-73023 · modification 0 · trip 299890936

2 stops kept in the trip sit up to 236 m from the detour shape.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 468: cancelled range [29..29] should be [28..29]

468 — Express Pierrefonds / Gouin → Ouest


detour_468_W_16_71606 · modification 0 · trip 299610762

1 stop kept in the trip sits up to 333 m from the detour shape; replacement stop 58286 is 120 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 470: cancelled range [24..24] should be [23..24]

470 — Express Pierrefonds → Ouest


detour_470_W_23_71609 · modification 0 · trip 300262400

1 stop kept in the trip sits up to 333 m from the detour shape; replacement stop 58286 is 120 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 50: cancelled range [14..14] should be [14..15]

50 — Vieux-Montréal / Vieux-Port → Ouest


detour_50_W_14_63627-73269 · modification 0 · trip 299891282

1 stop kept in the trip sits up to 241 m from the detour shape; replacement stop 54346 is 241 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 97: cancelled range [1..1] should be [1..9]

97 — Avenue-du-Mont-Royal → Est


detour_97_E_18_64739-72785 · modification 1 · trip 299595484

8 stops kept in the trip sit up to 470 m from the detour shape; replacement stop 54010 is 502 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 97: cancelled range [35..35] should be [27..36]

97 — Avenue-du-Mont-Royal → Ouest

detour_97_W_17_53917-72787 · modification 1 · trip 299595485

9 stops kept in the trip sit up to 487 m from the detour shape; replacement stop 54010 is 487 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair

Route 37: a replacement stop is not on the detour

37 — Jolicoeur → Est


detour_37_E_12_72326 · modification 0 · trip 299613139

replacement stop temp_stop_2631 is 148 m from it.

STM's feed as published



After repair




— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair


Route 50: a replacement stop is not on the detour

50 — Vieux-Montréal / Vieux-Port → Est
detour_50_E_16_63626 · modification 0 · trip 299891283
replacement stop 54346 is 123 m from it.

STM's feed as published



After repair



Scheduled route
 Detour shape from the feed
 Stop still served
 Stop cancelled
 Replacement stop
 Changed by the repair


Route 57: a replacement stop is not on the detour

57 — Charlevoix → Nord


detour_57_N_9_71636 · modification 0 · trip 299613530

replacement stop 52829 is 196 m from it.

STM's feed as published



After repair



— Scheduled route — Detour shape from the feed ● Stop still served ○ Stop cancelled ★ Replacement stop ○ Changed by the repair