Customer readiness test
Lahoun Solar Plant

One-time browser test · 2026-11-13T07:34:54.811516+00:00 UTC
https://main.d3o3iryvy33gj9.amplifyapp.com/portfolio

23/23	12	2	9
Questions attempted	Passed functional checks	Failed checks	Review / blocked

Key findings

- November 13, 2026, 07:34-07:45 UTC (18:34-18:45 Sydney): all 23 questions completed; 12 functional/retrieval passes, two failures, nine partial/informational/unverified results.
- P1: Q27 requested external clipping API still failed. Assistant now gives a labelled fallback estimate of 33,349.24 kWh, which does not prove that API is healthy.
- Improvement: Q18 now reports 100.0% availability along with energy, yield and PR, without the prior explicit calculation error. Figures are not independently recalculated.
- P2: Q7 restored Inverter 2, hourly granularity and the three-day window, but lost the original MPPT-level breakdown by returning only two aggregate inverter traces.
- Partial answers: Q11 and Q21 returned populated clipping charts but omitted the requested written numerical lists. Q6 had an empty current-day dataframe; Q12 listed only six available days.
- Q17 used yesterday's data and classified all 282 returned rows as daytime; daytime filtering and missing power-mismatch output require review. Q10 BOM source mapping is unverified.
- Latest available data repeatedly stops at November 12 23:25. Missing data is informational unless an explicit API/tool error is present; no independent freshness guarantee is made.
- Three monthly PDFs validated: October 2026 (13 pages), December 2025 (12 pages), September 2026 (13 pages). Manual/PVsyst passes mean source retrieval, not validated engineering or safety advice.
- Safety review needed for Q9: operational instructions mention opening equipment and electrical measurement without an explicit isolation/qualified-person warning. No equipment actions were performed.
- Four customer UI areas and six selected job-card details inspected. No cleaning-log save, card status change, team-chat message, email or GitHub upload performed.
- Read-only S3 snapshot at 07:35:29 UTC: api_error=false, last modified 07:31:50 UTC. Upstream status does not establish healthy chat analytics or fresh data.
- Compared with the previous run: Q12: passed → review; Q17: passed → review; Q11: passed → review; Q18: failed → passed; Q6: passed → review; Q21: passed → review

> API/tool errors are highest priority, followed by failed application responses. Missing data is reported separately. An answer or HTTP 200 alone is not a functional pass. Numerical results have not been independently recomputed. This test did not change daily schedules or run the upstream pipeline.

Single-plant pipeline snapshot

Abdali_Mall_Lahoun.json · api_error: **false**

S3 last modified: 2026-11-13T07:31:50.000Z

Checked: 2026-11-13T07:35:29.009Z

Question results

ID	Test question	Result	Finding
Q9	I have a COMMUNICATION_FAULT what do I do to my inverters?	**PASSED**	Manual guidance, diagram references and manufacturer PDF returned: retrieval/response pass only. Important safety concern: answer suggests opening the inverter and voltage measurement without an explicit isolation/qualified-person warning. Do not treat this as validated operational advice; no equipment actions performed.
Q27	Use 'clipping_loss_via_requests' in order to calculate clipping loss if any for July 2026	**FAILED**	P1 API/tool failure persists: requested clipping_loss_via_requests could not reach the external service. Assistant now explicitly supplies an alternative site-data estimate: 33,349.24 kWh total, six inverter values. A fallback estimate does not establish recovery of the requested API.
Q1	Please generate last months report	**PASSED**	October 2026 Lahoun PDF downloaded, readable and correct plant/month, 13 pages. Retrieval verified, not numerical accuracy or fresh recomputation.
Q12	Was there any 0 production days in the last 7 days?	**REVIEW**	Partial coverage: answer says last seven days but lists only six values, November 7-12. Explicitly states latest data ends November 12 23:25 with November 13 unavailable. No zero production among returned days, but full seven-day result not established. Missing data is informational, not an API failure.

ID	Test question	Result	Finding
Q16	Please generate December 2025 performance report	**PASSED**	December 2025 Lahoun PDF downloaded, readable and correct plant/month, 12 pages. Retrieval only; not independent validation of the historical numerical tables.
Q17	How is my data quality for POA and power? How many of them show missing data during daytime or mismatches with satellite prediction?	**REVIEW**	Partial/unverified analysis: today's request returned November 12 data only, with 282 rows all classified as daytime and 69 POA mismatches. Missing-data counts are reported but power mismatch analysis is not explicitly supplied. All-day daytime classification requires review; no explicit API error and no independent recalculation.
Q3	Please plot last 3 days hourly performance ratio for my MPPTs for inverter 2	**PASSED**	Hourly Inverter 2 MPPT PR chart returned 12 populated traces. Available coverage is 48 hours, November 11-12, within the requested November 11-13 window; missing current-day data is a coverage limitation, not an API error.
Q4	Please plot last 3 days hourly performance ratio for my Strings for inverter 2	**REVIEW**	Informational/unavailable data: explicitly states this plant does not record string-level data and suggests MPPT level instead. No string-level chart or silent substitute returned. Statement not independently verified against the source schema.
Q5	Please plot the last 4 days hourly performance ratio for all my inverters	**PASSED**	All-inverter hourly PR chart returned six populated traces covering 72 hours, November 10-12, within the requested four-day window. November 13 is missing; coverage limitation noted, values not independently recomputed.
Q11	Please figure out how much clipping loss was found in the last 6 months broken by inverters, list them down and plot it as well	**REVIEW**	Partial output: populated six-month clipping bar chart returned, one trace with six inverter bars. The requested numerical inverter-by-inverter list is absent from the written answer. Chart values exist but this is not full completion of the list-and-plot request.

ID	Test question	Result	Finding
Q18	How did my plant perform yesterday?	**PASSED**	Improved from prior failure: now returns energy 3,834.68 kWh, yield 4.88 kWh/kWp, PR 0.916 and reported technical/contractual availability 100.0%, with calculation-method details and no explicit tool error. Functional response pass only; figures and contractual-method equivalence not independently verified.
Q20	Is there shading happening with my plant? Please analyze the pyranometer and check for frequent dips at certain times	**PASSED**	Returned quantified 30-day shading analysis with recurring times, dip rates, measured/modelled ratios and calibration/orientation/model caveats. Moderate shading interpretation is not site-confirmed and calculations not independently recomputed.
Q2	Based on pvsyst report, what is the rated power of this plant and array configuration	**PASSED**	Retrieved two plant-specific PVsyst source sections for system summary and array characteristics. Source-retrieval pass only; rated power and array configuration not extracted into prose.
Q6	Please plot my current and voltage in a dual axes plot on the deepest possible granularity level for inverter3	**REVIEW**	No current-day data: chart explicitly titled Dataframe Empty for 2026-11-13 has zero traces. Current/voltage plot not delivered; no explicit API failure observed.
Q10	When was the last time the BOM data showed up	**REVIEW**	Claims latest BOM timestamp November 12 23:25, using non-empty satellite/source field with value 0.0. BOM source mapping remains unverified; a non-empty source value alone is not evidence of valid BOM data.
Q19	Please find out the daily POA poa summed up as a Wh/m^2, daily for the last 12 months and then calculate the median, mean and kurt	**PASSED**	Returned daily POA median, mean and kurtosis in Wh/m² over 313 valid days, with missing/NaN days and November 12 23:25 cutoff disclosed. Response-level pass only; full daily series, integration and statistics not independently validated.
Q14	Pull up the latest cleaning log	**REVIEW**	No November cleaning logs returned; does not establish whether an older latest cleaning log exists. Informational/no records, not an API failure.

ID	Test question	Result	Finding
Q15	Jim cleaned the pyranometer today, can you add it to the cleaning log?	**REVIEW**	Asked for required Date, Fault Cause, Action Taken and Status before adding the log. Tester supplied no extra fields or confirmation; no record saved. Save capability remains untested.
Q8	How can I shut down my inverters?	**PASSED**	Manual shutdown guidance, diagram references and manufacturer PDF returned. Retrieval/response pass only; procedure not independently safety-certified and no equipment actions performed.
Q13	Please change to dark mode	**PASSED**	Dark-mode action returned and fresh screenshot visibly confirms dark interface.
Q21	Please figure out how much clipping loss was found in the last 2 months broken by inverters, list them down and plot it as well	**REVIEW**	Partial output: two-month clipping chart contains one populated trace with six inverter bars, but requested numerical per-inverter list is absent from written answer. Not an API outage; list-and-plot request only partially fulfilled.
Q7	Please repeat the first plotting question, but interchange it with Specific yield on 1 axes, and energy production on the other axes on a single dual axes plot (Memory Test)	**FAILED**	P2 partial context loss: improved to correct Inverter 2, hourly, last-three-day window and two axes, but original first plot was MPPT-level (12 traces). Follow-up collapses to aggregate inverter specific yield/energy (two traces), losing MPPT breakdown. Current-day coverage also absent.
Q46	Can you generate report for moth of september 2026	**PASSED**	September 2026 Lahoun PDF downloaded, readable and correct plant/month, 13 pages. Retrieval verified, not numerical accuracy.

Application UI checks

Area	Result	Finding
AI_brain_UI	passed	Customer AI Brain feed, diagnostic/time disclosures and heatmap rendered. Legacy fullscreen/layout parity not exhaustively asserted.
Maintenance_UI	passed	Task/filter/calendar loaded; previous/next controls showed October then November. Site states once-a-year maintenance; legacy scheduling controls absent by design.

Area	Result	Finding
Job_cards_UI	passed	Six selected existing job-card detail panels inspected and captured, not the entire board inventory. No create/resolve/reassign actions; viewing may mark cards as read.
Teams_UI	passed	Customer Team Chat participants, message history and composer rendered. No message sent; not a Microsoft Teams integration test.

Customer navigation differs from the legacy daily-test site. Unavailable legacy tabs are not counted as passes.

Q9 · passed

I have a COMMUNICATION_FAULT what do I do to my inverters?

Duration: 39.2 seconds · Manual guidance, diagram references and manufacturer PDF returned: retrieval/response pass only. Important safety concern: answer suggests opening the inverter and voltage measurement without an explicit isolation/qualified-person warning. Do not treat this as validated operational advice; no equipment actions performed.

Observed answer

To troubleshoot and resolve a COMMUNICATION_FAULT on your inverters, follow these detailed steps referencing the manual diagrams:

Open the inverter cover to access internal components: Rotate the cover in the direction indicated by arrow 1 and secure it as shown. Diagram:
Identify the four critical switch positions on the inverter, and ensure each toggle switch is in the correct ON or OFF position. Diagram:
Use the inverter user interface to check for status, communication information, and navigate for detailed diagnostic data. Diagram:
Inspect the bottom of the device: Confirm that all four toggle switches are set as required. Diagram:
Verify cable connections to the inverter, especially if multiple cables are present. Ensure all are securely attached, following this connection setup:
Check and re-seat all plugs or connectors, pressing them down and inserting as shown in the process diagram:
With a multimeter, measure voltage between L1, L2, L3, and PE, using the arrows for reference in this diagram:

Manual Reference: STP_110-60_Manual.pdf

STP_110-60_Manual.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Technical details
Answered by Manual Agent
· 22.9s

Browser evidence


PT

I have a COMMUNICATION FA...


to my inverters?

To troubleshoot and resolve a COMMUNICATION_FAULT on your inverters, follow these detailed steps referencing the manual diagrams:


1. Open the inverter cover to access internal components: Rotate the cover in the direction indicated by arrow 1 and secure it as shown. Diagram:



2. Identify the four critical switch positions on the inverter, and ensure each toggle switch is in the correct ON or OFF position. Diagram:



3. Use the inverter user interface to check for status, communication information, and navigate for detailed diagnostic data. Diagram:



Ask about Lahoun Solar Plant

Q27 · failed

Use 'clipping_loss_via_requests' in order to calculate clipping loss if any for July 2026

Duration: 38.7 seconds · P1 API/tool failure persists: requested clipping_loss_via_requests could not reach the external service. Assistant now explicitly supplies an alternative site-data estimate: 33,349.24 kWh total, six inverter values. A fallback estimate does not establish recovery of the requested API.

Observed answer

I first used clipping_loss_via_requests for July 2026, but the external clipping analytics service was unavailable, so it did not return clipping values. I then used calculate_clipping_or_curtailment_losses_ag as the fallback estimate from site data.

Yes — there was clipping loss in July 2026.

Estimated clipping loss by inverter:

inverter1: 6791.51 kWh
inverter2: 8166.85 kWh
inverter3: 7798.30 kWh
inverter4: 4130.33 kWh
inverter5: 3688.40 kWh
inverter6: 2773.85 kWh


Total estimated clipping loss across all inverters:

33349.24 kWh

Status:

clipping_loss_via_requests: Failed (external service unreachable)
Fallback estimate: Good
How this was worked out
Technical details
Answered by Data Agent
· 28.1s

Browser evidence


PT
I have a COMMUNICATION FA...
Manual Reference: STP_110-60_Manual.pdf
STP_110-60_Manual.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Technical details
Answered by Manual Agent · 22.9s
Use 'clipping_loss_via_requests' in order to calculate clipping loss if any for July 2026
I first used clipping_loss_via_requests for July 2026, but the external clipping analytics service was unavailable, so it did not return clipping values. I then used calculate_clipping_or_curtailment_losses_ag as the fallback estimate from site data.
Yes — there was clipping loss in July 2026.
Estimated clipping loss by inverter:
inverter1: 6791.51 kWh
inverter2: 8166.85 kWh
inverter3: 7798.30 kWh
inverter4: 4130.33 kWh
inverter5: 3688.40 kWh
inverter6: 2773.85 kWh
Total estimated clipping loss across all inverters:
33349.24 kWh
Status:
clipping_loss_via_requests : Failed (external service unreachable)
Fallback estimate: Good
How this was worked out
Technical details
Answered by Data Agent · 28.1s
Ask about Lahoun Solar Plant

Q1 · passed

Please generate last months report


Duration: 43.5 seconds · October 2026 Lahoun PDF downloaded, readable and correct plant/month, 13 pages. Retrieval verified, not numerical accuracy or fresh recomputation.

Observed answer

I've generated the plant performance report for October 2026. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'

Abdali_Mall_Lahoun_October_2026_external_report.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent
· 4.3s

Browser evidence


PT
I have a COMMUNICATION FA...
I first used clipping_loss_via_requests for July 2026, but the external clipping analytics service was unavailable, so it did not return clipping values. I then used calculate_clipping_or_curtailment_losses_ag as the fallback estimate from site data.
Yes — there was clipping loss in July 2026.
Estimated clipping loss by inverter:
inverter1: 6791.51 kWh
inverter2: 8166.85 kWh
inverter3: 7798.30 kWh
inverter4: 4130.33 kWh
inverter5: 3688.40 kWh
inverter6: 2773.85 kWh
Total estimated clipping loss across all inverters:
33349.24 kWh
Status:
clipping_loss_via_requests: Failed (external service unreachable)
Fallback estimate: Good
How this was worked out
Technical details
Answered by Data Agent · 28.1s
Please generate last months report
I've generated the plant performance report for October 2026. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'
Abdali_Mall_Lahoun_October_2026_exte...
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent · 4.3s
Ask about Lahoun Solar Plant

Q12 · review

Was there any 0 production days in the last 7 days?

Duration: 40.5 seconds · Partial coverage: answer says last seven days but lists only six values, November 7-12. Explicitly states latest data ends November 12 23:25 with November 13 unavailable. No zero production among returned days, but full seven-day result not established. Missing data is informational, not an API failure.

Observed answer

No. In the last 7 days with available data, there was no day with zero actual energy production.


Daily actual energy production:

2026-11-07: 2424.63 kWh
2026-11-08: 3207.16 kWh
2026-11-09: 4152.37 kWh
2026-11-10: 4009.04 kWh
2026-11-11: 4002.97 kWh
2026-11-12: 3834.68 kWh

Note: 2026-11-13 is not fully available yet in the database; the latest recorded data ends at 2026-11-12 23:25:00.

How this was worked out
Technical details
Answered by Data Agent
· 12.7s

Browser evidence


PT
I have a COMMUNICATION FA...
How this was worked out
Technical details
Answered by Data Agent · 28.1s
Please generate last months report
I've generated the plant performance report for October 2026. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'
Abdali_Mall_Lahoun_October_2026_exte...
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent · 4.3s
Was there any 0 production days in the last 7 days?
No. In the last 7 days with available data, there was no day with zero actual energy production.
Daily actual energy production:
2026-11-07: 2424.63 kWh
2026-11-08: 3207.16 kWh
2026-11-09: 4152.37 kWh
2026-11-10: 4009.04 kWh
2026-11-11: 4002.97 kWh
2026-11-12: 3834.68 kWh
Note: 2026-11-13 is not fully available yet in the database; the latest recorded data ends at 2026-11-12 23:25:00.
How this was worked out
Technical details
Answered by Data Agent · 12.7s
Ask about Lahoun Solar Plant

Q16 · passed

Please generate December 2025 performance report


Duration: 14.2 seconds · December 2025 Lahoun PDF downloaded, readable and correct plant/month, 12 pages. Retrieval only; not independent validation of the historical numerical tables.

Observed answer

I've generated the plant performance report for December 2025. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'

Abdali_Mall_Lahoun_December_2025_external_report.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent
· 3.4s

Browser evidence


PT
I have a COMMUNICATION FA...
How this was worked out
Answered by Report Agent · 4.3s
Was there any 0 production days in the last 7 days?
No. In the last 7 days with available data, there was no day with zero actual energy production.
Daily actual energy production:
2026-11-07: 2424.63 kWh
2026-11-08: 3207.16 kWh
2026-11-09: 4152.37 kWh
2026-11-10: 4009.04 kWh
2026-11-11: 4002.97 kWh
2026-11-12: 3834.68 kWh
Note: 2026-11-13 is not fully available yet in the database; the latest recorded data ends at 2026-11-12 23:25:00.
How this was worked out
Technical details
Answered by Data Agent · 12.7s
Please generate December 2025 performance report
I've generated the plant performance report for December 2025. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'
Abdali_Mall_Lahoun_December_2025_ex...
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent · 3.4s
Ask about Lahoun Solar Plant

Q17 · review

How is my data quality for POA and power? How many of them show missing data during daytime or mismatches with satellite prediction?

Duration: 31.0 seconds · Partial/unverified analysis: today's request returned November 12 data only, with 282 rows all classified as daytime and 69 POA mismatches. Missing-data counts are reported but power mismatch analysis is not explicitly supplied. All-day daytime classification requires review; no explicit API error and no independent recalculation.

Observed answer

Assessed over available returned data only: 2026-11-12 00:00 to 2026-11-12 23:25.

Results:

Total records analyzed: 282
Daytime records analyzed: 282
Missing POA records during daytime: 0
Missing power records during daytime: 0
Missing both POA and power during daytime: 0
POA mismatches vs satellite/modelled prediction during daytime: 69


Mismatch rule used:

|pyranometer_1 - modelled_poa_1| > 150 W/m²
and relative difference > 25%

Important note:

The query did not return data for 2026-11-13; the available data stopped at 2026-11-12 23:25, so this assessment is only for that returned coverage.
Also, the extracted data suggests modelled/measured POA indicated daytime for all returned rows, so the daytime filter did not reduce the set.
How this was worked out
Technical details
Answered by Data Agent
· 15.6s

Browser evidence


PT
I have a COMMUNICATION FA...
Abdali_Mall_Lahoun_December_2025_ex...
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent · 3.4s
How is my data quality for POA and power? How many of them show missing data during daytime or mismatches with satellite prediction?
Assessed over available returned data only: 2026-11-12 00:00 to 2026-11-12 23:25.
Results:
• Total records analyzed: 282
• Daytime records analyzed: 282
• Missing POA records during daytime: 0
• Missing power records during daytime: 0
• Missing both POA and power during daytime: 0
• POA mismatches vs satellite/modelled prediction during daytime: 69
Mismatch rule used:
• |pyranometer_1 - modelled_poa_1| > 150 W/m²
• and relative difference > 25%
Important note:
• The query did not return data for 2026-11-13; the available data stopped at 2026-11-12 23:25, so this assessment is only for that returned coverage.
• Also, the extracted data suggests modelled/measured POA indicated daytime for all returned rows, so the daytime filter did not reduce the set.
How this was worked out
Technical details
Answered by Data Agent · 15.6s
Ask about Lahoun Solar Plant

Q3 · passed

Please plot last 3 days hourly performance ratio for my MPPTs for inverter 2

Duration: 26.4 seconds · Hourly Inverter 2 MPPT PR chart returned 12 populated traces. Available coverage is 48 hours, November 11-12, within the requested November 11-13 window; missing current-day data is a coverage limitation, not an API error.

Observed answer

I've created the visualization for you.

Hourly Performance Ratio for Each MPPT of Inverter 2 (Last 3 Days)
Pin
How this was worked out
Answered by Graph Agent
· 16.2s

Browser evidence

PT

I have a COMMUNICATION FA...

Mismatch rule used:

- |pyranometer_1 - modelled_poa_1| > 150 W/m²
- and relative difference > 25%

Important note:

- The query did not return data for 2026-11-13; the available data stopped at 2026-11-12 23:25, so this assessment is only for that returned coverage.
- Also, the extracted data suggests modelled/measured POA indicated daytime for all returned rows, so the daytime filter did not reduce the set.

› How this was worked out


› Technical details

Answered by Data Agent · 15.6s

Please plot last 3 days hourly performance ratio for my MPPTs for inverter 2

I've created the visualization for you.

Hourly Performance Ratio for E... Pin



› How this was worked out

Answered by Graph Agent · 16.2s

Ask about Lahoun Solar Plant

Q4 · review

Please plot last 3 days hourly performance ratio for my Strings for inverter 2

Duration: 15.7 seconds · Informational/unavailable data: explicitly states this plant does not record string-level data and suggests MPPT level instead. No string-level chart or silent substitute returned. Statement not independently verified against the source schema.

Observed answer

This plant does not record string-level data, so there is nothing to plot for strings. Try the same chart at MPPT level instead.

How this was worked out
Answered by Graph Agent
· 4.5s

Browser evidence

PT

I have a COMMUNICATION FA...

all returned rows, so the daytime filter did not reduce the set.

> How this was worked out


> Technical details

Answered by Data Agent · 15.6s

Please plot last 3 days hourly performance ratio for my MPPTs for inverter 2

I've created the visualization for you.

Hourly Performance Ratio for E... Pin



> How this was worked out

Answered by Graph Agent · 16.2s

Please plot last 3 days hourly performance ratio for my Strings for inverter 2

This plant does not record string-level data, so there is nothing to plot for strings. Try the same chart at MPPT level instead.

> How this was worked out

Answered by Graph Agent · 4.5s

Ask about Lahoun Solar Plant

Q5 · passed

Please plot the last 4 days hourly performance ratio for all my inverters

Duration: 23.3 seconds · All-inverter hourly PR chart returned six populated traces covering 72 hours, November 10-12, within the requested four-day window. November 13 is missing; coverage limitation noted, values not independently recomputed.

Observed answer


I've created the visualization for you.

Hourly Performance Ratio for All Inverters (Last 4 Days)
Pin
How this was worked out
Answered by Graph Agent
· 12.9s

Browser evidence

PT

I have a COMMUNICATION FA...



› How this was worked out

Answered by Graph Agent · 16.2s

Please plot last 3 days hourly performance ratio for my Strings for inverter 2

This plant does not record string-level data, so there is nothing to plot for strings. Try the same chart at MPPT level instead.


› How this was worked out

Answered by Graph Agent · 4.5s

Please plot the last 4 days hourly performance ratio for all my inverters

I've created the visualization for you.

Hourly Performance Ratio for A... Pin



› How this was worked out

Answered by Graph Agent · 12.9s

Ask about Lahoun Solar Plant

Q11 · review

Please figure out how much clipping loss was found in the last 6 months broken by inverters, list them down and plot it as well

Duration: 35.8 seconds · Partial output: populated six-month clipping bar chart returned, one trace with six inverter bars. The requested numerical inverter-by-inverter list is absent from the written answer. Chart values exist but this is not full completion of the list-and-plot request.

Observed answer


I've created the visualization for you.

Clipping Loss by Inverter - Last 6 Months
Pin
How this was worked out
Answered by Graph Agent
· 25.3s

Browser evidence

PT

I have a COMMUNICATION FA...




› How this was worked out

Answered by Graph Agent · 12.9s

Please figure out how much clipping loss was found in the last 6 months broken by inverters, list them down and plot it as well

I've created the visualization for you.

Clipping Loss by Inverter - Last... Pin



› How this was worked out

Answered by Graph Agent · 25.3s

Ask about Lahoun Solar Plant

Q18 · passed

How did my plant perform yesterday?

Duration: 27.9 seconds · Improved from prior failure: now returns energy 3,834.68 kWh, yield 4.88 kWh/kWp, PR 0.916 and reported technical/contractual availability 100.0%, with calculation-method details and no explicit tool error. Functional response pass only; figures and contractual-method equivalence not independently verified.

Observed answer

Yesterday (2026-11-12), the plant performed well overall.

Key metrics

Total energy: 3,834.68 kWh
Specific yield: 4.88 kWh/kWp
Performance ratio: 0.916
Technical/contractual availability: 100.0%

Operational assessment

The plant followed a normal solar production profile: generation ramped up after 07:00, stayed strong through midday, and declined toward sunset.
Peak hourly average plant power was around 496.7 kW at 09:00.
Irradiance also looked normal for a clear productive day, peaking around 625.8 W/m² at 12:00 on the POA pyranometer.
A PR of 91.6% indicates strong conversion of available irradiance into energy.
Availability at 100% suggests no plant-level downtime was detected.

Inverter observations

Inverters 1–5 tracked each other closely through the day.
Inverter 6 produced materially less than the others throughout daylight hours. For example around 09:00 its hourly average was about 40.9 kW, while the others were mostly around 87.5–93.8 kW.
This suggests inverter6 is likely smaller, derated, or affected by a persistent underperformance condition relative to the rest of the fleet.

Data note


The dataset ended at 23:25 rather than 23:55. Since this missing portion is after sunset, it does not materially affect the daily performance interpretation.

Overall conclusion

The plant had a solid day with good energy production, high PR, and full reported availability. The only notable point is the consistently lower output from inverter6 compared with inverters 1–5.
How this was worked out
Technical details

Answered by Data Agent
· 17.6s

Browser evidence



Q20 · passed

Is there shading happening with my plant? Please analyze the pyranometer and check for frequent dips at certain times

Duration: 37.0 seconds · Returned quantified 30-day shading analysis with recurring times, dip rates, measured/modelled ratios and calibration/orientation/model caveats. Moderate shading interpretation is not site-confirmed and calculations not independently recomputed.

Observed answer

I analyzed the last 30 days of measured POA pyranometer data against modelled POA, using daylight periods only.

Findings:

There are recurring dips at specific times, most notably around 09:00–09:50.
The strongest repeated dip time is 09:15, with dips on 7 of 30 days (23.3% of days at that clock time).
Other frequent dip times are 09:00, 09:25, 09:40, 09:45, 09:50, and a smaller cluster around 10:50–11:05.
A few afternoon events also recur, especially around 15:05, but they are less systematic than the morning cluster.

Key evidence:

Overall measured/modelled POA median ratio: 0.621
Morning median ratio: 0.613
Afternoon median ratio: 0.633
Morning P10 ratio: 0.274
Afternoon P10 ratio: 0.314

Most frequent dip clock-times:

09:15: dip rate 23.3%, median ratio 0.520
12:50: dip rate 23.3%, median ratio 0.913
09:00: dip rate 20.0%, median ratio 0.472
09:25: dip rate 20.0%, median ratio 0.555
09:40: dip rate 20.0%, median ratio 0.597
09:45: dip rate 20.0%, median ratio 0.614
09:50: dip rate 20.0%, median ratio 0.628
10:50–11:05: dip rate 20.0%, median ratios 0.803–0.859

Assessment:

Yes, the repeated morning dips are consistent with possible shading on or near the pyranometer. The pattern is time-localized and recurs at similar clock times, which is a classic shading signature. However, the sensor is also reading substantially below modelled POA even outside those dip windows, so shading is likely not the only issue. Possible additional causes are calibration bias,

mounting/tilt mismatch, persistent obstruction, dirt, or model/sensor mismatch.
The 12:50 recurrence is weaker evidence for shading because the median ratio there remains relatively high (0.913), suggesting occasional transient dips rather than a strong fixed obstruction.


Bottom line:

There is moderate evidence of time-specific shading, especially around 09:00–09:50.
There is also a broader low-bias in measured vs modelled irradiance that should be investigated separately.

Analysis window used:

2026-10-14 00:00 to 2026-11-12 23:25
Note: available data did not extend through 2026-11-13.
How this was worked out
Technical details
Answered by Data Agent
· 26.8s

Browser evidence


PT
I have a COMMUNICATION FA...
I analyzed the last 30 days of measured POA pyranometer data against modelled POA, using daylight periods only.
Findings:
• There are recurring dips at specific times, most notably around 09:00–09:50.
• The strongest repeated dip time is 09:15, with dips on 7 of 30 days (23.3% of days at that clock time).
• Other frequent dip times are 09:00, 09:25, 09:40, 09:45, 09:50, and a smaller cluster around 10:50–11:05.
• A few afternoon events also recur, especially around 15:05, but they are less systematic than the morning cluster.
Key evidence:
• Overall measured/modelled POA median ratio: 0.621
• Morning median ratio: 0.613
• Afternoon median ratio: 0.633
• Morning P10 ratio: 0.274
• Afternoon P10 ratio: 0.314
Most frequent dip clock-times:
• 09:15: dip rate 23.3%, median ratio 0.520
• 12:50: dip rate 23.3%, median ratio 0.913
• 09:00: dip rate 20.0%, median ratio 0.472
• 09:25: dip rate 20.0%, median ratio 0.555
• 09:40: dip rate 20.0%, median ratio 0.597
• 09:45: dip rate 20.0%, median ratio 0.614
• 09:50: dip rate 20.0%, median ratio 0.628
• 10:50–11:05: dip rate 20.0%, median ratios 0.803–0.859
Assessment:
• Yes, the repeated morning dips are consistent with possible shading on or near the pyranometer.
• The pattern is time-localized and recurs at similar clock times, which is a classic shading signature.
• However, the sensor is also reading substantially below modelled POA even outside those dip windows, so shading is likely not the
Ask about Lahoun Solar Plant

Q2 · passed

Based on pvsyst report, what is the rated power of this plant and array configuration

Duration: 17.3 seconds · Retrieved two plant-specific PVsyst source sections for system summary and array characteristics. Source-retrieval pass only; rated power and array configuration not extracted into prose.

Observed answer

Found 2 relevant PVsyst report sections:

[Abdali_Mall_Lahoun] System summary (Page 2, Table 2)
[Abdali_Mall_Lahoun] PV Array Characteristics, including array configurations (Page 3, Table 2)
How this was worked out
Technical details
Answered by PVsyst Agent
· 6.9s

Browser evidence

PT

I have a COMMUNICATION FA...

signature.

- However, the sensor is also reading substantially below modelled POA even outside those dip windows, so shading is likely not the only issue. Possible additional causes are calibration bias, mounting/tilt mismatch, persistent obstruction, dirt, or model/sensor mismatch.
- The 12:50 recurrence is weaker evidence for shading because the median ratio there remains relatively high (0.913), suggesting occasional transient dips rather than a strong fixed obstruction.

Bottom line:

- There is moderate evidence of time-specific shading, especially around 09:00–09:50.
- There is also a broader low-bias in measured vs modelled irradiance that should be investigated separately.

Analysis window used:

- 2026-10-14 00:00 to 2026-11-12 23:25
- Note: available data did not extend through 2026-11-13.

› How this was worked out

› Technical details


Answered by Data Agent · 26.8s

Based on pvsyst report, what is the rated power of this plant and array configuration

Found 2 relevant PVsyst report sections:

1. [Abdali_Mall_Lahoun] System summary (Page 2, Table 2)
2. [Abdali_Mall_Lahoun] PV Array Characteristics, including array configurations (Page 3, Table 2)





› How this was worked out

Ask about Lahoun Solar Plant

Q6 · review

Please plot my current and voltage in a dual axes plot on the deepest possible granularity level for inverter3

Duration: 18.8 seconds · No current-day data: chart explicitly titled Dataframe Empty for 2026-11-13 has zero traces. Current/voltage plot not delivered; no explicit API failure observed.

Observed answer

I've created the visualization for you.

Inverter 3 Current and Voltage - Dataframe Empty for 2026-11-13
Pin
How this was worked out
Answered by Graph Agent
· 8.6s

Browser evidence


PT

I have a COMMUNICATION FA...

Found 2 relevant PVsyst report sections:

1. [Abdali_Mall_Lahoun] System summary (Page 2, Table 2)
2. [Abdali_Mall_Lahoun] PV Array Characteristics, including array configurations (Page 3, Table 2)





› How this was worked out


› Technical details

Answered by PVsyst Agent · 6.9s

Please plot my current and voltage in a dual axes plot on the deepest possible granularity level for inverter3

I've created the visualization for you.

Inverter 3 Current and Voltage ... Pin



› How this was worked out

Answered by Graph Agent · 8.6s

Ask about Lahoun Solar Plant

Q10 · review

When was the last time the BOM data showed up

Duration: 23.4 seconds · Claims latest BOM timestamp November 12 23:25, using non-empty satellite/source field with value 0.0. BOM source mapping remains unverified; a non-empty source value alone is not evidence of valid BOM data.

Observed answer

The most recent timestamp when BOM data was available is 2026-11-12 23:25:00.

Note: I checked the satellite/source field and found the latest non-empty source entry at that time. The source value at that timestamp is "0.0", and the dataset itself currently only extends to 2026-11-12 23:25:00, not up to the current time.

How this was worked out
Technical details
Answered by Data Agent
· 13.3s


Browser evidence

I have a COMMUNICATION FA...

Please plot my current and voltage in a dual axes plot on the deepest possible granularity level for inverter3

I've created the visualization for you.

Inverter 3 Current and Voltage ... Pin



How this was worked out

Answered by Graph Agent · 8.6s

When was the last time the BOM data showed up

The most recent timestamp when BOM data was available is 2026-11-12 23:25:00.

Note: I checked the satellite/source field and found the latest non-empty source entry at that time. The source value at that timestamp is "0.0", and the dataset itself currently only extends to 2026-11-12 23:25:00, not up to the current time.

How this was worked out

Technical details

Answered by Data Agent · 13.3s

Ask about Lahoun Solar Plant

Q19 · passed

Please find out the daily POA poa summed up as a Wh/m^2, daily for the last 12 months and then calculate the median, mean and kurt

Duration: 23.4 seconds · Returned daily POA median, mean and kurtosis in Wh/m² over 313 valid days, with missing/NaN days and November 12 23:25 cutoff disclosed. Response-level pass only; full daily series, integration and statistics not independently validated.

Observed answer

Using pyranometer_1 over 2025-11-13 to 2026-11-13, I calculated daily POA totals in Wh/m² for the last 12 months.

Results for daily POA totals:

Median: 5738.30 Wh/m²
Mean: 5744.62 Wh/m²
Kurtosis: -0.324
Valid daily totals used: 313 days


Notes:

The extracted daily series ends at 2026-11-12 23:25:00, so 2026-11-13 is not complete.
There are missing/NaN days in the period, so the statistics were computed on the 313 non-NaN daily totals only.
Daily totals were derived from the daily aggregated pyranometer_1 values and expressed in Wh/m².

If you want, I can also return the full list of all 313 daily totals by date.

How this was worked out
Technical details
Answered by Data Agent
· 12.3s

Browser evidence


PT
I have a COMMUNICATION FA...
The most recent timestamp when BOM data was available is 2026-11-12 23:25:00.
Note: I checked the satellite/source field and found the latest non-empty source entry at that time. The source value at that timestamp is "0.0", and the dataset itself currently only extends to 2026-11-12 23:25:00, not up to the current time.
How this was worked out
Technical details
Answered by Data Agent · 13.3s
Please find out the daily POA poa summed up as a Wh/m^2, daily for the last 12 months and then calculate the median, mean and kurt
Using pyranometer_1 over 2025-11-13 to 2026-11-13, I calculated daily POA totals in Wh/m² for the last 12 months.
Results for daily POA totals:
Median: 5738.30 Wh/m²
Mean: 5744.62 Wh/m²
Kurtosis: -0.324
Valid daily totals used: 313 days
Notes:
The extracted daily series ends at 2026-11-12 23:25:00, so 2026-11-13 is not complete.
There are missing/NaN days in the period, so the statistics were computed on the 313 non-NaN daily totals only.
Daily totals were derived from the daily aggregated pyranometer_1 values and expressed in Wh/m².
If you want, I can also return the full list of all 313 daily totals by date.
How this was worked out
Technical details
Answered by Data Agent · 12.3s
Ask about Lahoun Solar Plant

Q14 · review

Pull up the latest cleaning log


Duration: 14.3 seconds · No November cleaning logs returned; does not establish whether an older latest cleaning log exists. Informational/no records, not an API failure.

Observed answer

No cleaning logs have been recorded for Abdali_Mall_Lahoun so far in November 2026.

Technical details
Answered by Data Entry Agent
· 3.3s

Browser evidence


PT
I have a COMMUNICATION FA...
Technical details
Answered by Data Agent · 13.3s
Please find out the daily POA poa summed up as a Wh/m^2, daily for the last 12 months and then calculate the median, mean and kurt
Using pyranometer_1 over 2025-11-13 to 2026-11-13, I calculated daily POA totals in Wh/m² for the last 12 months.
Results for daily POA totals:
Median: 5738.30 Wh/m²
Mean: 5744.62 Wh/m²
Kurtosis: -0.324
Valid daily totals used: 313 days
Notes:
The extracted daily series ends at 2026-11-12 23:25:00, so 2026-11-13 is not complete.
There are missing/NaN days in the period, so the statistics were computed on the 313 non-NaN daily totals only.
Daily totals were derived from the daily aggregated pyranometer_1 values and expressed in Wh/m².
If you want, I can also return the full list of all 313 daily totals by date.
How this was worked out
Technical details
Answered by Data Agent · 12.3s
Pull up the latest cleaning log
No cleaning logs have been recorded for Abdali_Mall_Lahoun so far in November 2026.
Technical details
Answered by Data Entry Agent · 3.3s
Ask about Lahoun Solar Plant

Q15 · review

Jim cleaned the pyranometer today, can you add it to the cleaning log?

Duration: 12.8 seconds · Asked for required Date, Fault Cause, Action Taken and Status before adding the log. Tester supplied no extra fields or confirmation; no record saved. Save capability remains untested.

Observed answer

To add a cleaning log entry, please provide the following required details:


Date
Fault Cause
Action Taken
Status

Site will be set automatically from the connected plant.

Optional fields you can also provide, but they are not required:

Activity Type (Inspection, Cleaning, HSE Incident, Spare Parts Usage, General Site Activity)
Priority
Responsibility
Estimated Duration
Start Work Time
End Work Time
Spare Part Use
Number Of Staff
Images
Notes
Technical details
Answered by Data Entry Agent
· 3s

Browser evidence


PT
I have a COMMUNICATION FA...
Technical details
Answered by Data Agent · 12.3s
Pull up the latest cleaning log
No cleaning logs have been recorded for Abdali_Mall_Lahoun so far in November 2026.
Technical details
Answered by Data Entry Agent · 3.3s
Jim cleaned the pyranometer today, can you add it to the cleaning log?
To add a cleaning log entry, please provide the following required details:
Date
Fault Cause
Action Taken
Status
Site will be set automatically from the connected plant.
Optional fields you can also provide, but they are not required:
Activity Type (Inspection, Cleaning, HSE Incident, Spare Parts Usage, General Site Activity)
Priority
Responsibility
Estimated Duration
Start Work Time
End Work Time
Spare Part Use
Number Of Staff
Images
Notes
Technical details
Answered by Data Entry Agent · 3s
Ask about Lahoun Solar Plant

Q8 · passed

How can I shut down my inverters?

Duration: 23.4 seconds · Manual shutdown guidance, diagram references and manufacturer PDF returned. Retrieval/response pass only; procedure not independently safety-certified and no equipment actions performed.

Observed answer

Shutdown Procedure (from the manufacturer manual):

Disconnect the AC miniature circuit breaker as shown in the system connection diagrams and ensure it is secured against reconnection.
Switch off all four DC load-break switches on the inverter and secure each against reconnection. These switches are labeled for exact identification in the diagram linked below.
Wait until all LEDs on the inverter have turned off to confirm the device is no longer energized.
Use a current clamp (as positioned in the diagram) to confirm that there is no current in any DC cables. Focus on the labeled cable positions and measurement points for accuracy.
Note and record the position of each DC connector (refer to the diagram) before disconnecting further.

Relevant Safety Precautions:

Only use measuring devices with a DC input voltage range of 1100 V or higher to avoid risk of electric shock.
Secure all breakers and switches against reconnection before proceeding with shutdown.
Strictly follow the outlined shutdown sequence to ensure safety and prevent equipment damage.

Relevant Diagram Image URLs:

Main shutdown and disconnect procedure:
Key/slot alignment for secure disconnection:
Cable-to-terminal tool application:

Manual reference (PDF): https://manual-aepco-sydney.s3.ap-southeast-2.amazonaws.c...

STP_110-60_Manual.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Technical details
Answered by Manual Agent
· 12.7s

Browser evidence

I have a COMMUNICATION FA...

Shutdown Procedure (from the manufacturer manual):


1. Disconnect the AC miniature circuit breaker as shown in the system connection diagrams and ensure it is secured against reconnection.
2. Switch off all four DC load-break switches on the inverter and secure each against reconnection. These switches are labeled for exact identification in the diagram linked below.
3. Wait until all LEDs on the inverter have turned off to confirm the device is no longer energized.
4. Use a current clamp (as positioned in the diagram) to confirm that there is no current in any DC cables. Focus on the labeled cable positions and measurement points for accuracy.
5. Note and record the position of each DC connector (refer to the diagram) before disconnecting further.

Relevant Safety Precautions:

- Only use measuring devices with a DC input voltage range of 1100 V or higher to avoid risk of electric shock.
- Secure all breakers and switches against reconnection before proceeding with shutdown.
- Strictly follow the outlined shutdown sequence to ensure safety and prevent equipment damage.

Relevant Diagram Image URLs:

- Main shutdown and disconnect procedure:



- Key/slot alignment for secure disconnection:

Ask about Lahoun Solar Plant

Q13 · passed

Please change to dark mode

Duration: 12.8 seconds · Dark-mode action returned and fresh screenshot visibly confirms dark interface.

Observed answer


Sure, I will turn on dark mode

Answered by UI Agent
· 2.1s


Browser evidence

PT


I have a COMMUNICATION FA...



- Key/slot alignment for secure disconnection:



- Cable-to-terminal tool application:



Manual reference (PDF): https://manual-aepco-sydney.s3.ap-southeast-2.amazonaws.c...

STP_110-60_Manual.pdf
PDF report

Preview | Open in a new tab

› How this was worked out

› Technical details

Answered by Manual Agent · 12.7s

Please change to dark mode

Sure, I will turn on dark mode

Answered by UI Agent · 2.1s

Ask about Lahoun Solar Plant

Q21 · review

Please figure out how much clipping loss was found in the last 2 months broken by inverters, list them down and plot it as well


Duration: 32.6 seconds · Partial output: two-month clipping chart contains one populated trace with six inverter bars, but requested numerical per-inverter list is absent from written answer. Not an API outage; list-and-plot request only partially fulfilled.

Observed answer

I've created the visualization for you.

Clipping Loss by Inverter (2026-09-13 to 2026-11-13)
Pin
How this was worked out
Answered by Graph Agent
· 21.5s

Browser evidence


PT
I have a COMMUNICATION FA...
sydney.s3.ap-southeast-2.amazonaws.c...
STP_110-60_Manual.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Technical details
Answered by Manual Agent · 12.7s
Please change to dark mode
Sure, I will turn on dark mode
Answered by UI Agent · 2.1s
Please figure out how much clipping loss was found in the last 2 months broken by inverters, list them down and plot it as well
I've created the visualization for you.
Clipping Loss by Inverter (2026...
Pin
Clipping Loss by Inverter (2026-09-13 to 2026-11-13)
Clipping Loss (kWh)
2000
1000
0
Inverter 1
Inverter 2
Inverter 3
Inverter 4
Inverter 5
Inverter 6
Inverter
How this was worked out
Answered by Graph Agent · 21.5s
Ask about Lahoun Solar Plant

Q7 · failed

Please repeat the first plotting question, but interchange it with Specific yield on 1 axes, and energy production on the other axes on a single dual axes plot (Memory Test)

Duration: 25.0 seconds · P2 partial context loss: improved to correct Inverter 2, hourly, last-three-day window and two axes, but original first plot was MPPT-level (12 traces). Follow-up collapses to aggregate inverter specific yield/energy (two traces), losing MPPT breakdown. Current-day coverage also absent.


Observed answer

I've created the visualization for you.

Inverter 2 - Hourly Specific Yield and Energy Production (Last 3 Days)
Pin
How this was worked out
Answered by Graph Agent
· 14.5s

Browser evidence

I have a COMMUNICATION FA...




› How this was worked out

Answered by Graph Agent · 21.5s

Please repeat the first plotting question, but interchange it with Specific yield on 1 axes, and energy production on the other axes on a single dual axes plot (Memory Test)

I've created the visualization for you.

Inverter 2 - Hourly Specific Yiel... Pin



› How this was worked out

Answered by Graph Agent · 14.5s

Ask about Lahoun Solar Plant

Q46 · passed

Can you generate report for moth of september 2026

Duration: 14.3 seconds · September 2026 Lahoun PDF downloaded, readable and correct plant/month, 13 pages. Retrieval verified, not numerical accuracy.

Observed answer

I've generated the plant performance report for September 2026. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'

Abdali_Mall_Lahoun_September_2026_external_report.pdf
PDF report
Preview
Open in a new tab
How this was worked out
Answered by Report Agent
· 3.5s

Browser evidence


PT

I have a COMMUNICATION FA...

Please repeat the first plotting question, but interchange it with Specific yield on 1 axes, and energy production on the other axes on a single dual axes plot (Memory Test)

I've created the visualization for you.

Inverter 2 - Hourly Specific Yiel... Pin



› How this was worked out

Answered by Graph Agent · 14.5s

Can you generate report for moth of september 2026

I've generated the plant performance report for September 2026. You can view it here: 'https://report-aepco-sydney.s3.ap-southeast-2.amazonaws.c...'

Abdali_Mall_Lahoun_September_2026_e...
PDF report


Preview Open in a new tab

› How this was worked out


Answered by Report Agent · 3.5s

Ask about Lahoun Solar Plant


AI_brain_UI


AEPCO
Lahoun Solar Plant
Jordan · 0.79 MWp · 6 inverters
Action needed
Fri 10:35 plant time · day
Yesterday (2026-11-12)
PT
Peter Tran
Admin · AEPC
Dark mode
Settings
Sign out
Hide the times
10:00:11 10:05:11 10:10:11 10:15:11 10:20:11 10:25:11 10:30:11
09:00
24 messages
09:55:11 from 09:00
Job card · High
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
12 cards
Open the latest job card
Hide the times
09:00:11 09:05:11 09:10:11 09:15:11 09:20:11 09:25:11 09:30:11 09:35:11 09:40:11 09:45:11 09:50:11 09:55:11
09:55:11 from 09:00
Low
Data expected but not received.
12 times
Hide the times
09:00:11 09:05:11 09:10:11 09:15:11 09:20:11 09:25:11 09:30:11 09:35:11 09:40:11 09:45:11 09:50:11 09:55:11
08:00
24 messages
08:55:11 from 08:00
Job card · High
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
12 cards
Open the latest job card
Hide the times
08:00:11 08:05:11 08:10:11 08:15:11 08:20:11 08:25:11 08:30:11 08:35:11 08:40:11 08:45:11 08:50:11 08:55:11
08:55:11 from 08:00
Low
Data expected but not received.
12 times
Hide the times
08:00:11 08:05:11 08:10:11 08:15:11 08:20:11 08:25:11 08:30:11 08:35:11 08:40:11 08:45:11 08:50:11 08:55:11
07:00
24 messages
07:55:11 from 07:00
Job card · High
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
12 cards
Open the latest job card
Hide the times
07:00:11 07:05:11 07:11:42 07:15:11 07:20:11 07:25:11 07:30:11 07:35:11 07:40:11 07:45:11 07:50:11 07:55:11
07:55:11 from 07:00
Low
Data expected but not received.
12 times
Show the times
06:00
24 messages
06:55:11 from 06:00
Job card · High
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
12 cards
Open the latest job card
Show the times
06:55:11 from 06:00
Low
Data expected but not received.
12 times
Show the times
05:00
Plant
YESTERDAY
Thu, Nov 12, 2026
Plant average 4.87 kWh/kWp
Inverter
MPPT
Below -10%
-10% to -5%
Within ±5%
Above +5%
No data
Point at the map for the numbers, click to open it on the map.
Open the map
From the heatmap
Worked out from the specific yield the map shows.
Inverter 5 MPPT 5 is -50.8% against its inverter
It runs on row A-16 (strings 5.5.1, 5.5.2 on the drawing). The plant reports each MPPT as a whole, so its strings cannot be told apart.
Check the strings of this MPPT on site: fuses, MC4 connectors and the DC isolator, then shading, soiling or a stalled tracker.
Open job cards (7)
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
2026-11-13 · high · unread
Module Temperature Probe 1 - 38.2% Daytime Deviation from Faiman Reference
2026-11-09 · medium
Pyranometer POA_1 - 16.8% Daytime Deviation from Satellite Reference
2026-11-06 · high
Portfolio
Maps
Views
AI Brain
Job Cards
Reports
Maintenance
Team Chat
P2Dingo
Learn

Maintenance_UI




Job_cards_UI


AEPCO
Lahoun Solar Plant
Jordan · 0.79 MWp · 6 inverters
Action needed
Fri 10:36 plant time · day
Yesterday (2026-11-12)
PT
Peter Tran
Admin · AEPC
Dark mode
Settings
Sign out
Job cards
Board
List
Sort: Priority
Any priority (436)
Drag a card to another column to assign, resolve or reopen it, or open the card to do it there. Nothing changes until you confirm.
TO DO 3
Open, nobody assigned yet
Data unavailable
NEW
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
8h
General inaccuracy temperature probe
Module Temperature Probe 1 - 38.2% Daytime Deviation from Faiman Reference
Temperature probe 1
3d
Tracker malfunction error
Pyranometer 1 tracker-shape mismatch vs satellite POA
Pyranometer 1 (plane of array)
8d
IN PROGRESS 0
Open and assigned
Nothing here
VERIFY ON SITE 4
The AI reports it fixed, still open
General inaccuracy pyranometer
Pyranometer POA_1 - 16.8% Daytime Deviation from Satellite Reference
Pyranometer 1 (plane of array)
6d
General inaccuracy temperature probe
Module Temperature Probe_1 - 33.8% Daytime Deviation from Faiman Reference
Temperature probe 1
7d
Electrical fault voltage
Inverter 2 MPPT 7 - Voltage 682 V vs Ideal 734 V, Alarms on 3/119 Points
Inverter 2 MPPT 7 +1
9d
Electrical fault voltage
Inverter 5 MPPT 5 - Voltage 674 V vs Ideal 734 V, Alarms on 4/119 Points
Inverter 5 MPPT 5 +1
9d
DONE 429
Resolved, most recent first
Data unavailable
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
1d
Data unavailable
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
1d
Data unavailable
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
2d
Data unavailable
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
2d
Data unavailable
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
2d
Data unavailable
Sustained Data Loss - 32 Consecutive Missing Cycles (160 min)
Whole plant
2d
Data unavailable
Portfolio
Maps
Views
AI Brain
Job Cards
Reports
Maintenance
Team Chat
P2Dingo
Learn


Job card evidence

Pyranometer POA_1 - 16.8% Daytime Deviation from Satellite Reference




Job card evidence

Module Temperature Probe 1 - 38.2% Daytime Deviation from Faiman Reference




Job card evidence

Pyranometer 1 tracker-shape mismatch vs satellite POA




Job card evidence

Module Temperature Probe_1 - 33.8% Daytime Deviation from Faiman Reference




Job card evidence

Inverter 2 MPPT 7 - Voltage 682 V vs Ideal 734 V, Alarms on 3/119 Points




Job card evidence

Inverter 5 MPPT 5 - Voltage 674 V vs Ideal 734 V, Alarms on 4/119 Points



Teams_UI


Lahoun Solar Plant
Jordan · 0.79 MWp · 6 inverters
Action needed
Fri 10:36 plant time · day
Yesterday (2026-11-12)
PT
Peter Tran
Admin · AEPC
Dark mode
Settings
Sign out
People (9)
Everyone with access to Lahoun Solar Plant. Click a name to mention them.
testuser2
Active 8 Nov
testuser1 (you)
Active 2 Nov
hassan
No recent messages
mohammad
No recent messages
oday
No recent messages
osama
No recent messages
osama_2026
No recent messages
raed
No recent messages
sabbagh
No recent messages
Team chat
Lahoun Solar Plant
Search messages
hi
5:16 pm Reply
testuser2
hi
10:34 pm Reply
Tuesday 3 November
testuser2
hi
5:17 pm Reply
Wednesday 4 November
testuser2
hi
1:30 am Reply
Thursday 5 November
testuser2
hi
5:03 pm Reply
Friday 6 November
testuser2
hi
12:16 am Reply
Sunday 8 November
testuser2
hi
11:13 pm Reply
Message the team. Type @ to mention someone.
Enter sends, Shift+Enter adds a line. Photos, PDFs, documents and voice notes up to 10 MB.
Portfolio
Maps
Views
AI Brain
Job Cards
Reports
Maintenance
Team Chat
P2Dingo
Learn

Scope and limitations

- One-time standalone test; daily schedules and application source unchanged.
- Credentials and browser authentication state are not saved.
- Enabled suite texts and dates preserved; no independent calculation verification.
- A new standalone repeat run; previous evidence files were preserved.
- Functional review used current answers and artifact payloads, not earlier verdicts.
- No alert email, Teams message, GitHub upload, upstream pipeline invocation or S3 write was performed.
- Opening existing job cards may mark them as read; no cards created, resolved or reassigned.
- No independent numerical recalculation, security audit or load test was performed.