## Problem report for:

## MPLUS1[wght].ttf

sha1: 03ad73705a2479d16543ff823e4f78a395e02dc8

Family name: MPLUS 1 Version: Version 1.001


## Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- Contour start point in contours with wrong direction
- Suggested new contour start point


uni7E6D tolerance: 0.27

## wrong\_start\_point


'wght=500.0'



'wght=900.0'



midway interpolation



proposed fix

