Problem report for:

Archivo[wdth,wght].ttf


sha1: 7b9deb8883fbf04a3a623094affd293bdae5a0fe

Family name: Archivo Version: Version 2.001


Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- Contour start point in contours with wrong direction
- Suggested new contour start point


"




'wght=100.0'




midway interpolation




proposed fix




'wdth=62.0'




'wdth=62.0 wght=100.0'




midway interpolation




proposed fix




'wdth=125.0'




'wdth=125.0 wght=100.0'




midway interpolation




proposed fix




'wdth=125.0'




'wdth=125.0 wght=100.0'




midway interpolation




proposed fix




wrong_structure












proposed fix




wrong_structure




'wdth=62.0 wght=900.0'



midway interpolation




proposed fix




wrong_structure


'wdth=125.0'




'wdth=125.0 wght=900.0'



midway interpolation




proposed fix




tolerance: 0.01

wrong_start_point


'wdth=125.0'



'wdth=125.0 wght=100.0'



midway interpolation



proposed fix

