Problem report for:

MPLUS2[wght].ttf

sha1: e020cad46932473e665d2c46e4eb46f65df4e162
Family name: M PLUS 2
Version: Version 1.001

Legend:

- ► Contour start point and direction
- ● Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- ● Suggested new contour start point
- ▭ Colored contours: contours with the wrong order

Tolerance: badness; closer to zero the worse

Glyph name: uni20B1.BRACKET.440

tolerance: 0.68

contour_order

”



midway interpolation



’wght=500.0’



proposed fix



Glyph name: uni3082.003

tolerance: 0.42

contour_order

”



midway interpolation



’wght=500.0’



proposed fix



Glyph name: uni3082.003

tolerance: 0.22

contour_order

'wght=500.0'



midway interpolation



'wght=900.0'



proposed fix



Glyph name: uni7E6D

tolerance: 0.27

wrong_start_point

'wght=500.0'



midway interpolation



'wght=900.0'



proposed fix