### Problem report for:

### LexendExa[wght].ttf

sha1: 2c493fb7702217928045aec7d063998b5fec01fe


Family name: Lexend Exa Version: Version 1.007

### Legend:


- Contour start point and direction
- Contour start point when the first two points overlap
- Contour start point in contours with wrong direction
- Suggested new contour start point

## contour\_order


"




'wght=900.0'



midway interpolation




proposed fix



uni20AD


# tolerance: 0.01

# wrong\_start\_point




"


'wght=199.9939'



midway interpolation




proposed fix




uni20AD

# contour\_order, wrong\_start\_point

'wght=199.9939'




'wght=100.0'




midway interpolation

tolerance: 0.06




proposed fix




uni20B1 tolerance: 0.42

## contour\_order


"




'wght=199.9939'



midway interpolation




proposed fix




uni20B1 tolerance: 0.60

## contour\_order

" 'wght=900.0'



midway interpolation



proposed fix

