


FL Profile - Simpson
Vermilion Range KNP
AB
Elevation: 2270 m
Aspect: S
Specifics: Pit is adjacent to avalanche: crown;

Banff Visitor Safety
28/02/2021 - 12:32
Co-ord: 50.98986N, -115.99281W
Slope Angle: 36°
Wind Loading: no

Stability:
Air Temperature: -10°C
Sky Cover: OVC
Precipitation: S-1
Wind: W Light Breeze

HS: 225
Layer Notes:
159-157cm: Bed surface
159-157cm: Problematic layer



Notes: Fracture line profile from avalanche triggered by recreational party on 2021-02-27 (reported on MIN). Thin sun-crust @ 157cm with 2cm of 4F facets above it. No data below 140cm.